INLET INSPECTION

GENERAL NOTES

INLET ID: #201 Intersection Knollview + Carpentersville Road

LOCATION OF INLET: #201 Carpentersville Road

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT Type B Inlet

WEATHER AT TIME OF INSPECTION: 44° Sunny

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

Inlet Newly Reconstructed

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type B Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: (NEW) ACCEPTABLE NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

Newly Reconstructed Inlet

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: Type N ECO

HEIGHT OF CURB PIECE: 6"

CONDITION OF CURB PIECE: (NEW) ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE (FULL ECO CURB PIECE)

LABEL FOR DRAINS TO WATERWAYS: Yes

WATERWAYS LABEL CONDITION: (NEW) ACCEPTABLE NEEDS REPLACEMENT

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

New

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Precast Concrete + Block Plaster coated

WALL CONDITION: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Inlet newly Reconstructed

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): No odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: (NEW) ACCEPTABLE NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert in 24" RCP

1 Invert out 24" RCP

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Newly Reconstructed
Inlet Box with new
Frame - Grate + Eco curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: CORNER OF #? N.W CORNER - NO BDG. NUMBER

LOCATION OF INLET: INTERSECTION OF SUMMIT + FILLMORE

DATE OF INSPECTION: 2-1-2013

INSPECTED BY: PAUL KLITSCH

INLET TYPE/STYLE: TYPE B

WEATHER AT TIME OF INSPECTION: CLOAR

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: N/A

WHERE WAS DEBRIS DISPOSED OF: N/A

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

TYPE B

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

(PHOTOS) OR VIDEO TAKEN:

GRATE INFORMATION

TYPE OF GRATE: BIKE SAFE 1½" X 4" OPENINGS

MEASUREMENT OF GRATE SIZE: 22" X 36"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: (BAR) PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS STAMPED ON BAR
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS:
WALL CONSTRUCTION MATERIAL TYPE:
WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT NONE
SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: UNABLE TO INSPECT INTERIOR AT THIS TIME.
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED) N/A
HOW WAS DEBRIS REMOVED: N/A
WHERE WAS DEBRIS DISPOSED OF: N/A
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): SLIGHT ; Sewer / Septic ?
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NONE OBSERVED

CONDITION OF BENCH: NEW ACCEPTABLE NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

ONE INVERT, APPROX. 10"

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: Corner of ~~Sum~~ # 56/53 Summit

LOCATION OF INLET: Intersection of Summit + Fillmore

DATE OF INSPECTION: 2-1-2023

INSPECTED BY: Pam Klitsch

INLET TYPE/STYLE: Type B

WEATHER AT TIME OF INSPECTION: Clear

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: N/A

WHERE WAS DEBRIS DISPOSED OF: N/A

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:
Bike Safe – 1½" x 4" openings
Type B

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

(PHOTOS) OR VIDEO TAKEN:

GRATE INFORMATION

TYPE OF GRATE:

MEASUREMENT OF GRATE SIZE: 22" X 36"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: (BAR) PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS STAMPED ON BAR
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS:
WALL CONSTRUCTION MATERIAL TYPE:
WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT N/A - NONE
SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: UNABLE TO INSPECT INTERIOR AT THIS TIME.
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED) N/A
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): NO
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: YES

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

ONE INVERT, APPROX. 10"
APPEARS TO BE CLAY/TERRA COTTA; FLUSH W/ WALL

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: # 244 NATALIE

LOCATION OF INLET: # 244 NATALIE

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B INLET

WEATHER AT TIME OF INSPECTION: 42° SUNNY

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" ofew curb Piece
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES) 6" ofew curb not ECO
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"
WALL CONSTRUCTION MATERIAL TYPE: Block
WALL CONDITION: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT Shallow
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: Inlet was repaired many years ago . needs some repairs - Blocks seperated
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): no odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert out 15" RCP

in Good condition

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet is in fair shape needs some repairs - seperated Block + Plaster coat

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #231 NATALIE

LOCATION OF INLET: #231 NATALIE

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B INLET

WEATHER AT TIME OF INSPECTION: 44° SUNNY

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: PICTURE TAKEN

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: 6" open curb NOT ECO

HEIGHT OF CURB PIECE: 6"

CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: yes

WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

6" open curb Piece NOT ECO

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete + Block

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Needs plaster coat

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR


ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 INV IN 15" RCP

1 INV OUT 15" RCP

in good condition

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet is in good condition

* Plaster coat Recomended

* 6" open hood needs Eco

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION	
GENERAL NOTES	
INLET ID: #221 Knollview Dr	
LOCATION OF INLET: 221 Knollview Dr	
DATE OF INSPECTION: 1-30-23	
INSPECTED BY: Steve Douglas	
INLET TYPE/STYLE: NJ DOT Type B Inlet	
WEATHER AT TIME OF INSPECTION: 44° Sunny	
LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR	
WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)	
WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO	
WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO	
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)	
AMOUNT OF DEBRIS REMOVED FROM INLET:	
WHERE WAS DEBRIS DISPOSED OF:	
ADDITIONAL COMMENTS OR NOTES:	
LEVEL 2 INSPECTION (DETAILED INSPECTION)	
INLET TYPE/STYLE: NJ DOT Type B Inlet	
TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO	
PHOTOS OR VIDEO TAKEN: Picture taken	
GRATE INFORMATION	
TYPE OF GRATE: Bicycle Grate	
MEASUREMENT OF GRATE SIZE: 22" x 48"	
CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT	
WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO	
ADDITIONAL GRATE COMMENTS	

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" open curb
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
6" open curb NOT Eco
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42"x48"
WALL CONSTRUCTION MATERIAL TYPE: Precast concrete + Block
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS:
Inlet was repaired recently Needs Plaster coat
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): no odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

2 INV IN 15" RCP

1 INV OUT 15" RCP

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #201 Knollview Drive

LOCATION OF INLET: #201 Knollview Drive

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B Inlet

WEATHER AT TIME OF INSPECTION:

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" open curb NOT ECO
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES) 6" open curb Piece not ECO
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"
WALL CONSTRUCTION MATERIAL TYPE: Precast concrete
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: Inlet in good condition Plaster coat needed
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): no odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

2 Invert in 15" RCP

1 Invert out 18" RCP

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet in good condition

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #203 CARPENTERSVILLE ROAD + NATALIE INTERSECTION

LOCATION OF INLET: #203 CARPENTERSVILLE ROAD

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B INLET

WEATHER AT TIME OF INSPECTION: SUNNY 42°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

NJ DOT TYPE B INLET

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: PICTURE TAKEN

GRATE INFORMATION

TYPE OF GRATE: BICYCLE GRATE

MEASUREMENT OF GRATE SIZE: 22" X 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" offset curb
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES) 6" offset curb not ECO
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"
WALL CONSTRUCTION MATERIAL TYPE: Precast concrete
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: Inlet leveling Blocks need repair
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): no odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR


ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - Invert in 15" RCP

1 - Invert out 15" RCP

Good condition

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet leveling Blocks need replacement

* needs Eco curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #200 NATALIE

LOCATION OF INLET: #200 NATALIE

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B INLET

WEATHER AT TIME OF INSPECTION: SUNNY 40°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

NJ DOT TYPE B INLET

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: PICTURES TAKEN

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: 6" open Hood

HEIGHT OF CURB PIECE: 6"

CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

6" open curb NOT ECO

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Leveling Blocks need to be replaced

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): NO odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert out 15" RCP
in Good condition

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet needs leveling
Block repair

* needs Eco curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #200 Intersection of Carpentersville Rd + Natalie

LOCATION OF INLET: #200 Carpentersville Road

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Type NJDOT B Inlet

WEATHER AT TIME OF INSPECTION: Sunny 40°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

NJ DOT Type B Inlet

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

Type B Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" OREO NOT ECO
HEIGHT OF CURB PIECE 6" CURB
CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW (ACCEPTABLE) NEEDS REPLACEMENT
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES) 6" OREO HOOD CURB Piece
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"
WALL CONSTRUCTION MATERIAL TYPE: Precast concrete
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS:
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): No odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert out 15" RCP
good condition

SKETCH OF PIPE CONNECTIONS

Type B Inlet



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet recently
Reconstructed
in Good condition

* Needs ECO curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #211 NATALIE

LOCATION OF INLET: #211 NATALIE

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B INLET

WEATHER AT TIME OF INSPECTION: 40° SUNNY

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

NJ DOT TYPE B INLET

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: PICTURE TAKEN

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: 6" open curb

HEIGHT OF CURB PIECE: 6"

CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: no

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

6" open curb not ECO

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42x48

WALL CONSTRUCTION MATERIAL TYPE: Block + precast concrete

WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT) NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Inlet Box needs Reconstruction

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR


ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert in - 15" RCP

1 Invert out 15" RCP

Good condition

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet needs Reconstruction

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #216 NATALIE

LOCATION OF INLET: #216 NATALIE

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE B Inlet

WEATHER AT TIME OF INSPECTION: 40° SUNNY

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE B Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE 6" OPEN CURB PIECE
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS NO
WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES) 6" OPEN CURB NOT ECO
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42 x 48
WALL CONSTRUCTION MATERIAL TYPE: PRECAST CONCRETE
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT SHALLOW
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: INLET WAS RECENTLY RECONSTRUCTED
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): NO ODOR
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW:

CONDITION OF BENCH: NEW ACCEPTABLE NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert out
15" RCP

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet was Recently
reconstructed in good condition
* there is settlement around Inlet
* Needs ECO curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #229 Knollview

LOCATION OF INLET: #229 Knollview Drive

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT Type B Inlet

WEATHER AT TIME OF INSPECTION: 45° Sunny

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type B Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 22" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: 6" OPEN CURB NOT ECO

HEIGHT OF CURB PIECE: 6"

CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

6" OPEN HOOD NOT ECO CURB

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"

WALL CONSTRUCTION MATERIAL TYPE: PRECAST CONCRETE + BLOCK

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

PLASTER COAT RECOMENDED

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): NO ODOR

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW:


CONDITION OF BENCH: NEW ACCEPTABLE NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert In 15" RCP

1 Invert out 15" RCP

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

needs Plaster coat

* needs Eco curb Piece

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #230 Knollview Drive (Yard Box Inlet)

LOCATION OF INLET: #230 Knollview

DATE OF INSPECTION: 1-30-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT Type E Inlet

WEATHER AT TIME OF INSPECTION: 47° Sunny

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type E Inlet (Yard Inlet)

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: Bicycle Grate

MEASUREMENT OF GRATE SIZE: 44"x48 (2-22"x48")

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE NA

HEIGHT OF CURB PIECE NA

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

TYPE E Inlet no curb

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42"x48"

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: YES

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 Invert out 15" RCP

SKETCH OF PIPE CONNECTIONS



Type E Inlet In Yard

ADDITIONAL COMMENTS OR FIELD NOTES

Inlet in YARD in good condition

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #107 Belt

LOCATION OF INLET: #107 Belt

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE E INLET

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

NJ DOT TYPE E INLET

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

TYPE E INLET

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT:

PHOTOS OR VIDEO TAKEN: Photo TAKEN

GRATE INFORMATION

TYPE OF GRATE: TYPE E Bicycle Grate

MEASUREMENT OF GRATE SIZE: 46x48

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES NO

ADDITIONAL GRATE COMMENTS

NJ DOT TYPE E
INLET FRAME + GRATE

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE N/O

HEIGHT OF CURB PIECE

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS N/O

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42x48

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete & Block

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Precast Box in good condition

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): N/O odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 15" Invert out

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet Box in good condition

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: # 180 North Riverview

LOCATION OF INLET: # 180 North Riverview

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT Type E Inlet

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type E Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Photo taken

GRATE INFORMATION

TYPE OF GRATE: Type E Inlet Bicycle Grate

MEASUREMENT OF GRATE SIZE: 46 x 48

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

NJ DOT Type E
Inlet Frame + Grate

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: None

HEIGHT OF CURB PIECE:

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES):

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42"x48"

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete + Block

WALL CONDITION: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Leveling Blocks need to be replaced

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

Inlet Box needs Block repair

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 15" INV IN

1 - 18" INV OUT

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet Box Block repair needed

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: # 157 North Riverview 2 Type E Inlets

LOCATION OF INLET: # 157 North riverview Double E Inlets

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: NJ DOT TYPE E Inlets (2)

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)


WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:



2 E Inlets Tied Together

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

(2) NJ DOT Type E Inlets

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Photo Taken

GRATE INFORMATION

TYPE OF GRATE: NJ DOT Type E Inlet

MEASUREMENT OF GRATE SIZE: 46" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

(2)- Type E Inlets Together

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE None

HEIGHT OF CURB PIECE

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 96"

WALL CONSTRUCTION MATERIAL TYPE: Precast concrete + Block

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Leveling course needs minor repair

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): NO odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)


1 15" INV IN

1 18" Inch INV IN

UNKNOWN OUTFLOW Possibly "24



SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet Boxes Are in good condition - some Block leveling repairs needed

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #145 North River View Inlet marked (A)

LOCATION OF INLET: #145 North Riverview

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: TYPE E Inlet

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT TYPE E Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Yes Photo Taken

GRATE INFORMATION

TYPE OF GRATE: TYPE E Bicycle Grate

MEASUREMENT OF GRATE SIZE: 46 x 48

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

NJ DOT Type E Inlet
Frame + Grate

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE None

HEIGHT OF CURB PIECE

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Pre cast concrete

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Top Leveling Blocks need to Be replaced (Deteriorated)

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): No odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Yes


CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 18" RCP INV in

1 18" RCP INV out

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Precast Inlet Box in good condition

Block leveling layer needs to be replaced

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: # 136 Forest Intersection of Forest & North Riverview

LOCATION OF INLET: #136 Forest Inlet marked (B)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: TYPE E Inlet

WEATHER AT TIME OF INSPECTION:

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: (YES) NO

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

Area around Inlet settled
water ponds on upper side

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type E Inlet

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Photo taken

GRATE INFORMATION

TYPE OF GRATE: NJ DOT Type E Inlet

MEASUREMENT OF GRATE SIZE: 46" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

NJ DOT Type E Inlet

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE none
HEIGHT OF CURB PIECE
CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS NO
WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 42" x 48"
WALL CONSTRUCTION MATERIAL TYPE: Precast concrete
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
LADDER RUNGS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
SUMP CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: Block leveling course needs to be replaced
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): NO odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: (YES) NO
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: NEW (ACCEPTABLE) NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 18" RCP INV IN
1 18" RCP INV OUT

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Precast Inlet Box in good condition

Block leveling layer needs to be replaced

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #90 North Riverview Inlet marked (B)

LOCATION OF INLET:

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Flat grate and frame 25 x 37 NDOT conforming

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE: Type A

Flat Inlet Grate not Bicycle Stream Flow

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Yes

GRATE INFORMATION

TYPE OF GRATE: Flat Grate

MEASUREMENT OF GRATE SIZE: 25"x37"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

Inlet grate does not meet DOT standards

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE None

HEIGHT OF CURB PIECE

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 24"x32"

WALL CONSTRUCTION MATERIAL TYPE: Block

WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT) NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

ADDITIONAL STRUCTURE COMMENTS:

Inlet is caving in
there is a hole in road in
front of Inlet

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: (YES) NO

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

Block that has fallen in

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

Block and concrete
in Inlet structure

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NO

CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 15" Invert out metal pipe

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

Inlet needs reconstruction
caving in

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #45 WOODLAWN Intersection of Riverview + WOODLAWN

LOCATION OF INLET: #45 WOODLAWN Inlet marked (B)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: TYPE A INLET

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

TYPE A INLET not Bicycle GRATE

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Pictures TAKEN

GRATE INFORMATION

TYPE OF GRATE: TYPE A INLET FRAME + GRATE not Bicycle

MEASUREMENT OF GRATE SIZE: 24" x 48"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

FRAME AND GRATE GOOD CONDITION

GRATE IS NOT BICYCLE SAFETY

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: No curb Piece

HEIGHT OF CURB PIECE:

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: no

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES):

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 24" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Block

WALL CONDITION: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT Shallow

SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

First row of Block needs repair - could not see any farther Down Due to Debri in Inlet

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: (YES) NO

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

Inlet Box Almost Full to Top with debri

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

Inlet Full of Leaf Debri

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: Unknown

CONDITION OF BENCH: NEW ACCEPTABLE NEEDS REPAIR Unknown

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

Debri In Inlet
Almost to top of Grate

SKETCH OF PIPE CONNECTIONS

ADDITIONAL COMMENTS OR FIELD NOTES

Inlet need to be cleaned
To Further Finish Report

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #49 WOODLAWN Intersection of WOODLAWN + Riverview

LOCATION OF INLET: #49 WOODLAWN Inlet marked (A)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: FLAT Stream Flow 16" x 30" non conforming

WEATHER AT TIME OF INSPECTION: cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

Inlet frame and grate do not meet DOT standards

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Picture taken

GRATE INFORMATION

TYPE OF GRATE: FLAT Grate Stream Flow type

MEASUREMENT OF GRATE SIZE: 16" x 30"

CONDITION OF GRATE: NEW ACCEPTABLE (NEEDS REPLACEMENT)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

Frame and Grate do not meet NJ DOT standards

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE None
HEIGHT OF CURB PIECE
CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS No
WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 20" x 20"
WALL CONSTRUCTION MATERIAL TYPE: Block
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT SHALLOW
SUMP CONDITION: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT
ADDITIONAL STRUCTURE COMMENTS: Inlet Box Does not meet DOT Standards
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): No odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NO

CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 8" INVERT OUT
APEARS TO BE METAL

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

SMALL INLET BOX IN
DECENT CONDITION BUT
DOES NOT MEET NJDOT STANDARDS

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: #93 Riverview Inlet marked (CB)

LOCATION OF INLET: #93 Riverview

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Type A Inlet Frame + Grate

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

Newly Installed Frame + Grate on Newly constructed Inlet Box

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

NJ DOT Type A

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Pictures taken

GRATE INFORMATION

TYPE OF GRATE: Type A Bicycle

MEASUREMENT OF GRATE SIZE: 24 x 48

CONDITION OF GRATE: (NEW) ACCEPTABLE NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

New construction

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE None

HEIGHT OF CURB PIECE

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE NEEDS REPLACEMENT

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

Type A Inlet
no curb Piece

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 24" x 48"

WALL CONSTRUCTION MATERIAL TYPE: Block + Plaster coated

WALL CONDITION: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT Shallow

SUMP CONDITION: (NEW) ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

New construction

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): no odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

Inlet newly constructed

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: Yes

CONDITION OF BENCH: (NEW) ACCEPTABLE NEEDS REPAIR

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

15" Invert out

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

newly constructed Inlet

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: 93 Riverview

LOCATION OF INLET: #93 Riverview Inlet marked (A)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Flat Stream Flow type Grate Non conforming

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: (YES) NO

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Pictures taken

GRATE INFORMATION

TYPE OF GRATE: Flat Stream Flow Grate

MEASUREMENT OF GRATE SIZE: 16" x 30"

CONDITION OF GRATE: NEW ACCEPTABLE (NEEDS REPLACEMENT)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

Frame and grate do not meet
WJ DOT standards
- Grate in poor shape -

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: NO curb Piece

HEIGHT OF CURB PIECE:

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: NO

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES):

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 18"x24"

WALL CONSTRUCTION MATERIAL TYPE: Block

WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT) NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT SHALLOW

SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)

ADDITIONAL STRUCTURE COMMENTS:

Inlet caving in
needs replacement

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): NO odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NO

CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 8" INV OUT
METAL PIPE

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

INLET DOES NOT MEET
NJ DOT STANDARDS

CAVING IN - NEEDS REPLACEMENT

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: 102 Riverview Riverview + Forrest Intersection

LOCATION OF INLET: 102 Riverview Inlet marke (A)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Type D Inlet Now conforming

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": YES (NO)

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

Inlet free of debri

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE: Type D Inlet Does not meet NJDOT standards

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: NO

PHOTOS OR VIDEO TAKEN: Pictures taken

GRATE INFORMATION

TYPE OF GRATE: Stream flow type

MEASUREMENT OF GRATE SIZE: 22 x 38

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: YES (NO)

ADDITIONAL GRATE COMMENTS

Inlet frame and Grate do not meet DOT standards

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE Open curb
HEIGHT OF CURB PIECE 6"
CONDITION OF CURB PIECE: NEW (ACCEPTABLE) NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS NO
WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 30" x 36"
WALL CONSTRUCTION MATERIAL TYPE: Block
WALL CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
CONDITION OF JOINTS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT) NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
ADDITIONAL STRUCTURE COMMENTS: Inlet is caving in and deteriorated - Recoaned A new B Inlet Be installed
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): NO odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE) Resident said that debri covers Inlet quickly during a storm and overflows onto her property Requests a Larger Inlet

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE

IS THERE A BENCH FOR DIRECTING FLOW: NO


CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

2 Inverts In 8"
1 - Clay
1 - Metal Pipe

1 - Invert Out
15" Metal Pipe

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

* Inlet need reconstruction

Install new B Inlet Box + Frame + Grate

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: # 140 Forest Ave Forest + Riverview Intersection

LOCATION OF INLET: #140 Forest Inlet marked (B)

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Douglas

INLET TYPE/STYLE: Flat Stream Flow no curb non conforming

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

Flat Stream Flow Type
Does not meet DOT Standards

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: no

PHOTOS OR VIDEO TAKEN: Pictures taken

GRATE INFORMATION

TYPE OF GRATE: Flat grate - Stream Flow

MEASUREMENT OF GRATE SIZE: 28"x38"

CONDITION OF GRATE: NEW ACCEPTABLE NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

Inlet Frame + Grate Do
not meet NJ DOT Standards

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)
CURB PIECE INFORMATION
TYPE OF CURB PIECE No curb Piece
HEIGHT OF CURB PIECE
CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT
CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE
LABEL FOR DRAINS TO WATERWAYS Yes
WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)
ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)
INTERIOR STRUCTURE INFORMATION
STRUCTURE INTERIOR MEASUREMENTS: 24 x 34
WALL CONSTRUCTION MATERIAL TYPE: Block
WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS
CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT
LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT Shallow
SUMP CONDITION: NEW ACCEPTABLE NEEDS REPAIR (NEEDS REPLACEMENT)
ADDITIONAL STRUCTURE COMMENTS:
INTERIOR DEBRIS & FLOWS
DEBRIS PRESENT IN STRUCTURE: YES (NO)
AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)
HOW WAS DEBRIS REMOVED:
WHERE WAS DEBRIS DISPOSED OF:
FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL
ODOR DETECTED (DESCRIBE ODOR): No odor
WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)
ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NO

CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

1 - 8" INV OUT
SDR 35 PIPE

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

curb behind Inlet
is leaning over At A
45° Angle - needs replacement

Inlet Does not meet DOT
STANDARDS

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

INLET INSPECTION

GENERAL NOTES

INLET ID: House # 202

LOCATION OF INLET: Riverview ROAD

DATE OF INSPECTION: 1-20-23

INSPECTED BY: Steve Dargis

INLET TYPE/STYLE: Type A Does not meet DOT Specs 28" x 38" grate

WEATHER AT TIME OF INSPECTION: Cloudy 45°

LEVEL 1 INLET INSPECTION - ROADSIDE INSPECTION NON-INTERIOR

WAS DEBRIS BLOCKING GRATE OR CURB PIECE: YES (NO)

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

WAS THE INLET LABELED WITH "NO DUMPING DRAINS TO WATERWAY": (YES) NO

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET:

WHERE WAS DEBRIS DISPOSED OF:

ADDITIONAL COMMENTS OR NOTES:

LEVEL 2 INSPECTION (DETAILED INSPECTION)

INLET TYPE/STYLE:

Flat Inlet grate

TOWN STRUCTURE NUMBER TAG/PLATE PRESENT: None

PHOTOS OR VIDEO TAKEN: Photo Taken

GRATE INFORMATION

TYPE OF GRATE: Flat Grate Stream Flow Type

MEASUREMENT OF GRATE SIZE: 28"x38"

CONDITION OF GRATE: NEW (ACCEPTABLE) NEEDS REPLACEMENT

WAS THERE ANY SIGNS OF SETTLEMENT OR DEPRESSIONS AROUND INLET: (YES) NO

ADDITIONAL GRATE COMMENTS

Inlet Frame and grate
Do not meet NJDOT Standards

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

CURB PIECE INFORMATION

TYPE OF CURB PIECE: NO curb Piece

HEIGHT OF CURB PIECE:

CONDITION OF CURB PIECE: NEW ACCEPTABLE NEEDS REPLACEMENT

CURB PIECE ECO HEAD TYPE: BAR PLATE FULL ECO CURB PIECE

LABEL FOR DRAINS TO WATERWAYS: ON concrete curb

WATERWAYS LABEL CONDITION: NEW ACCEPTABLE (NEEDS REPLACEMENT)

ADDITIONAL CURB PIECE COMMENTS (DESCRIBE DAMAGE, ISSUES)

Flat grate NO curb Piece

INTERIOR STRUCTURE INFORMATION

STRUCTURE INTERIOR MEASUREMENTS: 24" x 28"

WALL CONSTRUCTION MATERIAL TYPE: Block

WALL CONDITION: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

CONDITION OF JOINTS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT NO JOINTS

CONDITION OF LEVELING BLOCKS: NEW (ACCEPTABLE) NEEDS REPAIR NEEDS REPLACEMENT

LADDER RUNGS: NEW ACCEPTABLE NEEDS REPAIR NEEDS REPLACEMENT SHALLOW NO STEPS

SUMP CONDITION: NEW ACCEPTABLE (NEEDS REPAIR) NEEDS REPLACEMENT

ADDITIONAL STRUCTURE COMMENTS:

Inlet needs flow channel

INTERIOR DEBRIS & FLOWS

DEBRIS PRESENT IN STRUCTURE: YES (NO)

AMOUNT OF DEBRIS REMOVED FROM INLET: DEPTH OF DEBRIS IN STRUCTURE OR CY (ESTIMATED)

HOW WAS DEBRIS REMOVED:

WHERE WAS DEBRIS DISPOSED OF:

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

ODOR DETECTED (DESCRIBE ODOR): NO odor

WAS THERE PONDING OR WATER BUILD UP AT INLET: YES (NO)

ADDITIONAL COMMENTS: (DESCRIBE TYPE OF DEBRIS - LEAFS, HOUSEHOLD TRASH, SANITARY WASTE)

CONTINUE - LEVEL 2 INSPECTION (INTERIOR DETAILED INSPECTION)

PIPE CONNECTIONS TO STRUCTURE


IS THERE A BENCH FOR DIRECTING FLOW: NO

CONDITION OF BENCH: NEW ACCEPTABLE (NEEDS REPAIR)

ADDITIONAL INFORMATION FOR INVERTS: (NUMBER OF INVERTS, SIZE OF PIPE, TYPE OF PIPE, DEPTH OF INVERT, CONDITION OF PIPE CONNECTION, PIPES CUT SMOOTH TO STRUCTURE WALL OR STICKING OUT)

ONE INVERT OUT CLAY PIPE

SKETCH OF PIPE CONNECTIONS



ADDITIONAL COMMENTS OR FIELD NOTES

INLET APPEARS TO SET LOW - BASICALLY SITS IN ALCOVE SPOT BUT COULD BE RAISED 3"

OFFICE TRACKING
DATE INSPECTION REVIEWED:
INSPECTION REPORT REVIEWED BY:
REPORT COPY FILED IN LOG BOOK:
REPAIR WORK REQUIRED:
REPAIR WORK LISTED IN REPAIR " TO DO LIST":
LOCATION PHOTOS OR VIDEO STORED/SAVED:
WAS PRIOR INSPECTION REPORT FOR STRUCTURE REVIEWED:
ADDITIONAL INFORMATION

- CENTRAL NJ OFFICE • 32 Brower Lane • Hillsborough, NJ 08844 • (908) 359-8291
- WESTERN NJ OFFICE • 1128 Route 31 • Lebanon, NJ 08833 • (908) 735-9500
- SOUTHCENTRAL NJ OFFICE • 4 AAA Drive, Suite 103 • Hamilton, NJ 08691 • (609) 689-1100
- DOYLESTOWN PA OFFICE • 501 North Main Street • Doylestown, PA 18901 • (215) 345-1876
- LEHIGH VALLEY PA OFFICE • 520 North New Street, 2nd Floor • Bethlehem, PA 18018 • (610) 332-1772
- BERKS COUNTY PA OFFICE • 4 Wellington Boulevard • Wyomissing, PA 19610 • (610) 670-6630
- NORTHERN DE OFFICE • 630 Churchmans Road, Suite 105 • Newark, DE 19702 • (302) 368-3184
- TOMS RIVER NJ OFFICE • 1705 Highway 37 • Toms River, NJ 08753 • (732) 573-0490
- FREEHOLD NJ OFFICE • 20 Gibson Place, Suite 100 • Freehold, NJ 07728 • (732) 303-8700
- ☒ PHILLIPSBURG NJ OFFICE • 755 Memorial Parkway, Suite 100, 2nd Floor • Phillipsburg, NJ 08865 • (908) 454-3080

Van Cleef Cherry, Weber & Associates

DAILY REPORT

Name John Gerbino 9AM-12PM-3Hrs

Position RE / Inspector

Job No. P9101053 Date 9-3-24

Owner ETOWN Location PBURG

Contractor /

DAILY PROGRESS DESCRIPTION AND REMARKS

checking Inlets For NON Compliance of DEP "NO Dumping to Waterways or circle symbol on Curb Pieces
checking inside inlets For conditions & Depths of Inlets

NOTE: Use back for required sketches

SOIL AND WATER CONDITIONS OF TRENCH

WEATHER:

VISITORS: PBURG PD TRAFFIC

EQUIPMENT WORKING	No.	HOURS Used	Down	TOTAL HOURS	REMARKS
/					

LAMP RECORD

Station	Remarks

COMPACTION TESTS

Station	Remarks

CONTRACTOR'S PERSONNEL ON JOB

Position	No.	Name	Remarks
Super			
Engr.			
Foreman			
Blasters			
Oper.			
Pipe Lay.			
Elect.			
Steel Workers			
Masons			
Trucks Dr.			
Laborers			

- ☐ CENTRAL NJ OFFICE • 32 Brower Lane • Hillsborough, NJ 08844 • (908) 359-8291
- ☐ WESTERN NJ OFFICE • 1128 Route 31 • Lebanon, NJ 08833 • (908) 735-9500
- ☐ SOUTHCENTRAL NJ OFFICE • 4 AAA Drive, Suite 103 • Hamilton, NJ 08691 • (609) 689-1100
- ☐ DOYLESTOWN PA OFFICE • 501 North Main Street • Doylestown, PA 18901 • (215) 345-1876
- ☐ LEHIGH VALLEY PA OFFICE • 520 North New Street, 2nd Floor • Bethlehem, PA 18018 • (610) 332-1772
- ☐ BERKS COUNTY PA OFFICE • 4 Wellington Boulevard • Wyomissing, PA 19610 • (610) 670-6630
- ☐ NORTHERN DE OFFICE • 630 Churchmans Road, Suite 105 • Newark, DE 19702 • (302) 368-3184
- ☐ TOMS RIVER NJ OFFICE • 1705 Highway 37 • Toms River, NJ 08753 • (732) 573-0490
- ☐ FREEHOLD NJ OFFICE • 20 Gibson Place, Suite 100 • Freehold, NJ 07728 • (732) 303-8700
- ☒ PHILLIPSBURG NJ OFFICE • 755 Memorial Parkway, Suite 100, 2nd Floor • Phillipsburg, NJ 08865 • (908) 454-3080

Van Cleef Cherry, Weber & Associates

DAILY REPORT

Name John Gerbino

Position RE / Inspector

Job No. 9100 Date 9-3-24

Owner _____ Location PBURG

Contractor / 1230-3:00 PM - 2.5 Hrs

DAILY PROGRESS DESCRIPTION AND REMARKS

checking inlets for curb heads + or
Labeling various Runs and
depths of inlets

NOTE: Use back for required sketches

SOIL AND WATER CONDITIONS OF TRENCH

WEATHER: 70's clear

VISITORS: PBURG PD TRAFFIC

EQUIPMENT WORKING	No.	HOURS Used	Down	TOTAL HOURS	REMARKS

LAMP RECORD

Station	Remarks


COMPACTION TESTS

Station	Remarks

CONTRACTOR'S PERSONNEL ON JOB

Position	No.	Name	Remarks
Super			
Engr.			
Foreman			
Blasters			
Oper.			
Pipe Lay.			
Elect.			
Steel Workers			
Masons			
Trucks Dr.			
Laborers			

Projects (continued)



Printed in China

Bultman

No Label
Needs New
Head
closed

Hudson ST

2'.8"

No Label
B
Needs New
curb piece

OLD
No Label
Needs
New
Head
needs new
gate
closed

needs new
closed
Summit Apt

No Label

Hudson
ST

Needs
Head
No
Label
closed

Old
Apt
needs new
head
Label
close

295
OLD
Label OK

Chamberlain St

Heckman

closed
Needs
Head old
Label

315
old
Needs
head
Label

293

Allen

closed Needs
Head
Label

2'1" OLD
Needs
head
269

2'0
Needs
Head

Needs
Head
Label

2'10 — new head

Chamberlain

Old Auburn
ST


2'6
34
Need new head
OLD
Label

Label old
Need closed
Head

Washington

No
Label
Head
closed

2'1 — New Label


STOCKTON
Needs hand rail old 2'9"
CHARTER ST
Needs everything old 2'd
WASHINGTON ST
closed
needs everything old
TYNDALL ST
needs everything
2'11"
old 2'8"
needs everything
BULLMAN ST

09-16 9:30a~

Structure #	Stamped?	Eco head?	Bike safe	Debris inside	Type
SW-1306	yes	yes	yes	yes	B-Standard
SW-475	yes	yes	yes	yes	B-Standard
SW-474	~~yes~~ No	No	yes	yes	B
SW-909	NO	No	No	yes	B
SW-908	No	No	No	yes	B
SW-910A	No	No	No	yes	B
SW-911	No	No	No	yes	A
SW-912	Faded sticker	No	No	yes	B
SW-914	Faded sticker	No	yes	yes	B
SW-915	No	No	No	yes	B
SW-917	No	No	No	yes	B
SW-918	No	No	No	yes	B
SW-478	NO	NO	yes	yes	B
SW 479	No	No	yes	yes	B
SW 480	Faded sticker	No	yes	yes	A
SW-477	No	No	yes	yes	A
SW 482	NO	No	yes	yes	A
SW 481	No	No	yes	No	A
SW 483	NO	No	yes	yes	A
SW 443	No	No	yes	yes	A
SW 441	No	No	yes	yes	A
SW 492	NO	No	yes	No	A
SW 985	yes	3 holes broken	yes	yes	B-was stamped
SW 987	yes	yes	yes	yes	B-Stan.
SW 986	yes	yes	yes	yes	B-stan

#	stamp	ECO	Bike	Debris	Type
SW 984	yes	no	yes	yes	Type E stan
SW 983	yes	yes	yes	yes	B-stan
SW 466	yes	no	yes	yes	A-stan
SW 465	yes	no	yes	yes	A stan
SW 463	yes	no	yes	yes	A stan
SW 464	yes	no	yes	yes	A stan
SW 462	yes	no	yes	yes	A stan
SW 454	yes	no	yes	yes	A stan
SW 457	yes	no	yes	yes	A stan
SW 453	yes	no	yes	yes	A stan.
SW 451	yes	no	yes	yes	A stan
SW 442	yes	no	yes	yes	A stan
SW 444	yes	no	yes	yes	A stan
SW 443	yes	no	yes	yes	A stan
SW 441	yes	no	yes	yes	A stan
SW 440	yes	no	yes	yes	A stan
SW 555A	Faded stk	no	yes	yes	B
SW 556A	FS	no	yes	yes	B
SW 554B	FS	no	yes	yes	B
SW 555B	FS	no	yes	yes	B
SW 555C	FS	no	yes	yes	B
SW 555	FS	no	yes	yes	B
SW 556	FS	no	yes	yes	B
SW 557 or 8	FS	no	yes	yes	B
New 1	yes	no	no	yes	B

#	stamp	eco	bike	debris	TYPE
SW 552	FS	No	yes	yes	A
SW 550	NO	NO	yes	yes	A
SW 549	NO	NO	yes	yes	A
SW 548	FS	NO	yes	yes	A
SW 551	FS	NO	yes	yes	A
SW 545	yes	NO	yes	No	A
SW 543	yes	NO	yes	yes	A
SW 544? Mill x Rocket	FS	NO	NO	yes	B
SW-78	FS	NO	NO	yes	B
SW-73D	FS	NO	NO	yes	B
SW 83	yes	NO	yes	yes	A
SW 84	yes	NO	yes	yes	A
SW 85	yes	yes	yes	yes	Stamp B

was able to make out 2 of these (SW 78 & SW 73D) there's another inlet right next to 73D on Center St... Hard to tell if it's one of the ones marked

SW544?

there was an inlet here that wasn't marked but it could be on another sheet

New?

MORGEN

CONGRESS

MAGNETIC

		DATE:	AUGUST 15, 2022
		SCALE:	1"=100'
		DESIGNED BY:	TMO
		DRAWN BY:	MC/JB/JDR
REV 1 - MAP UPDATES AND CORRECTIONS	TMO	CHECKED BY:	TMO
REVISIONS	AUTH. DATE	JOB NO.	9110.001

Van Cleef ENGINEERING WITH FOCUS

VAN CLEEF ENGINEERING ASSOCIATES, LLC
751 MINEBROOK ROAD, SUITE 1-6, PHILLIPSBURG, NJ 08865
WEB: WWW.VANCLEFENGINEERING.COM
PHONE (908) 454-0880
CERT. OF AUTHORIZATION NO. 24GA27837500


Bridges/Highways
Construction Inspection
Environmental
Geotechnical/Dams
Landscape Architecture
Local/Regional Planning
Municipal Engineering
Site Development
Surveying/Aerial Drones/GIS
Water/Wastewater

SANITARY AND STORMWATER REPAIRS
FIELD MAP 12

TOWN OF PHILLIPSBURG
WARREN COUNTY, NEW JERSEY

13
16





REVISIONS	AUTH.	DATE
REV 1 – MAP UPDATES AND CORRECTIONS	TMO	03/22/2024

DATE: AUGUST 15, 2022
SCALE: 1"=100'
DESIGNED BY: TMO
DRAWN BY: MC/JB/JDR
CHECKED BY: TMO
JOB NO. 0110.031

Van Cleef ENGINEERING WITH FOCUS
VAN CLEEF ENGINEERING ASSOCIATES, LLC
Bridges/Highways
Construction Inspection
Environmental
Geotechnical/Dams
Landscape Architecture
Local/Regional Planning
Municipal Engineering
Site Development
Surveying/Aerial Drones/GIS
Water/Wastewater

SANITARY AND STORMWATER FIELD MAP 13

TOWN OF PHILLIPSBURG
WARREN COUNTY, NEW JERSEY

14
16

#	DRAINS TO RIVER	ECO. HEAD	BIKE SAFE	DEBRIS/ CLOGGED YES/NO	TYPE	STANDARD
173	NO	NO	NO	~~DEBRIS~~ YES	B	NO
172	NO	NO	NO	YES	B	NO
171	NO	NO	NO	YES	B	NO
174	DON'T EXIST	1 SECTION OF BATES + MARSHALL				
175						
1488	NO	N/A	YES	YES	A	NO
1487	NO	N/A	YES	YES	A	NO
1486	NO	N/A	YES	YES	A	NO
1650	NO	NO	YES	YES	B	NO
1490	YES	N/A	YES	YES	A	YES
1489	NO	N/A	YES	YES	A	NO
Me D's LOT 1339	NO	YES	YES	YES	B	NO
Wcee LOT 1625	NO	N/A	YES	NO	A	NO
367	MAN HOLE? (MARSHALL ST.)					
1338	NO	NO	NO	YES	B	NO
1337	NO	NO	NO	YES	B	NO
1336	NO	NO	NO	YES	B	NO
1626	NO	NO	NO	YES	B	NO
1335	NO	NO	NO	YES	B	NO
1334	NO	NO	NO	YES	B	NO
977	NO	NO	NO	YES	B	NO
978	NO	NO	NO	YES	B	NO
* NOT SHOWN ON MAP	NO	NO	NO	YES	B	NO
1169	MANHOLE					
1168	NO	NO	NO	YES - YES	B	NO
1167	YES	NO	NO	NO ~~YES~~	B	NO
1167 A	YES	NO	NO	YES	B	NO
j	NO	N/A	YES	YES	A	

#

		DRAINS TO RIVER?	ECO-HEADS?	BIKE SAFE?	DEBRIS?	TYPE?	STANDARDS?
GRASS	ARBY 1	NO	N/A	YES	FULL	A	NO
	" 2	NO	N/A		FULL	A	NO
	" 3	NO	N/A		FULL	A	NO
PARKING LOT	" 4	YES	YES		YES	B	YES
	" 5	YES	YES		YES	B	YES
	1166A	NO	N/A	YES	YES	~~B~~ A	NO
	1166	YES	N/A	YES	YES	E	YES
	1165	YES	N/A	YES	YES	E	YES
	1166 B		YES	YES	YES	B	
	1166 C		YES			B	
	1166 D		YES			B	
	1166 E		N/A			E	

* 1166A → ~~F~~ ARE IN CVS PARKING LOT

	1166 F	YES	YES	YES	YES	B	YES
	POPEYE'S 1	NO	N/A	YES	?	11 ADJ. SEGMENTS ACROSS D. WAY	
	POPEYE'S 2	NO	N/A	YES	YES	A	
MON. PKWY	1161	YES	YES	YES	YES	B	YES
	1162						
	1163						
	1164						
MON. PKWY QUADRANTS	Q1	YES	YES	YES	YES	B	YES
	Q-2						
	Q-3						
	Q-4						
	ARBY GRASS 6	NO	N/A	YES	FULL	A	NO


ARBYS IN GRASS STILL HAVE FILTER FABRIC AND/OR ARE FULL

#		Drains to River?	Eco Head?	Bike Safe?	Debris?	Type	Standards
Mon. Pkwy Across From McD's	M-1	Yes	Yes	Yes	~~No~~ Yes	B	Yes
	M-2	↓	↓	↓	↓	↓	↓
	M-3	↓	↓	↓	↓	↓	↓
	1252	Could Not Locate			—	—	—
	1253	Yes	Yes, But Broken	Yes	Yes	B	Yes
	1254	Yes	Yes, But Broken	Yes	Yes	B	Yes
Wawa Parking Lot	W-1	Yes	Yes	Yes	Yes	B	Yes
	W-2	↓	↓	↓	↓	↓	↓
	W-3	↓	↓	↓	↓	↓	↓
	W-4	↓	↓	↓	↓	↓	↓
	1184	Manhole?					
Medium Pkg Lot	1187A	No	No	Yes	Yes	B	No
Marshall x Lincoln	176	No	No	Yes	Yes	~~A~~B	No
	177	No	↓	↓	↓	B	↓
	178	No	↓	↓	↓	B	↓
	329	Manhole					
Marshall x Grant	179	No	No	Yes	Yes	B	No
	180	Yes	↓	↓	↓	↓	↓
	181	No	↓	↓	↓	↓	↓
	330	M. Hole					
	182	Yes	Yes	Yes	Yes	B	Yes
	183	No	No	No	Yes	B	No
	331	M. Hole					
	184	No	No	Yes	Yes	B	No
	186 ~~185~~	Yes	Yes	Yes	Yes	B	Yes
	185 ~~186~~	No	No	N/A	Yes		No

↳ Open at Curb w/ Metal Plate @ Sidewalk

#	DRAINS TO RIVER	ECO-ROAD	BIKE SAFE	DEBRIS	TYPE	STANDARD
147	NO	NO	YES	YES	B	NO
148	YES	NO	YES	YES	B	NO
1610	NO	NO	YES	YES	B	NO
149	YES	N/A	YES	YES	A	YES
1260	NO	NO	YES	YES	B	NO
1261	NO	NO	YES	YES	B	NO
1262	COULD	NOT	LOCATE			
1627	NO	N/A	YES	YES	E	NO
1627A	↓	N/A	↓	↓	E	↓
1627B		N/A			E	
1627C		NO			B	

480 Mon. Pkwy Parking Lot



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December , 1995

REVISED: October 2006

STREET INDEX

ABBOTT ST. H-27
ACE LA. N-22
ALLAN ST. N-22
ANDERSON ST. K-16
ANDOVER ST. L-12
ANDREWS AL. H-12
ANN ST. L-27
ARLINGTON AVE. O-27
BACH ST. O-5
BANK ST. F-7
BARRYMORE ST. F-7
BARTLETT ST. H-12
BATES ST. L-27
BEERS AL. N-11
BELT RD. N-11
BELVIDERE RD. M-9
BENNETT ST. O-9
BEST AVE. I-31
BEXER AL. N-27
BOWERS AVE. O-8
BOWMAY AVE. O-14
BRAINARD ST. O-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-8
BURWELL AL. O-9
CAHILL ST. N-28
CAMHART AL. I-28
CARPENTERSVILLE RD. I-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. B-11
CHERRY LANE O-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHRISTMAS AL. O-6
CHRISTIE AL. N-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. N-13
COLUMBUS AVE. N-22
COMPRESSION ST. N-12
COMSTOCK AL. H-12
CONGRESS ST. I-28
CORLISS AVE. N-11
CROSS ST. O-18
CULKIN ST. O-23
DAVIS ST. O-14
DEAN AL. F-11
DELAWARE RD. K-3
DIMMICK AL. K-13
DRILL ST. O-11
DUGAN AL. O-11
EILEEN AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. O-11
ELM ST. F-18
ELMHURST DR. F-30
EMIRE ST. F-30
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. N-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. F-7
FAIRS ST. F-27
FERGUSON ST. F-6
FILMORE ST. O-11
FIRST ST. F-7
FISHER ST. F-18
FISHS AVE. O-32
FLINT BRIDGE F-7
FOHILTZ LA. I-30
FOURTH ST. F-6
FOX AL. E-18
FOX ST. F-17
FRACE ST. O-10
FRANCIS AVE. O-10
FRANKLIN ST. O-10
FREDERICK ST. O-10
FRONT ST. F-6
FROST AVE. O-8
FULTON ST. F-6
GATE ST. F-18
GLEN AVE. O-10
GRACE AVE. O-10
GRAND ST. F-18
GRANT ST. O-11
GREEN AL. O-27
GREEN ST. F-7
GREENWOOD ST. O-27
GRIFFITH AL. O-32
HAGERTY AVE. O-11
HAGERTY BLVD. O-11
HAMZENEL ST. O-11
HARRIS ST. O-11
HART ST. O-11
HECKMAN ST. O-11
HENDERSON ST. O-11
HENSHAW ST. O-11
HILL ST. O-11
HILLCREST BLVD. O-11
HUDSON AL. O-11
HOWARD ST. O-11
HUGHSON ST. O-11
HUNTSON AVE. O-11
IVY ST. O-11
JAMES BAKER WAY O-11
JEFFERSON ST. O-11
JERSEY ST. O-11
JOHN ST. O-11
JOHN MITCHELL AVE. O-11
JOSEPH ST. O-11
JUDD AL. O-11
KAITLYN CT. O-11
KENT ST. O-11
KNEEDLER AVE. O-11
KNOLL VIEW DRIVE O-11
KORP AL. O-11
KURLAND AL. O-11
LAKE AL. O-11
LEHMON AL. O-11
LESHER AL. O-11
LEWIS ST. O-11
LIMEKILN RD. O-11
LINCOLN RD. O-11
LINCOLN ST. O-11
LINER BLVD. O-11
LOCK ST. O-11
LOGAN ST. O-11
LYNDALE ST. O-11
LYNN RD. O-11
MADISON ST. O-11
MARKET ST. O-11
MARSHALL ST. O-11
MARY ST. O-11
MARKEN ST. O-11
MELROSE ST. O-11
MEMORIAL PKWY. O-11
MERCER ST. O-11
METZ ST. O-11
MEYNER RD. O-11
MILL ST. O-11
MILLER ST. O-11
MITCHELL AL. O-11
MORRIS ST. O-11
MOULE AL. O-11
NATALIE DRIVE O-11
NELSON ST. O-11
NORTH AL. O-11
NO. MAIN ST. O-11
NO. RIVERVIEW RD. O-11
OAK AL. O-11
ORCHARD AL. O-11
PARK RD. O-11
PEACH ST. O-11
PEAR AL. O-11
PEARL ST. O-11
PERDOE AVE. O-11
PICKFORD AVE. O-11
PINE AL. O-11
PLEASANT AVE. O-11
POTTS AVE. O-11
PROSPECT ST. O-11
PURSEL ST. O-11
RAILROAD AVE. O-11
RANDALL ST. O-11
RAYMOND ST. O-11
REESE WAY O-11
REESE CT. O-11
RICHARD RD. O-11
RICHMOND ST. O-11
RIDGE ST. O-11
RIVER ST. O-11
RIVERSIDE WAY O-11
RIVERVIEW CIR. O-11
RIVERVIEW RD. O-11
ROCK AL. O-11
ROSE ST. O-11
ROSEBERRY ST. O-11
SARGENT AVE. O-11
SAWMILL ST. O-11
SAYRE AVE. O-11
SCHULTZ AVE. O-11
SHAFFER AVE. O-11
SHERWOOD ST. O-11
SHILLINGER AL. O-11
SHIMER ST. O-11
SILK AVE. O-11
STIGREAVES ST. O-11
SMITH AVE. O-11
SONORA ST. O-11
SO. MAIN ST. O-11
SPINNER AL. O-11
SPRUCE AL. O-11
ST. JOHN AL. O-11
STANLEY ST. O-11
STEELE ST. O-11
STEWART AL. O-11
STOCKTON ST. O-11
STRYKER ST. O-11
STULL AL. O-11
SUMMIT AVE. O-11
SUSAN ST. O-11
TAYLOR AL. O-11
TERRY ST. O-11
THIRD ST. O-11
THOMAS ST. O-11
TIGHE AL. O-11
TRUE AL. O-11
TUTTLE ST. O-11
TYNDALL AVE. O-11
UNION SQ. O-11
VALLEY VIEW DR. O-11
WALNUT ST. O-11
WARREN ST. O-11
WASHINGTON ST. O-11
WATSON PL. O-11
WEBSTER ST. O-11
WILBUR AVE. O-11
WILLEVIEW ST. O-11
WILLIAM ST. O-11

Corey Conners
Darryl Mullin
9/10/18

Broken crate

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

0 500 1000

GRAPHIC SCALE OF FEET

F-ZONE

Tom Courter
Brian Summit
9/10/18

411/413 warren st
419 warren st

Filmore and Pear alley
315 chambers st
224 stockton st both
3 stockton and bales (storage systems USA)
Stockton st (edsion field)
Linclon st (infront of JCPL)
450 warren st (across the street)
400 wilson st
88 heckman st
on stockton behind 110 heckman st
250 heckman and Outback on stockton
276 heckman st
301 heckman st
325 firth st and across the street
284 chambers St
291 chambers st
348 chambers st
331 chambers st
156 Lewis st
Warren st (infront of elementy school

DELAWARE KNOLLS ALL

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

9-10-18

Kevin + Chad

SCALE: 1" = 500'

DATE: December 1, 1995

F-ZONE

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

Tom Conaer
Brian summit
9/10/18

SCALE: 1" = 500'

GRAPHIC SCALE OF FEET

DATE: December 1, 1991

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

I-78

F-ZONE

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

Mike Stires 9-10-18
Mike Anthony

F-ZONE

353 Hudson St

85 Lewis
59 BRAINARD (Hudson St SIDE)
BRAINARD + TYNDALL
3 ELIZABETH
? HUDSON
HUDSON JUST PASS BRAINARD GOING- UP HILL
HUDSON + CHAMBER
FRANCIS TMILLER
HARRIS + BULLMAN

Brian S. Hoban & Don Vaughan 1-27-22

1-27-22
SUTTON
VAUGHN

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED: October 2006

Summitt / Duckworth 1/26/22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Summitt / Duckworth 1/26/22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Tom C 3-3-22

Tom C 3-3-22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. O-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-16
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTEWINK AL. G-6
CHRISTIE AL. K-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE. D-13
COMPRESSOR ST. O-25
CONSTOCK AL. D-14
CONGRESS ST. H-14
CORLISS AVE. F-11
CROSS ST. K-5
CULKIN ST. K-13
DAVIS ST. N-11
DEAN AL. E-11
DELAWARE RD. D-11
DIMMICK AL. N-11
DRILL ST. 6-11
DUGAN AL. E-14
ELDEN AVE. E-15
ELIZABETH ST. I-8
ELLEN ST. F-11
ELM ST. I-4
ELMHURST DR. H-27
EMMA ST. K-13
ENGINE ST. K-16
ESSEX ST. E-7
EVELYN AVE. I-30
FAIRBANKS ST. H-10
FAIRVIEW AVE. E-8
FARM ST. I-7
FERGUSON ST. P-27
FILMORE ST. I-8
FIFTH ST. P-11
FIRST AL. I-4
FIRTH ST. K-27
FISHER AVE. K-13
FOGHT BRIDGE E-16
FORREST LA. E-7
FOURTH ST. I-30
FOX AL. E-8
FRACE ST. P-17
FRANCIS AVE. P-10
FRANKLIN ST. H-10
FREDERICK ST. H-10
FRONT ST. C-10
FROST AVE. P-9
FULTON ST. P-14
GATE ST. R-27
GLEN AVE. P-11
GRACE AVE. N-10
GRAND ST. N-29
GRANT ST. L-13
GREEN AL. L-11
GREEN ST. P-22
GREENWOOD ST. G-29
GRIFFITH AL. G-29
HAGERTY AVE. N-7
HANOVER ST. D-13
HARRIS ST. D-9
HARTE ST. D-9
HECKMAN ST. I-15
HEMLOCK ST. G-32
HENDERSON ST. I-11
HENSHAW CT. G-11
HILL ST. K-25
HILLCREST BLVD. N-9
HILLSIDE RD. D-27
HOWARD ST. B-16
HUDSON ST. B-12
INGERSOLL AVE. D-11
IRWIN ST. D-12
IVY, ST. C-15
J. BAKER WAY C-16
JAMES ST. M-23
JEFFERSON ST. D-19
JERSEY ST. C-16
JOHN ST. D-16
JOHN MITCHELL AVE. N-9
JOSEPH ST. N-9
JUDD AL. N-5
KAITLYN CT. P-27
KENT ST. H-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE I-25
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. B-12
LENNON AL. I-24
LESHER AL. I-24
LEWIS ST. I-24
LINCOLN RD. N-13
LINCOLN ST. K-8
LINER BLVD. O-32
LOCK ST. O-32
LOGAN ST. O-30
LYNDALE ST. M-31
LYNN RD. K-19
MADISON ST. K-30
MARKET ST. B-12
MARSHALL ST. I-14
MARY ST. J-14
McKEEN ST. P-21
MELROSE ST. D-31
MEMORIAL PKWY. P-13
MERCER ST. E-18
METZ ST. G-10
MEYNER RD. I-19
MILL ST. M-25
MILLER ST. J-11
MITCHELL AL. D-10
MORRIS ST. B-8
MOULE AL. N-21
NATALIE DRIVE N-32, K-
NELSON ST. N-30
NORTH AL. N-14
NO. MAIN ST. C-8
NO. RIVERVIEW RD. C-28
OAK AL. H-13
ORCHARD AL. G-9
PARK RD. G-24
PEACH ST. L-22
PEAR AL. L-22
PEARL ST. P-11
PERODE AVE. L-25
PROFFORD AVE. P-11
PINE AL. P-18
PLEASANT AVE. B-10
POTTS AVE. J-11
PROSPECT ST. L-10
PURSEL ST. L-24
RAILROAD AVE. L-14
RANDALL ST. C-10
RAYMOND ST. G-9
REESE WAY B-11
REESE CT. B-14
RICHARD RD. K-21
RICHMOND ST. P-29
RIDGE ST. P-29
RIVER ST. O-16
RIVERSIDE WAY C-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. M-13
ROSE ST. G-8
ROSEBERRY ST. B-9
SARGENT AVE. D-11
SAWMILL ST. G-27
SAYRE AVE. P-25
SCHULTZ AVE. K-23
SHAFER AVE. N-11
SHERWOOD ST. G-8
SHILLINGER AL. G-30
SHIMER ST. J-14
SILK AVE. Y-11
SITGREAVES ST. Y-15
SMITH AVE. Y-17
SONORA ST. C-20
SO. MAIN ST. C-27
SPINNER AL. B-9
SPRUCE AL. P-11
ST. JOHN AL. P-16
STANLEY ST. K-14
STEELE ST. P-29
STEWART AL. L-29
STOCKTON ST. N-25
STRYKER ST. K-16
STULL AL. K-12
SUMMIT AVE. B-8
SUSAN ST. D-10
TAYLOR AL. O-10
TERRY ST. O-11
THIRD ST. H-12
THOMAS ST. P-23
TICHE AL. D-13
TITUS AL. H-12
TUTTLE ST. P-23
TYNDALL AVE. B-11
UNION SQ. B-9
VALLEY VIEW CIR. P-28
VALLEY ST. P-28
WARREN ST. P-30
WASHINGTON ST. K-18
WATSON PL. P-16
WEBSTER ST. L-23
WILBUR AVE. L-22
WILLEVER ST. D-10
WILLIAM ST. N-24
WILSON ST. B-24
WISE AL. P-22, K-
WOODLAWN RD. I-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Corey Connors 4-1-2022 Dan Vaughn

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

WALNUT STREET

GREEN STREET

COLUMBUS AVENUE

PROSPECT STREET

LINCOLN STREET

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

CAHILL ST.

SAYRE AVENUE

WILBUR AVENUE

MILL STREET

BANK STREET

MEYNER ROAD

LINCOLN ROAD

HILLSIDE

STANLEY STREET

PEARL STREET

GRAND STREET

LOGAN STREET

LINDEN STREET

RIDGE STREET

LOCK STREET

MELROSE STREET

GATE STREET

CUTTLE STREET

WASHINGTON ST.

MADISON STREET

CONGRESS ST.

VALLEY VIEW CIR.

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON STREET

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

ROSEBERRY STREET

BARRYMORE STREET

FROST AVENUE

PICKFORD STREET

HARTE ST.

BURKE STREET

PROSPECT AVENUE

LINCOLN ROAD

LINER BLVD.

BELVIDERE ROAD

DELAWARE WAY

NORTH MAIN STREET

FOURTH STREET

THIRD STREET

SECOND STREET

FIRST STREET

SOUTH MAIN STREET

MARKET ST.

ELIZABETH ST.

FRONT STREET

HARRIS STREET

CHAMBERS ST.

WASHINGTON AVE.

SUMMIT

MITCHELL

BULLMAN

BURWELL

BENNETT

STULL ALLEY

SHIMER ST.

BRAINARD

REESE

WAYNE

HUDSON ST.

HANOVER STREET

REESE COURT

HOWARD

MERCER

STORGEAVES

JEFFERSON

STOCKTON

WASHINGTON

MAIN

SPRUCE

PINE

LAKE

CEDAR

HICKORY

WALNUT

CHESTNUT

POPLAR

MIDDLE

ALLEY

ALLAN

ANN

JAMES

WILLIAM

THOMAS

PURSEL

GRIFFITH

PERRINE

HILL

GRANT

BANK

PARK RD.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

CENTER

ESSEX STREET

HECKMAN

MARSHALL

ANDERSON

FISHER PLACE

KNEEDLER AVENUE

WATSON

BLM STREET

CONGRESS

KATTELL

MADISON STREET

GATE

CUTTLE

VALLEY VIEW

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

MEMORIAL PARKWAY (RT. 22)

DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

I-78

FAIRBANKS STREET

BOBCE AVENUE

HAGERTY AVE.

FERGUSON ST.

BARRYMORE STREET

BELVIDERE ROAD

DELAWARE WAY

NORTH MAIN STREET

FOURTH STREET

THIRD STREET

SECOND STREET

FIRST STREET

SOUTH MAIN STREET

MARKET ST.

ELIZABETH ST.

FRONT STREET

HARRIS STREET

CHAMBERS ST.

WASHINGTON AVE.

SUMMIT

MITCHELL

BULLMAN

BURWELL

BENNETT

STULL ALLEY

SHIMER ST.

BRAINARD

REESE

WAYNE

HUDSON ST.

HANOVER STREET

REESE COURT

HOWARD

MERCER

STORGEAVES

JEFFERSON

STOCKTON

WASHINGTON

MAIN

SPRUCE

PINE

LAKE

CEDAR

HICKORY

WALNUT

CHESTNUT

POPLAR

MIDDLE

ALLEY

ALLAN

ANN

JAMES

WILLIAM

THOMAS

PURSEL

GRIFFITH

PERRINE

HILL

GRANT

BANK

PARK RD.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

CENTER

ESSEX STREET

HECKMAN

MARSHALL

ANDERSON

FISHER PLACE

KNEEDLER AVENUE

WATSON

BLM STREET

CONGRESS

KATTELL

MADISON STREET

GATE

CUTTLE

VALLEY VIEW

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

KEY TO INDEX

ABBOTT AL. N-32
BROADVIEW ST. O-9
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-28
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. O-32
CENTER RD. O-32
CENTER ST. O-22
CHAMBERS ST. O-11
CHERRY LANE O-10
CHESTNUT ST. O-21
CHINA AL. O-8
CHINTEWINK AL. O-6
CHRISTINE AL. N-13
CHURCH ST. B-11
CLAIRMONT ST. O-31
COLBY PL. O-9
COLUMBUS AVE. O-22
COMPRESSOR ST. O-15
COMSTOCK AL. O-15
CONGRESS ST. O-15
CORLISS AVE. N-11
CROSS ST. O-15
CULKIN ST. O-25
DAVIS ST. K-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. K-11
DUGAN AL. H-11
ELDER AVE. H-11
ELIZABETH ST. H-11
ELLEN ST. O-14
ELM ST. F-19
ELMHURST DR. H-30
EMIRE ST. F-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. O-19
EVELYN AVE. H-11
FAIRBANKS ST. K-8
FAIRVIEW AVE. L-7
FERGUSON ST. R-27
FILMORE ST. K-8
FIFTH ST. F-11
FIRST AL. F-14
FIRTH ST. K-27
FISHER AVE. K-13
FOOT BRIDGE P-19
FORREST LA. F-30
FOURTH ST. H-5
FOX AL. C-8
FOX ST. C-17
FRACE ST. P-10
FRANCIS AVE. H-10
FRANKLIN ST. H-10
FREDERICK ST. O-10
FRONT ST. O-10
FROST AVE. R-9
FULTON ST. F-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. F-13
GREEN AL. F-11
GREEN ST. F-22
GREENWOOD ST. O-28
GRIFFITH AL. O-29
HAGERTY AVE. N-7
HANOVER ST. N-13
HARRIS ST. O-9
HARTE ST. P-9
HECKMAN ST. P-15
HEMLOCK ST. F-32
HENDERSON ST. F-11
HENSHAW CT. G-11
HILL ST. F-25
HILLCREST BLVD. K-9
HILLSIDE RD. R-27
HOWARD ST. B-10
HUDSON ST. O-11
INGERSOLL AVE. O-11
IRWIN ST. O-15
IVY ST. C-16
JAMES RIVER WAY K-23
JEFFERSON ST. O-18
JERSEY ST. C-18
JOHN ST. C-19
JOHN MITCHELL AVE. N-9
JOSEPH ST. H-9
JUDD AL. H-9
KAITLYN CT. P-27
KENT ST. K-18
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. C-25
LANE AL. C-25
LENNON AL. N-11
LESHER AL. O-13
LEWIS ST. O-15
LINCOLN RD. M-10
LINCOLN ST. L-12
LINER BLVD. M-12
LOCK ST. N-35
LOGAN ST. P-22
LYNDALE ST. O-28
LYNN RD. M-36
MADISON ST. F-14
MARKET ST. F-14
MARSHALL ST. K-14
MARY ST. O-28
MARSEN ST. K-14
MELROSE ST. P-19
MEMORIAL PKWY. K-22
MERCER ST. O-18
METZ ST. F-10
MEYNER RD. M-25
MILL ST. F-25
MILLER ST. O-15
MITCHELL AL. O-9
MORRIS ST. O-18
MOULE AL. O-29
NATALIE DRIVE L-31
NELSON ST. P-19
NORTH AL. O-9
NO. MAIN ST. F-10
NO. RIVERVIEW RD. L-28
OAK AL. O-9
ORCHARD AL. O-9
PARK RD. O-28
PEACH ST. O-9
PEAR AL. O-9
PEARL ST. O-28
PERRINE AVE. O-29
PICKFORD AVE. O-9
PINE AL. O-9
PLEASANT AVE. O-9
POTTS AVE. O-9
PROSPECT ST. O-9
PURSEL ST. O-29
RAILROAD AVE. O-29
RANDALL ST. O-9
RAYMOND ST. O-9
REESE WAY O-9
REESE CT. O-9
RICHARD RD. O-9
RICHMOND ST. O-9
RIDGE ST. O-9
RIVER ST. O-9
RIVERSIDE WAY O-9
RIVERVIEW CIR. O-9
RIVERVIEW RD. O-9
ROCK AL. O-9
ROSE ST. O-9
ROSEBERRY ST. O-9
SARGENT AVE. O-9
SAWMILL ST. O-9
SAYRE AVE. O-9
SCHULTZ AVE. O-9
SHAFER AVE. O-9
SHERWOOD ST. O-9
SHILLINGER AL. O-9
SHIMER ST. O-9
SILK AVE. O-9
STORGEAVES ST. O-9
SMITH AVE. O-9
SONYEA ST. O-9
SO. MAIN ST. O-9
SPINNER AL. O-9
SPRUCE AL. O-9
ST. JOHN AL. O-9
STANLEY ST. O-9
STEELE ST. O-9
STEWART AL. O-9
STOCKTON ST. O-9
STRYKER ST. O-9
STULL AL. O-9
SUMMIT AVE. O-9
SUSAN ST. O-9
TAYLOR AL. O-9
TERRY ST. O-9
THIRD ST. O-9
THOMAS ST. O-9
TIGHE AL. O-9
TITUS AL. O-9
TUTTLE ST. O-9
TYNDALL AVE. O-9
UNION SQ. O-9
VALLEY VIEW CIR. O-9
WALNUT ST. O-9
WARREN ST. O-9
WASHINGTON ST. O-9
WATSON PL. O-9
WEBSTER ST. O-9
WILBUR AVE. O-9
WILLOVER ST. O-9
WILLIAM ST. O-9
WILSON ST. O-9
WISE AL. O-9
WOODLAWN RD. O-9


THE TOWN OF PHILLIPSBURG
OFFICIAL MAP
WARREN COUNTY, NEW JERSEY
UPDATED 5-07
SCALE: 1" = 500'
GRAPHIC SCALE OF FEET
DATE: December 1, 1998
REVISED October 2005
TOWNSHIP OF LOPATCONG
TOWNSHIP OF POHATCONG
DELAWARE RIVER
COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON
I-78
Martha - PAPWA
4/1/22

T. Courter

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

T. Courter
K. Weigand
4/1/22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG


TOWNSHIP OF POHATCONG

DELAWARE - COMMONWEALTH OF PENNSYLVANIA RIVER

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

I-78

BRAINARD ST. O-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. O-9
BURNELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AV. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. O-6
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE.
COMPRESSION ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST.
CULVER ST. O-25
DAVIS ST. N-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. I-14
ELM ST. P-19
ELMHURST DR. M-30
EMIRE ST. P-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. H-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. O-7
FARM ST. B-27
FERGUSON ST. J-8
FILMORE ST. F-11
FIFTH ST. E-4
FIRST AL. M-27
FIRTH ST. K-13
FISHER AVE. O-16
FOGHT BRIDGE E-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. D-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. M-10
FREDERICK ST. O-10
FRONT ST. O-10
FROST AVE. R-9
FULTON ST. E-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-29
GRIFFITH AL. N-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. I-9
HARTE ST. P-9
HECKMAN ST. P-15
HEMLOCK ST. O-32
HENDERSON ST. I-11
HENSHAW CT. O-11
HILL ST. O-25
HILLCREST BLVD. K-9
HILLSIDE RD. Q-27
HOWARD ST. O-16
HUDSON ST. D-12
INGERSOLL AVE. D-11
IRWIN ST. G-12
IVY ST. G-12
J. T. BAKER WAY L-23
JAMES ST. C-19
JEFFERSON ST. D-19
JERSEY ST. I-19
JOHN ST. N-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. N-9
JUDD AL. I-8
KAITLYN CT. P-27
KENT ST. L-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE J-31
KORP AL. J-25
KURLAND AL. J-25
LAKE AL. B-10
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD. M-13
LINCOLN RD. K-8
LINCOLN ST. O-32
LINER BLVD. O-30
LOCK ST. O-31
LOGAN ST. K-19
LYNDALE ST. M-9
LYNN RD. N-9
MADISON ST. B-12
MARKET ST. I-14
MARSHALL ST. I-14
MARY ST. E-21
MCKEEN ST. O-31
MELROSE ST. D-13
MEMORIAL PKWY. E-18
MERCER ST. O-10
METZ ST. M-25
MEYNER RD. J-11
MILL ST. D-10
MITCHELL AL. B-8
MORRIS ST. N-21
MOULE AL. J-32, K-
NATALIE DRIVE N-30
NELSON ST. I-14
NORTH AL. C-8
NO. MAIN ST. J-29
NO. RIVERVIEW RD. H-13
OAK AL. G-9
ORCHARD AL. P-24
PARK RD. L-22
PEACH ST. E-11
PEAR AL. P-29
PEARL ST. L-25
PERODE AVE. P-11
PICKFORD AVE. F-16
PINE AL. B-10
PLEASANT AVE. J-11
POTTS AVE. M-10
PROSPECT ST. L-24
PURSEL ST. J-14
RAILROAD AVE. O-10
RANDALL ST. G-9
RAYMOND ST. B-11
REESE WAY B-14
REESE CT. J-21
RICHARD RD. P-29
RICHMOND ST. R-29
RIDGE ST. O-16
RIVER ST. C-7
RIVERSIDE WAY I-27
RIVERVIEW CIR. N-29
RIVERVIEW RD. M-13
ROCK AL. N-9
ROSE ST. N-9
ROSEBERRY ST. O-11
SARGENT AVE. I-25
SAWMILL ST. K-23
SAYRE AVE. H-11
SCHULTZ AVE. G-8
SHAFER AVE. O-30
SHERWOOD ST. J-14
SHILLINGER AL. I-11
SHIMER ST. H-15
SILK AVE. P-17
SITGREAVES ST. F-20
SMITH AVE. O-27
SONORA ST. B-9
SQ. MAIN ST. I-11
SPINNER AL. I-18
SPRUCE AL. K-14
ST. JOHN AL. O-29
STANLEY ST. L-29
STEELE ST. N-25
STEWART AL. O-16
STOCKTON ST. A-12
STRYKER ST. F-8
STULL AL. O-10
SUMMIT AVE. O-10
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TRIHE AL. H-12
TITUS AL. O-29
TUTTLE ST. B-11
TYNDALL AVE. B-9
UNION SQ. P-28
VALLEY VIEW CIR. M-24
WALNUT ST. K-23
WARREN ST. K-18
WASHINGTON ST. D-18
WATSON PL. P-16
WEBSTER ST. L-23
WILBUR AVE. M-22
WILLEVER ST. O-19
WILLIAM ST. M-24
WILSON ST. K-7
WIRE AL. K-
WOODLAWN RD. I-28



Cory Conners 5-6-22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom Coulter 5-06-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG


TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
FROST AVENUE
BARRYMORE STREET
BOWERS AVE.
PICKFORD STREET
HARTE ST.
BURKE STREET
FRACE ST.
FREDERICK STREET
SAMPSON STREET
MICKEL STREET
WILLIAMS ST.
SUSAN ST.
MORRIS STREET
GRACE STREET
GORLISS AVENUE
FLOUR AVENUE
PRUNE AVENUE
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE ROAD
DELAWARE AVENUE
BAKER WAY
NORTH MAIN STREET
FOURTH STREET
THIRD STREET
SECOND STREET
FIRST STREET
FAIRBANKS STREET
FERGUSON STREET
BOULEVARD
HAGERTY AVE.
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
ANDERSON STREET
KNEEDLER AVENUE
FISHER PLACE
WATSON PLACE
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVENUE
BATES STREET
PROSPECT STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
STOCKTON STREET
ESSEX STREET
CAHILL ST.
RICHARD RD.
METZNER ROAD
LYNN RD.
SAYRE AVENUE
WILBUR AVENUE
MILL STREET
HILL STREET
BANK STREET
CENTER STREET
LINCOLN ROAD
MORRIS CANAL WAY
SAWMILL ST.
GATE STREET
TUTTLE STREET
HARRINGTON ST.
RIDGE STREET
LOCK STREET
HILLSIDE
CONGRESS
KAITLYN CT.
STANLEY STREET
PEARL STREET
GRAND STREET
LOGAN STREET
MADISON STREET
MELROSE STREET
LINDALE STREET
KNOLL VIEW DRIVE
NATALIE DRIVE
RIVERVIEW CIR.
WOODLAWN ROAD
NORTH RIVERVIEW ROAD
FORREST LA.
BELT AVE.
ELMHURST ROAD
CARPENTERSVILLE ROAD
OAKLYN RD.
HEMLOCK DR.
CENTER ROAD
BRAINARD ST.
BROAD ST.
BROADVIEW ST.
BULLMAN ST.
BURKE ST.
BURWELL AL.
CAHILL ST.
CARHART AL.
CARPENTERSVILLE RD.
CEDAR AL.
CENTER RD.
CENTER ST.
CHAMBERS ST.
CHERRY LANE
CHESTNUT ST.
CIRNA AL.
CHINTEWINK AL.
CHRISTIE AL.
CHURCH ST.
CLARMONT ST.
COLBY PL.
COLUMBUS AVE.
COMPRESSION ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST.
CULVON ST.
DAVIS ST.
DEAN AL.
DELAWARE RD.
DIMMICK AL.
DRILL ST.
DUGAN AL.
ELDER AVE.
ELIZABETH ST.
ELLEN ST.
ELM ST.
ELMHURST DR.
EMIRE ST.
EMMA ST.
ENGINE ST.
ESSEX ST.
EVELYN AVE.
FAIRBANKS ST.
FAIRVIEW AVE.
FARM ST.
FERGUSON ST.
FILMORE ST.
FIFTH ST.
FIRST AL.
FIRTH ST.
FISHER AVE.
FOGHT BRIDGE
FORREST LA.
FOURTH ST.
FOX AL.
FOX ST.
FRACE ST.
FRANCIS AVE.
FRANKLIN ST.
FREDERICK ST.
FRONT ST.
FROST AVE.
FULTON ST.
GATE ST.
GLEN AVE.
GRACE AVE.
GRAND ST.
GRANT ST.
GREEN AL.
GREEN ST.
GREENWOOD ST.
GRIFFITH AL.
HAGERTY AVE.
HANOVER ST.
HARRIS ST.
HARTE ST.
HECKMAN ST.
HEMLOCK ST.
HENDERSON ST.
HENSHAW CT.
HILL ST.
HILLCREST BLVD.
HILLSIDE RD.
HOWARD ST.
HUDSON ST.
INGERSOLL AVE.
IRWIN ST.
IVY ST.
J. J. BAKER WAY
JAMES ST.
JEFFERSON ST.
JERSEY AL.
JOHN ST.
JOHN MITCHELL AVE.
JOSEPH ST.
JUDD AL.
KAITLYN CT.
KENT ST.
KNEEDLER AVE.
KNOLL VIEW DRIVE
KORP AL.
KURLAND AL.
LAKE AL.
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD.
LINCOLN RD.
LINCOLN ST.
LINER BLVD.
LOCK ST.
LOGAN ST.
LYNDALE ST.
LYNN RD.
MADISON ST.
MARKET ST.
MARSHALL ST.
MARY ST.
McKEEN ST.
MELROSE ST.
MEMORIAL PKWY.
MERCER ST.
METZ ST.
METZNER RD.
MILL ST.
MILLER ST.
MITCHELL AL.
MORRIS ST.
MOULE AL.
NATALIE DRIVE
NELSON ST.
NORTH AL.
NO. MAIN ST.
NO. RIVERVIEW RD.
OAK AL.
ORCHARD AL.
PARK RD.
PEACH ST.
PEAR AL.
PEARL ST.
PERDOE AVE.
PICKFORD AVE.
PINE AL.
PLEASANT AVE.
POTTS AVE.
PROSPECT ST.
PURSEL ST.
RAILROAD AVE.
RANDALL ST.
RAYMOND ST.
REESE WAY
REESE CT.
RICHARD RD.
RICHMOND ST.
RIDGE ST.
RIVER ST.
RIVERSIDE WAY
RIVERVIEW CIR.
RIVERVIEW RD.
ROCK AL.
ROSE ST.
ROSEBERRY ST.
SARGENT AVE.
SAWMILL ST.
SAYRE AVE.
SCHULTZ AVE.
SHAFER AVE.
SHERWOOD ST.
SHILLINGER AL.
SHIMER ST.
SILK AVE.
SIDGREAVES ST.
SMITH AVE.
SONORA ST.
SO. MAIN ST.
SPRINNER AL.
SPRUCE AL.
ST. JOHN AL.
STANLEY ST.
STEELE ST.
STEWART AL.
STOCKTON ST.
STRYKER ST.
STULL AL.
SUMMIT AVE.
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TICHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WISE AL.
WOODLAWN RD.



U T S R Q P O N M L K J I H G F E D C B A

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

DELAWARE RIVER

CITY OF EASTON

I-78

BROAD ST. N-6
BROADVIEW ST. N-32
BULLMAN ST. O-8
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE C-18
CHESTNUT ST. O-21
CHINA AL. G-9
CHINTEWINK AL. G-9
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-7
COLBY PL. O-11
COLUMBUS AVE. O-25
COMPRESSOR ST. N-14
COMSTOCK AL. F-11
CONGRESS ST. K-9
CORLISS AVE. K-13
CROSS ST. N-11
CULVON ST. E-11
DAVIS ST. N-11
DEAN AL. E-11
DELAWARE RD. N-11
DIMMICK AL. B-11
DRILL ST. B-14
DUGAN AL. P-19
ELDER AVE. P-19
ELIZABETH ST. P-30
ELLEN ST. P-32
ELM ST. P-32
ELMHURST DR. P-32
ENNIE ST. P-32
EMMA ST. O-11
ENGINE ST. I-18
ESSEX ST. I-18
EVELYN AVE. I-18
FAIRBANKS ST. O-7
FAIRVIEW AVE. P-27
FARM ST. N-27
FERGUSON ST. P-11
FILMORE ST. P-11
FIRTH PL. P-14
FIRST AL. P-27
FIRTH ST. N-28
FISHER AVE. O-18
FOCHT BRIDGE O-20
FORREST LA. N-20
FOURTH ST. N-20
FOX AL. O-11
FOX ST. P-18
FRACE ST. P-18
FRANCIS AVE. P-19
FRANKLIN ST. P-10
FREDERICK ST. P-10
FRONT ST. P-10
FROST AVE. P-11
FULTON ST. P-14
GATE ST. P-27
GLEN AVE. P-11
GRACE AVE. P-19
GRAND ST. O-28
GRANT ST. P-28
GREEN AL. P-28
GREEN ST. P-22
GREENWOOD ST. P-22
GRIFFITH AL. P-25
HAGERTY AVE. N-7
HANOVER ST. O-13
HARRIS ST. O-13
HARTE ST. O-13
HECKMAN ST. O-32
HEMLOCK ST. O-32
HENDERSON ST. O-32
HENSHAW CT. O-32
HILL ST. I-25
HILLCREST BLVD. I-25
HILLSIDE RD. I-25
HOWARD ST. I-25
HUDSON ST. I-25
INGERSOLL AVE. I-25
IRWIN ST. I-25
IVY ST. I-25
JAILER BANKER WAY I-25
JEFFERSON ST. I-25
JERSEY ST. I-25
JOHN ST. I-25
JOHN MITCHELL AVE. I-25
JOSEPH ST. I-25
JUDD AL. I-25
KAITLYN CT. I-25
KENT ST. I-25
KNEEDLER AVE. I-25
KNOLL VIEW DRIVE I-25
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. I-25
LENNON AL. I-25
LESHER AL. I-25
LEWIS ST. I-25
LIMEKILN RD. I-25
LINCOLN RD. I-25
LINCOLN ST. I-25
LINER BLVD. I-25
LOCK ST. I-25
LOGAN ST. I-25
LYNDALE ST. I-25
MAIN RD. I-25
MADISON ST. I-25
MARKET ST. I-25
MARSHALL ST. I-25
MARY ST. I-25
McKEEN ST. I-25
MELROSE ST. I-25
MEMORIAL PKWY. I-25
MERCER ST. I-25
METZ ST. I-25
MEYNER RD. I-25
MILL ST. I-25
MILLER ST. I-25
MITCHELL AL. I-25
MORRIS ST. I-25
MOULE AL. I-25
NATALIE DRIVE I-25
NELSON ST. I-25
NORTH AL. I-25
NO. MAIN ST. I-25
NO. RIVERVIEW RD. I-25
OAK AL. I-25
ORCHARD AL. I-25
PARK RD. I-25
PEACH ST. I-25
PEAR AL. I-25
PEARL ST. I-25
PERDOE AVE. I-25
PROVOST AVE. I-25
PINE AL. I-25
PLEASANT AVE. I-25
POTTS AVE. I-25
PROSPECT ST. I-25
PURSES. ST. I-25
RAILROAD AVE. I-25
RANDALL ST. I-25
RAYMOND ST. I-25
REESE WAY I-25
REESE CT. I-25
RICHARD RD. I-25
RICHMOND ST. I-25
RIDGE ST. I-25
RIVER ST. I-25
RIVERSIDE WAY I-25
RIVERVIEW CIR. I-25
RIVERVIEW RD. I-25
ROCK AL. I-25
ROSE ST. I-25
ROSEBERRY ST. I-25
SARGENT AVE. I-25
SAWMILL ST. I-25
SAYRE AVE. I-25
SCHULTZ AVE. I-25
SHAFER AVE. I-25
SHERWOOD ST. I-25
SHILLINGER AL. I-25
SHIMER ST. I-25
SILK AVE. I-25
STORGEAVES ST. I-25
SMITH AVE. I-25
SONDEN ST. I-25
SO. MAIN ST. I-25
SPRINER AL. I-25
SPRUCE AL. I-25
ST. JOHN AL. I-25
STANLEY ST. I-25
STEELE ST. I-25
STEWART AL. I-25
STOCKTON ST. I-25
STRYKER ST. I-25
STULL AL. I-25
SUMMIT AVE. I-25
SUSAN ST. I-25
TAYLOR AL. I-25
TERRY ST. I-25
THIRD ST. I-25
THOMAS ST. I-25
TICHE AL. I-25
TITUS AL. I-25
TUTTLE ST. I-25
TYNDALL AVE. I-25
UNION SQ. I-25
VALLEY VIEW CIR. I-25
WALNUT ST. I-25
WARREN ST. I-25
WASHINGTON ST. I-25
WATSON PL. I-25
WEBSTER ST. I-25
WILBUR AVE. I-25
WILLEVER ST. I-25
WILLIAM ST. I-25
WILSON ST. I-25
WOOD AL. I-25
WOODLAWN RD. I-25

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom C
7-29-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
BARRYMORE STREET
FROST AVENUE
BOWERS AVE.
HILLCREST AVENUE
PICKFORD STREET
HARTE ST.
BURKE STREET
FAIRBANKS STREET
BOULEVARD
HAGERTY ST.
ROAD
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
FERGUSON ST.
BELVIDERE AVENUE
DELAWARE ROAD
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
ANDERSON STREET
KNEEDLER AVENUE
FISHER PLACE
WATSON
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVE.
BATES STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
STOCKTON STREET
ESSEX STREET
CAHILL ST.
RICHARD RD.
SAYRE AVENUE
MEYNER ROAD
CENTER STREET
LIMEKILN ROAD
WILBUR AVENUE
GATE STREET
TUTTLE ST.
HILLSIDE
RIDGE STREET
LOCK STREET
MELROSE AVENUE
STANLEY STREET
PEARL ST.
GRAND ST.
LOGAN ST.
MADISON STREET
CONGRESS STREET
KAITLYN CT.
VALLEY VIEW ROAD
NORTH RIVERVIEW ROAD
RIVERVIEW CIR.
WOODLAWN ROAD
CORRECT LN.
BELT ROAD
CARPENTERSVILLE ROAD
NATALIE DRIVE
KNOLL VIEW DRIVE
ELMHURST DRIVE
OAKLYN RD.
HEMLOCK DR.
CANAL WAY
MORRIS
SAWMILL ST.
MAIN ST.
SOUTH MAIN ST.
NORTH MAIN ST.
RAYMOND ST.
EVELYN AVE.
SHULTZ AVE.
HENDERSON
MILLER
FRANCIS AVE.
POTTS AVE.
IRWIN
HUDSON
MARY ST.
DAVIS
DOLBY PLACE
ORCHARD ALLEY
SOUTH
FRONT STREET
THIRD STREET
SECOND STREET
FIRST ST.
CHAMBERS STREET
HARRIS STREET
SHIMER ST.
BRAINARD
WALNUT
REESE
MARKET
ELIZABETH ST.
HANOVER STREET
REESE COURT
MERCER STREET
HOWARD
STRYKER
SOUTH ABUTMENT
NORTH ABUTMENT
SUSQUEHANNA RIVER
MORRIS CANAL
DELAWARE & RARITAN CANAL
PENNSYLVANIA RAILROAD
LEHIGH VALLEY RAILROAD
CONRAIL
NORFOLK SOUTHERN RAILWAY

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTZWICK AL. G-6
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE. J-17
COMPRESSOR ST. L-11
COMSTOCK AL. E-11
CONGRESS ST. L-11
CORLISS AVE. D-25
CROSS ST. G-14
CULVON ST. F-11
DAVIS ST. K-5
DEAN AL. K-13
DELAWARE RD. N-11
DIMMICK AL. E-11
DRILL ST. E-11
DUGAN AL. B-11
ELDER AVE. B-11
ELIZABETH ST. G-14
ELLEN ST. P-18
ELM ST. H-30
ELMHURST DR. I-10
EMPIRE ST. K-22
EMMA ST. L-11
ENGINE ST. L-19
ERICK ST. B-11
EVELYN AVE. F-8
FAIRBANKS ST. L-7
FAIRVIEW AVE. K-27
FARM ST. L-8
FERGUSON ST. P-18
FILMORE ST. L-22
FIFTH ST. E-14
FIRST AL. K-27
FIRTH ST. K-13
FISHER AVE. J-16
FOCHT BRIDGE L-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-7
FOX ST. E-7
FRACE ST. I-10
FRANCIS AVE. H-10
FRANKLIN ST. H-10
FREDERICK ST. G-10
FRONT ST. P-9
FROST AVE. E-14
FULTON ST. K-27
GATE ST. K-11
GLEN AVE. H-10
GRACE AVE. H-29
GRAND ST. L-13
GRANT ST. F-11
GREEN AL. P-22
GREEN ST. P-22
GREENWOOD ST. H-25
GRIFFITH AL. N-7
HAGERTY AVE. H-13
HANOVER ST. G-9
HARRIS ST. P-9
HARTE ST. I-15
HECKMAN ST. K-32
HEMLOCK ST. I-11
HENDERSON ST. L-25
HENSHAW CT. O-9
HILL ST. K-27
HILLCREST BLVD. B-16
HILLSIDE RD. H-27
HOWARD ST. G-16
HUDSON ST. G-11
INGERSOLL AVE. B-12
IRWIN ST. O-15
I. T. PAKER WAY I-23
JAMES ST. N-22
JEFFERSON ST. M-24
JERSEY ST. K-32
JOHN ST. L-9
JOHN MITCHELL AVE. N-9
JOSEPH ST. I-5
JUDD AL. I-27
KAITLYN CT. I-30
KENT ST. O-16
KNEEDLER AVE. J-31
KNOLL VIEW DRIVE J-25
KORP AL. B-9
KURLAND AL. P-20
LAKE AL. K-19
LENNON AL. D-18
LESHER AL. I-23
LEWIS ST. M-22
LIMEKILN RD. L-24
LINCOLN RD. M-24
LINCOLN ST. I-12
LINER BLVD. I-25
LOCK ST. B-10
LOGAN ST. O-30
LYNDALE ST. O-31
LYNN RD. I-19
MADISON ST. N-30
MARKET ST. B-12
MARSHALL ST. I-14
MARY ST. I-8
McKEEN ST. L-21
MELROSE ST. G-21
MEMORIAL PKWY. A-32, K-
MERCER ST. D-10
METZ ST. I-16
MEYNER RD. I-19
MILL ST. H-25
MILLER ST. I-11
MITCHELL AL. I-11
MORRIS ST. D-8
MOULE AL. G-21
NATALIE DRIVE A-32, K-
NELSON ST. I-14
NORTH AL. I-8
NO. MAIN ST. O-8
NO. RIVERVIEW RD. K-28
OAK AL. K-8
ORCHARD AL. O-8
PARK RD. K-24
PEACH ST. I-22
PEAR AL. L-11
PEARL ST. L-25
PERDOE AVE. L-7
PICKFORD AVE. I-11
PINE AL. I-16
PLEASANT AVE. B-10
POTTS AVE. B-11
PROSPECT ST. H-24
PURSEL ST. I-14
RAILROAD AVE. I-14
RANDALL ST. G-10
RAYMOND ST. O-9
REESE WAY O-11
REESE CT. B-14
RICHARD RD. K-21
RICHMOND ST. P-29
RIDGE ST. K-29
RIVER ST. P-16
RIVERSIDE WAY O-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. I-13
ROSE ST. K-5
ROSEBERRY ST. O-9
SARGENT AVE. O-11
SAWMILL ST. K-25
SAYRE AVE. K-23
SCHULTZ AVE. M-11
SHARON AVE. B-8
SHERWOOD ST. O-30
SHILLINGER AL. I-14
SHIMER ST. O-11
SILK AVE. O-11
SITGREAVES ST. I-19
SMITH AVE. O-20
SONDRA ST. O-27
SO. MAIN ST. B-9
SPINNER AL. I-11
SPRUCE AL. I-18
ST. JOHN AL. K-14
STANLEY ST. O-29
STEELE ST. I-29
STEWART AL. I-29
STOCKTON ST. I-25
STRYKER ST. G-12
STULL AL. O-8
SUMMIT AVE. O-10
SUSAN ST. O-10
TAYLOR AL. O-20
TERRY ST. O-27
THIRD ST. B-9
THOMAS ST. I-11
TIGHE AL. I-25
TITUS AL. I-11
TUTTLE ST. O-25
TYNDALL AVE. B-9
UNION SQ. B-8
VALLEY VIEW CIR. P-20
WALNUT ST. K-19
WARREN ST. D-18
WASHINGTON ST. I-15
WATSON PL. I-23
WEBSTER ST. M-22
WILBUR AVE. N-22
WILLEVER ST. O-10
WILLIAM ST. M-24
WILSON ST. I-32, K-
WISE PL. I-7
WOODLAWN RD. I-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Martin S

TOM C

8-23-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

MONTEREY

ROSEBERRY STREET

BARRYMORE STREET

BOWERS AVE.

FROST AVENUE

PICKFORD STREET

HARTE ST.

BURKE STREET

FRACE ST.

FREDERICK STREET

SARGENT AVENUE

MICHAEL STREET

JOHN STREET

INGERSOLL AVENUE

GRACE STREET

CORLISS AVENUE

ELDER STREET

FAIRBANKS STREET

HILLCREST AVE.

HAGERTY BOULEVARD

MEMORIAL PARKWAY (RT. 22)

MARSHALL STREET

HECKMAN STREET

FISHER PLACE

KNEEDLER AVENUE

ANDERSON STREET

WATSON PLACE

WALNUT STREET

BLM STREET

GREEN STREET

COLUMBUS AVE.

BATES STREET

PROSPECT STREET

LINCOLN ROAD

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

STOCKTON STREET

ESSEX STREET

CAHILL ST.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

SAYRE AVENUE

WILBUR AVENUE

PERDUE ALLEY

HILL STREET

BANK STREET

GATE STREET

TUTTLE STREET

RIDGE STREET

LOOK STREET

STANLEY STREET

HILLSIDE

VALLEY VIEW

PEARL ST.

GRAND ST.

LOGAN ST.

MADISON STREET

MELROSE STREET

KAITLYN CT.

CONGRESS ST.

CULKIN STREET

STEWART ALLEY

ALLAN STREET

MILL STREET

GRIFFITH ALLEY

GARNART

JAMES ST.

PURSEL ST.

THOMAS ST.

ANN ST.

WILLIAM ST.

CENTER ST.

CHESTNUT ST.

PEACH ST.

MEYNER ST.

EMMA ST.

PARK RD.

KURLAND ALLEY

MORRIS CANAL WAY

SAWMILL ST.

ABBOTT ST.

CENTER ST.

ANDOVER STREET

SOUTH MAIN ST.

DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

I-78

RIVERVIEW CIR.

NORTH RIVERVIEW

WOODLAWN ROAD

FOREST LN.

ELMHURST AVE.

BELT ROAD

CARPENTERSVILLE ROAD

NATALIE DRIVE

KNOLL VIEW DRIVE

OAKLYN RD.

HEMLOCK DR.

LOCK ST.

LOCUST ST.

LYNDALE ST.

LYNN RD.

MADISON ST.

MARKET ST.

MARSHALL ST.

MARY ST.

McKEEN ST.

MELROSE ST.

MEMORIAL PKWY.

MERCER ST.

METZ ST.

MEYNER RD.

MILL ST.

MILLER ST.

MITCHELL AL.

MORRIS ST.

MOULE AL.

NATALIE DRIVE

NELSON ST.

NORTH AL.

NO. MAIN ST.

NO. RIVERVIEW RD.

OAK AL.

ORCHARD AL.

PARK RD.

PEACH ST.

PEAR AL.

PEARL ST.

PERDOE AVE.

PICKFORD AVE.

PINE AL.

PLEASANT AVE.

POTTS AVE.

PROSPECT ST.

PURSEL ST.

RAILROAD AVE.

RANDALL ST.

RAYMOND ST.

REESE WAY

REESE CT.

RICHARD RD.

RICHMOND ST.

RIDGE ST.

RIVER ST.

RIVERSIDE WAY

RIVERVIEW CIR.

RIVERVIEW RD.

ROCK AL.

ROSE ST.

ROSEBERRY ST.

SARGENT AVE.

SAWMILL ST.

SAYRE AVE.

SCHULTZ AVE.

SHARPE AVE.

SHERWOOD ST.

SHILLINGER AL.

SHIMER ST.

SILK AVE.

STIRGEAVES ST.

SMITH AVE.

SONORA ST.

SO. MAIN ST.

SPINNER AL.

SPRUCE AL.

ST. JOHN AL.

STANLEY ST.

STEELE ST.

STEWART AL.

STOCKTON ST.

STRYKER ST.

STULL AL.

SUMMIT AVE.

SUSAN ST.

TAYLOR AL.

TERRY ST.

THIRD ST.

THOMAS ST.

TIGHE AL.

TITUS AL.

TUTTLE ST.

TYNDALL AVE.

UNION SQ.

VALLEY VIEW CIR.

WALNUT ST.

WARREN ST.

WASHINGTON ST.

WATSON PL.

WEBSTER ST.

WILBUR AVE.

WILLEVER ST.

WILLIAM ST.

WILSON ST.

WIRE AL.

WOODLAWN RD.

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTEWINK AL. G-6
CHRISTIE AL. N-13
CHURCH ST. B-11
CLARMONT ST. D-31
COLBY PL. H-15
COLUMBUS AVE.
COMPRESSOR ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST. L-12
CULKIN ST. O-25
DAVIS ST. H-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. G-14
ELM ST. P-19
ELMHURST DR. N-30
EMIRE ST. I-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. H-11
FAIRBANKS ST. D-8
FAIRVIEW AVE. I-7
FARM ST. R-27
FERGUSON ST. L-8
FILMORE ST. F-11
FIFTH ST. L-4
FIRST AL. L-27
FIRTH ST. K-13
FISHER AVE. K-16
FOCHT BRIDGE F-7
FORREST LA. L-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. D-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. N-10
FREDERICK ST. N-10
FRONT ST. C-10
FROST AVE. R-9
FULTON ST. I-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-29
GRIFFITH AL. M-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. D-9
HARTE ST. P-9
HECKMAN ST. I-15
HEMLOCK ST. B-32
HENDERSON ST. I-11
HENSHAW CT. O-11
HILL ST. L-25
HILLCREST BLVD. K-9
HILLSIDE RD. L-27
HOWARD ST. B-16
HUDSON ST. B-12
INGERSOLL AVE. O-11
IRWIN ST. I-12
IVY ST. O-15
J. T. BAKER WAY O-15
JAMES ST. K-23
JEFFERSON ST. O-19
JERSEY ST. O-16
JOHN ST. H-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. H-9
JUDD AL. I-5
KAITLYN CT. L-27
KENT ST. L-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE O-31
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. B-10
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD.
LINCOLN RD.
LINCOLN ST. M-13
LINER BLVD. K-8
LOCK ST. O-30
LOGAN ST. L-30
LYNDALE ST. I-31
LYNN RD. H-30
MADISON ST. N-30
MARKET ST. E-12
MARSHALL ST. I-14
MARY ST. I-21
McKEEN ST. L-21
MELROSE ST. O-30
MEMORIAL PKWY. I-18
MERCER ST. D-10
METZ ST. I-19
MEYNER RD. H-28
MILL ST. I-11
MILLER ST. I-11
MITCHELL AL. I-8
MORRIS ST. I-8
MOULE AL. I-21
NATALIE DRIVE J-32, K-
NELSON ST. I-14
NORTH AL. O-8
NO. MAIN ST. I-8
NO. RIVERVIEW RD. O-13
OAK AL. E-8
ORCHARD AL. E-8
PARK RD. K-24
PEACH ST. P-22
PEAR AL. P-29
PEARL ST. P-25
PERDOE AVE. L-11
PICKFORD AVE. L-6
PINE AL. B-10
PLEASANT AVE. I-10
POTTS AVE. I-11
PROSPECT ST. L-10
PURSEL ST. L-24
RAILROAD AVE. I-14
RANDALL ST. O-9
RAYMOND ST. B-9
REESE WAY B-14
REESE CT. B-14
RICHARD RD. K-21
RICHMOND ST. B-29
RIDGE ST. R-29
RIVER ST. C-16
RIVERSIDE WAY O-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. I-13
ROSE ST. O-8
ROSEBERRY ST. B-8
SARGENT AVE. O-11
SAWMILL ST. I-21
SAYRE AVE. K-23
SCHULTZ AVE. N-11
SHARPE AVE. O-8
SHERWOOD ST. O-30
SHILLINGER AL. I-14
SHIMER ST. B-11
SILK AVE. O-15
STIRGEAVES ST. O-27
SMITH AVE. O-20
SONORA ST. O-27
SO. MAIN ST. B-9
SPINNER AL. I-11
SPRUCE AL. E-18
ST. JOHN AL. I-14
STANLEY ST. O-29
STEELE ST. I-25
STEWART AL. O-29
STOCKTON ST. O-15
STRYKER ST. B-12
STULL AL. O-5
SUMMIT AVE. O-10
SUSAN ST. O-10
TAYLOR AL. I-12
TERRY ST. O-28
THIRD ST. B-11
THOMAS ST. B-9
TIGHE AL. I-9
TITUS AL. I-8
TUTTLE ST. I-7
TYNDALL AVE. I-25
UNION SQ. I-25
VALLEY VIEW CIR. O-28
WALNUT ST. B-18
WARREN ST. B-13
WASHINGTON ST. B-15
WATSON PL. B-13
WEBSTER ST. I-13
WILBUR AVE. N-22
WILLEVER ST. O-10
WILLIAM ST. N-24, K-
WILSON ST. I-12, K-
WIRE AL. O-26
WOODLAWN RD. I-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

M. Anthony
9-22-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. G-18
CENTER RD. G-32
CENTER ST. J-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-6
CHINTENIMIK AL. D-8
CHRISTIE AL. N-13
CHURCH ST. N-11
CLARMONT ST. D-31
COLBY PL. K-
COLUMBUS AVE. D-15
COMPRESSOR ST. D-23
COMSTOCK AL. N-14
CONGRESS ST. L-25
CORLISS AVE. L-23
CROSS ST. D-11
CULION ST. D-30
DAVIS ST. N-31
DEAN AL. L-29
DELAWARE RD. N-30
DIAMOCK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. K-14
ELM ST. K-19
ELMHURST DR. K-19
EMMA ST. K-30
ENDINE ST. K-22
ESSEX ST. D-11
EVELYN AVE. L-19
FAIRBANKS ST. N-13
FAIRVIEW AVE. D-8
FARM ST. L-17
FERGUSON ST. R-27
FILMORE ST. L-11
FIFTH ST. L-11
FIRST AL. L-27
FIRTH ST. K-27
FISHER AVE. D-10
FOCHT BRIDGE D-18
FORREST LN. L-7
FOURTH ST. L-10
FOX AL. N-5
FOX ST. B-17
FRACE ST. B-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. D-10
FROST AVE. D-10
FULTON ST. K-14
GATE ST. L-27
GLEN AVE. F-11
GRACE AVE. I-10
GRAND ST. D-29
GRANT ST. L-13
GREEN AL. L-11
GREEN ST. K-22
GREENWOOD ST. K-29
GRIFFITH AL. N-25
HAGERTY AVE. K-25
HANOVER ST. K-23
HARRIS ST. N-11
HARTE ST. D-8
HECKMAN ST. I-7
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. L-25
HILL ST. D-27
HILLCREST BLVD. D-16
HILLSIDE RD. D-12
HOWARD ST. D-11
HUDSON ST. D-12
INGERSOLL AVE. D-11
IRWIN ST. D-12
IVY ST. L-19
James P. BAKER WAY D-33
JAMES ST. L-19
JEFFERSON ST. L-16
JERSEY ST. L-14
JOHN ST. N-9
JOHN MITCHELL AVE. N-9
JOSEPH ST. I-2
JUDD AL. K-27
KAITLIN CT. L-30
KENT ST. L-16
KNEEDLER AVE. D-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. L-25
LAKE AL. L-
LENNON AL. L-
LESHER AL. L-
LEWIS ST. L-
LINCOLN RD. L-
LINCOLN ST. L-
LINER BLVD. D-8
LOCK ST. L-32
LOGAN ST. D-30
LYNDALE ST. N-31
LYNN RD. N-30
MADISON ST. N-30
MARKET ST. L-12
MARSHALL ST. L-14
MARY ST. L-14
McKEEN ST. K-21
MELROSE ST. K-21
MEMORIAL PKWY. L-31
MERCER ST. D-18
METZ ST. D-18
MEYNER RD. I-18
MILL ST. N-25
MILLER ST. I-11
MITCHELL AL. D-9
MORRIS ST. D-21
MOULE AL. J-32
NATALIE DRIVE K-
NELSON ST. N-30
NORTH AL. L-14
NO. MAIN ST. D-8
NO. RIVERVIEW RD. L-29
OAK AL. N-13
ORCHARD AL. K-24
PARK RD. K-22
PEACH ST. K-22
PEAR AL. D-11
PEARL ST. K-23
PEDRICK AVE. L-23
PICKFORD AVE. L-18
PINE AL. L-18
PLEASANT AVE. D-10
POTTS AVE. I-7
PROSPECT ST. N-10
PURSEL ST. L-24
RAILROAD AVE. D-14
RANDALL ST. L-10
RAYMOND ST. D-9
REESE WAY B-11
REESE CT. B-14
RICHARD RD. J-21
RICHMOND ST. R-28
RIDGE ST. R-29
RIVER ST. D-16
RIVERSIDE WAY C-27
RIVERVIEW CIR. L-29
RIVERVIEW RD. L-13
ROCK AL. L-22
ROSE ST. K-29
ROSEBERRY ST. N-25
SARGENT AVE. K-25
SAWMILL ST. K-23
SAYRE AVE. N-11
SCHULTZ AVE. D-8
SHAFER AVE. D-30
SHERWOOD ST. L-14
SHILLINGER AL. C-11
SHIMER ST. L-19
SILK AVE. G-20
STORGEAZES ST. D-9
SMITH AVE. D-9
SONORA ST. I-11
SQ. MAIN ST. L-16
SPINNER AL. K-14
SPRUCE AL. K-25
ST. JOHN AL. D-29
STANLEY ST. L-28
STEELE ST. D-25
STEWART AL. D-16
STOCKTON ST. L-12
STRYKER ST. D-8
STULL AL. D-10
SUMMIT AVE. L-
SUSAN ST. L-
TAYLOR AL. L-
TERRY ST. L-
THIRD ST. H-12
THOMAS ST. B-23
TIOHE AL. L-19
TITUS AL. L-14
TUTTLE ST. L-
TYNDALL AVE. B-11
UNION SQ. B-9
VALLEY VIEW CIR. K-28
WALNUT ST. K-20
WARREN ST. D-18
WASHINGTON ST. D-16
WATSON PL. L-33
WEBSTER ST. K-
WILBUR AVE. D-22
WILLEVOR ST. L-
WILLIAM ST. K-24
WILSON ST. K-
WISE AL. L-
WOODLAWN RD. L-28

9-22-22 Strips

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE O-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. G-6
CHRISTIE AL. N-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. E-11
COLUMBUS AVE. I-22
COMPRESSOR ST. E-11
COMSTOCK AL. N-11
CONGRESS ST. E-11
CORLISS AVE. E-11
CROSS ST. D-15
CULVON ST. D-25
DAVIS ST. H-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. G-14
ELM ST. P-10
ELMHURST DR. H-30
EMPIRE ST. P-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. O-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. I-7
FARM ST. F-27
FERGUSON ST. F-8
FILMORE ST. L-11
FIFTH ST. L-27
FIRST AL. K-27
FIRTH ST. K-13
FISHER AVE. P-16
FOOHT BRIDGE E-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. O-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. N-10
FREDERICK ST. O-10
FRONT ST. O-9
FROST AVE. B-9
FULTON ST. E-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-28
GRIFFITH AL. M-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. O-9
HARTE ST. O-9
HECKMAN ST. F-15
HEMLOCK ST. I-32
HENDERSON ST. I-26
HENSHAW CT. I-11
HILL ST. L-25
HILLCREST BLVD. K-9
HILLSIDE RD. O-27
HOWARD ST. O-16
HUDSON ST. O-12
INGERSOLL AVE. O-11
IRWIN ST. O-12
IVY ST. O-15
JAMES P. BAKER WAY O-32
JEFFERSON ST. J-23
JERSEY ST. E-19
JOHN ST. O-16
JOHN MITCHELL AVE. O-14
JOSEPH ST. N-9
JUDD AL. N-9
KAITLYN CT. I-5
KENT ST. P-27
KNEEDLER AVE. P-30
KNOLL VIEW DRIVE K-16
KORP AL. N-31
KURLAND AL. L-25
LAKE AL. L-11
LENNON AL. L-11
LESHER AL. L-11
LEWIS ST. L-11
LINCOLN RD. L-11
LINCOLN ST. L-11
LINER BLVD. L-11
LOCK ST. L-11
LOGAN ST. L-11
LYNDALE ST. L-11
LYNN RD. L-11
MADISON ST. L-11
MARKET ST. L-11
MARSHALL ST. L-11
MARY ST. L-11
McKEEN ST. L-11
MELROSE ST. L-11
MEMORIAL PKWY. L-11
MERCER ST. L-11
METZ ST. L-11
MEYNER RD. L-11
MILL ST. L-11
MILLER ST. L-11
MITCHELL AL. L-11
MORRIS ST. L-11
MOULE AL. L-11
NATALIE DRIVE L-11
NELSON ST. L-11
NORTH AL. L-11
NO. MAIN ST. L-11
NO. RIVERVIEW RD. L-11
OAK AL. L-11
ORCHARD AL. L-11
PARK RD. L-11
PEACH ST. L-11
PEAR AL. L-11
PEARL ST. L-11
PERIODE AVE. L-11
PICKFORD AVE. L-11
PINE AL. L-11
PLEASANTY AVE. L-11
POTTS AVE. L-11
PROSPECT ST. L-11
PURSEL ST. L-11
RAILROAD AVE. L-11
RANDALL ST. L-11
RAYMOND ST. L-11
REESE WAY L-11
REESE CT. L-11
RICHARD RD. L-11
RICHMOND ST. L-11
RIDGE ST. L-11
RIVER ST. L-11
RIVERSIDE WAY L-11
RIVERVIEW CIR. L-11
RIVERVIEW RD. L-11
ROCK AL. L-11
ROSE ST. L-11
ROSSBERRY ST. L-11
SARGENT AVE. L-11
SAWMILL ST. L-11
SAYRE AVE. L-11
SCHULTZ AVE. L-11
SHAFER AVE. L-11
SHERWOOD ST. L-11
SHILLINGER AL. L-11
SHIMER ST. L-11
SILK AVE. L-11
SITGREAVES ST. L-11
SMITH AVE. L-11
SONORA ST. L-11
SO. MAIN ST. L-11
SPINNER AL. L-11
SPRUCE AL. L-11
ST. JOHN AL. L-11
STANLEY ST. L-11
STEELE ST. L-11
STEWART AL. L-11
STOCKTON ST. L-11
STRYKER ST. L-11
STULL AL. L-11
SUMMIT AVE. L-11
SUSAN ST. L-11
TAYLOR AL. L-11
TERRY ST. L-11
THIRD ST. L-11
THOMAS ST. L-11
TICHE AL. L-11
TITUS AL. L-11
TUTTLE ST. L-11
TYNDALL AVE. L-11
UNION SQ. L-11
VALLEY VIEW CIR. L-11
WALNUT ST. L-11
WARREN ST. L-11
WASHINGTON ST. L-11
WATSON PL. L-11
WEBSTER ST. L-11
WILBUR AVE. L-11
WILLEVER ST. L-11
WILLIAM ST. L-11
WILSON ST. L-11
WISE PL. L-11
WOODLAWN RD. L-11

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

9/22/22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

U.S. ROUTE 22

U.S. HIGHWAY 22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CANHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. D-18
CENTER RD. D-32
CENTER ST. C-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-8
CHINTEWINK AL. E-13
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. D-31
COLBY PL. D-15
COLUMBUS AVE. D-25
COMPRESSOR ST. H-14
COMSTOCK AL. F-7
CONGRESS ST. H-14
CORLISS AVE. E-22
CROSS ST. D-15
CULKIN ST. D-25
DAVIS ST. H-14
DEAN AL. F-7
DELAWARE RD. F-31
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. E-11
ELIZABETH ST. B-11
ELLEN ST. D-14
ELM ST. D-14
ELMHURST DR. H-30
EMIRE ST. H-10
EMMA ST. K-22
ENGINE ST. E-11
ESSEX ST. L-19
EVELYN AVE. E-8
FAIRBANKS ST. F-7
FAIRVIEW AVE. L-27
FARM ST. K-24
FERGUSON ST. F-11
FILMORE ST. K-13
FIFTH ST. B-11
FIRST AL. H-27
FIRTH ST. K-13
FISHER AVE. D-16
FOCHT BRIDGE N-30
FORREST LA. N-29
FOURTH ST. N-29
FOX AL. B-17
FOX ST. C-7
FRACE ST. H-10
FRANCIS AVE. F-10
FRANKLIN ST. H-10
FREDERICK ST. H-10
FRONT ST. B-10
FROST AVE. H-14
FULTON ST. D-14
GATE ST. H-27
GLEN AVE. K-11
GRACE AVE. H-10
GRAND ST. D-29
GRANT ST. L-13
GREEN AL. L-21
GREEN ST. C-22
GREENWOOD ST. H-29
GRIFFITH AL. M-25
HAGERTY AVE. H-13
HANOVER ST. B-9
HARRIS ST. B-9
HARTE ST. D-11
HECKMAN ST. L-32
HEMLOCK ST. H-32
HENDERSON ST. D-11
HENSHAW CT. H-11
HILL ST. L-25
HILLCREST BLVD. H-11
HILLSIDE RD. K-27
HOWARD ST. D-8
HUDSON ST. D-12
INGERSOLL AVE. D-17
IRWIN ST. D-12
IVY ST. D-15
J. ALEXANDER WAY L-23
JAMES ST. M-23
JEFFERSON ST. L-19
JERSEY ST. D-16
JOHN ST. D-14
JOHN MITCHELL AVE. H-8
JOSEPH ST. E-8
JUDD AL. K-13
KAITLYN CT. H-27
KENT ST. L-30
KNEEDLER AVE. D-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. L-25
LAKE AL. K-8
LENNOX AL. D-32
LESHER AL. G-30
LEWIS ST. D-30
LINCOLN RD. K-20
LINCOLN ST. D-18
LINER BLVD. D-32
LOCK ST. G-30
LOGAN ST. H-31
LYNDALE ST. N-19
LYNN RD. N-30
MADISON ST. N-30
MARKET ST. D-12
MARSHALL ST. I-14
MARY ST. I-14
McKEEN ST. E-21
MELROSE ST. P-13
MEMORIAL PKWY. G-16
MERCER ST. G-10
METZ ST. H-10
MEYNER RD. I-19
MILL ST. M-25
MILLER ST. J-11
MITCHELL AL. D-10
MORRIS ST. B-8
MOULE AL. M-21
NATALIE DRIVE A-32, K-
NELSON ST. M-30
NORTH AL. I-14
NO. MAIN ST. C-8
NO. RIVERVIEW RD. M-29
OAK AL. H-13
ORCHARD AL. B-8
PARK RD. K-24
PEACH ST. K-22
PEAR AL. E-11
PEARL ST. E-11
PERDOE AVE. L-28
PICKFORD AVE. L-25
PINE AL. F-11
PLEASANT AVE. F-16
POTTS AVE. B-10
PROSPECT ST. B-11
PURSEL ST. M-10
RAILROAD AVE. M-24
RANDALL ST. I-14
RAYMOND ST. G-10
REESE WAY G-9
REESE CT. B-11
RICHARD RD. B-14
RICHMOND ST. K-21
RIDGE ST. N-29
RIVER ST. N-29
RIVERSIDE WAY C-7
RIVERVIEW CIR. C-27
RIVERVIEW RD. H-29
ROCK AL. M-8
ROSE ST. M-8
ROSEBERRY ST. G-9
SARGENT AVE. B-11
SAWMILL ST. K-25
SAYRE AVE. L-23
SCHULTZ AVE. H-11
SHAFER AVE. D-8
SHERWOOD ST. D-30
SHILLINGER AL. D-14
SHIMER ST. G-11
SILK AVE. C-15
STIRGEAVES ST. P-18
SMITH AVE. C-17
SOMORA ST. C-20
SQ. MAIN ST. G-20
SPINNER AL. B-9
SPRUCE AL. B-11
ST. JOHN AL. F-16
STANLEY ST. F-14
STEELE ST. G-29
STEWART AL. O-29
STOCKTON ST. N-28
STRYKER ST. G-16
STULL AL. D-12
SUMMIT AVE. D-8
SUSAN ST. D-10
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TIGHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WIRE AL.
WOODLAWN RD.

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

9-22-22
Tom C

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
BARRYMORE AVENUE
FROST AVENUE
BOWERS AVE.
HILLCREST AVENUE
PICKFORD STREET
METZ STREET
HARTE ST.
FRACE ST.
BURKE STREET
FREDERICK AVENUE
MORELL AVENUE
SARGENT AVENUE
JOHN STREET
INGERSOLL AVENUE
GRACE STREET
CORISS AVENUE
ELBERT AVENUE
FAIRBANKS STREET
MASERT ST.
FERGUSON ST.
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE AVENUE
DELAWARE ROAD
HALDRESS SOUTH
HALDRESS NORTH
POTTS AVE.
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
FISHER PLACE
KNEEDLER AVENUE
ANDERSON STREET
WATSON PLACE
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVENUE
BATES STREET
PROSPECT STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
HENDERSON STREET
SHULTZ AVE.
EVELYN AVE.
RAYMOND ST.
ORCHARD ALLEY
DAVIS PLACE
COLBY PLACE
STOCKTON STREET
HUDSON STREET
IRWIN STREET
FRANCIS AVE.
MILLER STREET
WEST BOUND AVENUE
EAST BOUND AVENUE
FOURTH STREET
THIRD STREET
BACH ST.
GLEN AVENUE
FILMORE STREET
LEWIS STREET
TAYLOR STREET
WASHINGTON STREET
SUMMIT AVE.
MITCHELL STREET
BULLMAN STREET
BURWELL STREET
BENNETT STREET
STULL ALLEY
CHAMBERS STREET
HARRIS STREET
SHIMER ST.
BRAINARD WAY
FRONT STREET
PLEASANT STREET
LAKE AL.
MARKET STREET
ELIZABETH ST.
STRYKER ST.
HANOVER STREET
RESSE COURT
MERCER STREET
HOWARD STREET
SOUTH MAIN STREET
SPRUCE ST.
CEDAR ST.
CHERRY ST.
CHESTNUT ST.
PEACH ST.
PEAR AL.
ORCHARD AL.
PARK RD.
PEARL ST.
PERIDOT AVE.
PICHFORD AVE.
PINE AL.
PLEASANT AVE.
POTTS AVE.
PROSPECT ST.
PURSEL ST.
RAILROAD AVE.
RANDALL ST.
RAYMOND ST.
REESE WAY
REESE CT.
RICHARD RD.
RICHMOND ST.
RIDGE ST.
RIVER ST.
RIVERSIDE WAY
RIVERVIEW CIR.
RIVERVIEW RD.
ROCK AL.
ROSE ST.
ROSEBERRY ST.
SARGENT AVE.
SAWMILL ST.
SAYRE AVENUE
SCHULTZ AVE.
SHAFER AVE.
SHERWOOD ST.
SHILLINGER AL.
SHIMER ST.
SILK AVE.
STIRGEAVES ST.
SMITH AVE.
SONORA ST.
SQ. MAIN ST.
SPRINGER AL.
SPRUCE AL.
ST. JOHN AL.
STANLEY ST.
STEELE ST.
STEWART AL.
STOCKTON ST.
STRYKER ST.
STULL AL.
SUMMIT AVE.
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TIGHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WIRE AL.
WOODLAWN RD.
GATE STREET
TUTTLE STREET
ARLINGTON ST.
RIDGE STREET
LOCK STREET
MELROSE STREET
STANLEY STREET
PEARL STREET
GRAND STREET
CONGRESS STREET
HILLSIDE ST.
KAITLYN CT.
MADISON STREET
LOGAN STREET
CLAWSON AVE.
LINCOLN AVE.
VALLEY VIEW DR.
KNOLL VIEW DRIVE
NATALIE DRIVE
RIVERVIEW CIR.
NORTH RIVERVIEW ROAD
WOODLAWN ROAD
FORREST LN.
BELT ROAD
ELMHURST DRIVE
CARPENTERSVILLE ROAD
DANLYN RD.
HEMLOCK DR.
CHERRY LANE
CHESTNUT ST.
CHAMBERS ST.
CENTER ST.
CENTER RD.
CEDAR AL.
CARPENTERSVILLE RD.
CAHILL ST.
CANAL WAY
MORRIS STREET
SAWMILL ST.
MAIN ST.
LIMEKILN ROAD
PURSEL STREET
KURLAND AL.
ALLAN STREET
MILL STREET
GRIFFITH ALLEY
WILBUR AVENUE
PERIDOT ALLEY
HILL STREET
BANK STREET
GARNART AL.
JAMES ST.
WILLIAM ST.
THOMAS STREET
ANN STREET
CENTER STREET
CHESTNUT ST.
PEACH ST.
WEBSTER ST.
PARK RD.
MOULE ALLEY
STEWART ALLEY
CURKIN STREET
ALLEY 1
ALLEY 2
ALLEY 3
ALLEY 4
ALLEY 5
ALLEY 6
ALLEY 7
ALLEY 8
ALLEY 9
ALLEY 10
ALLEY 11
ALLEY 12
ALLEY 13
ALLEY 14
ALLEY 15
ALLEY 16
ALLEY 17
ALLEY 18
ALLEY 19
ALLEY 20
ALLEY 21
ALLEY 22
ALLEY 23
ALLEY 24
ALLEY 25
ALLEY 26
ALLEY 27
ALLEY 28
ALLEY 29
ALLEY 30
ALLEY 31
ALLEY 32
ALLEY 33
ALLEY 34
ALLEY 35
ALLEY 36
ALLEY 37
ALLEY 38
ALLEY 39
ALLEY 40
ALLEY 41
ALLEY 42
ALLEY 43
ALLEY 44
ALLEY 45
ALLEY 46
ALLEY 47
ALLEY 48
ALLEY 49
ALLEY 50
ALLEY 51
ALLEY 52
ALLEY 53
ALLEY 54
ALLEY 55
ALLEY 56
ALLEY 57
ALLEY 58
ALLEY 59
ALLEY 60
ALLEY 61
ALLEY 62
ALLEY 63
ALLEY 64
ALLEY 65
ALLEY 66
ALLEY 67
ALLEY 68
ALLEY 69
ALLEY 70
ALLEY 71
ALLEY 72
ALLEY 73
ALLEY 74
ALLEY 75
ALLEY 76
ALLEY 77
ALLEY 78
ALLEY 79
ALLEY 80
ALLEY 81
ALLEY 82
ALLEY 83
ALLEY 84
ALLEY 85
ALLEY 86
ALLEY 87
ALLEY 88
ALLEY 89
ALLEY 90
ALLEY 91
ALLEY 92
ALLEY 93
ALLEY 94
ALLEY 95
ALLEY 96
ALLEY 97
ALLEY 98
ALLEY 99
ALLEY 100
ALLEY 101
ALLEY 102
ALLEY 103
ALLEY 104
ALLEY 105
ALLEY 106
ALLEY 107
ALLEY 108
ALLEY 109
ALLEY 110
ALLEY 111
ALLEY 112
ALLEY 113
ALLEY 114
ALLEY 115
ALLEY 116
ALLEY 117
ALLEY 118
ALLEY 119
ALLEY 120
ALLEY 121
ALLEY 122
ALLEY 123
ALLEY 124
ALLEY 125
ALLEY 126
ALLEY 127
ALLEY 128
ALLEY 129
ALLEY 130
ALLEY 131
ALLEY 132
ALLEY 133
ALLEY 134
ALLEY 135
ALLEY 136
ALLEY 137
ALLEY 138
ALLEY 139
ALLEY 140
ALLEY 141
ALLEY 142
ALLEY 143
ALLEY 144
ALLEY 145
ALLEY 146
ALLEY 147
ALLEY 148
ALLEY 149
ALLEY 150
ALLEY 151
ALLEY 152
ALLEY 153
ALLEY 154
ALLEY 155
ALLEY 156
ALLEY 157
ALLEY 158
ALLEY 159
ALLEY 160
ALLEY 161
ALLEY 162
ALLEY 163
ALLEY 164
ALLEY 165
ALLEY 166
ALLEY 167
ALLEY 168
ALLEY 169
ALLEY 170
ALLEY 171
ALLEY 172
ALLEY 173
ALLEY 174
ALLEY 175
ALLEY 176
ALLEY 177
ALLEY 178
ALLEY 179
ALLEY 180
ALLEY 181
ALLEY 182
ALLEY 183
ALLEY 184
ALLEY 185
ALLEY 186
ALLEY 187
ALLEY 188
ALLEY 189
ALLEY 190
ALLEY 191
ALLEY 192
ALLEY 193
ALLEY 194
ALLEY 195
ALLEY 196
ALLEY 197
ALLEY 198
ALLEY 199
ALLEY 200
ALLEY 201
ALLEY 202
ALLEY 203
ALLEY 204
ALLEY 205
ALLEY 206
ALLEY 207
ALLEY 208
ALLEY 209
ALLEY 210
ALLEY 211
ALLEY 212
ALLEY 213
ALLEY 214
ALLEY 215
ALLEY 216
ALLEY 217
ALLEY 218
ALLEY 219
ALLEY 220
ALLEY 221
ALLEY 222
ALLEY 223
ALLEY 224
ALLEY 225
ALLEY 226
ALLEY 227
ALLEY 228
ALLEY 229
ALLEY 230
ALLEY 231
ALLEY 232
ALLEY 233
ALLEY 234
ALLEY 235
ALLEY 236
ALLEY 237
ALLEY 238
ALLEY 239
ALLEY 240
ALLEY 241
ALLEY 242
ALLEY 243
ALLEY 244
ALLEY 245
ALLEY 246
ALLEY 247
ALLEY 248
ALLEY 249
ALLEY 250
ALLEY 251
ALLEY 252
ALLEY 253
ALLEY 254
ALLEY 255
ALLEY 256
ALLEY 257
ALLEY 258
ALLEY 259
ALLEY 260
ALLEY 261
ALLEY 262
ALLEY 263
ALLEY 264
ALLEY 265
ALLEY 266
ALLEY 267
ALLEY 268
ALLEY 269
ALLEY 270
ALLEY 271
ALLEY 272
ALLEY 273
ALLEY 274
ALLEY 275
ALLEY 276
ALLEY 277
ALLEY 278
ALLEY 279
ALLEY 280
ALLEY 281
ALLEY 282
ALLEY 283
ALLEY 284
ALLEY 285
ALLEY 286
ALLEY 287
ALLEY 288
ALLEY 289
ALLEY 290
ALLEY 291
ALLEY 292
ALLEY 293
ALLEY 294
ALLEY 295
ALLEY 296
ALLEY 297
ALLEY 298
ALLEY 299
ALLEY 300
ALLEY 301
ALLEY 302
ALLEY 303
ALLEY 304
ALLEY 305
ALLEY 306
ALLEY 307
ALLEY 308
ALLEY 309
ALLEY 310
ALLEY 311
ALLEY 312
ALLEY 313
ALLEY 314
ALLEY 315
ALLEY 316
ALLEY 317
ALLEY 318
ALLEY 319
ALLEY 320
ALLEY 321
ALLEY 322
ALLEY 323
ALLEY 324
ALLEY 325
ALLEY 326
ALLEY 327
ALLEY 328
ALLEY 329
ALLEY 330
ALLEY 331
ALLEY 332
ALLEY 333
ALLEY 334
ALLEY 335
ALLEY 336
ALLEY 337
ALLEY 338
ALLEY 339
ALLEY 340
ALLEY 341
ALLEY 342
ALLEY 343
ALLEY 344
ALLEY 345
ALLEY 346
ALLEY 347
ALLEY 348
ALLEY 349
ALLEY 350
ALLEY 351
ALLEY 352
ALLEY 353
ALLEY 354
ALLEY 355
ALLEY 356
ALLEY 357
ALLEY 358
ALLEY 359
ALLEY 360
ALLEY 361
ALLEY 362
ALLEY 363
ALLEY 364
ALLEY 365
ALLEY 366
ALLEY 367
ALLEY 368
ALLEY 369
ALLEY 370
ALLEY 371
ALLEY 372
ALLEY 373
ALLEY 374
ALLEY 375
ALLEY 376
ALLEY 377
ALLEY 378
ALLEY 379
ALLEY 380
ALLEY 381
ALLEY 382
ALLEY 383
ALLEY 384
ALLEY 385
ALLEY 386
ALLEY 387
ALLEY 388
ALLEY 389
ALLEY 390
ALLEY 391
ALLEY 392
ALLEY 393
ALLEY 394
ALLEY 395
ALLEY 396
ALLEY 397
ALLEY 398
ALLEY 399
ALLEY 400
ALLEY 401
ALLEY 402
ALLEY 403
ALLEY 404
ALLEY 405
ALLEY 406
ALLEY 407
ALLEY 408
ALLEY 409
ALLEY 410
ALLEY 411
ALLEY 412
ALLEY 413
ALLEY 414
ALLEY 415
ALLEY 416
ALLEY 417
ALLEY 418
ALLEY 419
ALLEY 420
ALLEY 421
ALLEY 422
ALLEY 423
ALLEY 424
ALLEY 425
ALLEY 426
ALLEY 427
ALLEY 428
ALLEY 429
ALLEY 430
ALLEY 431
ALLEY 432
ALLEY 433
ALLEY 434
ALLEY 435
ALLEY 436
ALLEY 437
ALLEY 438
ALLEY 439
ALLEY 440
ALLEY 441
ALLEY 442
ALLEY 443
ALLEY 444
ALLEY 445
ALLEY 446
ALLEY 447
ALLEY 448
ALLEY 449
ALLEY 450
ALLEY 451
ALLEY 452
ALLEY 453
ALLEY 454
ALLEY 455
ALLEY 456
ALLEY 457
ALLEY 458
ALLEY 459
ALLEY 460
ALLEY 461
ALLEY 462
ALLEY 463
ALLEY 464
ALLEY 465
ALLEY 466
ALLEY 467
ALLEY 468
ALLEY 469
ALLEY 470
ALLEY 471
ALLEY 472
ALLEY 473
ALLEY 474
ALLEY 475
ALLEY 476
ALLEY 477
ALLEY 478
ALLEY 479
ALLEY 480
ALLEY 481
ALLEY 482
ALLEY 483
ALLEY 484
ALLEY 485
ALLEY 486
ALLEY 487
ALLEY 488
ALLEY 489
ALLEY 490
ALLEY 491
ALLEY 492
ALLEY 493
ALLEY 494
ALLEY 495
ALLEY 496
ALLEY 497
ALLEY 498
ALLEY 499
ALLEY 500
ALLEY 501
ALLEY 502
ALLEY 503
ALLEY 504
ALLEY 505
ALLEY 506
ALLEY 507
ALLEY 508
ALLEY 509
ALLEY 510
ALLEY 511
ALLEY 512
ALLEY 513
ALLEY 514
ALLEY 515
ALLEY 516
ALLEY 517
ALLEY 518
ALLEY 519
ALLEY 520
ALLEY 521
ALLEY 522
ALLEY 523
ALLEY 524
ALLEY 525
ALLEY 526
ALLEY 527
ALLEY 528
ALLEY 529
ALLEY 530
ALLEY 531
ALLEY 532
ALLEY 533
ALLEY 534
ALLEY 535
ALLEY 536
ALLEY 537
ALLEY 538
ALLEY 539
ALLEY 540
ALLEY 541
ALLEY 542
ALLEY 543
ALLEY 544
ALLEY 545
ALLEY 546
ALLEY 547
ALLEY 548
ALLEY 549
ALLEY 550
ALLEY 551
ALLEY 552
ALLEY 553
ALLEY 554
ALLEY 555
ALLEY 556
ALLEY 557
ALLEY 558
ALLEY 559
ALLEY 560
ALLEY 561
ALLEY 562
ALLEY 563
ALLEY 564
ALLEY 565
ALLEY 566
ALLEY 567
ALLEY 568
ALLEY 569
ALLEY 570
ALLEY 571
ALLEY 572
ALLEY 573
ALLEY 574
ALLEY 575
ALLEY 576
ALLEY 577
ALLEY 578
ALLEY 579
ALLEY 580
ALLEY 581
ALLEY 582
ALLEY 583
ALLEY 584
ALLEY 585
ALLEY 586
ALLEY 587
ALLEY 588
ALLEY 589
ALLEY 590
ALLEY 591
ALLEY 592
ALLEY 593
ALLEY 594
ALLEY 595
ALLEY 596
ALLEY 597
ALLEY 598
ALLEY 599
ALLEY 600
ALLEY 601
ALLEY 602
ALLEY 603
ALLEY 604
ALLEY 605
ALLEY 606
ALLEY 607
ALLEY 608
ALLEY 609
ALLEY 610
ALLEY 611
ALLEY 612
ALLEY 613
ALLEY 614
ALLEY 615
ALLEY 616
ALLEY 617
ALLEY 618
ALLEY 619
ALLEY 620
ALLEY 621
ALLEY 622
ALLEY 623
ALLEY 624
ALLEY 625
ALLEY 626
ALLEY 627
ALLEY 628
ALLEY 629
ALLEY 630
ALLEY 631
ALLEY 632
ALLEY 633
ALLEY 634
ALLEY 635
ALLEY 636
ALLEY 637
ALLEY 638
ALLEY 639
ALLEY 640
ALLEY 641
ALLEY 642
ALLEY 643
ALLEY 644
ALLEY 645
ALLEY 646
ALLEY 647
ALLEY 648
ALLEY 649
ALLEY 650
ALLEY 651
ALLEY 652
ALLEY 653
ALLEY 654
ALLEY 655
ALLEY 656
ALLEY 657
ALLEY 658
ALLEY 659
ALLEY 660
ALLEY 661
ALLEY 662
ALLEY 663
ALLEY 664
ALLEY 665
ALLEY 666
ALLEY 667
ALLEY 668
ALLEY 669
ALLEY 670
ALLEY 671
ALLEY 672
ALLEY 673
ALLEY 674
ALLEY 675
ALLEY 676
ALLEY 677
ALLEY 678
ALLEY 679
ALLEY 680
ALLEY 681
ALLEY 682
ALLEY 683
ALLEY 684
ALLEY 685
ALLEY 686
ALLEY 687
ALLEY 688
ALLEY 689
ALLEY 690
ALLEY 691
ALLEY 692
ALLEY 693
ALLEY 694
ALLEY 695
ALLEY 696
ALLEY 697
ALLEY 698
ALLEY 699
ALLEY 700
ALLEY 701
ALLEY 702
ALLEY 703
ALLEY 704
ALLEY 705
ALLEY 706
ALLEY 707
ALLEY 708
ALLEY 709
ALLEY 710
ALLEY 711
ALLEY 712
ALLEY 713
ALLEY 714
ALLEY 715
ALLEY 716
ALLEY 717
ALLEY 718
ALLEY 719
ALLEY 720
ALLEY 721
ALLEY 722
ALLEY 723
ALLEY 724
ALLEY 725
ALLEY 726
ALLEY 727
ALLEY 728
ALLEY 729
ALLEY 730
ALLEY 731
ALLEY 732
ALLEY 733
ALLEY 734
ALLEY 735
ALLEY 736
ALLEY 737
ALLEY 738
ALLEY 739
ALLEY 740
ALLEY 741
ALLEY 742
ALLEY 743
ALLEY 744
ALLEY 745
ALLEY 746
ALLEY 747
ALLEY 748
ALLEY 749
ALLEY 750
ALLEY 751
ALLEY 752
ALLEY 753
ALLEY 754
ALLEY 755
ALLEY 756
ALLEY 757
ALLEY 758
ALLEY 759
ALLEY 760
ALLEY 761
ALLEY 762
ALLEY 763
ALLEY 764
ALLEY 765
ALLEY 766
ALLEY 767
ALLEY 768
ALLEY 769
ALLEY 770
ALLEY 771
ALLEY 772
ALLEY 773
ALLEY 774
ALLEY 775
ALLEY 776
ALLEY 777
ALLEY 778
ALLEY 779
ALLEY 780
ALLEY 781
ALLEY 782
ALLEY 783
ALLEY 784
ALLEY 785
ALLEY 786
ALLEY 787
ALLEY 788
ALLEY 789
ALLEY 790
ALLEY 791
ALLEY 792
ALLEY 793
ALLEY 794
ALLEY 795
ALLEY 796
ALLEY 797
ALLEY 798
ALLEY 799
ALLEY 800
ALLEY 801
ALLEY 802
ALLEY 803
ALLEY 804
ALLEY 805
ALLEY 806
ALLEY 807
ALLEY 808
ALLEY 809
ALLEY 810
ALLEY 811
ALLEY 812
ALLEY 813
ALLEY 814
ALLEY 815
ALLEY 816
ALLEY 817
ALLEY 818
ALLEY 819
ALLEY 820
ALLEY 821
ALLEY 822
ALLEY 823
ALLEY 824
ALLEY 825
ALLEY 826
ALLEY 827
ALLEY 828
ALLEY 829
ALLEY 830
ALLEY 831
ALLEY 832
ALLEY 833
ALLEY 834
ALLEY 835
ALLEY 836
ALLEY 837
ALLEY 838
ALLEY 839
ALLEY 840
ALLEY 841
ALLEY 842
ALLEY 843
ALLEY 844
ALLEY 845
ALLEY 846
ALLEY 847
ALLEY 848
ALLEY 849
ALLEY 850
ALLEY 851
ALLEY 852
ALLEY 853
ALLEY 854
ALLEY 855
ALLEY 856
ALLEY 857
ALLEY 858
ALLEY 859
ALLEY 860
ALLEY 861
ALLEY 862
ALLEY 863
ALLEY 864
ALLEY 865
ALLEY 866
ALLEY 867
ALLEY 868
ALLEY 869
ALLEY 870
ALLEY 871
ALLEY 872
ALLEY 873
ALLEY 874
ALLEY 875
ALLEY 876
ALLEY 877
ALLEY 878
ALLEY 879
ALLEY 880
ALLEY 881
ALLEY 882
ALLEY 883
ALLEY 884
ALLEY 885
ALLEY 886
ALLEY 887
ALLEY 888
ALLEY 889
ALLEY 890
ALLEY 891
ALLEY 892
ALLEY 893
ALLEY 894
ALLEY 895
ALLEY 896
ALLEY 897
ALLEY 898
ALLEY 899
ALLEY 900
ALLEY 901
ALLEY 902
ALLEY 903
ALLEY 904
ALLEY 905
ALLEY 906
ALLEY 907
ALLEY 908
ALLEY 909
ALLEY 910
ALLEY 911
ALLEY 912
ALLEY 913
ALLEY 914
ALLEY 915
ALLEY 916
ALLEY 917
ALLEY 918
ALLEY 919
ALLEY 920
ALLEY 921
ALLEY 922
ALLEY 923
ALLEY 924
ALLEY 925
ALLEY 926
ALLEY 927
ALLEY 928
ALLEY 929
ALLEY 930
ALLEY 931
ALLEY 932
ALLEY 933
ALLEY 934
ALLEY 935
ALLEY 936
ALLEY 937
ALLEY 938
ALLEY 939
ALLEY 940
ALLEY 941
ALLEY 942
ALLEY 943
ALLEY 944
ALLEY 945
ALLEY 946
ALLEY 947
ALLEY 948
ALLEY 949
ALLEY 950
ALLEY 951
ALLEY 952
ALLEY 953
ALLEY 954
ALLEY 955
ALLEY 956
ALLEY 957
ALLEY 958
ALLEY 959
ALLEY 960
ALLEY 961
ALLEY 962
ALLEY 963
ALLEY 964
ALLEY 965
ALLEY 966
ALLEY 967
ALLEY 968
ALLEY 969
ALLEY 970
ALLEY 971
ALLEY 972
ALLEY 973
ALLEY 974
ALLEY 975
ALLEY 976
ALLEY 977
ALLEY 978
ALLEY 979
ALLEY 980
ALLEY 981
ALLEY 982
ALLEY 983
ALLEY 984
ALLEY 985
ALLEY 986
ALLEY 987
ALLEY 988
ALLEY 989
ALLEY 990
ALLEY 991
ALLEY 992
ALLEY 993
ALLEY 994
ALLEY 995
ALLEY 996
ALLEY 997
ALLEY 998
ALLEY 999
ALLEY 1000

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

10/4/22

Duckworth

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

WALNUT STREET

COLUMBUS AVENUE

PROSPECT STREET

LINCOLN ROAD

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

HENDERSON

MARKET ST.

ELIZABETH ST.

HOWARD

MERCER STREET

SAYRE AVENUE

CANAL WAY

MORRIS

SOUTH MAIN STREET

NORTH MAIN STREET

STANLEY STREET

LOGAN STREET

PEARL ST.

GRAND ST.

MADISON STREET

WOODLAWN ROAD

RIVERVIEW CIR.

RIVERVIEW ROAD

FOREST LN.

BELT ROAD

CARPENTERSVILLE ROAD

ELMHURST ROAD

OAKLYN RD.

HEMLOCK DR.

NATALIE DRIVE

LINCOLN HWY.


METNER ROAD

RICHARD RD.

CAHILL ST.

LYNN RD.

BRAINARD ST. O-11
BROAD ST. O-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARMART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. G-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. O-9
CHINA AL. L-21
CHINTENWAK AL. O-5
CHRISTIE AL. K-13
CHURCH ST. B-11
CLAIRMONT ST. C-31
COLBY PL. H-11
COLUMBUS AVE. O-13
COMPRESSOR ST. O-25
CONESTOCK AL. O-14
CONGRESS ST. K-11
CORLISS AVE. O-11
CROSS ST. O-18
CULVON ST. O-9
DAVIS ST. O-9
DEAN AL. L-21
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. K-11
ELDER AVE. K-11
ELIZABETH ST. B-11
ELLEN ST. B-14
ELM ST. B-19
ELMHURST DR. H-30
EMBIE ST. H-10
EMMA ST. K-22
ENGINE ST. K-11
ESSEX ST. O-18
EVELYN AVE. O-11
FAIRBANKS ST. O-9
FAIRVIEW AVE. O-9
FARM ST. K-27
FERGUSON ST. I-8
FILMORE ST. I-11
FIFTH ST. I-14
FIRST AL. I-27
FIRTH ST. I-13
FISHER AVE. K-28
FOCHT BRIDGE I-7
FORREST LA. I-30
FOURTH ST. K-5
FOX AL. K-6
FOX ST. K-17
FRACE ST. I-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. I-10
FROST AVE. I-9
FULTON ST. K-14
GATE ST. K-27
GLEN AVE. K-11
GRACE AVE. K-10
GRAND ST. K-29
GRANT ST. K-13
GREEN AL. K-11
GREEN ST. K-22
GREENWOOD ST. K-29
GRIFFITH AL. K-25
HAGERTY AVE. I-7
HANOVER ST. N-13
HARRIS ST. I-9
HARTE ST. I-7
HECKMAN ST. I-15
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. I-11
HILL ST. I-25
HILLCREST BLVD. I-9
HILLSIDE RD. K-27
HOWARD ST. I-16
HUDSON ST. I-12
INGERSOLL AVE. I-11
IRWIN ST. I-15
IVY ST. I-15
J. J. BAKER WAY I-23
JAMES ST. I-23
JEFFERSON ST. I-16
JERSEY ST. I-14
JOHN ST. I-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. I-9
JUDD AL. I-5
KAITLYN CT. K-27
KENT ST. I-30
KNEEDLER AVE. I-16
KNOLL VIEW DRIVE I-31
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. I-25
LENNON AL. I-25
LESHER AL. I-25
LEWIS ST. I-25
LIMEKILN RD. I-25
LINCOLN ST. I-25
LINER BLVD. I-25
LOCK ST. I-25
LOGAN ST. I-25
LYNDALE ST. I-25
LYNN RD. I-25
MADISON ST. I-25
MARKET ST. I-25
MARSHALL ST. I-14
MARY ST. I-14
McKEON ST. E-31
MELROSE ST. I-13
MEMORIAL PKWY. I-13
MERCER ST. I-18
METZ ST. I-18
MEYNER RD. I-18
MILL ST. I-25
MILLER ST. I-11
MITCHELL AL. I-11
MORRIS ST. I-8
MOULE AL. I-21
NATALIE DRIVE I-30
NELSON ST. I-30
NORTH AL. I-30
NO. MAIN ST. I-8
NO. RIVERVIEW RD. I-28
OAK AL. I-13
ORCHARD AL. I-9
PARK RD. I-24
PEACH ST. I-22
PEAR AL. I-29
PEARL ST. I-29
PERDOE AVE. I-25
PICKFORD AVE. I-25
PINE AL. I-16
PLEASANT AVE. I-10
POTTS AVE. I-10
PROSPECT ST. I-10
PURSEL ST. I-14
RAILROAD AVE. I-14
RANDALL ST. I-14
RAYMOND ST. I-14
REESE WAY I-27
REESE CT. I-27
RICHARD RD. I-27
RICHMOND ST. I-28
RIDGE ST. I-28
RIVER ST. I-28
RIVERSIDE WAY I-28
RIVERVIEW CIR. I-28
RIVERVIEW RD. I-28
ROCK AL. I-28
ROSE ST. I-28
ROSEBERRY ST. I-28
SARGENT AVE. I-28
SAWMILL ST. I-28
SAYRE AVE. I-28
SCHULTZ AVE. I-28
SHAFER AVE. I-28
SHERWOOD ST. I-28
SHILLINGER AL. I-28
SHIMER ST. I-28
SILK AVE. I-28
SITGREAVES ST. I-28
SMITH AVE. I-28
SONOMA ST. I-28
SO. MAIN ST. I-28
SPINNER AL. I-28
SPRUCE AL. I-28
ST. JOHN AL. I-28
STANLEY ST. I-28
STEELE ST. I-28
STEWART AL. I-28
STOCKTON ST. I-28
STRYKER ST. I-28
STULL AL. I-28
SUMMIT AVE. I-28
SUSAN ST. I-28
TAYLOR AL. I-28
TERRY ST. I-28
THIRD ST. I-28
THOMAS ST. I-28
TIGHE AL. I-28
TITUS AL. I-28
TUTTLE ST. I-28
TYNDALL AVE. I-28
UNION SQ. I-28
VALLEY VIEW CIR. I-28
WALNUT ST. I-28
WARREN ST. I-28
WASHINGTON ST. I-28
WATSON PL. I-28
WEBSTER ST. I-28
WILBUR AVE. I-28
WILLEVER ST. I-28
WILLIAM ST. I-28
WILSON ST. I-28
WISE AL. I-28
WOODLAWN RD. I-28



USROPONML
IGFEDCBA

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

10/17/22

Snyder & Summit

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET

BARRYMORE AVENUE

FROST AVENUE

BOWERS AVE.

HILLCREST STREET

PICKFORD STREET

METZ STREET

HARTE ST.

FRACE STREET

BURKE STREET

FREDERICK STREET

SARGENT AVENUE

FAIRBANKS STREET

WASHINGTON BOULEVARD

JOHN STREET

GRACE STREET

CORLISS AVENUE

ELDER AVENUE

SUSAN ST.

TAYLOR STREET

THRESHOLD AVENUE

SUPPRESSOR STREET

PROSPECT STREET

LINCOLN ROAD

FERGUSON ST.

LINER BLVD.

TILDRESS SOUTH

TILDRESS NORTH

BELVIDERE AVENUE

DELAWARE ROAD

MEMORIAL PARKWAY (RT. 22)

MARSHALL STREET

HECKMAN STREET

FISHER PLACE

KNEEDLER AVENUE

WATSON STREET

ANDERSON STREET

BATES STREET

LINCOLN STREET

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

STOCKTON STREET

ESSEX STREET

IRWIN STREET

MILLER STREET

HENDERSON STREET

SHULTZ AVE.

EVELYN AVE.

RAYMOND ST.

ORCHARD ALLEY

FOURTH STREET

THIRD STREET

MAIN STREET

SOUTH STREET

MARKET STREET

ELIZABETH ST.

HARRIS STREET

CHAMBERS STREET

BULLMAN STREET

BURWELL STREET

BENNETT STREET

MITCHELL STREET

SUMMIT AVE.

SHIMER ST.

BRAINARD STREET

FRONT STREET

PLEASANT STREET

WASHINGTON STREET

HOWARD STREET

MERCER STREET

HANOVER STREET

BESSE COURT

WALNUT STREET

ELM STREET

GREEN STREET

COLUMBUS AVENUE

CAHILL ST.

RICHARD RD.

SAYRE AVENUE

WILBUR AVENUE

MILL STREET

GRIFFITH ALLEY

PERDOE ALLEY

HILL STREET

BANK STREET

MEYNER ROAD

LINCOLN ROAD

CENTER STREET

CHESTNUT STREET

THOMAS STREET

ANN STREET

JAMES STREET

PURSEL STREET

WILLIAM ST.

MADISON STREET

CONGRESS STREET

HILLSIDE

KAITLYN CT.

GATE STREET

TUTTLE STREET

TYNDALL AVE.

RIDGE STREET

LOCK STREET

MELROSE STREET

STANLEY STREET

PEARL STREET

GRAND STREET

LOGAN STREET

LYNDALE ST.

OLD MILL ROAD

VALLEY VIEW CIR.

GREENWOOD ST.

SYCAMORE ST.

BROADVIEW ST.

BARTLEY CIR.

KENT STREET

NORTH MAIN ST.

CANAL WAY

MORRIS STREET

SAWMILL ST.

ABBOTT ST.

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW ROAD

WOODLAWN ROAD

FOREST LN.

BELT AVE.

ELMHURST DRIVE

NATALIE DRIVE

CARPENTERSVILLE ROAD

OAKLYN RD.

HEMLOCK DR.

HEMLOCK CIRCLE

NORTH MAIN ST.

SOUTH MAIN ST.

MORRIS CANAL


DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

I-78

BRAINARD ST.	C-11
BROAD ST.	C-6
BROADVIEW ST.	N-32
BULLMAN ST.	D-9
BURKE ST.	D-9
BURWELL AL.	D-9
CAHILL ST.	K-20
CARHART AL.	L-28
CARPENTERSVILLE RD.	K-31
CEDAR AL.	E-18
CENTER RD.	L-32
CENTER ST.	L-32
CHAMBERS ST.	D-11
CHERRY LANE	L-18
CHESTNUT ST.	L-21
CHINA AL.	D-5
CHINTZWINK AL.	E-6
CHRISTIE AL.	H-5
CHURCH ST.	D-11
CLARMONT ST.	L-31
COLBY PL.	D-15
COLUMBUS AVE.	L-15
COMPRESSOR ST.	N-
COMSTOCK AL.	Z-1
CONGRESS ST.	D-25
CORLISS AVE.	K-14
CROSS ST.	K-11
CULVON ST.	K-5
DAVIS ST.	K-13
DEAN AL.	N-11
DELAWARE RD.	N-11
DIAMOND AL.	K-11
DRILL ST.	N-11
DUGAN AL.	L-11
ELDER AVE.	B-7
ELIZABETH ST.	B-11
ELLEN ST.	B-14
ELM ST.	B-18
ELMHURST DR.	B-19
EMIRE ST.	B-30
EMMA ST.	N-22
ENGINE ST.	B-5
ESSEX ST.	L-19
EVELYN AVE.	L-11
FAIRBANKS ST.	L-8
FAIRVIEW AVE.	L-7
FARM ST.	B-27
FERGUSON ST.	L-11
FILMORE ST.	B-11
FIFTH ST.	B-9
FIRST AL.	B-27
FIRTH ST.	L-13
FISHER AVE.	B-18
FOCHT BRIDGE	L-30
FORREST LA.	L-30
FOURTH ST.	B-5
FOX AL.	B-8
FOX ST.	L-17
FRACE ST.	L-10
FRANCIS AVE.	L-10
FRANKLIN ST.	L-10
FREDERICK ST.	L-10
FRONT ST.	L-10
FROST AVE.	L-9
FULTON ST.	L-14
GATE ST.	L-27
GLEN AVE.	L-11
GRACE AVE.	L-9
GRAND ST.	L-29
GRANT ST.	L-13
GREEN AL.	L-11
GREEN ST.	L-22
GREENWOOD ST.	L-29
GRIFFITH AL.	L-25
HAGERTY AVE.	L-7
HANOVER ST.	L-13
HARRIS ST.	L-9
HARTE ST.	L-9
HECKMAN ST.	L-11
HEMLOCK ST.	L-32
HENDERSON ST.	L-11
HENSHAW CT.	L-11
HILL ST.	L-25
HILLCREST BLVD.	L-9
HILLSIDE RD.	L-27
HOWARD ST.	L-16
HUDSON ST.	L-12
INGERSOLL AVE.	L-12
IRWIN ST.	L-12
IVY ST.	L-19
JAMES ST.	L-19
JEFFERSON ST.	L-19
JERSEY ST.	L-19
JOHN ST.	L-14
JOHN MITCHELL AVE.	N-9
JOSEPH ST.	L-9
JUDD AL.	L-14
KAITLYN CT.	L-27
KENT ST.	L-30
KNEEDLER AVE.	L-16
KNOLL VIEW DRIVE	L-31
KORP AL.	L-25
KURLAND AL.	L-25
LAKE AL.	L-15
LENNOX AL.	L-32
LESHER AL.	L-32
LEWIS ST.	L-32
LINDSLIN RD.	L-32
LINCOLN RD.	L-32
LINCOLN ST.	L-32
LINER BLVD.	L-32
LOCK ST.	L-22
LOGAN ST.	L-22
LYNDALE ST.	L-30
LYNN RD.	N-30
MADISON ST.	L-30
MARKET ST.	L-14
MARSHALL ST.	L-14
MARY ST.	L-14
McKEEN ST.	L-14
MELROSE ST.	L-14
MEMORIAL PKWY.	L-14
MERCER ST.	L-14
METZ ST.	L-14
MEYNER RD.	L-14
MILL ST.	L-25
MILLER ST.	L-25
MITCHELL AL.	L-25
MORRIS ST.	L-25
MOULE AL.	L-25
NATALIE DRIVE	L-32
NELSON ST.	L-32
NORTH AL.	L-32
NO. MAIN ST.	L-32
NO. RIVERVIEW RD.	L-32
OAK AL.	L-32
ORCHARD AL.	L-32
PARK RD.	L-32
PEACH ST.	L-32
PEAR AL.	L-32
PEARL ST.	L-32
PERDOE AVE.	L-32
PICKFORD AVE.	L-32
PINE AL.	L-32
PLEASANT AVE.	L-32
POTTS AVE.	L-32
PROSPECT ST.	L-32
PURSEL ST.	L-32
RAILROAD AVE.	L-32
RANDALL ST.	L-32
RAYMOND ST.	L-32
REESE WAY	L-32
REESE CT.	L-32
RICHARD RD.	L-32
RICHMOND ST.	L-32
RIDGE ST.	L-32
RIVER ST.	L-32
RIVERSIDE WAY	L-32
RIVERVIEW CIR.	L-32
RIVERVIEW RD.	L-32
ROCK AL.	L-32
ROSE ST.	L-32
ROSEBERRY ST.	L-32
SARGENT AVE.	L-32
SAWMILL ST.	L-32
SAYRE AVE.	L-32
SCHULTZ AVE.	L-32
SHAFER AVE.	L-32
SHERWOOD ST.	L-32
SHILLINGER AL.	L-32
SHIMER ST.	L-32
SILK AVE.	L-32
STIRGEAVES ST.	L-32
SMITH AVE.	L-32
SONORA ST.	L-32
SO. MAIN ST.	L-32
SPINNER AL.	L-32
SPRUCE AL.	L-32
ST. JOHN AL.	L-32
STANLEY ST.	L-32
STEELE ST.	L-32
STEWART AL.	L-32
STOCKTON ST.	L-32
STRYKER ST.	L-32
STULL AL.	L-32
SUMMIT AVE.	L-32
SUSAN ST.	L-32
TAYLOR AL.	L-32
TERRY ST.	L-32
THIRD ST.	L-32
THOMAS ST.	L-32
TIGHE AL.	L-32
TITUS AL.	L-32
TUTTLE ST.	L-32
TYNDALL AVE.	L-32
UNION SQ.	L-32
VALLEY VIEW CIR.	L-32
WALNUT ST.	L-32
WARREN ST.	L-32
WASHINGTON ST.	L-32
WATSON PL.	L-32
WEBSTER ST.	L-32
WILBUR AVE.	L-32
WILLEVA ST.	L-32
WILLIAM ST.	L-32
WILSON ST.	L-32
WISE AL.	L-32
WOODLAWN RD.	L-32



Snyder & Pugh
10-24-22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. O-18
CENTER RD. O-32
CENTER ST. L-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-5
CHINTEWINK AL. D-6
CHRISTIE AL. D-13
CHURCH ST. B-11
CLAIRMONT ST. O-31
COLBY PL. N-15
COLUMBUS AVE. J-25
COMPRESSOR ST. F-14
COMSTOCK AL. F-11
CONGRESS ST. K-11
CORLISS AVE. K-11
CROSS ST. K-5
CULVON ST. K-13
DAMS ST. K-13
DEAN AL. K-11
DELAWARE RD. K-11
DIMMICK AL. B-11
DRILL ST. B-11
DUGAN AL. B-14
ELDER AVE. B-14
ELIZABETH ST. B-14
ELLEN ST. B-14
ELM ST. B-18
ELMHURST DR. N-30
EMIRE ST. N-10
EMMA ST. N-22
ENGINE ST. K-19
ESSEX ST. K-19
EVELYN AVE. K-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. O-8
FARM ST. K-27
FERGUSON ST. B-8
FILMORE ST. F-11
FIFTH ST. F-11
FIRST AL. F-27
FIRTH ST. F-13
FISHER AVE. K-13
FOCHT BRIDGE N-18
FORREST LA. N-7
FOURTH ST. N-7
FOX AL. K-5
FOX ST. F-8
FRACE ST. F-17
FRANCIS AVE. F-10
FRANKLIN ST. F-10
FREDERICK ST. F-10
FRONT ST. F-10
FROST AVE. F-10
FULTON ST. F-9
GATE ST. F-14
GLEN AVE. F-11
GRACE AVE. F-10
GRAND ST. F-29
GRANT ST. F-13
GREEN AL. F-13
GREEN ST. F-22
GREENWOOD ST. F-29
GRIFFITH AL. F-25
HAGERTY AVE. F-13
HANOVER ST. O-7
HARRIS ST. O-9
HARTE ST. O-9
HECKMAN ST. O-15
HEMLOCK ST. O-32
HENDERSON ST. O-11
HENSHAW CT. O-11
HILL ST. O-25
HILLCREST BLVD. O-9
HILLSIDE RD. O-27
HOWARD ST. O-16
HUDSON ST. O-12
INGERSOLL AVE. O-11
IRWIN ST. O-12
IVY ST. O-15
J. J. BAKER WAY O-15
JAMES ST. O-23
JEFFERSON ST. O-16
JERSEY ST. O-14
JOHN ST. O-11
JOHN MITCHELL AVE. O-9
JOSEPH ST. O-9
JUDD AL. O-10
KAITLYN CT. P-27
KENT ST. O-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE O-17
KORP AL. O-17
KURLAND AL. O-17
LAKE AL. O-17
LENNON AL. O-17
LESHER AL. O-17
LEWIS ST. O-17
LINDOLN RD. O-17
LINCOLN RD. O-17
LINCOLN ST. O-17
LINER BLVD. O-17
LOCK ST. O-17
LOGAN ST. O-17
LYNDALE ST. O-17
LYNN RD. O-17
MADISON ST. O-17
MARKET ST. O-17
MARSHALL ST. O-17
MARY ST. O-17
McKEEN ST. O-17
MELROSE ST. O-17
MEMORIAL PKWY. O-17
MERCER ST. O-17
METZ ST. O-17
MEYNER RD. O-17
MILL ST. O-17
MILLER ST. O-17
MITCHELL AL. O-17
MORRIS ST. O-17
MOULE AL. O-17
NATALIE DRIVE O-17
NELSON ST. O-17
NORTH AL. O-17
NO. MAIN ST. O-17
NO. RIVERVIEW RD. O-17
OAK AL. O-17
ORCHARD AL. O-17
PARK RD. O-17
PEACH ST. O-17
PEAR AL. O-17
PEARL ST. O-17
PERDOE AVE. O-17
PICKFORD AVE. O-17
PINE AL. O-17
PLEASANT AVE. O-17
POTTS AVE. O-17
PROSPECT ST. O-17
PURSEL ST. O-17
RAILROAD AVE. O-17
RANDALL ST. O-17
RAYMOND ST. O-17
REESE WAY O-17
REESE CT. O-17
RICHARD RD. O-17
RICHMOND ST. O-17
RIDGE ST. O-17
RIVER ST. O-17
RIVERSIDE WAY O-17
RIVERVIEW CIR. O-17
RIVERVIEW RD. O-17
ROCK AL. O-17
ROSE ST. O-17
ROSEBERRY ST. O-17
SARGENT AVE. O-17
SAWMILL ST. O-17
SAYRE AVE. O-17
SCHULTZ AVE. O-17
SHAFER AVE. O-17
SHERWOOD ST. O-17
SHILLINGER AL. O-17
SHIVER ST. O-17
SILK AL. O-17
SITGREAVES ST. O-17
SMITH AVE. O-17
SONORA ST. O-17
SO. MAIN ST. O-17
SPINNER AL. O-17
SPRUCE AL. O-17
ST. JOHN AL. O-17
STANLEY ST. O-17
STEELE ST. O-17
STEWART AL. O-17
STOCKTON ST. O-17
STRYKER ST. O-17
STULL AL. O-17
SUMMIT AVE. O-17
SUSAN ST. O-17
TAYLOR AL. O-17
TERRY ST. O-17
THIRD ST. O-17
THOMAS ST. O-17
TIGHE AL. O-17
TITUS AL. O-17
TUTTLE ST. O-17
TYNDALL AVE. O-17
UNION SQ. O-17
VALLEY VIEW CIR. O-17
WALNUT ST. O-17
WARREN ST. O-17
WASHINGTON ST. O-17
WATSON PL. O-17
WEBSTER ST. O-17
WILBUR AVE. O-17
WILLEVER ST. O-17
WILLIAM ST. O-17
WILSON ST. O-17
WOODLAWN RD. O-17

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom L
12-7-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG


COMMONWEALTH OF PENNSYLVANIA

DELAWARE RIVER

CITY OF EASTON

I-78

ROSEBERRY STREET
FROST AVENUE
BARRYMORE STREET
BOWERS AVE.
PICKFORD
HARTE ST.
BURKE STREET
FRANCE ST.
FREDERICK
INGERSOLL
SARGENT
JOHN
GRACE
CORLISS
EUBERT
FRANCIS
COMPRESSION
FAIRBANKS STREET
BOULEVARD
MASERNY AVE.
FERGUSON ST.
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE AVENUE
DELAWARE ROAD
OLD TAVERN WAY
NORTH MAIN STREET
ROSE ALLEY
BROAD STREET
FOURTH STREET
ALLEY
MEMORIAL PARKWAY (RT. 22)
WEST BOUND AVENUE
EAST BOUND AVENUE
ORCHARD ALLEY
JOSEPH ST.
FRANCIS AVE.
HENDERSON
SHULTZ AVE.
HUDSON
MILLER
POTTS AVE.
IRWIN
MARSHALL
MEMORIAL PARKWAY (RT. 22)
HECKMAN
FISHER PLACE
ANDERSON
KNEEDLER AVENUE
WATSON
WALNUT STREET
ELM STREET
GREEN STREET
BATES STREET
LONDON ALLEY
PROSPECT STREET
ROOK ALLEY
UNCOLN STREET
GRANT STREET
DRAWER ALLEY
ST. JOHN ALLEY
SHILLINGER ALLEY
TIGHE ALLEY
WILSON STREET
RAILROAD AVE.
WARREN STREET
FIRTH STREET
STOCKTON
ESSEX STREET
CAHILL ST.
RICHARD RD.
METNER ROAD
SAYRE AVENUE
COLUMBUS AVENUE
CHRISTINE ST.
CHESTNUT
PEACH
DATE
WEBSTER
CENTER
THOMAS
ANN
JAMES
WILLIAM ST.
PURSEL
ALLAN
MOULE
ALLEY
GRIFFITH
WILBUR AVENUE
MERCER
HILL
MILL
BROWN
GARDNER
BANK STREET
GREEN STREET
CORLISS ST.
GATE STREET
TUTTLE
ARLINGTON ST.
CONGRESS
HILLSIDE
KATELYN CT.
RIDGE STREET
LOCK
WASHINGTON
STANLEY STREET
GREENWOOD
PEARL
GRAND
LOGAN
SHERWOOD
LINCOLN
MADISON STREET
VALLEY VIEW DR.
RIVERVIEW CIR.
NORTH RIVERVIEW ROAD
WOODLAWN ROAD
FOREST LN.
ELMHURST AVE.
DRIVE
CENTER ROAD
OAKLYN RD.
HEMLOCK DR.
HEMLOCK DRIVE
NATALIE DRIVE
CARPENTERSVILLE ROAD
CANAL WAY
MORRIS
SAWMILL
ABBOTT ST.
BROOKS STREET
SOUTH
LINCOLN ROAD
RIVERVIEW
NORTH
BELT
ROAD



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP


WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

12-12-22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARMART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. D-18
CENTER RD. J-32
CENTER ST. J-22
CHAMBERS ST. C-11
CHERRY LANE D-18
CHESTNUT ST. D-9
CHINA AL. D-9
CHINTHINK AL. D-9
CHRISTIE AL. L-12
CHURCH ST. D-11
CLAREMONT ST. D-10
COLBY PL. D-15
COLUMBUS AVE. K-25
COMPRESSOR ST. G-14
CONSTOCK AL. G-11
CONGRESS ST. K-24
CORLISS AVE. G-14
CROSS ST. G-11
CULVON ST. K-25
DAVIS ST. D-14
DEAN AL. L-11
DELAWARE RD. G-5
DIMMICK AL. N-13
DRILL ST. N-11
DUGAN AL. K-10
ELDEN AVE. N-11
ELIZABETH ST. E-11
ELLEN ST. D-14
ELM ST. D-14
ELMHURST DR. K-28
EMIRE ST. K-20
EMMA ST. D-9
ENGINE ST. K-20
ESSEX ST. D-9
EVELYN AVE. K-11
FAIRBANKS ST. D-8
FAIRVIEW AVE. K-11
FARM ST. K-27
FERGUSON ST. D-7
FILMORE ST. E-11
FIFTH ST. D-11
FIRST AL. D-11
FIRTH ST. D-11
FISHER AVE. K-26
FOCHT BRIDGE K-28
FORREST LA. L-28
FOURTH ST. D-11
FOX AL. D-10
FOX ST. D-10
FRACE ST. D-10
FRANCIS AVE. D-10
FRANKLIN ST. D-10
FREDERICK ST. D-10
FRONT ST. D-10
FROST AVE. D-10
FULTON ST. D-10
GATE ST. D-10
GLEN AVE. D-10
GRACE AVE. D-10
GRAND ST. D-10
GRANT ST. D-10
GREEN AL. D-10
GREEN ST. D-10
GREENWOOD ST. D-10
GRIFFITH AL. D-10
HAGERTY AVE. D-10
HANOVER ST. D-10
HARRIS ST. D-10
HARTE ST. D-10
HECKMAN ST. D-10
HEMLOCK ST. D-10
HENDERSON ST. D-10
HENSHAW CT. D-10
HILL ST. D-10
HILLCREST BLVD. D-10
HILLSIDE RD. D-10
HOWARD ST. D-10
HUDSON ST. D-10
INGERSOLL AVE. D-10
IRWIN ST. D-10
IVY ST. D-10
JAMES ST. D-10
JEFFERSON ST. D-10
JERSEY ST. D-10
JOHN ST. D-10
JOHN MITCHELL AVE. D-10
JOSEPH ST. D-10
JUDD AL. D-10
KAITLYN CT. D-10
KENT ST. D-10
KNEEDLER AVE. D-10
KNOLL VIEW DRIVE D-10
KORP AL. D-10
KURLAND AL. D-10
LAKE AL. D-10
LENNOX AL. D-10
LESHER AL. D-10
LEWIS ST. D-10
LINKSHIRE RD. D-10
LINCOLN RD. D-10
LINCOLN ST. D-10
LINER BLVD. D-10
LOCK ST. D-10
LOGAN ST. D-10
LYNDALE ST. D-10
LYNN RD. D-10
MADISON ST. D-10
MARKET ST. D-10
MARSHALL ST. D-10
MARY ST. D-10
McKEON ST. D-10
MELROSE ST. D-10
MEMORIAL PKWY. D-10
MERCER ST. D-10
METZ ST. D-10
MEYNER RD. D-10
MILL ST. D-10
MILLER ST. D-10
MITCHELL AL. D-10
MORRIS ST. D-10
MOULE AL. D-10
NATALIE DRIVE D-10
NELSON ST. D-10
NORTH AL. D-10
NO. MAIN ST. D-10
NO. RIVERVIEW RD. D-10
OAK AL. D-10
ORCHARD AL. D-10
PARK RD. D-10
PEACH ST. D-10
PEAR AL. D-10
PEARL ST. D-10
PERDOE AVE. D-10
PICKFORD AVE. D-10
PINE AL. D-10
PLEASANT AVE. D-10
POTTS AVE. D-10
PROSPECT ST. D-10
PURSEL ST. D-10
RAILROAD AVE. D-10
RANDALL ST. D-10
RAYMOND ST. D-10
REESE WAY D-10
REESE CT. D-10
RICHARD RD. D-10
RICHMOND ST. D-10
RIDGE ST. D-10
RIVER ST. D-10
RIVERSIDE WAY D-10
RIVERVIEW CIR. D-10
RIVERVIEW RD. D-10
ROCK AL. D-10
ROSE ST. D-10
ROSEBERRY ST. D-10
SARGENT AVE. D-10
SAWMILL ST. D-10
SAYRE AVE. D-10
SCHULTZ AVE. D-10
SHAFER AVE. D-10
SHERWOOD ST. D-10
SHILLINGER AL. D-10
SHIMER ST. D-10
SILK AVE. D-10
STIRGEAVES ST. D-10
SMITH AVE. D-10
SONORA ST. D-10
SO. MAIN ST. D-10
SPINNER AL. D-10
SPRUCE AL. D-10
ST. JOHN AL. D-10
STANLEY ST. D-10
STEELE ST. D-10
STEWART AL. D-10
STOCKTON ST. D-10
STRYKER ST. D-10
STULL AL. D-10
SUMMIT AVE. D-10
SUSAN ST. D-10
TAYLOR AL. D-10
TERRY ST. D-10
THIRD ST. D-10
THOMAS ST. D-10
TICHE AL. D-10
TITUS AL. D-10
TUTTLE ST. D-10
TYNDALL AVE. D-10
UNION SQ. D-10
VALLEY VIEW CIR. D-10
WALNUT ST. D-10
WARREN ST. D-10
WASHINGTON ST. D-10
WATSON PL. D-10
WEBSTER ST. D-10
WILBUR AVE. D-10
WILLEVER ST. D-10
WILLIAM ST. D-10
WILSON ST. D-10
WIRE AL. D-10
WOODLAWN RD. D-10



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. D-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. D-18
CENTER RD. D-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE G-18
CHESTNUT ST. I-23
CHINA AL. D-5
CHINTEWINK AL. G-6
CHRISTIE AL. E-13
CHURCH ST. D-11
CLAIRMONT ST. D-31
COLBY PL. M-15
COLUMBUS AVE. I-
COMPRESSOR ST. I-
COMSTOCK AL. I-
CONGRESS ST. I-
CORLISS AVE. I-
CROSS ST. J-25
CULVER ST. K-24
DAVIS ST. K-14
DEAN AL. F-11
DELAWARE RD. K-3
DENNICK AL. K-13
DRILL ST. E-11
DUGAN AL. E-11
ELDEN AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. D-14
ELM ST. F-18
ELMHURST DR. N-30
EMIRE ST. D-10
EMMA ST. K-22
ENONE ST. K-11
ESSEX ST. I-19
EVELYN AVE. H-11
FAIRBANKS ST. F-9
FAIRVIEW AVE. I-7
FARM ST. B-27
FERGUSON ST. L-11
FILMORE ST. I-11
FIFTH ST. I-27
FIRST AL. I-27
FIRTH ST. K-13
FISHER AVE. D-18
FOCHT BRIDGE F-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-6
FOX ST. D-17
FRACE ST. I-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. D-10
FROST AVE. D-9
FULTON ST. I-14
GATE ST. K-21
GLEN AVE. K-11
GRACE AVE. K-13
GRAND ST. I-13
GRANT ST. I-11
GREEN AL. I-11
GREEN ST. I-22
GREENWOOD ST. K-25
GRIFFITH AL. K-25
HAGERTY AVE. N-7
HANOVER ST. I-13
HARRIS ST. D-9
HARTE ST. D-9
HECKMAN ST. I-15
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. I-11
HILL ST. L-25
HILLCREST BLVD. D-27
HILLSIDE RD. M-16
HOWARD ST. I-16
HUDSON ST. D-11
INGERSOLL AVE. D-12
IRWIN ST. I-15
IVY ST. I-15
J. J. FASKER WAY I-23
JAMES ST. L-23
JEFFERSON ST. K-14
JERSEY ST. I-23
JOHN ST. I-14
JOHN MITCHELL AVE. K-9
JOSEPH ST. I-9
JUDD AL. I-9
KAITLIN CT. I-7
KENT ST. L-30
KNEEDLER AVE. I-7
KNOLL VIEW DRIVE I-21
KORP AL. L-25
KURLAND AL. I-25
LAKE AL. B-10
LENNON AL. I-16
LESNER AL. I-16
LEWIS ST. I-16
LINCOLN RD. L-20
LINCOLN ST. I-20
LINER BLVD. I-32
LOCK ST. B-30
LOGAN ST. I-30
LYNDALE ST. I-30
LYNN RD. I-30
MADISON ST. K-22
MARKET ST. I-14
MARSHALL ST. I-14
MAY ST. I-14
McKEEN ST. I-21
MELROSE ST. I-21
MEMORIAL PKWY. I-18
MERCER ST. I-18
METZ ST. I-19
MEYNER RD. I-19
MILL ST. I-11
MILLER ST. I-11
MITCHELL AL. I-10
MORRIS ST. I-9
MOULE AL. I-9
NATALIE DRIVE I-9
NELSON ST. I-9
NORTH AL. I-14
NO. MAIN ST. I-14
NO. RIVERVIEW RD. I-28
OAK AL. I-13
ORCHARD AL. I-13
PARK RD. I-24
PEACH ST. I-22
PEAR AL. I-22
PEARL ST. I-29
PERDUE AVE. P-25
PICKFORD AVE. I-7
PINE AL. I-16
PLEASANT AVE. I-16
POTTS AVE. I-10
PROSPECT ST. I-10
PURSEL ST. I-24
RAILROAD AVE. I-24
RANDALL ST. I-24
RAYMOND ST. I-24
REESE WAY I-24
REESE CT. I-24
RICHARD RD. I-28
RICHMOND ST. I-28
RIDGE ST. I-28
RIVER ST. I-16
RIVERSIDE WAY I-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-28
ROCK AL. I-13
ROSE ST. I-13
ROSSBERRY ST. I-9
SARGENT AVE. I-11
SAWMILL ST. I-25
SAYRE AVE. K-23
SCHULTZ AVE. I-8
SHARON AVE. I-8
SHERWOOD ST. I-14
SHILLINGER AL. I-14
SMITH ST. I-17
SILK AVE. I-17
SITGREAVES ST. I-17
SMITH AVE. I-20
SONDRA ST. I-27
SO. MAIN ST. I-9
SPINNER AL. I-11
SPRUCE AL. I-18
ST. JOHN AL. K-14
STANLEY ST. I-28
STEELE ST. I-28
STEWART AL. I-25
STOCKTON ST. I-15
STRYKER ST. I-12
STULL AL. I-8
SUMMIT AVE. I-10
SUSAN ST. I-10
TAYLOR AL. I-10
TERRY ST. I-10
THIRD ST. I-10
THOMAS ST. I-10
TIGHE AL. I-12
TITUS AL. H-12
TUTTLE ST. I-26
TYNDALL AVE. I-11
UNION SQ. I-11
VALLEY VIEW CIR. I-28
WALNUT ST. I-28
WARREN ST. I-28
WASHINGTON ST. I-16
WATSON PL. I-16
WEBSTER ST. I-23
WILBUR AVE. I-22
WILLEVER ST. I-10
WILLIAM ST. I-24
WILSON ST. K-
WISE PL. I-
WOODLAWN RD. I-28

Summit and Snyder

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Summit & Snyder 1/12/23

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom C
Don V
01-12-23

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

FROST AVENUE

PICKFORD STREET

HARTE STREET

BURKE STREET

PROSPECT AVENUE

LINCOLN ROAD

LINER BLVD.

BATES STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

WALNUT STREET

GREEN STREET

COLUMBUS AVENUE

WILBUR AVENUE

SAYRE AVENUE

CAHILL ST.

RICHARD RD.

MEYNER ROAD

HILLSIDE

GATE STREET

RIDGE STREET

STANLEY STREET

MELROSE STREET

PEARL ST.

GRAND ST.

LOGAN ST.

MADISON STREET

LYNDALE

HILL STREET

BANK STREET

RIVERVIEW ROAD

WOODLAWN ROAD

CARPENTERSVILLE ROAD

NATALIE DRIVE

OAKLYN RD.

HEMLOCK DR.

ELMHURST DRIVE

CANAL WAY

MORRIS STREET

SAWMILL ST.

MAIN STREET

SOUTH MAIN STREET

NORTH MAIN STREET

MARKET ST.

ELIZABETH ST.

HOWARD STREET


MERCER STREET

STOCKTON STREET

WASHINGTON STREET

MEMORIAL PARKWAY (RT. 22)

BRAINARD ST.	C-11
BROAD ST.	F-6
BROADVIEW ST.	L-32
BULLMAN ST.	D-9
BURKE ST.	D-9
BURWELL AL.	D-9
CAHILL ST.	K-20
CARHART AL.	I-28
CARPENTERSVILLE RD.	L-31
CEDAR AL.	L-18
CENTER RD.	D-32
CENTER ST.	I-22
CHAMBERS ST.	D-11
CHERRY LANE	D-18
CHESTNUT ST.	I-21
CHINA AL.	D-8
CHINTEWINK AL.	D-8
CHRISTIE AL.	M-12
CHURCH ST.	E-11
CLAIRMONT ST.	D-31
COLBY PL.	H-15
COLUMBUS AVE.	H-
COMPRESSOR ST.	
COMSTOCK AL.	
CONGRESS ST.	
CORLISS AVE.	
CROSS ST.	
CULVER ST.	
DAVIS ST.	
DEAN AL.	
DELAWARE RD.	
DIMMICK AL.	
DRILL ST.	
DUGAN AL.	
ELDER AVE.	
ELIZABETH ST.	
ELLEN ST.	
ELM ST.	
ELMHURST DR.	
EMIRE ST.	
EMMA ST.	
ENDINE ST.	
ESSEX ST.	
EVELYN AVE.	
FAIRBANKS ST.	
FAIRVIEW AVE.	
FARM ST.	
FERGUSON ST.	
FILMORE ST.	
FIFTH ST.	
FIRST AL.	
FIRTH ST.	
FISHER AVE.	
FOCHT BRIDGE	
FORREST LA.	
FOURTH ST.	
FOX AL.	
FOX ST.	
FRACE ST.	
FRANCIS AVE.	
FRANKLIN ST.	
FREDERICK ST.	
FRONT ST.	
FROST AVE.	
FULTON ST.	
GATE ST.	
GLEN AVE.	
GRACE AVE.	
GRAND ST.	
GRANT ST.	
GREEN AL.	
GREEN ST.	
GREENWOOD ST.	
GRIFFITH AL.	
HAGERTY AVE.	
HANOVER ST.	
HARRIS ST.	
HARTE ST.	
HECKMAN ST.	
HEMLOCK ST.	
HENDERSON ST.	
HENSHAW CT.	
HILL ST.	
HILLCREST BLVD.	
HILLSIDE RD.	
HOWARD ST.	
HUDSON ST.	
INGERSOLL AVE.	
IRWIN ST.	
IVY ST.	
J. BAKER WAY	
JAMES ST.	
JEFFERSON ST.	
JERSEY ST.	
JOHN ST.	
JOHN MITCHELL AVE.	
JOSEPH ST.	
JUDD AL.	
KAITLYN CT.	
KENT ST.	
KNEEDLER AVE.	
KNOLL VIEW DRIVE	
KORP AL.	
KURLAND AL.	
LAKE AL.	
LENNON AL.	
LESHER AL.	
LEWIS ST.	
LINCOLN RD.	
LINCOLN ST.	
LINER BLVD.	
LOCK ST.	
LOGAN ST.	
LYNDALE ST.	
LYNN RD.	
MADISON ST.	
MARKET ST.	
MARSHALL ST.	
MARY ST.	
McKEEN ST.	
MELROSE ST.	
MEMORIAL PKWY.	
MERCER ST.	
METZ ST.	
MEYNER RD.	
MILL ST.	
MILLER ST.	
MITCHELL AL.	
MORRIS ST.	
MOULE AL.	
NATALIE DRIVE	
NELSON ST.	
NORTH AL.	
NO. MAIN ST.	
NO. RIVERVIEW RD.	
OAK AL.	
ORCHARD AL.	
PARK RD.	
PEACH ST.	
PEAR AL.	
PEARL ST.	
PERDOE AVE.	
PICKFORD AVE.	
PINE AL.	
PLEASANT AVE.	
POTTS AVE.	
PROSPECT ST.	
PURSEL ST.	
RAILROAD AVE.	
RANDALL ST.	
RAYMOND ST.	
REESE WAY	
REESE CT.	
RICHARD RD.	
RICHMOND ST.	
RIDGE ST.	
RIVER ST.	
RIVERSIDE WAY	
RIVERVIEW CIR.	
RIVERVIEW RD.	
ROCK AL.	
ROSE ST.	
ROSEBERRY ST.	
SARGENT AVE.	
SAWMILL ST.	
SAYRE AVE.	
SCHULTZ AVE.	
SHAFER AVE.	
SHERWOOD ST.	
SHILLINGER AL.	
SHIMER ST.	
SILK AVE.	
STOREAVES ST.	
SMITH AVE.	
SONORA ST.	
SO. MAIN ST.	
SPINNER AL.	
SPRUCE AL.	
ST. JOHN AL.	
STANLEY ST.	
STEELE ST.	
STEWART AL.	
STOCKTON ST.	
STRYKER ST.	
STILL AL.	
SUMMIT AVE.	
SUSAN ST.	
TAYLOR AL.	
TERRY ST.	
THIRD ST.	
THOMAS ST.	
TIGHE AL.	
TITUS AL.	
TUTTLE ST.	
TYNDALL AVE.	
UNION SQ.	
VALLEY VIEW CIR.	
WALNUT ST.	
WARREN ST.	
WASHINGTON ST.	
WATSON PL.	
WEBSTER ST.	
WILBUR AVE.	
WILLEVER ST.	
WILLIAM ST.	
WILSON ST.	
WIRE AL.	
WOODLAWN RD.	



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. D-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. D-18
CENTER RD. D-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE G-18
CHESTNUT ST. I-23
CHINA AL. D-5
CHINTEWINK AL. G-6
CHRISTIE AL. E-13
CHURCH ST. D-11
CLAIRMONT ST. D-31
COLBY PL. M-15
COLUMBUS AVE. I-
COMPRESSOR ST. I-
COMSTOCK AL. I-
CONGRESS ST. I-
CORLISS AVE. I-
CROSS ST. J-25
CULVER ST. K-24
DAVIS ST. K-14
DEAN AL. F-11
DELAWARE RD. K-3
DENNICK AL. K-13
DRILL ST. E-11
DUGAN AL. E-11
ELDEN AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. D-14
ELM ST. F-18
ELMHURST DR. N-30
EMIRE ST. D-10
EMMA ST. K-22
ENONE ST. K-11
ESSEX ST. I-19
EVELYN AVE. H-11
FAIRBANKS ST. F-9
FAIRVIEW AVE. I-7
FARM ST. B-27
FERGUSON ST. L-11
FILMORE ST. I-11
FIFTH ST. I-27
FIRST AL. I-27
FIRTH ST. K-13
FISHER AVE. D-18
FOCHT BRIDGE F-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-6
FOX ST. D-17
FRACE ST. I-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. D-10
FROST AVE. D-9
FULTON ST. I-14
GATE ST. K-21
GLEN AVE. K-11
GRACE AVE. K-13
GRAND ST. I-13
GRANT ST. I-11
GREEN AL. I-11
GREEN ST. I-22
GREENWOOD ST. K-25
GRIFFITH AL. K-25
HAGERTY AVE. N-7
HANOVER ST. I-13
HARRIS ST. D-9
HARTE ST. D-9
HECKMAN ST. I-15
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. I-11
HILL ST. L-25
HILLCREST BLVD. D-27
HILLSIDE RD. M-16
HOWARD ST. I-16
HUDSON ST. D-11
INGERSOLL AVE. D-12
IRWIN ST. I-15
IVY ST. I-15
J. J. FASKER WAY I-23
JAMES ST. L-23
JEFFERSON ST. K-14
JERSEY ST. I-23
JOHN ST. I-14
JOHN MITCHELL AVE. K-9
JOSEPH ST. I-9
JUDD AL. I-9
KAITLIN CT. I-7
KENT ST. L-30
KNEEDLER AVE. I-7
KNOLL VIEW DRIVE I-21
KORP AL. L-25
KURLAND AL. I-25
LAKE AL. B-10
LENNON AL. I-16
LESNER AL. I-16
LEWIS ST. I-16
LINCOLN RD. L-20
LINCOLN ST. I-20
LINER BLVD. I-32
LOCK ST. B-30
LOGAN ST. I-30
LYNDALE ST. I-30
LYNN RD. I-30
MADISON ST. K-22
MARKET ST. I-14
MARSHALL ST. I-14
MAY ST. I-14
McKEEN ST. I-21
MELROSE ST. I-21
MEMORIAL PKWY. I-18
MERCER ST. I-18
METZ ST. I-19
MEYNER RD. I-19
MILL ST. I-11
MILLER ST. I-11
MITCHELL AL. I-10
MORRIS ST. I-9
MOULE AL. I-9
NATALIE DRIVE I-9
NELSON ST. I-9
NORTH AL. I-14
NO. MAIN ST. I-14
NO. RIVERVIEW RD. I-28
OAK AL. I-13
ORCHARD AL. I-13
PARK RD. I-24
PEACH ST. I-22
PEAR AL. I-22
PEARL ST. I-29
PERDUE AVE. P-25
PICKFORD AVE. I-7
PINE AL. I-16
PLEASANT AVE. I-16
POTTS AVE. I-10
PROSPECT ST. I-10
PURSEL ST. I-24
RAILROAD AVE. I-24
RANDALL ST. I-24
RAYMOND ST. I-24
REESE WAY I-24
REESE CT. I-24
RICHARD RD. I-28
RICHMOND ST. I-28
RIDGE ST. I-28
RIVER ST. I-16
RIVERSIDE WAY I-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-28
ROCK AL. I-13
ROSE ST. I-13
ROSSBERRY ST. I-9
SARGENT AVE. I-11
SAWMILL ST. I-25
SAYRE AVE. K-23
SCHULTZ AVE. I-8
SHARON AVE. I-8
SHERWOOD ST. I-14
SHILLINGER AL. I-14
SMITH ST. I-17
SILK AVE. I-17
SITGREAVES ST. I-17
SMITH AVE. I-20
SONDRA ST. I-27
SO. MAIN ST. I-9
SPINNER AL. I-11
SPRUCE AL. I-18
ST. JOHN AL. K-14
STANLEY ST. I-28
STEELE ST. I-28
STEWART AL. I-25
STOCKTON ST. I-15
STRYKER ST. I-12
STULL AL. I-8
SUMMIT AVE. I-10
SUSAN ST. I-10
TAYLOR AL. I-10
TERRY ST. I-10
THIRD ST. I-10
THOMAS ST. I-10
TIGHE AL. I-12
TITUS AL. H-12
TUTTLE ST. I-26
TYNDALL AVE. I-11
UNION SQ. I-11
VALLEY VIEW CIR. I-28
WALNUT ST. I-28
WARREN ST. I-28
WASHINGTON ST. I-16
WATSON PL. I-16
WEBSTER ST. I-23
WILBUR AVE. I-22
WILLEVER ST. I-10
WILLIAM ST. I-24
WILSON ST. K-
WISE PL. I-
WOODLAWN RD. I-28

Summit and Snyder

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Summit & Snyder 1/12/23

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom C
Don V
01-12-23

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

FROST AVENUE

PICKFORD STREET

HARTE STREET

BURKE STREET

PROSPECT AVENUE

LINCOLN ROAD

LINER BLVD.

BATES STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

WALNUT STREET

GREEN STREET

COLUMBUS AVENUE

WILBUR AVENUE

SAYRE AVENUE

CAHILL ST.

RICHARD RD.

MEYNER ROAD

HILLSIDE

GATE STREET

RIDGE STREET

STANLEY STREET

MELROSE STREET

PEARL ST.

GRAND ST.

LOGAN ST.

MADISON STREET

LYNDALE

HILL STREET

BANK STREET

RIVERVIEW ROAD

WOODLAWN ROAD

CARPENTERSVILLE ROAD

NATALIE DRIVE

OAKLYN RD.

HEMLOCK DR.

ELMHURST DRIVE

CANAL WAY

MORRIS STREET

SAWMILL ST.

MAIN STREET

SOUTH MAIN STREET

NORTH MAIN STREET

MARKET ST.

ELIZABETH ST.

HOWARD STREET


MERCER STREET

STOCKTON STREET

WASHINGTON STREET

MEMORIAL PARKWAY (RT. 22)

BRAINARD ST.	C-11
BROAD ST.	F-6
BROADVIEW ST.	L-32
BULLMAN ST.	D-9
BURKE ST.	D-9
BURWELL AL.	D-9
CAHILL ST.	K-20
CARHART AL.	I-28
CARPENTERSVILLE RD.	L-31
CEDAR AL.	L-18
CENTER RD.	D-32
CENTER ST.	I-22
CHAMBERS ST.	D-11
CHERRY LANE	D-18
CHESTNUT ST.	I-21
CHINA AL.	D-8
CHINTEWINK AL.	D-8
CHRISTIE AL.	M-12
CHURCH ST.	E-11
CLAIRMONT ST.	D-31
COLBY PL.	H-15
COLUMBUS AVE.	H-
COMPRESSOR ST.	
COMSTOCK AL.	
CONGRESS ST.	
CORLISS AVE.	
CROSS ST.	
CULVER ST.	
DAVIS ST.	
DEAN AL.	
DELAWARE RD.	
DIMMICK AL.	
DRILL ST.	
DUGAN AL.	
ELDER AVE.	
ELIZABETH ST.	
ELLEN ST.	
ELM ST.	
ELMHURST DR.	
EMIRE ST.	
EMMA ST.	
ENDINE ST.	
ESSEX ST.	
EVELYN AVE.	
FAIRBANKS ST.	
FAIRVIEW AVE.	
FARM ST.	
FERGUSON ST.	
FILMORE ST.	
FIFTH ST.	
FIRST AL.	
FIRTH ST.	
FISHER AVE.	
FOCHT BRIDGE	
FORREST LA.	
FOURTH ST.	
FOX AL.	
FOX ST.	
FRACE ST.	
FRANCIS AVE.	
FRANKLIN ST.	
FREDERICK ST.	
FRONT ST.	
FROST AVE.	
FULTON ST.	
GATE ST.	
GLEN AVE.	
GRACE AVE.	
GRAND ST.	
GRANT ST.	
GREEN AL.	
GREEN ST.	
GREENWOOD ST.	
GRIFFITH AL.	
HAGERTY AVE.	
HANOVER ST.	
HARRIS ST.	
HARTE ST.	
HECKMAN ST.	
HEMLOCK ST.	
HENDERSON ST.	
HENSHAW CT.	
HILL ST.	
HILLCREST BLVD.	
HILLSIDE RD.	
HOWARD ST.	
HUDSON ST.	
INGERSOLL AVE.	
IRWIN ST.	
IVY ST.	
J. BAKER WAY	
JAMES ST.	
JEFFERSON ST.	
JERSEY ST.	
JOHN ST.	
JOHN MITCHELL AVE.	
JOSEPH ST.	
JUDD AL.	
KAITLYN CT.	
KENT ST.	
KNEEDLER AVE.	
KNOLL VIEW DRIVE	
KORP AL.	
KURLAND AL.	
LAKE AL.	
LENNON AL.	
LESHER AL.	
LEWIS ST.	
LINCOLN RD.	
LINCOLN ST.	
LINER BLVD.	
LOCK ST.	
LOGAN ST.	
LYNDALE ST.	
LYNN RD.	
MADISON ST.	
MARKET ST.	
MARSHALL ST.	
MARY ST.	
McKEEN ST.	
MELROSE ST.	
MEMORIAL PKWY.	
MERCER ST.	
METZ ST.	
MEYNER RD.	
MILL ST.	
MILLER ST.	
MITCHELL AL.	
MORRIS ST.	
MOULE AL.	
NATALIE DRIVE	
NELSON ST.	
NORTH AL.	
NO. MAIN ST.	
NO. RIVERVIEW RD.	
OAK AL.	
ORCHARD AL.	
PARK RD.	
PEACH ST.	
PEAR AL.	
PEARL ST.	
PERDOE AVE.	
PICKFORD AVE.	
PINE AL.	
PLEASANT AVE.	
POTTS AVE.	
PROSPECT ST.	
PURSEL ST.	
RAILROAD AVE.	
RANDALL ST.	
RAYMOND ST.	
REESE WAY	
REESE CT.	
RICHARD RD.	
RICHMOND ST.	
RIDGE ST.	
RIVER ST.	
RIVERSIDE WAY	
RIVERVIEW CIR.	
RIVERVIEW RD.	
ROCK AL.	
ROSE ST.	
ROSEBERRY ST.	
SARGENT AVE.	
SAWMILL ST.	
SAYRE AVE.	
SCHULTZ AVE.	
SHAFER AVE.	
SHERWOOD ST.	
SHILLINGER AL.	
SHIMER ST.	
SILK AVE.	
STOREAVES ST.	
SMITH AVE.	
SONORA ST.	
SO. MAIN ST.	
SPINNER AL.	
SPRUCE AL.	
ST. JOHN AL.	
STANLEY ST.	
STEELE ST.	
STEWART AL.	
STOCKTON ST.	
STRYKER ST.	
STILL AL.	
SUMMIT AVE.	
SUSAN ST.	
TAYLOR AL.	
TERRY ST.	
THIRD ST.	
THOMAS ST.	
TIGHE AL.	
TITUS AL.	
TUTTLE ST.	
TYNDALL AVE.	
UNION SQ.	
VALLEY VIEW CIR.	
WALNUT ST.	
WARREN ST.	
WASHINGTON ST.	
WATSON PL.	
WEBSTER ST.	
WILBUR AVE.	
WILLEVER ST.	
WILLIAM ST.	
WILSON ST.	
WIRE AL.	
WOODLAWN RD.	



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

12-12-22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARMART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. D-18
CENTER RD. J-32
CENTER ST. J-22
CHAMBERS ST. C-11
CHERRY LANE D-18
CHESTNUT ST. D-9
CHINA AL. D-9
CHINTHINK AL. D-9
CHRISTIE AL. L-12
CHURCH ST. D-11
CLAREMONT ST. D-10
COLBY PL. D-15
COLUMBUS AVE. K-25
COMPRESSOR ST. G-14
CONSTOCK AL. G-11
CONGRESS ST. K-24
CORLISS AVE. G-14
CROSS ST. G-11
CULVON ST. K-25
DAVIS ST. D-14
DEAN AL. L-11
DELAWARE RD. G-5
DIMMICK AL. N-13
DRILL ST. N-11
DUGAN AL. K-10
ELDEN AVE. N-11
ELIZABETH ST. E-11
ELLEN ST. D-14
ELM ST. D-14
ELMHURST DR. K-28
EMIRE ST. K-20
EMMA ST. D-9
ENGINE ST. K-20
ESSEX ST. D-9
EVELYN AVE. K-11
FAIRBANKS ST. D-8
FAIRVIEW AVE. K-11
FARM ST. K-27
FERGUSON ST. D-7
FILMORE ST. E-11
FIFTH ST. D-11
FIRST AL. D-11
FIRTH ST. D-11
FISHER AVE. K-26
FOCHT BRIDGE K-28
FORREST LA. L-28
FOURTH ST. D-11
FOX AL. D-10
FOX ST. D-10
FRACE ST. D-10
FRANCIS AVE. D-10
FRANKLIN ST. D-10
FREDERICK ST. D-10
FRONT ST. D-10
FROST AVE. D-10
FULTON ST. D-10
GATE ST. D-10
GLEN AVE. D-10
GRACE AVE. D-10
GRAND ST. D-10
GRANT ST. D-10
GREEN AL. D-10
GREEN ST. D-10
GREENWOOD ST. D-10
GRIFFITH AL. D-10
HAGERTY AVE. D-10
HANOVER ST. D-10
HARRIS ST. D-10
HARTE ST. D-10
HECKMAN ST. D-10
HEMLOCK ST. D-10
HENDERSON ST. D-10
HENSHAW CT. D-10
HILL ST. D-10
HILLCREST BLVD. D-10
HILLSIDE RD. D-10
HOWARD ST. D-10
HUDSON ST. D-10
INGERSOLL AVE. D-10
IRWIN ST. D-10
IVY ST. D-10
JAMES ST. D-10
JEFFERSON ST. D-10
JERSEY ST. D-10
JOHN ST. D-10
JOHN MITCHELL AVE. D-10
JOSEPH ST. D-10
JUDD AL. D-10
KAITLYN CT. D-10
KENT ST. D-10
KNEEDLER AVE. D-10
KNOLL VIEW DRIVE D-10
KORP AL. D-10
KURLAND AL. D-10
LAKE AL. D-10
LENNOX AL. D-10
LESHER AL. D-10
LEWIS ST. D-10
LINKSHIRE RD. D-10
LINCOLN RD. D-10
LINCOLN ST. D-10
LINER BLVD. D-10
LOCK ST. D-10
LOGAN ST. D-10
LYNDALE ST. D-10
LYNN RD. D-10
MADISON ST. D-10
MARKET ST. D-10
MARSHALL ST. D-10
MARY ST. D-10
McKEON ST. D-10
MELROSE ST. D-10
MEMORIAL PKWY. D-10
MERCER ST. D-10
METZ ST. D-10
MEYNER RD. D-10
MILL ST. D-10
MILLER ST. D-10
MITCHELL AL. D-10
MORRIS ST. D-10
MOULE AL. D-10
NATALIE DRIVE D-10
NELSON ST. D-10
NORTH AL. D-10
NO. MAIN ST. D-10
NO. RIVERVIEW RD. D-10
OAK AL. D-10
ORCHARD AL. D-10
PARK RD. D-10
PEACH ST. D-10
PEAR AL. D-10
PEARL ST. D-10
PERDOE AVE. D-10
PICKFORD AVE. D-10
PINE AL. D-10
PLEASANT AVE. D-10
POTTS AVE. D-10
PROSPECT ST. D-10
PURSEL ST. D-10
RAILROAD AVE. D-10
RANDALL ST. D-10
RAYMOND ST. D-10
REESE WAY D-10
REESE CT. D-10
RICHARD RD. D-10
RICHMOND ST. D-10
RIDGE ST. D-10
RIVER ST. D-10
RIVERSIDE WAY D-10
RIVERVIEW CIR. D-10
RIVERVIEW RD. D-10
ROCK AL. D-10
ROSE ST. D-10
ROSEBERRY ST. D-10
SARGENT AVE. D-10
SAWMILL ST. D-10
SAYRE AVE. D-10
SCHULTZ AVE. D-10
SHAFER AVE. D-10
SHERWOOD ST. D-10
SHILLINGER AL. D-10
SHIMER ST. D-10
SILK AVE. D-10
STIRGEAVES ST. D-10
SMITH AVE. D-10
SONORA ST. D-10
SO. MAIN ST. D-10
SPINNER AL. D-10
SPRUCE AL. D-10
ST. JOHN AL. D-10
STANLEY ST. D-10
STEELE ST. D-10
STEWART AL. D-10
STOCKTON ST. D-10
STRYKER ST. D-10
STULL AL. D-10
SUMMIT AVE. D-10
SUSAN ST. D-10
TAYLOR AL. D-10
TERRY ST. D-10
THIRD ST. D-10
THOMAS ST. D-10
TICHE AL. D-10
TITUS AL. D-10
TUTTLE ST. D-10
TYNDALL AVE. D-10
UNION SQ. D-10
VALLEY VIEW CIR. D-10
WALNUT ST. D-10
WARREN ST. D-10
WASHINGTON ST. D-10
WATSON PL. D-10
WEBSTER ST. D-10
WILBUR AVE. D-10
WILLEVER ST. D-10
WILLIAM ST. D-10
WILSON ST. D-10
WIRE AL. D-10
WOODLAWN RD. D-10

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom L
12-7-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA


DELAWARE RIVER

CITY OF EASTON

I-78

ROSEBERRY STREET
FROST AVENUE
BARRYMORE STREET
BOWERS AVE.
PICKFORD
HARTE ST.
BURKE STREET
FRANCE ST.
FREDERICK
INGERSOLL
SARGENT
JOHN
GRACE
CORLISS
EUBERT
FRANCIS
FAIRBANKS STREET
BOULEVARD
HASERT AVE.
FERGUSON ST.
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE AVENUE
DELAWARE ROAD
OLD TAVERN WAY
NORTH MAIN STREET
ROSE ALLEY
BROAD STREET
FOURTH STREET
ALLEY
THIRD STREET
BIRCH ST.
MEMORIAL PARKWAY (RT. 22)
WEST BOUND
EAST BOUND
AVENUE
ORCHARD ALLEY
RAYMOND ST.
EVELYN AVE.
HENSHAW COURT
GLEN
GREEN
FILMORE
LEWIS
TAYLOR
WASHINGTON
MORRIS
STILL
BENNETT
BURWELL
BULLMAN
MITCHELL
SUMMIT
CHAMBERS
HARRIS
SHIMER ST.
BRAINARD
FRONT STREET
RANDALL
LAKE AL.
PLEASANT
TYNDALL
REESE
MAIN STREET
HANOVER STREET
COURT
MARKET
ELIZABETH ST.
SOUTH
HILLCREST NORTH
HILLCREST SOUTH
POTTS AVE.
MILLER
SPRING ALLEY
HENDERSON
FRANCIS AVE.
HUDSON
SHULTZ AVE.
IRWIN
STREET
MARSHALL
MEMORIAL PKWY. (RT. 22)
ANDERSON
HECKMAN
FISHER
KNEEDLER AVENUE
PLACE
WATSON
MARY
ST.
JOHN
DAVIS
PLACE
DOLBY
PARK
BATES STREET
LEHIGH ALLEY
PROSPECT STREET
ROCK ALLEY
UNCOLN STREET
GRANT STREET
DIAMOND ALLEY
ST. JOHN ALLEY
WARREN STREET
FIRTH STREET
SHILLINGER ALLEY
WILSON STREET
TIGHE ALLEY
RAILROAD AVE.
STOCKTON
ESSEX STREET
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVENUE
CHESTNUT ST.
CENTER
THOMAS
ANN
JAMES
WILLIAM ST.
PURSEL
ALLAN
MILL
GRIFFITH
WILBUR AVENUE
PEACH
PEARL
HILL
SAYRE AVENUE
CAHILL ST.
RICHARD RD.
METNER ROAD
LINCOLN ROAD
CENTER ST.
ABBOTT ST.
MORRIS
CANAL WAY
SAWMILL
BANK
NORTH
SOUTH
MAGNOLIA
WATERSON
STOCKTON
MAIN
LAKE
SPRUCE
PINE
MERCER
SOUTH
CEDAR
RIVER ST.
CHERRY
HOWARD
GATE STREET
TUTTLE
ARLINGTON ST.
CONGRESS
HILLSIDE
KATELYN CT.
RIDGE STREET
LOCK
WASHINGTON
VALLEY VIEW DR.
ROAD
STANLEY STREET
GREENWOOD
PEARL
GRAND
LOGAN
SHERWOOD ST.
BARNETT CT.
MADISON STREET
RIVERVIEW CIR.
RIVERVIEW ROAD
WOODLAWN ROAD
FOREST LN.
ELMHURST AVE.
DRIVE
CENTER ROAD
OAKLYN RD.
HEMLOCK DR.
NATALIE DRIVE
CARPENTERSVILLE ROAD
BELL
BEST
KNOLL VIEW DRIVE
HUDSON STREET
WARREN STREET
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WOODLAWN RD.

BRAINARD ST. O-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. O-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE O-18
CHESTNUT ST. L-25
CHINA AL. O-3
CHINTEWINK AL. O-6
CHRISTIE AL. P-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLEPY PL. H-15
COLUMBUS AVE. N-32
COMPRESSION ST. O-9
COMSTOCK AL. O-11
CONGRESS ST. O-11
CORLISS AVE. O-11
CROSS ST. O-11
CULVON ST. K-25
DAVIS ST. H-14
DEAN AL. F-11
DELAWARE RD. K-5
DIAMUCK AL. K-13
DRILL ST. M-11
DUGAN AL. K-11
ELDER AVE. K-11
ELIZABETH ST. B-11
ELLEN ST. K-14
ELM ST. F-19
ELMHURST DR. K-30
EMBURE ST. P-10
EMMA ST. K-22
ENGINE ST. H-11
ESSEX ST. I-19
EVELYN AVE. N-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. N-7
FARM ST. P-27
FERGUSON ST. F-8
FILMORE ST. L-11
FIFTH ST. M-7
FIRST AL. M-27
FIRTH ST. O-13
FISHER AVE. O-16
FOCHT BRIDGE F-7
FORREST LA. L-30
FOURTH ST. M-5
FOX AL. P-8
FOX ST. O-17
FRACE ST. P-27
FRANCIS AVE. I-10
FRANKLIN ST. O-10
FREDERICK ST. O-10
FRONT ST. K-10
FROST AVE. I-9
FULTON ST. K-9
GATE ST. M-14
GLEN AVE. K-27
GRACE AVE. F-11
GRAND ST. N-10
GRANT ST. O-29
GREEN AL. O-13
GREEN ST. F-11
GREENWOOD ST. P-22
GRIFFITH AL. P-29
HAGERTY AVE. M-25
HANOVER ST. N-7
HARRIS ST. O-13
HARTE ST. O-9
HECKMAN ST. P-9
HEMLOCK ST. I-15
HENDERSON ST. O-32
HENSHAW CT. O-11
HILL ST. H-25
HILLCREST BLVD. K-25
HILLSIDE RD. K-8
HOWARD ST. O-27
HUDSON ST. K-16
INGERSOLL AVE. O-16
IRWIN ST. O-11
IVY ST. O-12
JAKE BAKER WAY O-12
JAMES ST. O-16
JEFFERSON ST. O-23
JERSEY ST. E-19
JOHN ST. O-16
JOHN MITCHELL AVE. K-14
JOSEPH ST. N-9
JUDD AL. I-9
KAITLYN CT. I-9
KENT ST. I-27
KNEEDLER AVE. O-30
KNOLL VIEW DRIVE O-18
KORP AL. P-15
KURLAND AL. O-31
LAKE AL. O-25
LENNON AL. O-25
LESHER AL. O-25
LEWIS ST. O-25
LINCOLN RD. O-10
LINCOLN ST. O-10
LINER BLVD. O-10
LOCK ST. O-10
LOGAN ST. O-10
LYNDALE ST. O-10
LYNN TR. O-10
MADISON ST. O-10
MARKET ST. O-10
MARSHALL ST. O-10
MARY ST. O-10
McKEEN ST. O-10
MELROSE ST. O-10
MEMORIAL PKWY. O-10
MERCER ST. O-10
METZ ST. O-10
MEYNER RD. O-10
MILL ST. O-10
MILLER ST. O-10
MITCHELL AL. O-10
MORRIS ST. O-10
MOULE AL. O-10
NATALIE DRIVE O-10
NELSON ST. O-10
NORTH AL. O-10
NO. MAIN ST. O-10
NO. RIVERVIEW RD. O-10
OAK AL. O-10
ORCHARD AL. O-10
PARK RD. O-10
PEACH ST. O-10
PEAR AL. O-10
PEARL ST. O-10
PERIODE AVE. O-10
PICKFORD AVE. O-10
PINE AL. O-10
PLEASANT AVE. O-10
POTTS AVE. O-10
PROSPECT ST. O-10
PURSEL ST. O-10
RAILROAD AVE. O-10
RANDALL ST. O-10
RAYMOND ST. O-10
REESE WAY O-10
REESE CT. O-10
RICHARD RD. O-10
RICHMOND ST. O-10
RIDGE ST. O-10
RIVER ST. O-10
RIVERSIDE WAY O-10
RIVERVIEW CIR. O-10
RIVERVIEW RD. O-10
ROCK AL. O-10
ROSE ST. O-10
ROSEBERRY ST. O-10
SARGENT AVE. O-10
SAWMILL ST. O-10
SAYRE AVE. O-10
SCHULTZ AVE. O-10
SHARON AVE. O-10
SHERWOOD ST. O-10
SHILLINGER AL. O-10
SHIMER ST. O-10
SILK AVE. O-10
SKYDEAVES ST. O-10
SMITH AVE. O-10
SONORA ST. O-10
SO. MAIN ST. O-10
SPRINNER AL. O-10
SPRUCE AL. O-10
ST. JOHN AL. O-10
STANLEY ST. O-10
STEELE ST. O-10
STEWART AL. O-10
STOCKTON ST. O-10
STRYKER ST. O-10
STULL AL. O-10
SUNNY AVE. O-10
SUSAN ST. O-10
TAYLOR AL. O-10
TERRY ST. O-10
THIRD ST. O-10
THOMAS ST. O-10
TIGHE AL. O-10
TITUS AL. O-10
TUTTLE ST. O-10
TYNDALL AVE. O-10
UNION SQ. O-10
VALLEY VIEW CIR. O-10
WALNUT ST. O-10
WARREN ST. O-10
WASHINGTON ST. O-10
WATSON PL. O-10
WEBSTER ST. O-10
WILBUR AVE. O-10
WILLEVER ST. O-10
WILLIAM ST. O-10
WILSON ST. O-10
WOODLAWN RD. O-10



Snyder & Pugh
10-24-22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. O-18
CENTER RD. O-32
CENTER ST. L-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-5
CHINTEWINK AL. D-6
CHRISTIE AL. D-13
CHURCH ST. B-11
CLAIRMONT ST. O-31
COLBY PL. N-15
COLUMBUS AVE. J-25
COMPRESSOR ST. F-14
COMSTOCK AL. F-11
CONGRESS ST. K-11
CORLISS AVE. K-11
CROSS ST. K-5
CULVON ST. K-13
DAMS ST. K-13
DEAN AL. K-11
DELAWARE RD. K-11
DIMMICK AL. B-11
DRILL ST. B-11
DUGAN AL. B-14
ELDER AVE. B-14
ELIZABETH ST. B-14
ELLEN ST. B-14
ELM ST. B-18
ELMHURST DR. N-30
EMIRE ST. N-10
EMMA ST. N-22
ENGINE ST. K-19
ESSEX ST. K-19
EVELYN AVE. K-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. O-8
FARM ST. K-27
FERGUSON ST. B-8
FILMORE ST. F-11
FIFTH ST. F-11
FIRST AL. F-27
FIRTH ST. F-13
FISHER AVE. K-13
FOCHT BRIDGE N-18
FORREST LA. N-7
FOURTH ST. N-7
FOX AL. K-5
FOX ST. F-8
FRACE ST. F-17
FRANCIS AVE. F-10
FRANKLIN ST. F-10
FREDERICK ST. F-10
FRONT ST. F-10
FROST AVE. F-10
FULTON ST. F-9
GATE ST. F-14
GLEN AVE. F-11
GRACE AVE. F-10
GRAND ST. F-29
GRANT ST. F-13
GREEN AL. F-13
GREEN ST. F-22
GREENWOOD ST. F-29
GRIFFITH AL. F-25
HAGERTY AVE. F-13
HANOVER ST. O-7
HARRIS ST. O-9
HARTE ST. O-9
HECKMAN ST. O-15
HEMLOCK ST. O-32
HENDERSON ST. O-11
HENSHAW CT. O-11
HILL ST. O-25
HILLCREST BLVD. O-9
HILLSIDE RD. O-27
HOWARD ST. O-16
HUDSON ST. O-12
INGERSOLL AVE. O-11
IRWIN ST. O-12
IVY ST. O-15
J. J. BAKER WAY O-15
JAMES ST. O-23
JEFFERSON ST. O-16
JERSEY ST. O-14
JOHN ST. O-11
JOHN MITCHELL AVE. O-9
JOSEPH ST. O-9
JUDD AL. O-10
KAITLYN CT. P-27
KENT ST. O-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE O-17
KORP AL. O-17
KURLAND AL. O-17
LAKE AL. O-17
LENNON AL. O-17
LESHER AL. O-17
LEWIS ST. O-17
LINDOLN RD. O-17
LINCOLN RD. O-17
LINCOLN ST. O-17
LINER BLVD. O-17
LOCK ST. O-17
LOGAN ST. O-17
LYNDALE ST. O-17
LYNN RD. O-17
MADISON ST. O-17
MARKET ST. O-17
MARSHALL ST. O-17
MARY ST. O-17
McKEEN ST. O-17
MELROSE ST. O-17
MEMORIAL PKWY. O-17
MERCER ST. O-17
METZ ST. O-17
MEYNER RD. O-17
MILL ST. O-17
MILLER ST. O-17
MITCHELL AL. O-17
MORRIS ST. O-17
MOULE AL. O-17
NATALIE DRIVE O-17
NELSON ST. O-17
NORTH AL. O-17
NO. MAIN ST. O-17
NO. RIVERVIEW RD. O-17
OAK AL. O-17
ORCHARD AL. O-17
PARK RD. O-17
PEACH ST. O-17
PEAR AL. O-17
PEARL ST. O-17
PERDOE AVE. O-17
PICKFORD AVE. O-17
PINE AL. O-17
PLEASANT AVE. O-17
POTTS AVE. O-17
PROSPECT ST. O-17
PURSEL ST. O-17
RAILROAD AVE. O-17
RANDALL ST. O-17
RAYMOND ST. O-17
REESE WAY O-17
REESE CT. O-17
RICHARD RD. O-17
RICHMOND ST. O-17
RIDGE ST. O-17
RIVER ST. O-17
RIVERSIDE WAY O-17
RIVERVIEW CIR. O-17
RIVERVIEW RD. O-17
ROCK AL. O-17
ROSE ST. O-17
ROSEBERRY ST. O-17
SARGENT AVE. O-17
SAWMILL ST. O-17
SAYRE AVE. O-17
SCHULTZ AVE. O-17
SHAFER AVE. O-17
SHERWOOD ST. O-17
SHILLINGER AL. O-17
SHIVER ST. O-17
SILK AL. O-17
SITGREAVES ST. O-17
SMITH AVE. O-17
SONORA ST. O-17
SO. MAIN ST. O-17
SPINNER AL. O-17
SPRUCE AL. O-17
ST. JOHN AL. O-17
STANLEY ST. O-17
STEELE ST. O-17
STEWART AL. O-17
STOCKTON ST. O-17
STRYKER ST. O-17
STULL AL. O-17
SUMMIT AVE. O-17
SUSAN ST. O-17
TAYLOR AL. O-17
TERRY ST. O-17
THIRD ST. O-17
THOMAS ST. O-17
TIGHE AL. O-17
TITUS AL. O-17
TUTTLE ST. O-17
TYNDALL AVE. O-17
UNION SQ. O-17
VALLEY VIEW CIR. O-17
WALNUT ST. O-17
WARREN ST. O-17
WASHINGTON ST. O-17
WATSON PL. O-17
WEBSTER ST. O-17
WILBUR AVE. O-17
WILLEVER ST. O-17
WILLIAM ST. O-17
WILSON ST. O-17
WOODLAWN RD. O-17

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

10/17/22

Snyder & Summit

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET

BARRYMORE AVENUE

FROST AVENUE

BOWERS AVE.

HILLCREST STREET

PICKFORD STREET

METZ STREET

HARTE ST.

FRACE STREET

BURKE STREET

FREDERICK STREET

SARGENT AVENUE

FAIRBANKS STREET

WASHINGTON BOULEVARD

JOHN STREET

GRACE STREET

CORLISS AVENUE

ELDER AVENUE

SUSAN ST.

TAYLOR STREET

THRESHOLD AVENUE

SUPPRESSOR STREET

PROSPECT STREET

LINCOLN ROAD

FERGUSON ST.

LINER BLVD.

TILDRESS SOUTH

TILDRESS NORTH

BELVIDERE AVENUE

DELAWARE ROAD

MEMORIAL PARKWAY (RT. 22)

MARSHALL STREET

HECKMAN STREET

FISHER PLACE

KNEEDLER AVENUE

WATSON STREET

ANDERSON STREET

BATES STREET

LINCOLN STREET

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

STOCKTON STREET

ESSEX STREET

IRWIN STREET

MILLER STREET

HENDERSON STREET

SHULTZ AVE.

EVELYN AVE.

RAYMOND ST.

ORCHARD ALLEY

FOURTH STREET

THIRD STREET

MAIN STREET

SOUTH STREET

MARKET STREET

ELIZABETH ST.

HARRIS STREET

CHAMBERS STREET

BULLMAN STREET

BURWELL STREET

BENNETT STREET

MITCHELL STREET

SUMMIT AVE.

SHIMER ST.

BRAINARD STREET

FRONT STREET

PLEASANT STREET

WASHINGTON STREET

HOWARD STREET

MERCER STREET

HANOVER STREET

BESSE COURT

WALNUT STREET

ELM STREET

GREEN STREET

COLUMBUS AVENUE

CAHILL ST.

RICHARD RD.

SAYRE AVENUE

WILBUR AVENUE

MILL STREET

GRIFFITH ALLEY

PERDOE ALLEY

HILL STREET

BANK STREET

MEYNER ROAD

LINCOLN ROAD

CENTER STREET

CHESTNUT STREET

THOMAS STREET

ANN STREET

JAMES STREET

PURSEL STREET

WILLIAM ST.

MADISON STREET

CONGRESS STREET

HILLSIDE

KAITLYN CT.

GATE STREET

TUTTLE STREET

TYNDALL AVE.

RIDGE STREET

LOCK STREET

MELROSE STREET

STANLEY STREET

PEARL STREET

GRAND STREET

LOGAN STREET

LYNDALE ST.

OLD MILL ROAD

VALLEY VIEW CIR.

GREENWOOD ST.

SYCAMORE ST.

BROADVIEW ST.

BARTLEY CIR.

KENT STREET

NORTH MAIN ST.

CANAL WAY

MORRIS STREET

SAWMILL ST.

ABBOTT ST.

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW ROAD

WOODLAWN ROAD

FOREST LN.

BELT AVE.

ELMHURST DRIVE

NATALIE DRIVE

CARPENTERSVILLE ROAD

OAKLYN RD.

HEMLOCK DR.

HEMLOCK CIRCLE

NORTH MAIN ST.

SOUTH MAIN ST.

MORRIS CANAL


DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

I-78

BRAINARD ST.	C-11
BROAD ST.	C-6
BROADVIEW ST.	N-32
BULLMAN ST.	D-9
BURKE ST.	D-9
BURWELL AL.	D-9
CAHILL ST.	K-20
CARHART AL.	L-28
CARPENTERSVILLE RD.	K-31
CEDAR AL.	E-18
CENTER RD.	L-32
CENTER ST.	L-32
CHAMBERS ST.	D-11
CHERRY LANE	L-18
CHESTNUT ST.	L-21
CHINA AL.	D-5
CHINTZWINK AL.	E-6
CHRISTIE AL.	H-5
CHURCH ST.	D-11
CLARMONT ST.	L-31
COLBY PL.	D-15
COLUMBUS AVE.	L-15
COMPRESSOR ST.	N-
COMSTOCK AL.	Z-1
CONGRESS ST.	D-25
CORLISS AVE.	K-14
CROSS ST.	K-11
CULVON ST.	K-5
DAVIS ST.	K-13
DEAN AL.	N-11
DELAWARE RD.	N-11
DIAMOND AL.	K-11
DRILL ST.	N-11
DUGAN AL.	L-11
ELDER AVE.	B-7
ELIZABETH ST.	B-11
ELLEN ST.	B-14
ELM ST.	B-18
ELMHURST DR.	B-19
EMIRE ST.	B-30
EMMA ST.	N-22
ENGINE ST.	B-5
ESSEX ST.	L-19
EVELYN AVE.	L-11
FAIRBANKS ST.	L-8
FAIRVIEW AVE.	L-7
FARM ST.	B-27
FERGUSON ST.	L-11
FILMORE ST.	B-11
FIFTH ST.	B-9
FIRST AL.	B-27
FIRTH ST.	L-13
FISHER AVE.	B-18
FOCHT BRIDGE	L-30
FORREST LA.	L-30
FOURTH ST.	B-5
FOX AL.	B-8
FOX ST.	L-17
FRACE ST.	L-10
FRANCIS AVE.	L-10
FRANKLIN ST.	L-10
FREDERICK ST.	L-10
FRONT ST.	L-10
FROST AVE.	L-9
FULTON ST.	L-14
GATE ST.	L-27
GLEN AVE.	L-11
GRACE AVE.	L-9
GRAND ST.	L-29
GRANT ST.	L-13
GREEN AL.	L-11
GREEN ST.	L-22
GREENWOOD ST.	L-29
GRIFFITH AL.	L-25
HAGERTY AVE.	L-7
HANOVER ST.	L-13
HARRIS ST.	L-9
HARTE ST.	L-9
HECKMAN ST.	L-11
HEMLOCK ST.	L-32
HENDERSON ST.	L-11
HENSHAW CT.	L-11
HILL ST.	L-25
HILLCREST BLVD.	L-9
HILLSIDE RD.	L-27
HOWARD ST.	L-16
HUDSON ST.	L-12
INGERSOLL AVE.	L-12
IRWIN ST.	L-12
IVY ST.	L-19
JAMES ST.	L-19
JEFFERSON ST.	L-19
JERSEY ST.	L-19
JOHN ST.	L-14
JOHN MITCHELL AVE.	N-9
JOSEPH ST.	L-9
JUDD AL.	L-14
KAITLYN CT.	L-27
KENT ST.	L-30
KNEEDLER AVE.	L-16
KNOLL VIEW DRIVE	L-31
KORP AL.	L-25
KURLAND AL.	L-25
LAKE AL.	L-15
LENNOX AL.	L-32
LESHER AL.	L-32
LEWIS ST.	L-32
LINDSLIN RD.	L-32
LINCOLN RD.	L-32
LINCOLN ST.	L-32
LINER BLVD.	L-32
LOCK ST.	L-22
LOGAN ST.	L-22
LYNDALE ST.	L-30
LYNN RD.	N-30
MADISON ST.	L-30
MARKET ST.	L-14
MARSHALL ST.	L-14
MARY ST.	L-14
McKEEN ST.	L-14
MELROSE ST.	L-14
MEMORIAL PKWY.	L-14
MERCER ST.	L-14
METZ ST.	L-14
MEYNER RD.	L-14
MILL ST.	L-25
MILLER ST.	L-25
MITCHELL AL.	L-25
MORRIS ST.	L-25
MOULE AL.	L-25
NATALIE DRIVE	L-32
NELSON ST.	L-32
NORTH AL.	L-32
NO. MAIN ST.	L-32
NO. RIVERVIEW RD.	L-32
OAK AL.	L-32
ORCHARD AL.	L-32
PARK RD.	L-32
PEACH ST.	L-32
PEAR AL.	L-32
PEARL ST.	L-32
PERDOE AVE.	L-32
PICKFORD AVE.	L-32
PINE AL.	L-32
PLEASANT AVE.	L-32
POTTS AVE.	L-32
PROSPECT ST.	L-32
PURSEL ST.	L-32
RAILROAD AVE.	L-32
RANDALL ST.	L-32
RAYMOND ST.	L-32
REESE WAY	L-32
REESE CT.	L-32
RICHARD RD.	L-32
RICHMOND ST.	L-32
RIDGE ST.	L-32
RIVER ST.	L-32
RIVERSIDE WAY	L-32
RIVERVIEW CIR.	L-32
RIVERVIEW RD.	L-32
ROCK AL.	L-32
ROSE ST.	L-32
ROSEBERRY ST.	L-32
SARGENT AVE.	L-32
SAWMILL ST.	L-32
SAYRE AVE.	L-32
SCHULTZ AVE.	L-32
SHAFER AVE.	L-32
SHERWOOD ST.	L-32
SHILLINGER AL.	L-32
SHIMER ST.	L-32
SILK AVE.	L-32
STIRGEAVES ST.	L-32
SMITH AVE.	L-32
SONORA ST.	L-32
SO. MAIN ST.	L-32
SPINNER AL.	L-32
SPRUCE AL.	L-32
ST. JOHN AL.	L-32
STANLEY ST.	L-32
STEELE ST.	L-32
STEWART AL.	L-32
STOCKTON ST.	L-32
STRYKER ST.	L-32
STULL AL.	L-32
SUMMIT AVE.	L-32
SUSAN ST.	L-32
TAYLOR AL.	L-32
TERRY ST.	L-32
THIRD ST.	L-32
THOMAS ST.	L-32
TIGHE AL.	L-32
TITUS AL.	L-32
TUTTLE ST.	L-32
TYNDALL AVE.	L-32
UNION SQ.	L-32
VALLEY VIEW CIR.	L-32
WALNUT ST.	L-32
WARREN ST.	L-32
WASHINGTON ST.	L-32
WATSON PL.	L-32
WEBSTER ST.	L-32
WILBUR AVE.	L-32
WILLEVA ST.	L-32
WILLIAM ST.	L-32
WILSON ST.	L-32
WISE AL.	L-32
WOODLAWN RD.	L-32



USROPONML
IGFEDCBA

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

10/4/22

Duckworth

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

WALNUT STREET

COLUMBUS AVENUE

PROSPECT STREET

LINCOLN ROAD

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

HENDERSON

MARKET ST.

ELIZABETH ST.

HOWARD

MERCER STREET

SAYRE AVENUE

CANAL WAY

MORRIS

SOUTH MAIN STREET

NORTH MAIN STREET

STANLEY STREET

LOGAN STREET

PEARL ST.

GRAND ST.

MADISON STREET

WOODLAWN ROAD

RIVERVIEW CIR.

RIVERVIEW ROAD

FOREST LN.

BELT ROAD

CARPENTERSVILLE ROAD

ELMHURST ROAD

OAKLYN RD.

HEMLOCK DR.

NATALIE DRIVE

LINCOLN HWY.

METNER ROAD

RICHARD RD.

CAHILL ST.

LYNN RD.

BRAINARD ST. O-11
BROAD ST. O-6
BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARMART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. G-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. O-9
CHINA AL. L-21
CHINTENWAK AL. O-5
CHRISTIE AL. K-13
CHURCH ST. B-11
CLAIRMONT ST. C-31
COLBY PL. H-11
COLUMBUS AVE. O-13
COMPRESSOR ST. O-25
CONESTOCK AL. O-14
CONGRESS ST. K-11
CORLISS AVE. O-11
CROSS ST. O-18
CULVON ST. O-9
DAVIS ST. O-9
DEAN AL. L-21
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. K-11
ELDER AVE. K-11
ELIZABETH ST. B-11
ELLEN ST. B-14
ELM ST. B-19
ELMHURST DR. H-30
EMBIE ST. H-10
EMMA ST. K-22
ENGINE ST. K-11
ESSEX ST. O-18
EVELYN AVE. O-11
FAIRBANKS ST. O-9
FAIRVIEW AVE. O-9
FARM ST. K-27
FERGUSON ST. I-8
FILMORE ST. I-11
FIFTH ST. I-14
FIRST AL. I-27
FIRTH ST. I-13
FISHER AVE. K-28
FOCHT BRIDGE I-7
FORREST LA. I-30
FOURTH ST. K-5
FOX AL. K-6
FOX ST. K-17
FRACE ST. I-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. I-10
FROST AVE. I-9
FULTON ST. K-14
GATE ST. K-27
GLEN AVE. K-11
GRACE AVE. K-10
GRAND ST. K-29
GRANT ST. K-13
GREEN AL. K-11
GREEN ST. K-22
GREENWOOD ST. K-29
GRIFFITH AL. K-25
HAGERTY AVE. I-7
HANOVER ST. N-13
HARRIS ST. I-9
HARTE ST. I-7
HECKMAN ST. I-15
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. I-11
HILL ST. I-25
HILLCREST BLVD. I-9
HILLSIDE RD. K-27
HOWARD ST. I-16
HUDSON ST. I-12
INGERSOLL AVE. I-11
IRWIN ST. I-15
IVY ST. I-15
J. J. BAKER WAY I-23
JAMES ST. I-23
JEFFERSON ST. I-16
JERSEY ST. I-14
JOHN ST. I-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. I-9
JUDD AL. I-5
KAITLYN CT. K-27
KENT ST. I-30
KNEEDLER AVE. I-16
KNOLL VIEW DRIVE I-31
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. I-25
LENNON AL. I-25
LESHER AL. I-25
LEWIS ST. I-25
LIMEKILN RD. I-25
LINCOLN ST. I-25
LINER BLVD. I-25
LOCK ST. I-25
LOGAN ST. I-25
LYNDALE ST. I-25
LYNN RD. I-25
MADISON ST. I-25
MARKET ST. I-25
MARSHALL ST. I-14
MARY ST. I-14
McKEON ST. E-31
MELROSE ST. I-13
MEMORIAL PKWY. I-13
MERCER ST. I-18
METZ ST. I-18
MEYNER RD. I-18
MILL ST. I-25
MILLER ST. I-11
MITCHELL AL. I-11
MORRIS ST. I-8
MOULE AL. I-21
NATALIE DRIVE I-30
NELSON ST. I-30
NORTH AL. I-30
NO. MAIN ST. I-8
NO. RIVERVIEW RD. I-28
OAK AL. I-13
ORCHARD AL. I-9
PARK RD. I-24
PEACH ST. I-22
PEAR AL. I-29
PEARL ST. I-29
PERDOE AVE. I-25
PICKFORD AVE. I-25
PINE AL. I-16
PLEASANT AVE. I-10
POTTS AVE. I-10
PROSPECT ST. I-10
PURSEL ST. I-14
RAILROAD AVE. I-14
RANDALL ST. I-14
RAYMOND ST. I-14
REESE WAY I-27
REESE CT. I-27
RICHARD RD. I-27
RICHMOND ST. I-28
RIDGE ST. I-28
RIVER ST. I-28
RIVERSIDE WAY I-28
RIVERVIEW CIR. I-28
RIVERVIEW RD. I-28
ROCK AL. I-28
ROSE ST. I-28
ROSEBERRY ST. I-28
SARGENT AVE. I-28
SAWMILL ST. I-28
SAYRE AVE. I-28
SCHULTZ AVE. I-28
SHAFER AVE. I-28
SHERWOOD ST. I-28
SHILLINGER AL. I-28
SHIMER ST. I-28
SILK AVE. I-28
SITGREAVES ST. I-28
SMITH AVE. I-28
SONOMA ST. I-28
SO. MAIN ST. I-28
SPINNER AL. I-28
SPRUCE AL. I-28
ST. JOHN AL. I-28
STANLEY ST. I-28
STEELE ST. I-28
STEWART AL. I-28
STOCKTON ST. I-28
STRYKER ST. I-28
STULL AL. I-28
SUMMIT AVE. I-28
SUSAN ST. I-28
TAYLOR AL. I-28
TERRY ST. I-28
THIRD ST. I-28
THOMAS ST. I-28
TIGHE AL. I-28
TITUS AL. I-28
TUTTLE ST. I-28
TYNDALL AVE. I-28
UNION SQ. I-28
VALLEY VIEW CIR. I-28
WALNUT ST. I-28
WARREN ST. I-28
WASHINGTON ST. I-28
WATSON PL. I-28
WEBSTER ST. I-28
WILBUR AVE. I-28
WILLEVER ST. I-28
WILLIAM ST. I-28
WILSON ST. I-28
WISE AL. I-28
WOODLAWN RD. I-28

9-22-22 Strips

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE O-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. G-6
CHRISTIE AL. N-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. E-11
COLUMBUS AVE. I-22
COMPRESSOR ST. E-11
COMSTOCK AL. N-11
CONGRESS ST. E-11
CORLISS AVE. E-11
CROSS ST. D-15
CULVON ST. D-25
DAVIS ST. H-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. G-14
ELM ST. P-10
ELMHURST DR. H-30
EMPIRE ST. P-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. O-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. I-7
FARM ST. F-27
FERGUSON ST. F-8
FILMORE ST. L-11
FIFTH ST. L-27
FIRST AL. K-27
FIRTH ST. K-13
FISHER AVE. P-16
FOOHT BRIDGE E-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. O-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. N-10
FREDERICK ST. O-10
FRONT ST. O-9
FROST AVE. B-9
FULTON ST. E-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-28
GRIFFITH AL. M-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. O-9
HARTE ST. O-9
HECKMAN ST. F-15
HEMLOCK ST. I-32
HENDERSON ST. I-26
HENSHAW CT. I-11
HILL ST. L-25
HILLCREST BLVD. K-9
HILLSIDE RD. O-27
HOWARD ST. O-16
HUDSON ST. O-12
INGERSOLL AVE. O-11
IRWIN ST. O-12
IVY ST. O-15
JAMES P. BAKER WAY O-32
JEFFERSON ST. J-23
JERSEY ST. E-19
JOHN ST. O-16
JOHN MITCHELL AVE. O-14
JOSEPH ST. N-9
JUDD AL. N-9
KAITLYN CT. I-5
KENT ST. P-27
KNEEDLER AVE. P-30
KNOLL VIEW DRIVE K-16
KORP AL. N-31
KURLAND AL. L-25
LAKE AL. L-11
LENNON AL. L-11
LESHER AL. L-11
LEWIS ST. L-11
LINCOLN RD. L-11
LINCOLN ST. L-11
LINER BLVD. L-11
LOCK ST. L-11
LOGAN ST. L-11
LYNDALE ST. L-11
LYNN RD. L-11
MADISON ST. L-11
MARKET ST. L-11
MARSHALL ST. L-11
MARY ST. L-11
McKEEN ST. L-11
MELROSE ST. L-11
MEMORIAL PKWY. L-11
MERCER ST. L-11
METZ ST. L-11
MEYNER RD. L-11
MILL ST. L-11
MILLER ST. L-11
MITCHELL AL. L-11
MORRIS ST. L-11
MOULE AL. L-11
NATALIE DRIVE L-11
NELSON ST. L-11
NORTH AL. L-11
NO. MAIN ST. L-11
NO. RIVERVIEW RD. L-11
OAK AL. L-11
ORCHARD AL. L-11
PARK RD. L-11
PEACH ST. L-11
PEAR AL. L-11
PEARL ST. L-11
PERIODE AVE. L-11
PICKFORD AVE. L-11
PINE AL. L-11
PLEASANTY AVE. L-11
POTTS AVE. L-11
PROSPECT ST. L-11
PURSEL ST. L-11
RAILROAD AVE. L-11
RANDALL ST. L-11
RAYMOND ST. L-11
REESE WAY L-11
REESE CT. L-11
RICHARD RD. L-11
RICHMOND ST. L-11
RIDGE ST. L-11
RIVER ST. L-11
RIVERSIDE WAY L-11
RIVERVIEW CIR. L-11
RIVERVIEW RD. L-11
ROCK AL. L-11
ROSE ST. L-11
ROSSBERRY ST. L-11
SARGENT AVE. L-11
SAWMILL ST. L-11
SAYRE AVE. L-11
SCHULTZ AVE. L-11
SHAFER AVE. L-11
SHERWOOD ST. L-11
SHILLINGER AL. L-11
SHIMER ST. L-11
SILK AVE. L-11
SITGREAVES ST. L-11
SMITH AVE. L-11
SONORA ST. L-11
SO. MAIN ST. L-11
SPINNER AL. L-11
SPRUCE AL. L-11
ST. JOHN AL. L-11
STANLEY ST. L-11
STEELE ST. L-11
STEWART AL. L-11
STOCKTON ST. L-11
STRYKER ST. L-11
STULL AL. L-11
SUMMIT AVE. L-11
SUSAN ST. L-11
TAYLOR AL. L-11
TERRY ST. L-11
THIRD ST. L-11
THOMAS ST. L-11
TICHE AL. L-11
TITUS AL. L-11
TUTTLE ST. L-11
TYNDALL AVE. L-11
UNION SQ. L-11
VALLEY VIEW CIR. L-11
WALNUT ST. L-11
WARREN ST. L-11
WASHINGTON ST. L-11
WATSON PL. L-11
WEBSTER ST. L-11
WILBUR AVE. L-11
WILLEVER ST. L-11
WILLIAM ST. L-11
WILSON ST. L-11
WISE PL. L-11
WOODLAWN RD. L-11

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

9/22/22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

U.S. ROUTE 22

U.S. HIGHWAY 22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CANHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. D-18
CENTER RD. D-32
CENTER ST. C-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-8
CHINTEWINK AL. E-13
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. D-31
COLBY PL. D-15
COLUMBUS AVE. D-25
COMPRESSOR ST. H-14
COMSTOCK AL. F-7
CONGRESS ST. H-14
CORLISS AVE. E-22
CROSS ST. D-15
CULKIN ST. D-25
DAVIS ST. H-14
DEAN AL. F-7
DELAWARE RD. F-31
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. E-11
ELIZABETH ST. B-11
ELLEN ST. D-14
ELM ST. D-14
ELMHURST DR. H-30
EMIRE ST. H-10
EMMA ST. K-22
ENGINE ST. E-11
ESSEX ST. L-19
EVELYN AVE. E-8
FAIRBANKS ST. F-7
FAIRVIEW AVE. L-27
FARM ST. K-24
FERGUSON ST. F-11
FILMORE ST. K-13
FIFTH ST. B-11
FIRST AL. H-27
FIRTH ST. K-13
FISHER AVE. D-16
FOCHT BRIDGE N-30
FORREST LA. N-29
FOURTH ST. N-29
FOX AL. B-17
FOX ST. C-7
FRACE ST. H-10
FRANCIS AVE. F-10
FRANKLIN ST. H-10
FREDERICK ST. H-10
FRONT ST. B-10
FROST AVE. H-14
FULTON ST. D-14
GATE ST. H-27
GLEN AVE. K-11
GRACE AVE. H-10
GRAND ST. D-29
GRANT ST. L-13
GREEN AL. L-21
GREEN ST. C-22
GREENWOOD ST. H-29
GRIFFITH AL. M-25
HAGERTY AVE. H-13
HANOVER ST. B-9
HARRIS ST. B-9
HARTE ST. D-11
HECKMAN ST. L-32
HEMLOCK ST. H-32
HENDERSON ST. D-11
HENSHAW CT. H-11
HILL ST. L-25
HILLCREST BLVD. H-11
HILLSIDE RD. K-27
HOWARD ST. D-8
HUDSON ST. D-12
INGERSOLL AVE. D-17
IRWIN ST. D-12
IVY ST. D-15
J. ALEXANDER WAY L-23
JAMES ST. M-23
JEFFERSON ST. L-19
JERSEY ST. D-16
JOHN ST. D-14
JOHN MITCHELL AVE. H-8
JOSEPH ST. E-8
JUDD AL. K-13
KAITLYN CT. H-27
KENT ST. L-30
KNEEDLER AVE. D-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. L-25
LAKE AL. K-8
LENNOX AL. D-32
LESHER AL. G-30
LEWIS ST. D-30
LINCOLN RD. K-20
LINCOLN ST. D-18
LINER BLVD. D-32
LOCK ST. G-30
LOGAN ST. H-31
LYNDALE ST. N-19
LYNN RD. N-30
MADISON ST. N-30
MARKET ST. D-12
MARSHALL ST. I-14
MARY ST. I-14
McKEEN ST. E-21
MELROSE ST. P-13
MEMORIAL PKWY. G-16
MERCER ST. G-10
METZ ST. H-10
MEYNER RD. I-19
MILL ST. M-25
MILLER ST. J-11
MITCHELL AL. D-10
MORRIS ST. B-8
MOULE AL. M-21
NATALIE DRIVE A-32, K-
NELSON ST. M-30
NORTH AL. I-14
NO. MAIN ST. C-8
NO. RIVERVIEW RD. M-29
OAK AL. H-13
ORCHARD AL. B-8
PARK RD. K-24
PEACH ST. K-22
PEAR AL. E-11
PEARL ST. E-11
PERDOE AVE. L-28
PICKFORD AVE. L-25
PINE AL. F-11
PLEASANT AVE. F-16
POTTS AVE. B-10
PROSPECT ST. B-11
PURSEL ST. M-10
RAILROAD AVE. M-24
RANDALL ST. I-14
RAYMOND ST. G-10
REESE WAY G-9
REESE CT. B-11
RICHARD RD. B-14
RICHMOND ST. K-21
RIDGE ST. N-29
RIVER ST. N-29
RIVERSIDE WAY C-7
RIVERVIEW CIR. C-27
RIVERVIEW RD. H-29
ROCK AL. M-8
ROSE ST. M-8
ROSEBERRY ST. G-9
SARGENT AVE. B-11
SAWMILL ST. K-25
SAYRE AVE. L-23
SCHULTZ AVE. H-11
SHAFER AVE. D-8
SHERWOOD ST. D-30
SHILLINGER AL. D-14
SHIMER ST. G-11
SILK AVE. C-15
STIRGEAVES ST. P-18
SMITH AVE. C-17
SOMORA ST. C-20
SQ. MAIN ST. G-20
SPINNER AL. B-9
SPRUCE AL. B-11
ST. JOHN AL. F-16
STANLEY ST. F-14
STEELE ST. G-29
STEWART AL. O-29
STOCKTON ST. N-28
STRYKER ST. G-16
STULL AL. D-12
SUMMIT AVE. D-8
SUSAN ST. D-10
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TIGHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WIRE AL.
WOODLAWN RD.

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

9-22-22
Tom C

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
BARRYMORE AVENUE
FROST AVENUE
BOWERS AVE.
HILLCREST AVENUE
PICKFORD STREET
METZ STREET
HARTE ST.
FRACE ST.
BURKE STREET
FREDERICK AVENUE
MORELL AVENUE
SARGENT AVENUE
JOHN STREET
INGERSOLL AVENUE
GRACE STREET
CORISS AVENUE
ELBERT AVENUE
FAIRBANKS STREET
MASERT ST.
FERGUSON ST.
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE AVENUE
DELAWARE ROAD
HALDRESS SOUTH
HALDRESS NORTH
POTTS AVE.
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
FISHER PLACE
KNEEDLER AVENUE
ANDERSON STREET
WATSON PLACE
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVENUE
BATES STREET
PROSPECT STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
HENDERSON STREET
SHULTZ AVE.
EVELYN AVE.
RAYMOND ST.
ORCHARD ALLEY
DAVIS PLACE
COLBY PLACE
STOCKTON STREET
HUDSON STREET
IRWIN STREET
FRANCIS AVE.
MILLER STREET
WEST BOUND AVENUE
EAST BOUND AVENUE
FOURTH STREET
THIRD STREET
BACH ST.
GLEN AVENUE
FILMORE STREET
LEWIS STREET
TAYLOR STREET
WASHINGTON STREET
SUMMIT AVE.
MITCHELL STREET
BULLMAN STREET
BURWELL STREET
BENNETT STREET
STULL ALLEY
CHAMBERS STREET
HARRIS STREET
SHIMER ST.
BRAINARD WAY
FRONT STREET
PLEASANT STREET
LAKE AL.
MARKET STREET
ELIZABETH ST.
STRYKER ST.
HANOVER STREET
RESSE COURT
MERCER STREET
HOWARD STREET
SOUTH MAIN STREET
SPRUCE ST.
CEDAR ST.
CHERRY ST.
CHESTNUT ST.
PEACH ST.
PEAR AL.
ORCHARD AL.
PARK RD.
PEARL ST.
PERIDOT AVE.
PICHFORD AVE.
PINE AL.
PLEASANT AVE.
POTTS AVE.
PROSPECT ST.
PURSEL ST.
RAILROAD AVE.
RANDALL ST.
RAYMOND ST.
REESE WAY
REESE CT.
RICHARD RD.
RICHMOND ST.
RIDGE ST.
RIVER ST.
RIVERSIDE WAY
RIVERVIEW CIR.
RIVERVIEW RD.
ROCK AL.
ROSE ST.
ROSEBERRY ST.
SARGENT AVE.
SAWMILL ST.
SAYRE AVENUE
SCHULTZ AVE.
SHAFER AVE.
SHERWOOD ST.
SHILLINGER AL.
SHIMER ST.
SILK AVE.
STIRGEAVES ST.
SMITH AVE.
SONORA ST.
SQ. MAIN ST.
SPRINGER AL.
SPRUCE AL.
ST. JOHN AL.
STANLEY ST.
STEELE ST.
STEWART AL.
STOCKTON ST.
STRYKER ST.
STULL AL.
SUMMIT AVE.
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TIGHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WIRE AL.
WOODLAWN RD.
GATE STREET
TUTTLE STREET
ARLINGTON ST.
RIDGE STREET
LOCK STREET
MELROSE STREET
STANLEY STREET
PEARL STREET
GRAND STREET
CONGRESS STREET
HILLSIDE ST.
KAITLYN CT.
MADISON STREET
LOGAN STREET
CLAWSON AVE.
LINCOLN AVE.
VALLEY VIEW DR.
KNOLL VIEW DRIVE
NATALIE DRIVE
RIVERVIEW CIR.
NORTH RIVERVIEW ROAD
WOODLAWN ROAD
FORREST LN.
BELT ROAD
ELMHURST DRIVE
CARPENTERSVILLE ROAD
DANLYN RD.
HEMLOCK DR.
CHERRY LANE
CHESTNUT ST.
CHAMBERS ST.
CENTER ST.
CENTER RD.
CEDAR AL.
CARPENTERSVILLE RD.
CAHILL ST.
CANAL WAY
MORRIS STREET
SAWMILL ST.
MAIN ST.
LIMEKILN ROAD
PURSEL STREET
KURLAND AL.
ALLAN STREET
MILL STREET
GRIFFITH ALLEY
WILBUR AVENUE
PERIDOT ALLEY
HILL STREET
BANK STREET
GARNART AL.
JAMES ST.
WILLIAM ST.
THOMAS STREET
ANN STREET
CENTER STREET
CHESTNUT ST.
PEACH ST.
WEBSTER ST.
PARK RD.
MOULE ALLEY
STEWART ALLEY
CURKIN STREET
ALLEY 1
ALLEY 2
ALLEY 3
ALLEY 4
ALLEY 5
ALLEY 6
ALLEY 7
ALLEY 8
ALLEY 9
ALLEY 10
ALLEY 11
ALLEY 12
ALLEY 13
ALLEY 14
ALLEY 15
ALLEY 16
ALLEY 17
ALLEY 18
ALLEY 19
ALLEY 20
ALLEY 21
ALLEY 22
ALLEY 23
ALLEY 24
ALLEY 25
ALLEY 26
ALLEY 27
ALLEY 28
ALLEY 29
ALLEY 30
ALLEY 31
ALLEY 32
ALLEY 33
ALLEY 34
ALLEY 35
ALLEY 36
ALLEY 37
ALLEY 38
ALLEY 39
ALLEY 40
ALLEY 41
ALLEY 42
ALLEY 43
ALLEY 44
ALLEY 45
ALLEY 46
ALLEY 47
ALLEY 48
ALLEY 49
ALLEY 50
ALLEY 51
ALLEY 52
ALLEY 53
ALLEY 54
ALLEY 55
ALLEY 56
ALLEY 57
ALLEY 58
ALLEY 59
ALLEY 60
ALLEY 61
ALLEY 62
ALLEY 63
ALLEY 64
ALLEY 65
ALLEY 66
ALLEY 67
ALLEY 68
ALLEY 69
ALLEY 70
ALLEY 71
ALLEY 72
ALLEY 73
ALLEY 74
ALLEY 75
ALLEY 76
ALLEY 77
ALLEY 78
ALLEY 79
ALLEY 80
ALLEY 81
ALLEY 82
ALLEY 83
ALLEY 84
ALLEY 85
ALLEY 86
ALLEY 87
ALLEY 88
ALLEY 89
ALLEY 90
ALLEY 91
ALLEY 92
ALLEY 93
ALLEY 94
ALLEY 95
ALLEY 96
ALLEY 97
ALLEY 98
ALLEY 99
ALLEY 100
ALLEY 101
ALLEY 102
ALLEY 103
ALLEY 104
ALLEY 105
ALLEY 106
ALLEY 107
ALLEY 108
ALLEY 109
ALLEY 110
ALLEY 111
ALLEY 112
ALLEY 113
ALLEY 114
ALLEY 115
ALLEY 116
ALLEY 117
ALLEY 118
ALLEY 119
ALLEY 120
ALLEY 121
ALLEY 122
ALLEY 123
ALLEY 124
ALLEY 125
ALLEY 126
ALLEY 127
ALLEY 128
ALLEY 129
ALLEY 130
ALLEY 131
ALLEY 132
ALLEY 133
ALLEY 134
ALLEY 135
ALLEY 136
ALLEY 137
ALLEY 138
ALLEY 139
ALLEY 140
ALLEY 141
ALLEY 142
ALLEY 143
ALLEY 144
ALLEY 145
ALLEY 146
ALLEY 147
ALLEY 148
ALLEY 149
ALLEY 150
ALLEY 151
ALLEY 152
ALLEY 153
ALLEY 154
ALLEY 155
ALLEY 156
ALLEY 157
ALLEY 158
ALLEY 159
ALLEY 160
ALLEY 161
ALLEY 162
ALLEY 163
ALLEY 164
ALLEY 165
ALLEY 166
ALLEY 167
ALLEY 168
ALLEY 169
ALLEY 170
ALLEY 171
ALLEY 172
ALLEY 173
ALLEY 174
ALLEY 175
ALLEY 176
ALLEY 177
ALLEY 178
ALLEY 179
ALLEY 180
ALLEY 181
ALLEY 182
ALLEY 183
ALLEY 184
ALLEY 185
ALLEY 186
ALLEY 187
ALLEY 188
ALLEY 189
ALLEY 190
ALLEY 191
ALLEY 192
ALLEY 193
ALLEY 194
ALLEY 195
ALLEY 196
ALLEY 197
ALLEY 198
ALLEY 199
ALLEY 200
ALLEY 201
ALLEY 202
ALLEY 203
ALLEY 204
ALLEY 205
ALLEY 206
ALLEY 207
ALLEY 208
ALLEY 209
ALLEY 210
ALLEY 211
ALLEY 212
ALLEY 213
ALLEY 214
ALLEY 215
ALLEY 216
ALLEY 217
ALLEY 218
ALLEY 219
ALLEY 220
ALLEY 221
ALLEY 222
ALLEY 223
ALLEY 224
ALLEY 225
ALLEY 226
ALLEY 227
ALLEY 228
ALLEY 229
ALLEY 230
ALLEY 231
ALLEY 232
ALLEY 233
ALLEY 234
ALLEY 235
ALLEY 236
ALLEY 237
ALLEY 238
ALLEY 239
ALLEY 240
ALLEY 241
ALLEY 242
ALLEY 243
ALLEY 244
ALLEY 245
ALLEY 246
ALLEY 247
ALLEY 248
ALLEY 249
ALLEY 250
ALLEY 251
ALLEY 252
ALLEY 253
ALLEY 254
ALLEY 255
ALLEY 256
ALLEY 257
ALLEY 258
ALLEY 259
ALLEY 260
ALLEY 261
ALLEY 262
ALLEY 263
ALLEY 264
ALLEY 265
ALLEY 266
ALLEY 267
ALLEY 268
ALLEY 269
ALLEY 270
ALLEY 271
ALLEY 272
ALLEY 273
ALLEY 274
ALLEY 275
ALLEY 276
ALLEY 277
ALLEY 278
ALLEY 279
ALLEY 280
ALLEY 281
ALLEY 282
ALLEY 283
ALLEY 284
ALLEY 285
ALLEY 286
ALLEY 287
ALLEY 288
ALLEY 289
ALLEY 290
ALLEY 291
ALLEY 292
ALLEY 293
ALLEY 294
ALLEY 295
ALLEY 296
ALLEY 297
ALLEY 298
ALLEY 299
ALLEY 300
ALLEY 301
ALLEY 302
ALLEY 303
ALLEY 304
ALLEY 305
ALLEY 306
ALLEY 307
ALLEY 308
ALLEY 309
ALLEY 310
ALLEY 311
ALLEY 312
ALLEY 313
ALLEY 314
ALLEY 315
ALLEY 316
ALLEY 317
ALLEY 318
ALLEY 319
ALLEY 320
ALLEY 321
ALLEY 322
ALLEY 323
ALLEY 324
ALLEY 325
ALLEY 326
ALLEY 327
ALLEY 328
ALLEY 329
ALLEY 330
ALLEY 331
ALLEY 332
ALLEY 333
ALLEY 334
ALLEY 335
ALLEY 336
ALLEY 337
ALLEY 338
ALLEY 339
ALLEY 340
ALLEY 341
ALLEY 342
ALLEY 343
ALLEY 344
ALLEY 345
ALLEY 346
ALLEY 347
ALLEY 348
ALLEY 349
ALLEY 350
ALLEY 351
ALLEY 352
ALLEY 353
ALLEY 354
ALLEY 355
ALLEY 356
ALLEY 357
ALLEY 358
ALLEY 359
ALLEY 360
ALLEY 361
ALLEY 362
ALLEY 363
ALLEY 364
ALLEY 365
ALLEY 366
ALLEY 367
ALLEY 368
ALLEY 369
ALLEY 370
ALLEY 371
ALLEY 372
ALLEY 373
ALLEY 374
ALLEY 375
ALLEY 376
ALLEY 377
ALLEY 378
ALLEY 379
ALLEY 380
ALLEY 381
ALLEY 382
ALLEY 383
ALLEY 384
ALLEY 385
ALLEY 386
ALLEY 387
ALLEY 388
ALLEY 389
ALLEY 390
ALLEY 391
ALLEY 392
ALLEY 393
ALLEY 394
ALLEY 395
ALLEY 396
ALLEY 397
ALLEY 398
ALLEY 399
ALLEY 400
ALLEY 401
ALLEY 402
ALLEY 403
ALLEY 404
ALLEY 405
ALLEY 406
ALLEY 407
ALLEY 408
ALLEY 409
ALLEY 410
ALLEY 411
ALLEY 412
ALLEY 413
ALLEY 414
ALLEY 415
ALLEY 416
ALLEY 417
ALLEY 418
ALLEY 419
ALLEY 420
ALLEY 421
ALLEY 422
ALLEY 423
ALLEY 424
ALLEY 425
ALLEY 426
ALLEY 427
ALLEY 428
ALLEY 429
ALLEY 430
ALLEY 431
ALLEY 432
ALLEY 433
ALLEY 434
ALLEY 435
ALLEY 436
ALLEY 437
ALLEY 438
ALLEY 439
ALLEY 440
ALLEY 441
ALLEY 442
ALLEY 443
ALLEY 444
ALLEY 445
ALLEY 446
ALLEY 447
ALLEY 448
ALLEY 449
ALLEY 450
ALLEY 451
ALLEY 452
ALLEY 453
ALLEY 454
ALLEY 455
ALLEY 456
ALLEY 457
ALLEY 458
ALLEY 459
ALLEY 460
ALLEY 461
ALLEY 462
ALLEY 463
ALLEY 464
ALLEY 465
ALLEY 466
ALLEY 467
ALLEY 468
ALLEY 469
ALLEY 470
ALLEY 471
ALLEY 472
ALLEY 473
ALLEY 474
ALLEY 475
ALLEY 476
ALLEY 477
ALLEY 478
ALLEY 479
ALLEY 480
ALLEY 481
ALLEY 482
ALLEY 483
ALLEY 484
ALLEY 485
ALLEY 486
ALLEY 487
ALLEY 488
ALLEY 489
ALLEY 490
ALLEY 491
ALLEY 492
ALLEY 493
ALLEY 494
ALLEY 495
ALLEY 496
ALLEY 497
ALLEY 498
ALLEY 499
ALLEY 500
ALLEY 501
ALLEY 502
ALLEY 503
ALLEY 504
ALLEY 505
ALLEY 506
ALLEY 507
ALLEY 508
ALLEY 509
ALLEY 510
ALLEY 511
ALLEY 512
ALLEY 513
ALLEY 514
ALLEY 515
ALLEY 516
ALLEY 517
ALLEY 518
ALLEY 519
ALLEY 520
ALLEY 521
ALLEY 522
ALLEY 523
ALLEY 524
ALLEY 525
ALLEY 526
ALLEY 527
ALLEY 528
ALLEY 529
ALLEY 530
ALLEY 531
ALLEY 532
ALLEY 533
ALLEY 534
ALLEY 535
ALLEY 536
ALLEY 537
ALLEY 538
ALLEY 539
ALLEY 540
ALLEY 541
ALLEY 542
ALLEY 543
ALLEY 544
ALLEY 545
ALLEY 546
ALLEY 547
ALLEY 548
ALLEY 549
ALLEY 550
ALLEY 551
ALLEY 552
ALLEY 553
ALLEY 554
ALLEY 555
ALLEY 556
ALLEY 557
ALLEY 558
ALLEY 559
ALLEY 560
ALLEY 561
ALLEY 562
ALLEY 563
ALLEY 564
ALLEY 565
ALLEY 566
ALLEY 567
ALLEY 568
ALLEY 569
ALLEY 570
ALLEY 571
ALLEY 572
ALLEY 573
ALLEY 574
ALLEY 575
ALLEY 576
ALLEY 577
ALLEY 578
ALLEY 579
ALLEY 580
ALLEY 581
ALLEY 582
ALLEY 583
ALLEY 584
ALLEY 585
ALLEY 586
ALLEY 587
ALLEY 588
ALLEY 589
ALLEY 590
ALLEY 591
ALLEY 592
ALLEY 593
ALLEY 594
ALLEY 595
ALLEY 596
ALLEY 597
ALLEY 598
ALLEY 599
ALLEY 600
ALLEY 601
ALLEY 602
ALLEY 603
ALLEY 604
ALLEY 605
ALLEY 606
ALLEY 607
ALLEY 608
ALLEY 609
ALLEY 610
ALLEY 611
ALLEY 612
ALLEY 613
ALLEY 614
ALLEY 615
ALLEY 616
ALLEY 617
ALLEY 618
ALLEY 619
ALLEY 620
ALLEY 621
ALLEY 622
ALLEY 623
ALLEY 624
ALLEY 625
ALLEY 626
ALLEY 627
ALLEY 628
ALLEY 629
ALLEY 630
ALLEY 631
ALLEY 632
ALLEY 633
ALLEY 634
ALLEY 635
ALLEY 636
ALLEY 637
ALLEY 638
ALLEY 639
ALLEY 640
ALLEY 641
ALLEY 642
ALLEY 643
ALLEY 644
ALLEY 645
ALLEY 646
ALLEY 647
ALLEY 648
ALLEY 649
ALLEY 650
ALLEY 651
ALLEY 652
ALLEY 653
ALLEY 654
ALLEY 655
ALLEY 656
ALLEY 657
ALLEY 658
ALLEY 659
ALLEY 660
ALLEY 661
ALLEY 662
ALLEY 663
ALLEY 664
ALLEY 665
ALLEY 666
ALLEY 667
ALLEY 668
ALLEY 669
ALLEY 670
ALLEY 671
ALLEY 672
ALLEY 673
ALLEY 674
ALLEY 675
ALLEY 676
ALLEY 677
ALLEY 678
ALLEY 679
ALLEY 680
ALLEY 681
ALLEY 682
ALLEY 683
ALLEY 684
ALLEY 685
ALLEY 686
ALLEY 687
ALLEY 688
ALLEY 689
ALLEY 690
ALLEY 691
ALLEY 692
ALLEY 693
ALLEY 694
ALLEY 695
ALLEY 696
ALLEY 697
ALLEY 698
ALLEY 699
ALLEY 700
ALLEY 701
ALLEY 702
ALLEY 703
ALLEY 704
ALLEY 705
ALLEY 706
ALLEY 707
ALLEY 708
ALLEY 709
ALLEY 710
ALLEY 711
ALLEY 712
ALLEY 713
ALLEY 714
ALLEY 715
ALLEY 716
ALLEY 717
ALLEY 718
ALLEY 719
ALLEY 720
ALLEY 721
ALLEY 722
ALLEY 723
ALLEY 724
ALLEY 725
ALLEY 726
ALLEY 727
ALLEY 728
ALLEY 729
ALLEY 730
ALLEY 731
ALLEY 732
ALLEY 733
ALLEY 734
ALLEY 735
ALLEY 736
ALLEY 737
ALLEY 738
ALLEY 739
ALLEY 740
ALLEY 741
ALLEY 742
ALLEY 743
ALLEY 744
ALLEY 745
ALLEY 746
ALLEY 747
ALLEY 748
ALLEY 749
ALLEY 750
ALLEY 751
ALLEY 752
ALLEY 753
ALLEY 754
ALLEY 755
ALLEY 756
ALLEY 757
ALLEY 758
ALLEY 759
ALLEY 760
ALLEY 761
ALLEY 762
ALLEY 763
ALLEY 764
ALLEY 765
ALLEY 766
ALLEY 767
ALLEY 768
ALLEY 769
ALLEY 770
ALLEY 771
ALLEY 772
ALLEY 773
ALLEY 774
ALLEY 775
ALLEY 776
ALLEY 777
ALLEY 778
ALLEY 779
ALLEY 780
ALLEY 781
ALLEY 782
ALLEY 783
ALLEY 784
ALLEY 785
ALLEY 786
ALLEY 787
ALLEY 788
ALLEY 789
ALLEY 790
ALLEY 791
ALLEY 792
ALLEY 793
ALLEY 794
ALLEY 795
ALLEY 796
ALLEY 797
ALLEY 798
ALLEY 799
ALLEY 800
ALLEY 801
ALLEY 802
ALLEY 803
ALLEY 804
ALLEY 805
ALLEY 806
ALLEY 807
ALLEY 808
ALLEY 809
ALLEY 810
ALLEY 811
ALLEY 812
ALLEY 813
ALLEY 814
ALLEY 815
ALLEY 816
ALLEY 817
ALLEY 818
ALLEY 819
ALLEY 820
ALLEY 821
ALLEY 822
ALLEY 823
ALLEY 824
ALLEY 825
ALLEY 826
ALLEY 827
ALLEY 828
ALLEY 829
ALLEY 830
ALLEY 831
ALLEY 832
ALLEY 833
ALLEY 834
ALLEY 835
ALLEY 836
ALLEY 837
ALLEY 838
ALLEY 839
ALLEY 840
ALLEY 841
ALLEY 842
ALLEY 843
ALLEY 844
ALLEY 845
ALLEY 846
ALLEY 847
ALLEY 848
ALLEY 849
ALLEY 850
ALLEY 851
ALLEY 852
ALLEY 853
ALLEY 854
ALLEY 855
ALLEY 856
ALLEY 857
ALLEY 858
ALLEY 859
ALLEY 860
ALLEY 861
ALLEY 862
ALLEY 863
ALLEY 864
ALLEY 865
ALLEY 866
ALLEY 867
ALLEY 868
ALLEY 869
ALLEY 870
ALLEY 871
ALLEY 872
ALLEY 873
ALLEY 874
ALLEY 875
ALLEY 876
ALLEY 877
ALLEY 878
ALLEY 879
ALLEY 880
ALLEY 881
ALLEY 882
ALLEY 883
ALLEY 884
ALLEY 885
ALLEY 886
ALLEY 887
ALLEY 888
ALLEY 889
ALLEY 890
ALLEY 891
ALLEY 892
ALLEY 893
ALLEY 894
ALLEY 895
ALLEY 896
ALLEY 897
ALLEY 898
ALLEY 899
ALLEY 900
ALLEY 901
ALLEY 902
ALLEY 903
ALLEY 904
ALLEY 905
ALLEY 906
ALLEY 907
ALLEY 908
ALLEY 909
ALLEY 910
ALLEY 911
ALLEY 912
ALLEY 913
ALLEY 914
ALLEY 915
ALLEY 916
ALLEY 917
ALLEY 918
ALLEY 919
ALLEY 920
ALLEY 921
ALLEY 922
ALLEY 923
ALLEY 924
ALLEY 925
ALLEY 926
ALLEY 927
ALLEY 928
ALLEY 929
ALLEY 930
ALLEY 931
ALLEY 932
ALLEY 933
ALLEY 934
ALLEY 935
ALLEY 936
ALLEY 937
ALLEY 938
ALLEY 939
ALLEY 940
ALLEY 941
ALLEY 942
ALLEY 943
ALLEY 944
ALLEY 945
ALLEY 946
ALLEY 947
ALLEY 948
ALLEY 949
ALLEY 950
ALLEY 951
ALLEY 952
ALLEY 953
ALLEY 954
ALLEY 955
ALLEY 956
ALLEY 957
ALLEY 958
ALLEY 959
ALLEY 960
ALLEY 961
ALLEY 962
ALLEY 963
ALLEY 964
ALLEY 965
ALLEY 966
ALLEY 967
ALLEY 968
ALLEY 969
ALLEY 970
ALLEY 971
ALLEY 972
ALLEY 973
ALLEY 974
ALLEY 975
ALLEY 976
ALLEY 977
ALLEY 978
ALLEY 979
ALLEY 980
ALLEY 981
ALLEY 982
ALLEY 983
ALLEY 984
ALLEY 985
ALLEY 986
ALLEY 987
ALLEY 988
ALLEY 989
ALLEY 990
ALLEY 991
ALLEY 992
ALLEY 993
ALLEY 994
ALLEY 995
ALLEY 996
ALLEY 997
ALLEY 998
ALLEY 999
ALLEY 1000

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

M. Anthony
9-22-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. G-18
CENTER RD. G-32
CENTER ST. J-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. D-6
CHINTENIMIK AL. D-8
CHRISTIE AL. N-13
CHURCH ST. N-11
CLARMONT ST. D-31
COLBY PL. K-
COLUMBUS AVE. D-15
COMPRESSOR ST. D-23
COMSTOCK AL. N-14
CONGRESS ST. L-25
CORLISS AVE. L-23
CROSS ST. D-11
CULION ST. D-30
DAVIS ST. N-31
DEAN AL. L-29
DELAWARE RD. N-30
DIAMOCK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. K-14
ELM ST. K-19
ELMHURST DR. K-19
EMMA ST. K-30
ENDINE ST. K-22
ESSEX ST. D-11
EVELYN AVE. L-19
FAIRBANKS ST. N-13
FAIRVIEW AVE. D-8
FARM ST. L-17
FERGUSON ST. R-27
FILMORE ST. L-11
FIFTH ST. L-11
FIRST AL. L-27
FIRTH ST. K-27
FISHER AVE. D-10
FOCHT BRIDGE D-18
FORREST LN. L-7
FOURTH ST. L-10
FOX AL. N-5
FOX ST. B-17
FRACE ST. B-10
FRANCIS AVE. I-10
FRANKLIN ST. I-10
FREDERICK ST. I-10
FRONT ST. D-10
FROST AVE. D-10
FULTON ST. K-14
GATE ST. L-27
GLEN AVE. F-11
GRACE AVE. I-10
GRAND ST. D-29
GRANT ST. L-13
GREEN AL. L-11
GREEN ST. K-22
GREENWOOD ST. K-29
GRIFFITH AL. N-25
HAGERTY AVE. K-25
HANOVER ST. K-23
HARRIS ST. N-11
HARTE ST. D-8
HECKMAN ST. I-7
HEMLOCK ST. I-32
HENDERSON ST. I-11
HENSHAW CT. L-25
HILL ST. D-27
HILLCREST BLVD. D-16
HILLSIDE RD. D-12
HOWARD ST. D-11
HUDSON ST. D-12
INGERSOLL AVE. D-11
IRWIN ST. D-12
IVY ST. L-19
James P. BAKER WAY D-33
JAMES ST. L-19
JEFFERSON ST. L-16
JERSEY ST. L-14
JOHN ST. N-9
JOHN MITCHELL AVE. N-9
JOSEPH ST. I-2
JUDD AL. K-27
KAITLIN CT. L-30
KENT ST. L-16
KNEEDLER AVE. D-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. L-25
LAKE AL. L-
LENNON AL. L-
LESHER AL. L-
LEWIS ST. L-
LINCOLN RD. L-
LINCOLN ST. L-
LINER BLVD. D-8
LOCK ST. L-32
LOGAN ST. D-30
LYNDALE ST. N-31
LYNN RD. N-30
MADISON ST. N-30
MARKET ST. L-12
MARSHALL ST. L-14
MARY ST. L-14
McKEEN ST. K-21
MELROSE ST. K-21
MEMORIAL PKWY. L-31
MERCER ST. D-18
METZ ST. D-18
MEYNER RD. I-18
MILL ST. N-25
MILLER ST. I-11
MITCHELL AL. D-9
MORRIS ST. D-21
MOULE AL. J-32
NATALIE DRIVE K-
NELSON ST. N-30
NORTH AL. L-14
NO. MAIN ST. D-8
NO. RIVERVIEW RD. L-29
OAK AL. N-13
ORCHARD AL. K-24
PARK RD. K-22
PEACH ST. K-22
PEAR AL. D-11
PEARL ST. K-23
PEDRICK AVE. L-23
PICKFORD AVE. L-18
PINE AL. L-18
PLEASANT AVE. D-10
POTTS AVE. I-7
PROSPECT ST. N-10
PURSEL ST. L-24
RAILROAD AVE. D-14
RANDALL ST. L-10
RAYMOND ST. D-9
REESE WAY B-11
REESE CT. B-14
RICHARD RD. J-21
RICHMOND ST. R-28
RIDGE ST. R-29
RIVER ST. D-16
RIVERSIDE WAY C-27
RIVERVIEW CIR. L-29
RIVERVIEW RD. L-13
ROCK AL. L-22
ROSE ST. K-29
ROSEBERRY ST. N-25
SARGENT AVE. K-25
SAWMILL ST. K-23
SAYRE AVE. N-11
SCHULTZ AVE. D-8
SHAFER AVE. D-30
SHERWOOD ST. L-14
SHILLINGER AL. C-11
SHIMER ST. L-19
SILK AVE. G-20
STORGEAZES ST. D-9
SMITH AVE. D-9
SONORA ST. I-11
SQ. MAIN ST. L-16
SPINNER AL. K-14
SPRUCE AL. K-25
ST. JOHN AL. D-29
STANLEY ST. L-28
STEELE ST. D-25
STEWART AL. D-16
STOCKTON ST. L-12
STRYKER ST. D-8
STULL AL. D-10
SUMMIT AVE. L-
SUSAN ST. L-
TAYLOR AL. L-
TERRY ST. L-
THIRD ST. H-12
THOMAS ST. B-23
TIOHE AL. L-19
TITUS AL. L-14
TUTTLE ST. L-
TYNDALL AVE. B-11
UNION SQ. B-9
VALLEY VIEW CIR. K-28
WALNUT ST. K-20
WARREN ST. D-18
WASHINGTON ST. D-16
WATSON PL. L-33
WEBSTER ST. K-
WILBUR AVE. D-22
WILLEVOR ST. L-
WILLIAM ST. K-24
WILSON ST. K-
WISE AL. L-
WOODLAWN RD. L-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Martin S

TOM C

8-23-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

MONTEREY

ROSEBERRY STREET

BARRYMORE STREET

BOWERS AVE.

FROST AVENUE

PICKFORD STREET

HARTE ST.

BURKE STREET

FRACE ST.

FREDERICK STREET

SARGENT AVENUE

MICHAEL STREET

JOHN STREET

INGERSOLL AVENUE

GRACE STREET

CORLISS AVENUE

ELDER STREET

FAIRBANKS STREET

HILLCREST AVE.

HAGERTY BOULEVARD

MEMORIAL PARKWAY (RT. 22)

MARSHALL STREET

HECKMAN STREET

FISHER PLACE

KNEEDLER AVENUE

ANDERSON STREET

WATSON PLACE

WALNUT STREET

BLM STREET

GREEN STREET

COLUMBUS AVE.

BATES STREET

PROSPECT STREET

LINCOLN ROAD

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

STOCKTON STREET

ESSEX STREET

CAHILL ST.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

SAYRE AVENUE

WILBUR AVENUE

PERDUE ALLEY

HILL STREET

BANK STREET

GATE STREET

TUTTLE STREET

RIDGE STREET

LOOK STREET

STANLEY STREET

HILLSIDE

VALLEY VIEW

PEARL ST.

GRAND ST.

LOGAN ST.

MADISON STREET

MELROSE STREET

KAITLYN CT.

CONGRESS ST.

CULKIN STREET

STEWART ALLEY

ALLAN STREET

MILL STREET

GRIFFITH ALLEY

GARNART

JAMES ST.

PURSEL ST.

THOMAS ST.

ANN ST.

WILLIAM ST.

CENTER ST.

CHESTNUT ST.

PEACH ST.

MEYNER ST.

EMMA ST.

PARK RD.

KURLAND ALLEY

MORRIS CANAL WAY

SAWMILL ST.

ABBOTT ST.

CENTER ST.

ANDOVER STREET

SOUTH MAIN ST.

DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

I-78

RIVERVIEW CIR.

NORTH RIVERVIEW

WOODLAWN ROAD

FOREST LN.

ELMHURST AVE.

BELT ROAD

CARPENTERSVILLE ROAD

NATALIE DRIVE

KNOLL VIEW DRIVE

OAKLYN RD.

HEMLOCK DR.

LOCK ST.

LOCUST ST.

LYNDALE ST.

LYNN RD.

MADISON ST.

MARKET ST.

MARSHALL ST.

MARY ST.

McKEEN ST.

MELROSE ST.

MEMORIAL PKWY.

MERCER ST.

METZ ST.

MEYNER RD.

MILL ST.

MILLER ST.

MITCHELL AL.

MORRIS ST.

MOULE AL.

NATALIE DRIVE

NELSON ST.

NORTH AL.

NO. MAIN ST.

NO. RIVERVIEW RD.

OAK AL.

ORCHARD AL.

PARK RD.

PEACH ST.

PEAR AL.

PEARL ST.

PERDOE AVE.

PICKFORD AVE.

PINE AL.

PLEASANT AVE.

POTTS AVE.

PROSPECT ST.

PURSEL ST.

RAILROAD AVE.

RANDALL ST.

RAYMOND ST.

REESE WAY

REESE CT.

RICHARD RD.

RICHMOND ST.

RIDGE ST.

RIVER ST.

RIVERSIDE WAY

RIVERVIEW CIR.

RIVERVIEW RD.

ROCK AL.

ROSE ST.

ROSEBERRY ST.

SARGENT AVE.

SAWMILL ST.

SAYRE AVE.

SCHULTZ AVE.

SHARPE AVE.

SHERWOOD ST.

SHILLINGER AL.

SHIMER ST.

SILK AVE.

STIRGEAVES ST.

SMITH AVE.

SONORA ST.

SO. MAIN ST.

SPINNER AL.

SPRUCE AL.

ST. JOHN AL.

STANLEY ST.

STEELE ST.

STEWART AL.

STOCKTON ST.

STRYKER ST.

STULL AL.

SUMMIT AVE.

SUSAN ST.

TAYLOR AL.

TERRY ST.

THIRD ST.

THOMAS ST.

TIGHE AL.

TITUS AL.

TUTTLE ST.

TYNDALL AVE.

UNION SQ.

VALLEY VIEW CIR.

WALNUT ST.

WARREN ST.

WASHINGTON ST.

WATSON PL.

WEBSTER ST.

WILBUR AVE.

WILLEVER ST.

WILLIAM ST.

WILSON ST.

WIRE AL.

WOODLAWN RD.

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTEWINK AL. G-6
CHRISTIE AL. N-13
CHURCH ST. B-11
CLARMONT ST. D-31
COLBY PL. H-15
COLUMBUS AVE.
COMPRESSOR ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST. L-12
CULKIN ST. O-25
DAVIS ST. H-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. G-14
ELM ST. P-19
ELMHURST DR. N-30
EMIRE ST. I-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. H-11
FAIRBANKS ST. D-8
FAIRVIEW AVE. I-7
FARM ST. R-27
FERGUSON ST. L-8
FILMORE ST. F-11
FIFTH ST. L-4
FIRST AL. L-27
FIRTH ST. K-13
FISHER AVE. K-16
FOCHT BRIDGE F-7
FORREST LA. L-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. D-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. N-10
FREDERICK ST. N-10
FRONT ST. C-10
FROST AVE. R-9
FULTON ST. I-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-29
GRIFFITH AL. M-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. D-9
HARTE ST. P-9
HECKMAN ST. I-15
HEMLOCK ST. B-32
HENDERSON ST. I-11
HENSHAW CT. O-11
HILL ST. L-25
HILLCREST BLVD. K-9
HILLSIDE RD. L-27
HOWARD ST. B-16
HUDSON ST. B-12
INGERSOLL AVE. O-11
IRWIN ST. I-12
IVY ST. O-15
J. T. BAKER WAY O-15
JAMES ST. K-23
JEFFERSON ST. O-19
JERSEY ST. O-16
JOHN ST. H-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. H-9
JUDD AL. I-5
KAITLYN CT. L-27
KENT ST. L-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE O-31
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. B-10
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD.
LINCOLN RD.
LINCOLN ST. M-13
LINER BLVD. K-8
LOCK ST. O-30
LOGAN ST. L-30
LYNDALE ST. I-31
LYNN RD. H-30
MADISON ST. N-30
MARKET ST. E-12
MARSHALL ST. I-14
MARY ST. I-21
McKEEN ST. L-21
MELROSE ST. O-30
MEMORIAL PKWY. I-18
MERCER ST. D-10
METZ ST. I-19
MEYNER RD. H-28
MILL ST. I-11
MILLER ST. I-11
MITCHELL AL. I-8
MORRIS ST. I-8
MOULE AL. I-21
NATALIE DRIVE J-32, K-
NELSON ST. I-14
NORTH AL. O-8
NO. MAIN ST. I-8
NO. RIVERVIEW RD. O-13
OAK AL. E-8
ORCHARD AL. E-8
PARK RD. K-24
PEACH ST. P-22
PEAR AL. P-29
PEARL ST. P-25
PERDOE AVE. L-11
PICKFORD AVE. L-6
PINE AL. B-10
PLEASANT AVE. I-10
POTTS AVE. I-11
PROSPECT ST. L-10
PURSEL ST. L-24
RAILROAD AVE. I-14
RANDALL ST. O-9
RAYMOND ST. B-9
REESE WAY B-14
REESE CT. B-14
RICHARD RD. K-21
RICHMOND ST. B-29
RIDGE ST. R-29
RIVER ST. C-16
RIVERSIDE WAY O-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. I-13
ROSE ST. O-8
ROSEBERRY ST. B-8
SARGENT AVE. O-11
SAWMILL ST. I-21
SAYRE AVE. K-23
SCHULTZ AVE. N-11
SHARPE AVE. O-8
SHERWOOD ST. O-30
SHILLINGER AL. I-14
SHIMER ST. B-11
SILK AVE. O-15
STIRGEAVES ST. O-27
SMITH AVE. O-20
SONORA ST. O-27
SO. MAIN ST. B-9
SPINNER AL. I-11
SPRUCE AL. E-18
ST. JOHN AL. I-14
STANLEY ST. O-29
STEELE ST. I-25
STEWART AL. O-29
STOCKTON ST. O-15
STRYKER ST. B-12
STULL AL. O-5
SUMMIT AVE. O-10
SUSAN ST. O-10
TAYLOR AL. I-12
TERRY ST. O-28
THIRD ST. B-11
THOMAS ST. B-9
TIGHE AL. I-9
TITUS AL. I-8
TUTTLE ST. I-7
TYNDALL AVE. I-25
UNION SQ. I-25
VALLEY VIEW CIR. O-28
WALNUT ST. B-18
WARREN ST. B-13
WASHINGTON ST. B-15
WATSON PL. B-13
WEBSTER ST. I-13
WILBUR AVE. N-22
WILLEVER ST. O-10
WILLIAM ST. N-24, K-
WILSON ST. I-12, K-
WIRE AL. O-26
WOODLAWN RD. I-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom C
7-29-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA


CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
BARRYMORE STREET
FROST AVENUE
BOWERS AVE.
HILLCREST AVENUE
PICKFORD STREET
HARTE ST.
BURKE STREET
FAIRBANKS STREET
BOULEVARD
HAGERTY ST.
ROAD
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
FERGUSON ST.
BELVIDERE AVENUE
DELAWARE ROAD
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
ANDERSON STREET
KNEEDLER AVENUE
FISHER PLACE
WATSON
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVE.
BATES STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
STOCKTON STREET
ESSEX STREET
CAHILL ST.
RICHARD RD.
SAYRE AVENUE
MEYNER ROAD
CENTER STREET
LIMEKILN ROAD
WILBUR AVENUE
GATE STREET
TUTTLE ST.
HILLSIDE
RIDGE STREET
LOCK STREET
MELROSE AVENUE
STANLEY STREET
PEARL ST.
GRAND ST.
LOGAN ST.
MADISON STREET
CONGRESS STREET
KAITLYN CT.
VALLEY VIEW ROAD
NORTH RIVERVIEW ROAD
RIVERVIEW CIR.
WOODLAWN ROAD
CORRECT LN.
BELT ROAD
CARPENTERSVILLE ROAD
NATALIE DRIVE
KNOLL VIEW DRIVE
ELMHURST DRIVE
OAKLYN RD.
HEMLOCK DR.
CANAL WAY
MORRIS
SAWMILL ST.
MAIN ST.
SOUTH MAIN ST.
NORTH MAIN ST.
RAYMOND ST.
EVELYN AVE.
SHULTZ AVE.
HENDERSON
MILLER
FRANCIS AVE.
POTTS AVE.
IRWIN
HUDSON
MARY ST.
DAVIS
DOLBY PLACE
ORCHARD ALLEY
SOUTH
FRONT STREET
THIRD STREET
SECOND STREET
FIRST ST.
CHAMBERS STREET
HARRIS STREET
SHIMER ST.
BRAINARD
WALNUT
REESE
MARKET
ELIZABETH ST.
HANOVER STREET
REESE COURT
MERCER STREET
HOWARD
STRYKER
SOUTH ABUTMENT
NORTH ABUTMENT
SUSQUEHANNA RIVER
MORRIS CANAL
DELAWARE & RARITAN CANAL
PENNSYLVANIA RAILROAD
LEHIGH VALLEY RAILROAD
CONRAIL
NORFOLK SOUTHERN RAILWAY

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTZWICK AL. G-6
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE. J-17
COMPRESSOR ST. L-11
COMSTOCK AL. E-11
CONGRESS ST. L-11
CORLISS AVE. D-25
CROSS ST. G-14
CULVON ST. F-11
DAVIS ST. K-5
DEAN AL. K-13
DELAWARE RD. N-11
DIMMICK AL. E-11
DRILL ST. E-11
DUGAN AL. B-11
ELDER AVE. B-11
ELIZABETH ST. G-14
ELLEN ST. P-18
ELM ST. H-30
ELMHURST DR. I-10
EMPIRE ST. K-22
EMMA ST. L-11
ENGINE ST. L-19
ERICK ST. B-11
EVELYN AVE. F-8
FAIRBANKS ST. L-7
FAIRVIEW AVE. K-27
FARM ST. L-8
FERGUSON ST. P-18
FILMORE ST. L-22
FIFTH ST. E-14
FIRST AL. K-27
FIRTH ST. K-13
FISHER AVE. J-16
FOCHT BRIDGE L-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-7
FOX ST. E-7
FRACE ST. I-10
FRANCIS AVE. H-10
FRANKLIN ST. H-10
FREDERICK ST. G-10
FRONT ST. P-9
FROST AVE. E-14
FULTON ST. K-27
GATE ST. K-11
GLEN AVE. H-10
GRACE AVE. H-29
GRAND ST. L-13
GRANT ST. F-11
GREEN AL. P-22
GREEN ST. P-22
GREENWOOD ST. H-25
GRIFFITH AL. N-7
HAGERTY AVE. H-13
HANOVER ST. G-9
HARRIS ST. P-9
HARTE ST. I-15
HECKMAN ST. K-32
HEMLOCK ST. I-11
HENDERSON ST. L-25
HENSHAW CT. O-9
HILL ST. K-27
HILLCREST BLVD. B-16
HILLSIDE RD. H-27
HOWARD ST. G-16
HUDSON ST. G-11
INGERSOLL AVE. B-12
IRWIN ST. O-15
I. T. PAKER WAY N-23
JAMES ST. I-23
JEFFERSON ST. M-22
JERSEY ST. O-16
JOHN ST. K-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. N-9
JUDD AL. I-5
KAITLYN CT. L-27
KENT ST. L-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE J-31
KORP AL. I-25
KURLAND AL. L-25
LAKE AL. B-10
LENNON AL. K-8
LESHER AL. J-8
LEWIS ST. K-30
LIMEKILN RD. K-30
LINCOLN RD. K-30
LINCOLN ST. K-30
LINER BLVD. K-30
LOCK ST. I-19
LOGAN ST. M-25
LYNDALE ST. N-30
LYNN RD. N-30
MADISON ST. K-22
MARKET ST. I-21
MARSHALL ST. I-14
MARY ST. E-11
McKEEN ST. L-21
MELROSE ST. D-10
MEMORIAL PKWY. D-10
MERCER ST. I-18
METZ ST. I-19
MEYNER RD. I-25
MILL ST. I-11
MILLER ST. I-11
MITCHELL AL. I-11
MORRIS ST. I-21
MOULE AL. I-32, K-32
NATALIE DRIVE L-30
NELSON ST. I-14
NORTH AL. I-8
NO. MAIN ST. O-8
NO. RIVERVIEW RD. K-28
OAK AL. K-13
ORCHARD AL. G-8
PARK RD. K-24
PEACH ST. L-22
PEAR AL. L-11
PEARL ST. L-25
PERODE AVE. L-25
PICKFORD AVE. I-7
PINE AL. I-16
PLEASANT AVE. B-10
POTTS AVE. I-11
PROSPECT ST. I-24
PURSEL ST. I-14
RAILROAD AVE. I-10
RANDALL ST. G-10
RAYMOND ST. G-9
REESE WAY I-11
REESE CT. I-14
RICHARD RD. K-21
RICHMOND ST. P-29
RIDGE ST. P-29
RIVER ST. P-16
RIVERSIDE WAY O-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. I-13
ROSE ST. K-5
ROSEBERRY ST. G-9
SARGENT AVE. G-11
SAWMILL ST. L-25
SAYRE AVE. K-23
SCHULTZ AVE. M-11
SHARON AVE. B-8
SHERWOOD ST. O-30
SHILLINGER AL. I-14
SHIMER ST. O-11
SILK AVE. O-11
SKIRGEAVES ST. I-19
SMITH AVE. O-20
SONDRA ST. O-27
SO. MAIN ST. B-9
SPINNER AL. I-11
SPRUCE AL. I-18
ST. JOHN AL. K-14
STANLEY ST. O-29
STEELE ST. I-29
STEWART AL. I-29
STOCKTON ST. I-25
STRYKER ST. G-12
STULL AL. G-8
SUMMIT AVE. O-10
SUSAN ST. O-10
TAYLOR AL. O-10
TERRY ST. I-11
THIRD ST. I-11
THOMAS ST. I-22
TIGHE AL. I-22
TITUS AL. I-25
TUTTLE ST. O-25
TYNDALL AVE. O-11
UNION SQ. B-9
VALLEY VIEW CIR. P-20
WALNUT ST. P-20
WARREN ST. K-19
WASHINGTON ST. D-18
WATSON PL. I-15
WEBSTER ST. I-23
WILBUR AVE. M-22
WILLEVER ST. O-10
WILLIAM ST. M-24
WILSON ST. K-32, K-33
WISE PL. I-32
WOODLAWN RD. I-28



Cory Conners 5-6-22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Tom Coulter 5-06-22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG


TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

ROSEBERRY STREET
FROST AVENUE
BARRYMORE STREET
BOWERS AVE.
PICKFORD STREET
HARTE ST.
BURKE STREET
FRACE ST.
FREDERICK STREET
SAMPSON STREET
MICKEL STREET
WILLIAMS ST.
SUSAN ST.
MORRIS STREET
GRACE STREET
GORLISS AVENUE
FLOUR AVENUE
PRUNE AVENUE
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
BELVIDERE ROAD
DELAWARE AVENUE
BAKER WAY
NORTH MAIN STREET
FOURTH STREET
THIRD STREET
SECOND STREET
FIRST STREET
FAIRBANKS STREET
FERGUSON STREET
BOULEVARD
HAGERTY AVE.
MEMORIAL PARKWAY (RT. 22)
MARSHALL STREET
HECKMAN STREET
ANDERSON STREET
KNEEDLER AVENUE
FISHER PLACE
WATSON PLACE
WALNUT STREET
ELM STREET
GREEN STREET
COLUMBUS AVENUE
BATES STREET
PROSPECT STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
STOCKTON STREET
ESSEX STREET
CAHILL ST.
RICHARD RD.
METZNER ROAD
LYNN RD.
SAYRE AVENUE
WILBUR AVENUE
MILL STREET
HILL STREET
BANK STREET
CENTER STREET
LINCOLN ROAD
MORRIS CANAL WAY
SAWMILL ST.
GATE STREET
TUTTLE STREET
HARRINGTON ST.
RIDGE STREET
LOCK STREET
HILLSIDE
CONGRESS
KAITLYN CT.
STANLEY STREET
PEARL STREET
GRAND STREET
LOGAN STREET
MADISON STREET
MELROSE STREET
LINDALE STREET
KNOLL VIEW DRIVE
NATALIE DRIVE
RIVERVIEW CIR.
WOODLAWN ROAD
NORTH RIVERVIEW ROAD
FORREST LA.
BELT AVE.
ELMHURST ROAD
CARPENTERSVILLE ROAD
OAKLYN RD.
HEMLOCK DR.
CENTER ROAD
BRAINARD ST.
BROAD ST.
BROADVIEW ST.
BULLMAN ST.
BURKE ST.
BURWELL AL.
CAHILL ST.
CARHART AL.
CARPENTERSVILLE RD.
CEDAR AL.
CENTER RD.
CENTER ST.
CHAMBERS ST.
CHERRY LANE
CHESTNUT ST.
CIRNA AL.
CHINTEWINK AL.
CHRISTIE AL.
CHURCH ST.
CLARMONT ST.
COLBY PL.
COLUMBUS AVE.
COMPRESSION ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST.
CULVON ST.
DAVIS ST.
DEAN AL.
DELAWARE RD.
DIMMICK AL.
DRILL ST.
DUGAN AL.
ELDER AVE.
ELIZABETH ST.
ELLEN ST.
ELM ST.
ELMHURST DR.
EMIRE ST.
EMMA ST.
ENGINE ST.
ESSEX ST.
EVELYN AVE.
FAIRBANKS ST.
FAIRVIEW AVE.
FARM ST.
FERGUSON ST.
FILMORE ST.
FIFTH ST.
FIRST AL.
FIRTH ST.
FISHER AVE.
FOGHT BRIDGE
FORREST LA.
FOURTH ST.
FOX AL.
FOX ST.
FRACE ST.
FRANCIS AVE.
FRANKLIN ST.
FREDERICK ST.
FRONT ST.
FROST AVE.
FULTON ST.
GATE ST.
GLEN AVE.
GRACE AVE.
GRAND ST.
GRANT ST.
GREEN AL.
GREEN ST.
GREENWOOD ST.
GRIFFITH AL.
HAGERTY AVE.
HANOVER ST.
HARRIS ST.
HARTE ST.
HECKMAN ST.
HEMLOCK ST.
HENDERSON ST.
HENSHAW CT.
HILL ST.
HILLCREST BLVD.
HILLSIDE RD.
HOWARD ST.
HUDSON ST.
INGERSOLL AVE.
IRWIN ST.
IVY ST.
J. J. BAKER WAY
JAMES ST.
JEFFERSON ST.
JERSEY AL.
JOHN ST.
JOHN MITCHELL AVE.
JOSEPH ST.
JUDD AL.
KAITLYN CT.
KENT ST.
KNEEDLER AVE.
KNOLL VIEW DRIVE
KORP AL.
KURLAND AL.
LAKE AL.
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD.
LINCOLN RD.
LINCOLN ST.
LINER BLVD.
LOCK ST.
LOGAN ST.
LYNDALE ST.
LYNN RD.
MADISON ST.
MARKET ST.
MARSHALL ST.
MARY ST.
McKEEN ST.
MELROSE ST.
MEMORIAL PKWY.
MERCER ST.
METZ ST.
METZNER RD.
MILL ST.
MILLER ST.
MITCHELL AL.
MORRIS ST.
MOULE AL.
NATALIE DRIVE
NELSON ST.
NORTH AL.
NO. MAIN ST.
NO. RIVERVIEW RD.
OAK AL.
ORCHARD AL.
PARK RD.
PEACH ST.
PEAR AL.
PEARL ST.
PERDOE AVE.
PICKFORD AVE.
PINE AL.
PLEASANT AVE.
POTTS AVE.
PROSPECT ST.
PURSEL ST.
RAILROAD AVE.
RANDALL ST.
RAYMOND ST.
REESE WAY
REESE CT.
RICHARD RD.
RICHMOND ST.
RIDGE ST.
RIVER ST.
RIVERSIDE WAY
RIVERVIEW CIR.
RIVERVIEW RD.
ROCK AL.
ROSE ST.
ROSEBERRY ST.
SARGENT AVE.
SAWMILL ST.
SAYRE AVE.
SCHULTZ AVE.
SHAFER AVE.
SHERWOOD ST.
SHILLINGER AL.
SHIMER ST.
SILK AVE.
SIDGREAVES ST.
SMITH AVE.
SONORA ST.
SO. MAIN ST.
SPRINNER AL.
SPRUCE AL.
ST. JOHN AL.
STANLEY ST.
STEELE ST.
STEWART AL.
STOCKTON ST.
STRYKER ST.
STULL AL.
SUMMIT AVE.
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TICHE AL.
TITUS AL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WISE AL.
WOODLAWN RD.



U T S R Q P O N M L K J I H G F E D C B A

T. Courter

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

T. Courter
K. Weigand
4/1/22

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

DELAWARE - COMMONWEALTH OF PENNSYLVANIA RIVER

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

I-78

BRAINARD ST. O-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. O-9
BURNELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AV. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. O-6
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE.
COMPRESSION ST.
COMSTOCK AL.
CONGRESS ST.
CORLISS AVE.
CROSS ST.
CULVER ST. O-25
DAVIS ST. N-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. N-11
DUGAN AL. E-11
ELDER AVE. N-11
ELIZABETH ST. B-11
ELLEN ST. I-14
ELM ST. P-19
ELMHURST DR. M-30
EMIRE ST. P-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. L-19
EVELYN AVE. H-11
FAIRBANKS ST. O-8
FAIRVIEW AVE. O-7
FARM ST. B-27
FERGUSON ST. J-8
FILMORE ST. F-11
FIFTH ST. E-4
FIRST AL. M-27
FIRTH ST. K-13
FISHER AVE. O-16
FOGHT BRIDGE E-7
FORREST LA. I-30
FOURTH ST. H-5
FOX AL. E-8
FOX ST. D-17
FRACE ST. P-10
FRANCIS AVE. I-10
FRANKLIN ST. M-10
FREDERICK ST. O-10
FRONT ST. O-10
FROST AVE. R-9
FULTON ST. E-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. L-13
GREEN AL. F-11
GREEN ST. P-22
GREENWOOD ST. O-29
GRIFFITH AL. N-25
HAGERTY AVE. N-7
HANOVER ST. B-13
HARRIS ST. I-9
HARTE ST. P-9
HECKMAN ST. P-15
HEMLOCK ST. O-32
HENDERSON ST. I-11
HENSHAW CT. O-11
HILL ST. O-25
HILLCREST BLVD. K-9
HILLSIDE RD. Q-27
HOWARD ST. O-16
HUDSON ST. D-12
INGERSOLL AVE. D-11
IRWIN ST. G-12
IVY ST. G-12
J. T. BAKER WAY L-23
JAMES ST. C-19
JEFFERSON ST. D-19
JERSEY ST. I-19
JOHN ST. N-14
JOHN MITCHELL AVE. N-9
JOSEPH ST. N-9
JUDD AL. I-8
KAITLYN CT. P-27
KENT ST. L-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE J-31
KORP AL. J-25
KURLAND AL. J-25
LAKE AL. B-10
LENNON AL.
LESHER AL.
LEWIS ST.
LIMEKILN RD. M-13
LINCOLN RD. K-8
LINCOLN ST. O-32
LINER BLVD. O-30
LOCK ST. O-31
LOGAN ST. K-19
LYNDALE ST. M-9
LYNN RD. N-9
MADISON ST. B-12
MARKET ST. I-14
MARSHALL ST. I-14
MARY ST. E-21
MCKEEN ST. O-31
MELROSE ST. D-13
MEMORIAL PKWY. E-18
MERCER ST. O-10
METZ ST. M-25
MEYNER RD. J-11
MILL ST. D-10
MITCHELL AL. B-8
MORRIS ST. N-21
MOULE AL. J-32, K-
NATALIE DRIVE N-30
NELSON ST. I-14
NORTH AL. C-8
NO. MAIN ST. J-29
NO. RIVERVIEW RD. H-13
OAK AL. G-9
ORCHARD AL. P-24
PARK RD. L-22
PEACH ST. E-11
PEAR AL. P-29
PEARL ST. L-25
PERODE AVE. P-11
PICKFORD AVE. F-16
PINE AL. B-10
PLEASANT AVE. J-11
POTTS AVE. M-10
PROSPECT ST. L-24
PURSEL ST. J-14
RAILROAD AVE. O-10
RANDALL ST. G-9
RAYMOND ST. B-11
REESE WAY B-14
REESE CT. J-21
RICHARD RD. P-29
RICHMOND ST. R-29
RIDGE ST. O-16
RIVER ST. C-7
RIVERSIDE WAY I-27
RIVERVIEW CIR. N-29
RIVERVIEW RD. M-13
ROCK AL. N-9
ROSE ST. N-9
ROSEBERRY ST. O-11
SARGENT AVE. I-25
SAWMILL ST. K-23
SAYRE AVE. H-11
SCHULTZ AVE. G-8
SHAFER AVE. O-30
SHERWOOD ST. J-14
SHILLINGER AL. I-11
SHIMER ST. H-15
SILK AVE. P-17
SITGREAVES ST. F-20
SMITH AVE. O-27
SONORA ST. B-9
SQ. MAIN ST. I-11
SPINNER AL. I-18
SPRUCE AL. K-14
ST. JOHN AL. O-29
STANLEY ST. L-29
STEELE ST. N-25
STEWART AL. O-16
STOCKTON ST. A-12
STRYKER ST. F-8
STULL AL. O-10
SUMMIT AVE. O-10
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TRIHE AL. H-12
TITUS AL. O-29
TUTTLE ST. B-11
TYNDALL AVE. B-9
UNION SQ. P-28
VALLEY VIEW CIR. M-24
WALNUT ST. K-23
WARREN ST. K-18
WASHINGTON ST. D-18
WATSON PL. P-16
WEBSTER ST. L-23
WILBUR AVE. M-22
WILLEVER ST. O-19
WILLIAM ST. M-24
WILSON ST. K-7
WIRE AL. K-
WOODLAWN RD. I-28

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

DELAWARE RIVER

CITY OF EASTON

I-78

BROAD ST. N-6
BROADVIEW ST. N-32
BULLMAN ST. O-8
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE C-18
CHESTNUT ST. O-21
CHINA AL. G-9
CHINTEWINK AL. G-9
CHRISTIE AL. H-13
CHURCH ST. B-11
CLARMONT ST. O-7
COLBY PL. O-11
COLUMBUS AVE. O-25
COMPRESSOR ST. N-14
COMSTOCK AL. F-11
CONGRESS ST. K-9
CORLISS AVE. K-13
CROSS ST. N-11
CULVON ST. E-11
DAVIS ST. N-11
DEAN AL. E-11
DELAWARE RD. N-11
DIMMICK AL. B-11
DRILL ST. B-14
DUGAN AL. P-19
ELDER AVE. P-19
ELIZABETH ST. P-30
ELLEN ST. P-32
ELM ST. P-32
ELMHURST DR. P-32
ENNIE ST. P-32
EMMA ST. O-11
ENGINE ST. I-18
ESSEX ST. I-18
EVELYN AVE. I-18
FAIRBANKS ST. O-7
FAIRVIEW AVE. P-27
FARM ST. N-27
FERGUSON ST. P-11
FILMORE ST. P-11
FIRTH PL. P-14
FIRST AL. P-27
FIRTH ST. N-28
FISHER AVE. O-18
FOCHT BRIDGE O-20
FORREST LA. N-20
FOURTH ST. N-20
FOX AL. O-11
FOX ST. P-18
FRACE ST. P-18
FRANCIS AVE. P-19
FRANKLIN ST. P-10
FREDERICK ST. P-10
FRONT ST. P-10
FROST AVE. P-11
FULTON ST. P-14
GATE ST. P-27
GLEN AVE. P-11
GRACE AVE. P-19
GRAND ST. O-28
GRANT ST. P-28
GREEN AL. P-28
GREEN ST. P-22
GREENWOOD ST. P-22
GRIFFITH AL. P-25
HAGERTY AVE. N-7
HANOVER ST. O-13
HARRIS ST. O-13
HARTE ST. O-13
HECKMAN ST. O-32
HEMLOCK ST. O-32
HENDERSON ST. O-32
HENSHAW CT. O-32
HILL ST. I-25
HILLCREST BLVD. I-25
HILLSIDE RD. I-25
HOWARD ST. I-25
HUDSON ST. I-25
INGERSOLL AVE. I-25
IRWIN ST. I-25
IVY ST. I-25
JAILER BANKER WAY I-25
JEFFERSON ST. I-25
JERSEY ST. I-25
JOHN ST. I-25
JOHN MITCHELL AVE. I-25
JOSEPH ST. I-25
JUDD AL. I-25
KAITLYN CT. I-25
KENT ST. I-25
KNEEDLER AVE. I-25
KNOLL VIEW DRIVE I-25
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. I-25
LENNON AL. I-25
LESHER AL. I-25
LEWIS ST. I-25
LIMEKILN RD. I-25
LINCOLN RD. I-25
LINCOLN ST. I-25
LINER BLVD. I-25
LOCK ST. I-25
LOGAN ST. I-25
LYNDALE ST. I-25
MAIN RD. I-25
MADISON ST. I-25
MARKET ST. I-25
MARSHALL ST. I-25
MARY ST. I-25
McKEEN ST. I-25
MELROSE ST. I-25
MEMORIAL PKWY. I-25
MERCER ST. I-25
METZ ST. I-25
MEYNER RD. I-25
MILL ST. I-25
MILLER ST. I-25
MITCHELL AL. I-25
MORRIS ST. I-25
MOULE AL. I-25
NATALIE DRIVE I-25
NELSON ST. I-25
NORTH AL. I-25
NO. MAIN ST. I-25
NO. RIVERVIEW RD. I-25
OAK AL. I-25
ORCHARD AL. I-25
PARK RD. I-25
PEACH ST. I-25
PEAR AL. I-25
PEARL ST. I-25
PERDOE AVE. I-25
PROVOST AVE. I-25
PINE AL. I-25
PLEASANT AVE. I-25
POTTS AVE. I-25
PROSPECT ST. I-25
PURSES. ST. I-25
RAILROAD AVE. I-25
RANDALL ST. I-25
RAYMOND ST. I-25
REESE WAY I-25
REESE CT. I-25
RICHARD RD. I-25
RICHMOND ST. I-25
RIDGE ST. I-25
RIVER ST. I-25
RIVERSIDE WAY I-25
RIVERVIEW CIR. I-25
RIVERVIEW RD. I-25
ROCK AL. I-25
ROSE ST. I-25
ROSEBERRY ST. I-25
SARGENT AVE. I-25
SAWMILL ST. I-25
SAYRE AVE. I-25
SCHULTZ AVE. I-25
SHAFER AVE. I-25
SHERWOOD ST. I-25
SHILLINGER AL. I-25
SHIMER ST. I-25
SILK AVE. I-25
STORGEAVES ST. I-25
SMITH AVE. I-25
SONDEN ST. I-25
SO. MAIN ST. I-25
SPRINER AL. I-25
SPRUCE AL. I-25
ST. JOHN AL. I-25
STANLEY ST. I-25
STEELE ST. I-25
STEWART AL. I-25
STOCKTON ST. I-25
STRYKER ST. I-25
STULL AL. I-25
SUMMIT AVE. I-25
SUSAN ST. I-25
TAYLOR AL. I-25
TERRY ST. I-25
THIRD ST. I-25
THOMAS ST. I-25
TICHE AL. I-25
TITUS AL. I-25
TUTTLE ST. I-25
TYNDALL AVE. I-25
UNION SQ. I-25
VALLEY VIEW CIR. I-25
WALNUT ST. I-25
WARREN ST. I-25
WASHINGTON ST. I-25
WATSON PL. I-25
WEBSTER ST. I-25
WILBUR AVE. I-25
WILLEVER ST. I-25
WILLIAM ST. I-25
WILSON ST. I-25
WOOD AL. I-25
WOODLAWN RD. I-25

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

Corey Connors 4-1-2022 Dan Vaughn

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON

DELAWARE RIVER

I-78

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

WALNUT STREET

GREEN STREET

COLUMBUS AVENUE

PROSPECT STREET

LINCOLN STREET

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

CAHILL ST.

SAYRE AVENUE

WILBUR AVENUE

MILL STREET

BANK STREET

MEYNER ROAD

LINCOLN ROAD

HILLSIDE

STANLEY STREET

PEARL STREET

GRAND STREET

LOGAN STREET

LINDEN STREET

RIDGE STREET

LOCK STREET

MELROSE STREET

GATE STREET

CUTTLE STREET

WASHINGTON ST.

MADISON STREET

CONGRESS ST.

VALLEY VIEW CIR.

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON STREET

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

ROSEBERRY STREET

BARRYMORE STREET

FROST AVENUE

PICKFORD STREET

HARTE ST.

BURKE STREET

PROSPECT AVENUE

LINCOLN ROAD

LINER BLVD.

BELVIDERE ROAD

DELAWARE WAY

NORTH MAIN STREET

FOURTH STREET

THIRD STREET

SECOND STREET

FIRST STREET

SOUTH MAIN STREET

MARKET ST.

ELIZABETH ST.

FRONT STREET

HARRIS STREET

CHAMBERS ST.

WASHINGTON AVE.

SUMMIT

MITCHELL

BULLMAN

BURWELL

BENNETT

STULL ALLEY

SHIMER ST.

BRAINARD

REESE

WAYNE

HUDSON ST.

HANOVER STREET

REESE COURT

HOWARD

MERCER

STORGEAVES

JEFFERSON

STOCKTON

WASHINGTON

MAIN

SPRUCE

PINE

LAKE

CEDAR

HICKORY

WALNUT

CHESTNUT

POPLAR

MIDDLE

ALLEY

ALLAN

ANN

JAMES

WILLIAM

THOMAS

PURSEL

GRIFFITH

PERRINE

HILL

GRANT

BANK

PARK RD.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

CENTER

ESSEX STREET

HECKMAN

MARSHALL

ANDERSON

FISHER PLACE

KNEEDLER AVENUE

WATSON

BLM STREET

CONGRESS

KATTELL

MADISON STREET

GATE

CUTTLE

VALLEY VIEW

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

MEMORIAL PARKWAY (RT. 22)

DELAWARE RIVER

COMMONWEALTH OF PENNSYLVANIA

I-78

FAIRBANKS STREET

BOBCE AVENUE

HAGERTY AVE.

FERGUSON ST.

BARRYMORE STREET

BELVIDERE ROAD

DELAWARE WAY

NORTH MAIN STREET

FOURTH STREET

THIRD STREET

SECOND STREET

FIRST STREET

SOUTH MAIN STREET

MARKET ST.

ELIZABETH ST.

FRONT STREET

HARRIS STREET

CHAMBERS ST.

WASHINGTON AVE.

SUMMIT

MITCHELL

BULLMAN

BURWELL

BENNETT

STULL ALLEY

SHIMER ST.

BRAINARD

REESE

WAYNE

HUDSON ST.

HANOVER STREET

REESE COURT

HOWARD

MERCER

STORGEAVES

JEFFERSON

STOCKTON

WASHINGTON

MAIN

SPRUCE

PINE

LAKE

CEDAR

HICKORY

WALNUT

CHESTNUT

POPLAR

MIDDLE

ALLEY

ALLAN

ANN

JAMES

WILLIAM

THOMAS

PURSEL

GRIFFITH

PERRINE

HILL

GRANT

BANK

PARK RD.

RICHARD RD.

MEYNER ROAD

LINCOLN ROAD

CENTER

ESSEX STREET

HECKMAN

MARSHALL

ANDERSON

FISHER PLACE

KNEEDLER AVENUE

WATSON

BLM STREET

CONGRESS

KATTELL

MADISON STREET

GATE

CUTTLE

VALLEY VIEW

KNOLL VIEW DRIVE

NATALIE DRIVE

NELSON

RIVERVIEW CIR.

RIVERVIEW NORTH

RIVERVIEW

WOODLAWN ROAD

FORREST LN.

ELMHURST AVE.

CARPENTERSVILLE ROAD

BELT ROAD

HEMLOCK DR.

CENTER ST.

CANAL WAY

MORRIS

MAIN ST.

SAWMILL

HOOVER STREET

LAFAYETTE ST.

RIVER

KEY TO INDEX

ABBOTT AL. N-32
BROADVIEW ST. O-9
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. K-28
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. O-32
CENTER RD. O-32
CENTER ST. O-22
CHAMBERS ST. O-11
CHERRY LANE O-10
CHESTNUT ST. O-21
CHINA AL. O-8
CHINTEWINK AL. O-6
CHRISTINE AL. N-13
CHURCH ST. B-11
CLAIRMONT ST. O-31
COLBY PL. O-9
COLUMBUS AVE. O-22
COMPRESSOR ST. O-15
COMSTOCK AL. O-15
CONGRESS ST. O-15
CORLISS AVE. N-11
CROSS ST. O-15
CULKIN ST. O-25
DAVIS ST. K-14
DEAN AL. F-11
DELAWARE RD. K-5
DIMMICK AL. K-13
DRILL ST. K-11
DUGAN AL. H-11
ELDER AVE. H-11
ELIZABETH ST. H-11
ELLEN ST. O-14
ELM ST. F-19
ELMHURST DR. H-30
EMIRE ST. F-10
EMMA ST. K-22
ENGINE ST. O-11
ESSEX ST. O-19
EVELYN AVE. H-11
FAIRBANKS ST. K-8
FAIRVIEW AVE. L-7
FERGUSON ST. R-27
FILMORE ST. K-8
FIFTH ST. F-11
FIRST AL. F-14
FIRTH ST. K-27
FISHER AVE. K-13
FOOT BRIDGE P-19
FORREST LA. F-30
FOURTH ST. H-5
FOX AL. C-8
FOX ST. C-17
FRACE ST. P-10
FRANCIS AVE. H-10
FRANKLIN ST. H-10
FREDERICK ST. O-10
FRONT ST. O-10
FROST AVE. R-9
FULTON ST. F-14
GATE ST. R-27
GLEN AVE. F-11
GRACE AVE. N-10
GRAND ST. O-29
GRANT ST. F-13
GREEN AL. F-11
GREEN ST. F-22
GREENWOOD ST. O-28
GRIFFITH AL. O-29
HAGERTY AVE. N-7
HANOVER ST. N-13
HARRIS ST. O-9
HARTE ST. P-9
HECKMAN ST. P-15
HEMLOCK ST. F-32
HENDERSON ST. F-11
HENSHAW CT. G-11
HILL ST. F-25
HILLCREST BLVD. K-9
HILLSIDE RD. R-27
HOWARD ST. B-10
HUDSON ST. O-11
INGERSOLL AVE. O-11
IRWIN ST. O-15
IVY ST. C-16
JAMES RIVER WAY K-23
JEFFERSON ST. O-18
JERSEY ST. C-18
JOHN ST. C-19
JOHN MITCHELL AVE. N-9
JOSEPH ST. H-9
JUDD AL. H-9
KAITLYN CT. P-27
KENT ST. K-18
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE L-31
KORP AL. L-25
KURLAND AL. C-25
LANE AL. C-25
LENNON AL. N-11
LESHER AL. O-13
LEWIS ST. O-15
LINCOLN RD. M-10
LINCOLN ST. L-12
LINER BLVD. M-12
LOCK ST. N-35
LOGAN ST. P-22
LYNDALE ST. O-28
LYNN RD. M-36
MADISON ST. F-14
MARKET ST. F-14
MARSHALL ST. K-14
MARY ST. O-28
MARSEN ST. K-14
MELROSE ST. P-19
MEMORIAL PKWY. K-22
MERCER ST. O-18
METZ ST. F-10
MEYNER RD. M-25
MILL ST. F-25
MILLER ST. O-15
MITCHELL AL. O-9
MORRIS ST. O-18
MOULE AL. O-29
NATALIE DRIVE L-31
NELSON ST. P-19
NORTH AL. O-9
NO. MAIN ST. F-10
NO. RIVERVIEW RD. L-28
OAK AL. O-9
ORCHARD AL. O-9
PARK RD. O-28
PEACH ST. O-9
PEAR AL. O-9
PEARL ST. O-28
PERRINE AVE. O-29
PICKFORD AVE. O-9
PINE AL. O-9
PLEASANT AVE. O-9
POTTS AVE. O-9
PROSPECT ST. O-9
PURSEL ST. O-29
RAILROAD AVE. O-29
RANDALL ST. O-9
RAYMOND ST. O-9
REESE WAY O-9
REESE CT. O-9
RICHARD RD. O-9
RICHMOND ST. O-9
RIDGE ST. O-9
RIVER ST. O-9
RIVERSIDE WAY O-9
RIVERVIEW CIR. O-9
RIVERVIEW RD. O-9
ROCK AL. O-9
ROSE ST. O-9
ROSEBERRY ST. O-9
SARGENT AVE. O-9
SAWMILL ST. O-9
SAYRE AVE. O-9
SCHULTZ AVE. O-9
SHAFER AVE. O-9
SHERWOOD ST. O-9
SHILLINGER AL. O-9
SHIMER ST. O-9
SILK AVE. O-9
STORGEAVES ST. O-9
SMITH AVE. O-9
SONYEA ST. O-9
SO. MAIN ST. O-9
SPINNER AL. O-9
SPRUCE AL. O-9
ST. JOHN AL. O-9
STANLEY ST. O-9
STEELE ST. O-9
STEWART AL. O-9
STOCKTON ST. O-9
STRYKER ST. O-9
STULL AL. O-9
SUMMIT AVE. O-9
SUSAN ST. O-9
TAYLOR AL. O-9
TERRY ST. O-9
THIRD ST. O-9
THOMAS ST. O-9
TIGHE AL. O-9
TITUS AL. O-9
TUTTLE ST. O-9
TYNDALL AVE. O-9
UNION SQ. O-9
VALLEY VIEW CIR. O-9
WALNUT ST. O-9
WARREN ST. O-9
WASHINGTON ST. O-9
WATSON PL. O-9
WEBSTER ST. O-9
WILBUR AVE. O-9
WILLOVER ST. O-9
WILLIAM ST. O-9
WILSON ST. O-9
WISE AL. O-9
WOODLAWN RD. O-9


THE TOWN OF PHILLIPSBURG
OFFICIAL MAP
WARREN COUNTY, NEW JERSEY
UPDATED 5-07
SCALE: 1" = 500'
GRAPHIC SCALE OF FEET
DATE: December 1, 1998
REVISED October 2005
TOWNSHIP OF LOPATCONG
TOWNSHIP OF POHATCONG
DELAWARE RIVER
COMMONWEALTH OF PENNSYLVANIA
CITY OF EASTON
I-78
Martha - PAPWA
4/1/22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Tom C 3-3-22

Tom C 3-3-22

BRAINARD ST. C-11
BROAD ST. F-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. O-9
BURWELL AL. D-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-16
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. L-21
CHINA AL. G-5
CHINTEWINK AL. G-6
CHRISTIE AL. K-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE. D-13
COMPRESSOR ST. O-25
CONSTOCK AL. D-14
CONGRESS ST. H-14
CORLISS AVE. F-11
CROSS ST. K-5
CULKIN ST. K-13
DAVIS ST. N-11
DEAN AL. E-11
DELAWARE RD. D-11
DIMMICK AL. N-11
DRILL ST. 6-11
DUGAN AL. E-14
ELDEN AVE. E-15
ELIZABETH ST. I-8
ELLEN ST. F-11
ELM ST. I-4
ELMHURST DR. H-27
EMMA ST. K-13
ENGINE ST. K-16
ESSEX ST. E-7
EVELYN AVE. I-30
FAIRBANKS ST. H-10
FAIRVIEW AVE. E-8
FARM ST. I-7
FERGUSON ST. P-27
FILMORE ST. I-8
FIFTH ST. P-11
FIRST AL. I-4
FIRTH ST. K-27
FISHER AVE. K-13
FOGHT BRIDGE E-16
FORREST LA. E-7
FOURTH ST. I-30
FOX AL. E-8
FRACE ST. P-17
FRANCIS AVE. P-10
FRANKLIN ST. H-10
FREDERICK ST. H-10
FRONT ST. C-10
FROST AVE. P-9
FULTON ST. P-14
GATE ST. R-27
GLEN AVE. P-11
GRACE AVE. N-10
GRAND ST. N-29
GRANT ST. L-13
GREEN AL. L-11
GREEN ST. P-22
GREENWOOD ST. G-29
GRIFFITH AL. G-29
HAGERTY AVE. N-7
HANOVER ST. D-13
HARRIS ST. D-9
HARTE ST. D-9
HECKMAN ST. I-15
HEMLOCK ST. G-32
HENDERSON ST. I-11
HENSHAW CT. G-11
HILL ST. K-25
HILLCREST BLVD. N-9
HILLSIDE RD. D-27
HOWARD ST. B-16
HUDSON ST. B-12
INGERSOLL AVE. D-11
IRWIN ST. D-12
IVY, ST. C-15
J. BAKER WAY C-16
JAMES ST. M-23
JEFFERSON ST. D-19
JERSEY ST. C-16
JOHN ST. D-16
JOHN MITCHELL AVE. N-9
JOSEPH ST. N-9
JUDD AL. N-5
KAITLYN CT. P-27
KENT ST. H-30
KNEEDLER AVE. O-16
KNOLL VIEW DRIVE I-25
KORP AL. I-25
KURLAND AL. I-25
LAKE AL. B-12
LENNON AL. I-24
LESHER AL. I-24
LEWIS ST. I-24
LINCOLN RD. N-13
LINCOLN ST. K-8
LINER BLVD. O-32
LOCK ST. O-32
LOGAN ST. O-30
LYNDALE ST. M-31
LYNN RD. K-19
MADISON ST. K-30
MARKET ST. B-12
MARSHALL ST. I-14
MARY ST. J-14
McKEEN ST. P-21
MELROSE ST. D-31
MEMORIAL PKWY. P-13
MERCER ST. E-18
METZ ST. G-10
MEYNER RD. I-19
MILL ST. M-25
MILLER ST. J-11
MITCHELL AL. D-10
MORRIS ST. B-8
MOULE AL. N-21
NATALIE DRIVE N-32, K-
NELSON ST. N-30
NORTH AL. N-14
NO. MAIN ST. C-8
NO. RIVERVIEW RD. C-28
OAK AL. H-13
ORCHARD AL. G-9
PARK RD. G-24
PEACH ST. L-22
PEAR AL. L-22
PEARL ST. P-11
PERODE AVE. L-25
PROFFORD AVE. P-11
PINE AL. P-18
PLEASANT AVE. B-10
POTTS AVE. J-11
PROSPECT ST. L-10
PURSEL ST. L-24
RAILROAD AVE. L-14
RANDALL ST. C-10
RAYMOND ST. G-9
REESE WAY B-11
REESE CT. B-14
RICHARD RD. K-21
RICHMOND ST. P-29
RIDGE ST. P-29
RIVER ST. O-16
RIVERSIDE WAY C-7
RIVERVIEW CIR. I-27
RIVERVIEW RD. I-29
ROCK AL. M-13
ROSE ST. G-8
ROSEBERRY ST. B-9
SARGENT AVE. D-11
SAWMILL ST. G-27
SAYRE AVE. P-25
SCHULTZ AVE. K-23
SHAFER AVE. N-11
SHERWOOD ST. G-8
SHILLINGER AL. G-30
SHIMER ST. J-14
SILK AVE. Y-11
SITGREAVES ST. Y-15
SMITH AVE. Y-17
SONORA ST. C-20
SO. MAIN ST. C-27
SPINNER AL. B-9
SPRUCE AL. P-11
ST. JOHN AL. P-16
STANLEY ST. K-14
STEELE ST. P-29
STEWART AL. L-29
STOCKTON ST. N-25
STRYKER ST. K-16
STULL AL. K-12
SUMMIT AVE. B-8
SUSAN ST. D-10
TAYLOR AL. O-10
TERRY ST. O-11
THIRD ST. H-12
THOMAS ST. P-23
TICHE AL. D-13
TITUS AL. H-12
TUTTLE ST. P-23
TYNDALL AVE. B-11
UNION SQ. B-9
VALLEY VIEW CIR. P-28
VALLEY ST. P-28
WARREN ST. P-30
WASHINGTON ST. K-18
WATSON PL. P-16
WEBSTER ST. L-23
WILBUR AVE. L-22
WILLEVER ST. D-10
WILLIAM ST. N-24
WILSON ST. B-24
WISE AL. P-22, K-
WOODLAWN RD. I-28

Brian S. Hoban & Don Vaughan 1-27-22

1-27-22
SUTTON
VAUGHN

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED: October 2006

Summitt / Duckworth 1/26/22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Summitt / Duckworth 1/26/22

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

1-26-23

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

1/26/2023

B.L.
K.D.
B.S.

cant open Pipe

New Basin

Basin

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

DELAWARE RIVER

I-78

U T S R Q P O N M L K J I H G F E D C B A

Brian Summitt
7/17/23

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Summitt
7/17/23

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

SCALE: 1" = 500'

GRAPHIC SCALE OF FEET


R. Wyckoff
M. Anthony
7/17/23

7/17/23 Mike Anthony
Ryan Wyckoff

U.S. PROPOSAL
J I G F E D C B A



Corey C
Tom Courter



THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

DATE: December 1, 1998
REVISED October 2005

Tom A 8/13/03
Mikes

BROAD ST. B-6
BROADVIEW ST. N-32
BULLMAN ST. D-9
BURKE ST. G-9
BURWELL AL. D-9
CAHILL ST. K-26
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. D-11
CENTER RD. D-18
CENTER ST. D-12
CHAMBERS ST. G-12
CHERRY LANE D-18
CHESTNUT ST. D-11
CHINA AL. G-9
CHINTEWINK AL. D-11
CHRISTIE AL. D-13
CHURCH ST. D-11
CLAIRMONT ST. G-12
COLBY PL. D-11
COLUMBUS AVE. K-25
COMPRESSOR ST. L-25
COMSTOCK AL. D-13
CONGRESS ST. L-24
CORLISS AVE. L-24
CROSS ST. G-11
CULKIN ST. K-24
DAWS ST. D-14
DEAN AL. D-11
DELAWARE RD. N-13
DIMRICK AL. D-13
DRILL ST. E-11
DUDAN AL. D-11
ELDER AVE. L-24
ELIZABETH ST. E-18
ELLEN ST. E-10
ELM ST. D-19
ELMHURST DR. M-28
EMIRE ST. D-14
EMMA ST. D-13
ENDINE ST. D-13
ESSEX ST. L-19
EVELYN AVE. D-14
FAIRBANKS ST. D-14
FAIRVIEW AVE. D-14
FARM LA. N-27
FERGUSON ST. D-13
FILMORE ST. D-14
FIRTH ST. E-12
FIRST ST. E-12
FIRTH ST. E-12
FISHER AVE. D-10
FOCHT BRIDGE N-29
FORREST LA. D-30
FOURTH ST. H-12
FOX AL. D-11
FOX ST. D-12
FRACE ST. D-10
FRANCIS AVE. D-10
FRANKLIN ST. D-10
FREDERICK ST. D-10
FRONT ST. D-10
FROST AVE. D-10
FULTON ST. D-14
GATE ST. D-27
GLEN AVE. D-10
GRACE AVE. D-10
GRAND ST. D-28
GRANT ST. D-28
GREEN AL. D-28
GREEN ST. D-28
GREENWOOD ST. D-28
GRIFFITH AL. D-28
HAGERTY AVE. D-7
HANOVER ST. D-12
HARRIS ST. D-12
HARTE ST. D-12
HECKMAN ST. D-12
HEMLOCK ST. D-12
HENDERSON ST. D-11
HENSHAW CT. D-11
HILL ST. D-12
HILLCREST BLVD. D-12
HILLSIDE RD. D-12
HOWARD ST. D-12
HUDSON ST. D-12
INGERSOLL AVE. D-12
IRWIN ST. D-12
IVY ST. D-12
J. BAKER WAY D-12
JAMES ST. D-12
JEFFERSON ST. D-12
JERSEY ST. D-12
JOHN ST. D-12
JOHN MITCHELL AVE. D-12
JOSEPH ST. D-12
JUDD AL. D-12
KAITLYN CT. D-12
KENT ST. D-12
KNEEDLER AVE. D-12
KNOLL VIEW DRIVE D-12
KORP AL. D-12
KURLAND AL. D-12
LANE AL. D-12
LENNON AL. D-12
LESHEN AL. D-12
LEWIS ST. D-12
LIMEKILN RD. D-12
LINCOLN RD. D-12
LINCOLN ST. D-12
LINER BLVD. D-12
LOCK ST. D-12
LOGAN ST. D-12
LYNDALE ST. D-12
LYNN RD. D-12
MADISON ST. D-12
MARKET ST. D-12
MARSHALL ST. D-12
MARY ST. D-12
McKEEN ST. D-12
MELROSE ST. D-12
MEMORIAL PKWY. D-12
MERCER ST. D-12
MIDDLE ST. D-12
MEYNER RD. D-12
MILL ST. D-12
MILLER ST. D-12
MITCHELL AL. D-12
MORRIS ST. D-12
MOULE AL. D-12
NATALIE DRIVE D-12
NELSON ST. D-12
NORTH AL. D-12
NO. MAIN ST. D-12
NO. RIVERVIEW RD. D-12
OAK AL. D-12
ORCHARD AL. D-12
PARK RD. D-12
PEACH ST. D-12
PEAR AL. D-12
PEARL ST. D-12
PENROSE AVE. D-12
PICKFORD AVE. D-12
PINE AL. D-12
PLEASANT AVE. D-12
POTTS AVE. D-12
PROSPECT ST. D-12
PURSEL ST. D-12
RAILROAD AVE. D-12
RAMDALL ST. D-12
RAYMOND ST. D-12
REESE WAY D-12
REESE CT. D-12
RICHARD RD. D-12
RICHMOND ST. D-12
RIDGE ST. D-12
RIVER ST. D-12
RIVERSIDE WAY D-12
RIVERVIEW DR. D-12
RIVERVIEW RD. D-12
ROCK AL. D-12
ROSE ST. D-12
ROSEBERRY ST. D-12
SARGENT AVE. D-12
SAWMILL ST. D-12
SAYRE AVE. D-12
SCHULTZ AVE. D-12
SHAFER AVE. D-12
SHERWOOD ST. D-12
SHILLINGER AL. D-12
SHIMER ST. D-12
SILK AVE. D-12
SLUDGEALEY ST. D-12
SMITH AVE. D-12
SONORA ST. D-12
SO. MAIN ST. D-12
SPRINER AL. D-12
SPRUCE AL. D-12
ST. JOHN AL. D-12
STANLEY ST. D-12
STEELE ST. D-12
STEWART AL. D-12
STOCKTON ST. D-12
STRYKER ST. D-12
STULL AL. D-12
SUMMIT AVE. D-12
SUSAN ST. D-12
TAYLOR AL. D-12
TERRY ST. D-12
THIRD ST. D-12
THOMAS ST. D-12
TIDHE AL. D-12
TITUS AL. D-12
TUTTLE ST. D-12
TYNDALL AVE. D-12
UNION SQ. D-12
VALLEY VIEW CIR. D-12
WALNUT ST. D-12
WARREN ST. D-12
WASHINGTON ST. D-12
WATSON PL. D-12
WEBSTER ST. D-12
WILBUR AVE. D-12
WILLEVOR ST. D-12
WILLIAM ST. D-12
WILSON ST. D-12
WINE AL. D-12
WOODLAWN RD. D-12

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

8-23-21

Weigand
Snyder

WEIGAND
SNYDER
8/23/21

SCALE: 1" = 500'

0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1991

Kevin Johnson
Robert Hoyd
8/23/21

TOWNSHIP OF LOPATCONG

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

Johnson
Hoyd
8/23/21

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED MAY-2007

SCALE: 1" = 500'

GRAPHIC SCALE OF FEET

8-25-23

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

DELAWARE COMMONWEALTH OF PENNSYLVANIA RIVER

CITY OF EASTON

MEMORIAL PARKWAY (RT. 22)

I-78

BROADVIEW ST. N-32
BULLMAN ST. O-9
BURKE ST. O-9
BURWELL AL. O-9
CAHILL ST. O-20
CARHART AL. L-28
CARPENTERSVILLE RD. L-31
CEDAR AL. E-18
CENTER RD. O-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE O-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. O-13
CHRISTIE AL. M-13
CHURCH ST. B-11
CLARMONT ST. O-31
COLBY PL. I-14
COLUMBUS AVE. O-5
COMPRESSOR ST. O-25
COMSTOCK AL. D-14
CONGRESS ST. O-17
CORLISS AVE. L-14
CROSS ST. O-27
CULVER ST. K-5
DAVIS ST. K-13
DEAN AL. N-11
DELAWARE RD. I-11
DIMMICK AL. N-11
DRILL ST. O-8
DUGAN AL. I-7
ELDER AVE. K-8
ELIZABETH ST. F-27
ELLEN ST. L-11
ELM ST. L-14
ELMHURST DR. E-27
EMIRE ST. L-13
EMMA ST. K-16
ENDINE ST. L-18
ESSEX ST. L-20
EVELYN AVE. I-8
FAIRBANKS ST. I-7
FAIRVIEW AVE. I-7
FARM ST. F-27
FERGUSON ST. L-11
FILMORE ST. L-14
FIFTH ST. L-27
FIRST AL. L-13
FIRTH ST. L-16
FISHER AVE. L-18
FOGHT BRIDGE I-7
FORREST LA. L-20
FOURTH ST. M-8
FOX AL. L-8
FOX ST. M-17
FRACE ST. O-17
FRANCIS AVE. L-10
FRANKLIN ST. L-10
FREDERICK ST. L-10
FRONT ST. O-10
FROST AVE. O-9
FULTON ST. L-14
GATE ST. L-27
GLEN AVE. L-11
GRACE AVE. L-10
GRAND ST. O-29
GRANT ST. O-13
GREEN AL. L-13
GREEN ST. P-22
GREENWOOD ST. L-29
GRIFFITH AL. N-8
HAGERTY AVE. L-25
HANOVER ST. N-8
HARRIS ST. O-9
HARTE ST. L-9
HECKMAN ST. L-15
HEMLOCK ST. L-32
HENDERSON ST. O-11
HENSHAW CT. I-11
HILL ST. L-11
HILLCREST BLVD. O-27
HILLSIDE RD. O-27
HOWARD ST. O-11
HUDSON ST. O-12
INGERSOLL AVE. O-11
IRWIN ST. O-12
IVY ST. O-12
J. T. BAKER WAY I-23
JAMES ST. L-23
JEFFERSON ST. O-23
JERSEY ST. L-16
JOHN ST. L-14
JOHN MITCHELL AVE. L-9
JOSEPH ST. I-9
JUDD AL. L-8
KAITLYN CT. I-27
KENT ST. L-30
KNEEDLER AVE. L-18
KNOLL VIEW DRIVE I-31
KORP AL. L-31
KURLAND AL. L-32
LAKE AL. L-23
LENNON AL. L-14
LESHER AL. L-21
LEWIS ST. L-8
LINDOLN RD. I-12
LINCOLN RD. I-11
LINCOLN ST. L-11
LINER BLVD. I-11
LOCK ST. L-27
LOGAN ST. L-27
LYNDALE ST. I-12
LYNN RD. I-12
MADISON ST. L-12
MARKET ST. L-12
MARSHALL ST. L-12
MARY ST. I-12
MARSH ST. L-12
MELROSE ST. L-12
MEMORIAL PKWY. I-12
MERCER ST. L-12
METZ ST. I-12
METZNER RD. I-12
MILL ST. L-12
MILLER ST. L-12
MITCHELL AL. L-12
MORRIS ST. L-12
MOULE AL. L-12
NATALIE DRIVE I-12
NELSON ST. L-12
NORTH AL. L-12
NO. MAIN ST. L-12
NO. RIVERVIEW RD. I-12
OAK AL. L-12
ORCHARD AL. L-12
PARK RD. L-12
PEACH ST. L-12
PEAR AL. L-12
PEARL ST. L-12
PERDOE AVE. L-12
PFOTZER AVE. L-12
PINE AL. L-12
PLEASANT AVE. L-12
POTTS AVE. L-12
PROSPECT ST. L-12
PURSEL ST. L-12
RAILROAD AVE. L-12
RANDALL ST. L-12
RAYMOND ST. L-12
REESE WAY L-12
REESE CT. L-12
RICHARD RD. L-12
RICHMOND ST. L-12
RIDGE ST. L-12
RIVER ST. L-12
RIVERSIDE WAY L-12
RIVERVIEW CIR. L-12
RIVERVIEW RD. L-12
ROCK AL. L-12
ROSE ST. L-12
ROSEBERRY ST. L-12
SARGENT AVE. L-12
SAWMILL ST. L-12
SAYRE AVE. L-12
SCHULTZ AVE. L-12
SHARPS AVE. L-12
SHERWOOD ST. L-12
SHILLINGER AL. L-12
SHIMER ST. L-12
SILK AVE. L-12
STOREAVES ST. L-12
SMITH AVE. L-12
SONORA ST. L-12
SO. MAIN ST. L-12
SPRINER AL. L-12
SPRUCE AL. L-12
ST. JOHN AL. L-12
STANLEY ST. L-12
STEELE ST. L-12
STEWART AL. L-12
STOCKTON ST. L-12
STRYKER ST. L-12
STULL AL. L-12
SUMMIT AVE. L-12
SUSAN ST. L-12
TAYLOR AL. L-12
TERRY ST. L-12
THIRD ST. L-12
THOMAS ST. L-12
TICHE AL. L-12
TITUS AL. L-12
TUTTLE ST. L-12
TYNDALL AVE. L-12
UNION SQ. L-12
VALLEY VIEW CIR. L-12
WALNUT ST. L-12
WARREN ST. L-12
WASHINGTON ST. L-12
WATSON PL. L-12
WEBSTER ST. L-12
WILBUR AVE. L-12
WILLEVER ST. L-12
WILLIAM ST. L-12
WILSON ST. L-12
WOODLAWN RD. L-12

11/21/23

Summit and Courter

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

DELAWARE COMMONWEALTH OF PENNSYLVANIA RIVER

CITY OF EASTON

I-78

U I S R O P O N M L J I H G F E D C B A

Miles
Tom A
12-28-23

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

12-27/12-28

Mike S Tom A

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

DELAWARE RIVER

I-78

U.S. ROUTE 22

MEMORIAL PARKWAY (RT. 22)

ROSEBERRY STREET

WALNUT STREET

ELM STREET

GREEN STREET

COLUMBUS AVENUE

MARSHALL STREET

HECKMAN STREET

ANDERSON STREET

KNEEDLER AVENUE

FISHER PLACE

WATSON PLACE

BATES STREET

PROSPECT STREET

LINCOLN STREET

GRANT STREET

WARREN STREET

FIRTH STREET

WILSON STREET

RAILROAD AVE.

CAHILL ST.

RICHARD RD.

METNER ROAD

SAYRE AVENUE

WILBUR AVENUE

MILL STREET

GRIFFIN ALLEY

PERRY STREET

HILL STREET

BANK STREET

GATE STREET

TUTTLE STREET

RIDGE STREET

LOCK STREET

WEST END

STANLEY STREET

PEARL ST.

GRAND ST.

LOGAN ST.

LINDEN ST.

HILLSIDE

VALLEY VIEW

CONGRESS

MADISON STREET

LINCOLN HWY.

HARRISON ST.

LYNDALE ST.

HILLCREST BLVD.

LINER BLVD.

BELVIDERE ROAD

DELAWARE ROAD

NORTH MAIN STREET

SOUTH MAIN STREET

FOURTH STREET

THIRD STREET

FRONT STREET

HARRIS STREET

CHAMBERS STREET

SHIMER ST.

BRAINARD

REESE

WATER ST.

MAIN ST.

MARKET STREET

ELIZABETH ST.

HOWARD

MERCER STREET

SOUTH MAIN

CEDAR

PINE ALLEY

RIVER ST.

STOCKTON

STORE ALLEY

WASHINGTON

SUMMIT AVE.

MITCHELL

BULLMAN

BURNELL

BENNETT

CASTILL ALLEY

MORRIS

SOUTHERN

HARRISON

HANOVER STREET

REESE COURT

MARY ST.

JOHN ST.

DAVIS

COLBY PL.

SHILLINGER ALLEY

SPRINGER ALLEY

MILLER

HENDERSON

SHULTZ AVE.

EVELYN AVE.

RAYMOND ST.

JOSEPH ST.

FRANCIS AVE.

HUDSON

IRWIN

POTTS AVE.

TITUS AL.

TYNDALL AVE.

RANDALL

PLEASANT AL.

LARE AL.

HENSHAW COURT

MEADOW COURT

GLEN

FILMORE

LEWIS

TAYLOR

HIGH

SPRUCE

PINE

CEDAR

LANE

ALLEN

ANN

JAMES

WILLIAM ST.

PURSEL

THOMAS

CENTER

CHESTNUT

EMMA

PARK RD.

PEACH

PEAR AL.

PERRY

PERRIDGE

HILL

GARNART

RICHER

GRIFFITH

WILBUR

STEWART ALLEY

MOULE ALLEY

ALLAN

CARLTON

DUNLOP

KORP

LEBANON

LEBANON CIR.

NORTH RIVERVIEW

RIVERVIEW CIR.

WOODLAWN ROAD

RIVERVIEW

FORREST AVE.

ELMHURST DRIVE

BELT ROAD

OAKLYN RD.

HEMLOCK DR.

NATALIE DRIVE

KNOLL VIEW DRIVE

CARPENTERSVILLE ROAD

ABBOTT ST.

CENTER ST.

MORRIS CANAL WAY

SAWMILL

MAIN ST.

ANDERSON STREET SOUTH

LIMEKILN ROAD

SUSSEX STREET

CAMPBELL

CANAL

RIVER

ROSEBERRY STREET

BARRYMORE STREET

FROST AVENUE

PICKFORD

HARTE ST.

BURKE STREET

FRACE ST.

FREDERICK

MITCHELL

SARGENT

INGERSOLL

GRACE

CORLISS

ELDER

BOWERS AVE.

HILLCREST

FAIRBANKS STREET

BOULEVARD

HAGERTY AVE.

FERGUSON

LINCOLN ROAD

PROSPECT AVENUE

WARREN

FIRTH

WILSON STREET

MILLCREST SOUTH

MILLCREST NORTH

FAIRVIEW

JOSEPH ST.

WEST BOUND AVENUE

EAST BOUND AVENUE

ORCHARD ALLEY

RAYMOND ST.

EVELYN AVE.

SHULTZ AVE.

MILLER

HENDERSON

SPRINGER ALLEY

SHILLINGER ALLEY

MARY ST.

JOHN ST.

DAVIS

COLBY PLACE

STOCKTON

WASHINGTON ST.

HOWARD

MERCER STREET

SOUTH MAIN

CEDAR

PINE ALLEY

RIVER ST.

STORE ALLEY

WATERSON

SUMMIT AVE.

MITCHELL

BULLMAN

BURNELL

BENNETT

CASTILL ALLEY

MORRIS

SOUTHERN

HARRISON

HANOVER STREET

REESE COURT

MARKET STREET

ELIZABETH ST.

STRYKER

FRONT STREET

HARRIS STREET

CHAMBERS STREET

SHIMER ST.

BRAINARD

REESE

WATER ST.

MAIN ST.

SOUTH

TYNDALL

RANDALL

PLEASANT AL.

LARE AL.

HENSHAW COURT

MEADOW COURT

GLEN

FILMORE

LEWIS

TAYLOR

HIGH

SPRUCE

PINE

CEDAR

LANE

ALLEN

ANN

JAMES

WILLIAM ST.

PURSEL

THOMAS

CENTER

CHESTNUT

EMMA

PARK RD.

PEACH

PEAR AL.

PERRY

PERRIDGE

HILL

GARNART

RICHER

GRIFFITH

WILBUR

STEWART ALLEY

MOULE ALLEY

ALLAN

CARLTON

DUNLOP

KORP

LEBANON

LEBANON CIR.

NORTH RIVERVIEW

RIVERVIEW CIR.

WOODLAWN ROAD

RIVERVIEW

FORREST AVE.

ELMHURST DRIVE

BELT ROAD

OAKLYN RD.

HEMLOCK DR.

NATALIE DRIVE

KNOLL VIEW DRIVE

CARPENTERSVILLE ROAD

ABBOTT ST.

CENTER ST.

MORRIS CANAL WAY

SAWMILL

MAIN ST.

ANDERSON STREET SOUTH

LIMEKILN ROAD

SUSSEX STREET

CAMPBELL

CANAL

RIVER

ROSEBERRY STREET

BARRYMORE STREET

FROST AVENUE

PICKFORD

HARTE ST.

BURKE STREET

FRACE ST.

FREDERICK

MITCHELL

SARGENT

INGERSOLL

GRACE

CORLISS

ELDER

BOWERS AVE.

HILLCREST

FAIRBANKS STREET

BOULEVARD

HAGERTY AVE.

FERGUSON

LINCOLN ROAD

PROSPECT AVENUE

WARREN

FIRTH

WILSON STREET

MILLCREST SOUTH

MILLCREST NORTH

FAIRVIEW

JOSEPH ST.

WEST BOUND AVENUE

EAST BOUND AVENUE

ORCHARD ALLEY

RAYMOND ST.

EVELYN AVE.

SHULTZ AVE.

MILLER

HENDERSON

SPRINGER ALLEY

SHILLINGER ALLEY

MARY ST.

JOHN ST.

DAVIS

COLBY PLACE

STOCKTON

WASHINGTON ST.

HOWARD

MERCER STREET

SOUTH MAIN

CEDAR

PINE ALLEY

RIVER ST.

STORE ALLEY

WATERSON

SUMMIT AVE.

MITCHELL

BULLMAN

BURNELL

BENNETT

CASTILL ALLEY

MORRIS

SOUTHERN

HARRISON

HANOVER STREET

REESE COURT

MARKET STREET

ELIZABETH ST.

STRYKER

FRONT STREET

HARRIS STREET

CHAMBERS STREET

SHIMER ST.

BRAINARD

REESE

WATER ST.

MAIN ST.

SOUTH

TYNDALL

RANDALL

PLEASANT AL.

LARE AL.

HENSHAW COURT

MEADOW COURT

GLEN

FILMORE

LEWIS

TAYLOR

HIGH

SPRUCE

PINE

CEDAR

LANE

ALLEN

ANN

JAMES

WILLIAM ST.

PURSEL

THOMAS

CENTER

CHESTNUT

EMMA

PARK RD.

PEACH

PEAR AL.

PERRY

PERRIDGE

HILL

GARNART

RICHER

GRIFFITH

WILBUR

STEWART ALLEY

MOULE ALLEY

ALLAN

CARLTON

DUNLOP

KORP

LEBANON

LEBANON CIR.

NORTH RIVERVIEW

RIVERVIEW CIR.

WOODLAWN ROAD

RIVERVIEW

FORREST AVE.

ELMHURST DRIVE

BELT ROAD

OAKLYN RD.

HEMLOCK DR.

NATALIE DRIVE

KNOLL VIEW DRIVE

CARPENTERSVILLE ROAD

ABBOTT ST.

CENTER ST.

MORRIS CANAL WAY

SAWMILL

MAIN ST.

ANDERSON STREET SOUTH

LIMEKILN ROAD

SUSSEX STREET

CAMPBELL

CANAL

RIVER

BROAD ST. F-6
BROADVIEW ST. N-32
BULLMANN ST. O-9
BURKE ST. O-9
BURNELL AL. O-9
CAHILL ST. K-20
CARHART AL. L-28
CARPENTERSVILLE RD. C-31
CEDAR AL. E-18
CENTER RD. G-32
CENTER ST. I-22
CHAMBERS ST. O-11
CHERRY LANE O-18
CHESTNUT ST. L-21
CHINA AL. O-5
CHINTEWINK AL. L-6
CHRISTIE AL. M-13
CHURCH ST. B-11
CLAIRMONT ST. O-31
COLBY PL. H-15
COLUMBUS AVE. D-15
COMPRESSOR ST. O-25
COMSTOCK AL. H-14
CONGRESS ST. F-11
CORLISS AVE. K-5
CRESS ST. K-13
CULVER ST. M-11
DAVIS ST. E-11
DEAN AL. N-11
DELAWARE RD. E-11
DIMMICK AL. B-11
DRILL ST. G-14
DUGAN AL. P-18
ELDER AVE. H-30
ELIZABETH ST. H-30
ELLEN ST. K-22
ELM ST. O-11
ELMHURST DR. L-18
EMPIRE ST. H-10
EMMA ST. O-8
ENGINE ST. L-7
ESSEX ST. H-5
EVELYN AVE. N-5
FAIRBANKS ST. O-8
FAIRVIEW AVE. L-17
FARM ST. I-10
FERGUSON ST. I-10
FILMORE ST. H-10
FIFTH ST. O-9
FIRST AL. O-9
FIRTH ST. K-20
FISHER AVE. L-28
FOCHT BRIDGE C-31
FORREST LA. E-18
FOURTH ST. G-32
FOX AL. I-22
FOX ST. O-11
FRACE ST. O-18
FRANCIS AVE. O-18
FRANKLIN ST. O-21
FREDERICK ST. O-11
FRONT ST. O-25
FROST AVE. N-7
FULTON ST. M-13
GATE ST. O-9
GLEN AVE. O-9
GRACE AVE. R-11
GRAND ST. R-27
GRANT ST. H-11
GREEN AL. L-11
GREEN ST. L-11
GREENWOOD ST. P-22
GRIFFITH AL. O-29
HAGERTY AVE. O-29
HANOVER ST. I-13
HARRIS ST. O-9
HARTE ST. O-9
HECKMAN ST. I-15
HEMLOCK ST. D-32
HENDERSON ST. I-22
HENSHAW CT. I-11
HILL ST. O-11
HILLCREST BLVD. L-11
HILLSIDE RD. O-25
HOWARD ST. O-27
HUDSON ST. O-16
INGERSOLL AVE. O-8
IRWIN ST. O-8
IVY ST. O-11
J. J. BAKER WAY O-15
JAMES ST. O-15
JEFFERSON ST. O-23
JERSEY ST. O-25
JOHN ST. O-16
JOHN MITCHELL AVE. O-14
JOSEPH ST. O-9
JUDD AL. O-9
KAITLYN CT. O-9
KENT ST. O-27
KNEEDLER AVE. O-27
KNOLL VIEW DRIVE O-16
KORP AL. O-16
KURLAND AL. O-25
LAKE AL. O-25
LENNON AL. O-25
LESHER AL. O-25
LEWIS ST. O-25
LINCOLN RD. O-25
LINCOLN ST. O-25
LINER BLVD. O-25
LOCK ST. O-25
LOGAN ST. O-25
LYNDALE ST. O-25
LYNN RD. O-25
MADISON ST. O-25
MARKET ST. O-25
MARSHALL ST. O-25
MARY ST. O-25
McKEEN ST. O-25
MELROSE ST. O-25
MEMORIAL PKWY. O-25
MERCER ST. O-25
METZ ST. O-25
MEYNER RD. O-25
MILL ST. O-25
MILLER ST. O-25
MITCHELL AL. O-25
MORRIS ST. O-25
MOULE AL. O-25
NATALIE DRIVE O-25
NELSON ST. O-25
NORTH AL. O-25
NO. MAIN ST. O-25
NO. RIVERVIEW RD. O-25
OAK AL. O-25
ORCHARD AL. O-25
PARK RD. O-25
PEACH ST. O-25
PEAR AL. O-25
PEARL ST. O-25
PERRIDGE AVE. O-25
PICKFORD AVE. O-25
PINE AL. O-25
PLEASANT AVE. O-25
POTTS AVE. O-25
PROSPECT ST. O-25
PURSEL ST. O-25
RAILROAD AVE. O-25
RANDALL ST. O-25
RAYMOND ST. O-25
REESE WAY O-25
REESE CT. O-25
RICHARD RD. O-25
RICHMOND ST. O-25
RIDGE ST. O-25
RIVER ST. O-25
RIVERSIDE WAY O-25
RIVERVIEW CIR. O-25
RIVERVIEW RD. O-25
ROCK AL. O-25
ROSE ST. O-25
ROSEBERRY ST. O-25
SARGENT AVE. O-25
SAWMILL ST. O-25
SAYRE AVE. O-25
SCHULTZ AVE. O-25
SHAFER AVE. O-25
SHERWOOD ST. O-25
SHILLINGER AL. O-25
SHIMER ST. O-25
SILK AVE. O-25
STEVENSON ST. O-25
SMITH AVE. O-25
SONORA ST. O-25
SO. MAIN ST. O-25
SPRINER AL. O-25
SPRUCE AL. O-25
ST. JOHN AL. O-25
STANLEY ST. O-25
STEELE ST. O-25
STEWART AL. O-25
STOCKTON ST. O-25
STRYKER ST. O-25
STULL AL. O-25
SUMMIT AVE. O-25
SUSAN ST. O-25
TAYLOR AL. O-25
TERSEY ST. O-25
THIRD ST. O-25
THOMAS ST. O-25
TICHE AL. O-25
TITUS AL. O-25
TUTTLE ST. O-25
TYNDALL AVE. O-25
UNION SQ. O-25
VALLEY VIEW CIR. O-25
WALNUT ST. O-25
WARREN ST. O-25
WASHINGTON ST. O-25
WATSON PL. O-25
WEBSTER ST. O-25
WILBUR AVE. O-25
WILLEVER ST. O-25
WILLIAM ST. O-25
WILSON ST. O-25
WOOD AVE. O-25
WOODLAWN RD. O-25

DISPOSED OF

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

12-18-23

Tom C Martin S.

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

TOWNSHIP OF LOPATCONG

TOWNSHIP OF POHATCONG

DELAWARE RIVER
COMMONWEALTH OF PENNSYLVANIA

CITY OF EASTON

I-78

OLDMANS

ROSEBERRY STREET
BARRYMORE STREET
FROST AVENUE
BORERS AVE
PICKFORD
HARTE ST.
BURKE STREET
FAIRBANKS STREET
BOULEVARD
HASBROUCK AVE.
PROSPECT AVENUE
LINCOLN ROAD
LINER BLVD.
FERGUSON
BELVIDERE
DELAWARE ROAD
TRACEE WAY
NORTH MAIN STREET
COURT STREET
FAIRVIEW
NEWHOUSE
MEMORIAL PARKWAY (RT. 22)
JOSEPH ST.
WEST BOUND AVENUE
EAST BOUND AVENUE
ORCHARD ALLEY
RAYMOND ST.
THIRD STREET
BACH ST.
PARK ALLEY
PARK PLACE
PARK AVENUE
GREEN GLEN
DEAN
FILLMORE
PEAR
LEWIS
ALGAR
MORROW
TAYLOR
WASHINGTON
STILL ALLEY
BENNETT
BURWELL
BULLMAN
MITCHELL
SUMMIT
CHAMBERS
HARRIS
FRONT
PLEASANT
RANDALL
LAKE AL.
SOUTH MAIN STREET
MARKET
ELIZABETH ST.
STRYKER
HANOVER STREET
REESE COURT
MERCER
HOWARD
SHIMER ST.
BRAINARD WAY
REESE
TYNDALL
HUDSON
IRWIN
STOCKTON
MARSHALL
HECKMAN
ANDERSON
FISHER
PLACE
DOLBY
BAWS
WATSON
KNEEDLER AVENUE
WALNUT STREET
ELM STREET
GREEN STREET
BATES STREET
PROSPECT STREET
LINCOLN STREET
GRANT STREET
WARREN STREET
FIRTH STREET
WILSON STREET
RAILROAD AVE.
SHULTZ AVE.
EVELYN AVE.
HENSHAW COURT
HENDERSON
MILLER
POTTS AVE
FRANCIS AVE.
SHELLINGER ALLEY
DEMUCK ALLEY
ST. JOHN ALLEY
LESHER ALLEY
LEMON ALLEY
ROCK ALLEY
DEMUCK
SHELLINGER
TIGHE ALLEY
STRYKER ALLEY
MEMORIAL PARKWAY (RT. 22)
MEMORIAL PKWY.
MEMORIAL PARKWAY
MEMORIAL PARKWAY (RT. 22)
MILLCREST SOUTH
MILLCREST NORTH
MILLCREST
CORLISS AVENUE
ELDER AVENUE
COMPRESSOR
JOHN
INGERSOLL
GRACE
SARGENT
FREDERICK
FORREST
BRIDGE
WILLOW ST.
ELM AVENUE
ELM ST.
ESSEX STREET
CAHILL ST.
RICHARD RD.
LYNN RD.
METYNER ROAD
SAYRE AVENUE
COLUMBUS AVE.
CENTER STREET
THOMAS
ANN
JAMES ST.
WILLIAM ST.
PURSEL
CHESTNUT ST.
MOULE
ALLEY
STREET
AVENUE
ROAD
GATE STREET
TUTTLE
HAGERTY
HILLSIDE
CONGRESS
CARLTON
VALLEY VIEW
RIDGE STREET
LOCK STREET
STANLEY STREET
GREENWOOD
PEARL ST.
GRAND ST.
LOGAN ST.
MADISON STREET
CHURCH
LYNDALE
MILL STREET
GRIFFITH
WILBUR AVENUE
PEROOE
HILL STREET
GARNET
BANK STREET
RIVERVIEW CIR.
NORTH RIVERVIEW
WOODLAWN ROAD
RIVERVIEW
FOREST LN.
ELMHURST ROAD
BELVIDERE AVE.
CARPENTERSVILLE ROAD
OAKLYN RD.
HEMLOCK DR.
KNOLL VIEW DRIVE
NATALIE DRIVE
MORRIS CANAL
MAIN
SAWMILL
PRITCHETT STREET
CENTER
ABBOTT ST.
MORGAN STREET
CEDAR
PINE ALLEY
STORE AVE.
JEFFERSON
SPRUCE
SOUTH MAIN
MERCER ST.
COURT
RIVER ST.
RIVERSIDE WAY
RIVERVIEW CIR.
RIVERVIEW RD.
ROSE ST.
ROSEBERRY ST.
SARGENT AVE.
SAWMILL ST.
SAYRE AVE.
SCHULTZ AVE.
SHAFER AVE.
SHERWOOD ST.
SHILLINGER AL.
SHIMER ST.
SILK AVE.
SITGREAVES ST.
SMITH AVE.
SONDRA ST.
SO. MAIN ST.
SPINNER AL.
SPRUCE AL.
ST. JOHN AL.
STANLEY ST.
STEELE ST.
STEWART AL.
STOCKTON ST.
STRYKER ST.
STULL AL.
SUMMIT AVE.
SUSAN ST.
TAYLOR AL.
TERRY ST.
THIRD ST.
THOMAS ST.
TIGHE AL.
TITUS PL.
TUTTLE ST.
TYNDALL AVE.
UNION SQ.
VALLEY VIEW CIR.
WALNUT ST.
WARREN ST.
WASHINGTON ST.
WATSON PL.
WEBSTER ST.
WILBUR AVE.
WILLEVER ST.
WILLIAM ST.
WILSON ST.
WOODLAWN RD.



B. Sutton
1-9-24

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Brian Sutton
1-9-24

BROADVIEW ST. I-32
BULLMAN ST. D-9
BURKE ST. D-9
BURWELL AL. D-9
CAHILL ST. L-20
CARHART AL. L-28
CARPENTERSVILLE RD. J-31
CEDAR AL. E-18
CENTER RD. D-32
CENTER ST. K-22
CHAMBERS ST. D-11
CHERRY LANE D-18
CHESTNUT ST. K-21
CHINA AL. D-5
CHINTEWINK AL. D-6
CHRISTIE AL. D-13
CHURCH ST. D-11
CLARMONT ST. D-31
COLBY PL. K-14
COLUMBUS AVE. D-25
COMPRESSOR ST. K-14
COMSTOCK AL. D-19
CONGRESS ST. K-20
CORLISS AVE. K-22
CROSS ST. D-10
CUJION ST. K-11
DAVIS ST. D-11
DEAN AL. E-11
DELAWARE RD. J-11
DIMRICK AL. D-11
DRILL ST. K-11
DUGAN AL. E-11
ELDER AVE. D-11
ELIZABETH ST. K-14
ELLEN ST. E-14
ELM ST. F-19
ELMHURST DR. F-20
EMIRE ST. E-10
EMMA ST. K-22
ENDINE ST. D-11
ESSEX ST. K-11
EVELYN AVE. D-11
FAIRBANKS ST. D-9
FAIRVIEW AVE. K-7
FARM ST. K-27
FERGUSON ST. D-11
FILMORE ST. E-11
FIFTH ST. J-14
FIRST AL. J-27
FISHER AVE. D-16
FOGHT BRIDGE D-7
FORREST LA. L-30
FOURTH ST. K-5
FOX AL. E-9
FOX ST. E-9
FRACE ST. D-10
FRANCIS AVE. E-10
FRANKLIN ST. D-10
FREDERICK ST. D-10
FRONT ST. D-9
FROST AVE. D-9
FULTON ST. E-14
GATE ST. L-27
GLEN AVE. J-17
GRACE AVE. D-10
GRAND ST. K-29
GRANT ST. D-11
GREEN AL. E-11
GREEN ST. K-22
GREENWOOD ST. D-28
GRIFFITH AL. D-7
HAGERTY AVE. D-7
HANOVER ST. D-13
HARRIS ST. D-9
HARTE ST. D-8
HECKMAN ST. D-16
HEMLOCK ST. L-32
HENDERSON ST. D-11
HENSHAW CT. D-11
HILL ST. K-11
HILLCREST BLVD. D-11
HILLSIDE RD. D-12
HOWARD ST. D-12
HUDSON ST. D-12
INGERSOLL AVE. D-13
IRWIN ST. D-13
IVY ST. K-23
J. BAKER WAY L-28
JAMES ST. D-19
JEFFERSON ST. D-19
JERSEY ST. D-19
JOHN ST. D-19
JOHN MITCHELL AVE. D-19
JOSEPH ST. D-19
JUDD AL. E-19
KAITLYN CT. K-5
KENT ST. K-23
KNEEDLER AVE. D-20
KNOLL VIEW DRIVE K-31
KORP AL. D-21
KURLAND AL. D-21
LAKE AL. D-21
LENNON AL. D-21
LESHER AL. D-21
LEWIS ST. D-21
LINCOLN RD. D-21
LINCOLN ST. D-21
LINER BLVD. D-21
LOCK ST. K-22
LOGAN ST. K-22
LYNDALE ST. D-31
LYNN RD. D-31
MADISON ST. K-22
MARKET ST. D-12
MARSHALL ST. D-12
MARY ST. D-12
McKEEN ST. D-12
MELROSE ST. K-22
MEMORIAL PKWY. D-12
MERCER ST. D-12
METZ ST. D-12
METZNER RD. D-12
MILL ST. D-12
MILLER ST. D-12
MITCHELL AL. D-12
MORRIS ST. D-12
MOULE AL. D-12
NATALIE DRIVE D-12
NELSON ST. D-12
NORTH AL. D-12
NO. MAIN ST. D-12
NO. RIVERVIEW RD. D-12
OAK AL. D-12
ORCHARD AL. D-12
PARK RD. D-12
PEACH ST. D-12
PEAR AL. D-12
PEARL ST. D-12
PERDOE AVE. D-12
PICKFORD AVE. D-12
PINE AL. D-12
PLEASANT AVE. D-12
POTTS AVE. D-12
PROSPECT ST. D-12
PURSEL ST. D-12
RAILROAD AVE. D-12
RANDALL ST. D-12
RAYMOND ST. D-12
REESE WAY D-12
REESE CT. D-12
RICHARD RD. D-12
RICHMOND ST. D-12
RIDGE ST. D-12
RIVER ST. D-12
RIVERSIDE WAY D-12
RIVERVIEW CIR. D-12
RIVERVIEW RD. D-12
ROCK AL. D-12
ROSE ST. D-12
ROSEBERRY ST. D-12
SARGENT AVE. D-12
SAWMILL ST. D-12
SAYRE AVE. D-12
SCHULTZ AVE. D-12
SHAFER AVE. D-12
SHERWOOD ST. D-12
SHILLINGER AL. D-12
SHIMER ST. D-12
SILK AVE. D-12
STOREAVES ST. D-12
SMITH AVE. D-12
SONORA ST. D-12
SO. MAIN ST. D-12
SPINNER AL. D-12
SPRUCE AL. D-12
ST. JOHN AL. D-12
STANLEY ST. D-12
STEELE ST. D-12
STEWART AL. D-12
STOCKTON ST. D-12
STRYKER ST. D-12
STULL AL. D-12
SUMMIT AVE. D-12
SUSAN ST. D-12
TAYLOR AL. D-12
TERRY ST. D-12
THIRD ST. D-12
THOMAS ST. D-12
TICHE AL. D-12
TITUS AL. D-12
TUTTLE ST. D-12
TYNDALL AVE. D-12
UNION SQ. D-12
VALLEY VEW CIR. D-12
WALNUT ST. D-12
WARREN ST. D-12
WASHINGTON ST. D-12
WATSON PL. D-12
WEBSTER ST. D-12
WILBUR AVE. D-12
WILLEVER ST. D-12
WILLIAM ST. D-12
WILSON ST. D-12
WISE AL. D-12
WOODLAWN RD. D-12

Tom C
1-9-24

THE TOWN OF PHILLIPSBURG

OFFICIAL MAP

WARREN COUNTY, NEW JERSEY

UPDATED 5-07

SCALE: 1" = 500'

500 0 500 1000

GRAPHIC SCALE OF FEET

DATE: December 1, 1998
REVISED October 2005

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

VACTOR INLET DEBRIS REMOVAL LOG		
Date	Location	Cubic Yards

VACTOR

DATE	LOCATION	CUBIC YARDS OF DEBRIS	
2-8-19	Rose st + Fourth	3 BASIN Clean	
2-8-19	Rose st + 3RD st	4 BASIN Clean	
2-8-19	BROAD st + 3RD st	2 BASIN Clean	
2-8-19	Chintewink Alley	1 BASIN Clean	
2-8-19	Andrews Alley + 3RD st	1 BASIN Clean	
4-27-20	Chamber + Washington	1 Basin Clean	
4-27-20	~~Chamber~~ + Stockton	1 Basin Clean	
4-27-20	Stockton + Rail Road	1 Basin Clean	
4-4-22	HECKman ? LEWIS	1 BASIN CLEAN	
9-7-22	Fillmore + BULLMAN	1 Basin Clean	
1-10-24	MORRIS + Main	1 Basin Clean	
1-10-24	Morris st	5 Basin Clean	
1-10-24	Marcus ~~Fillmore~~ Chamber st	4 Basin Clean	
1-10-24	Morris	3 Basin Clean	
1-10-24	Summit	10 Basin Clean	
1-10-24	Fillmore	14 Basin Clean	

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

INLET INSPECTION LOG & FIELD NOTES

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

INLET DEBRIS REMOVAL RECORDS

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

J. SPPP FORM 9 – STORM DRAIN INLET RETROFITTING

All records must be available upon request by NJDEP.

1. Describe the procedure for ensuring that municipally owned storm drain inlets are retrofitted.
The Municipal Stormwater Coordinator is responsible to require retro fit of Municipally owned storm drain inlets. Under certain conditions listed for hydraulic performance and when retrofitting inlets is cost prohibitive. Based on a 2018 NJDEP audit and recommendations, the Municipality has instituted a log to track whether inlets were retro-fitted as required or reason for not being retro-fitted.
2. Describe the inspection process to verify that appropriate retrofits are completed on municipally owned storm drain inlets.
Municipal projects are inspected either by the Municipality's DPW or by the Municipal Engineer.
3. Describe the procedure for ensuring that privately owned storm drain inlets are retrofitted.
For private sites, the Municipal ordinance requires retro fit based on type of improvement and would be enforced project review by Land Use Board (if required) or by Code Department issuance of project permits.
4. Describe the inspection process to verify that appropriate retrofits are completed on privately owned storm drain inlets.
The Municipal Construction/Code Department will inspect work for private sites that do not trigger site improvements to be inspected by the Municipal Engineer. The Municipality will maintain a report log tracking private retro fits and date of inspection.
5. Describe how you ensure that newly installed storm drain inlets include corresponding catch basins or other BMPs to collect solids
The Municipal Engineer will over see inlet updates as required for new construction on Town projects they are assigned and DPW and construction Offical will over updates to projects the Town Engineer is not involved in.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

PRIVATE SITE INLET RETRO-FIT LOG BOOK

Date Of Inspection:
Block – Lot:
Street Address:

Inspected By (Name/Department):

Retro Fit Required & Why:

Retro-Fit Completed:

Date Of Inspection:
Block – Lot:
Street Address:

Inspected By (Name/Department):

Retro Fit Required & Why:

Retro-Fit Completed:

Date Of Inspection:
Block – Lot:

Street Address:

Inspected By (Name/Department):

Retro Fit Required & Why:

Retro-Fit Completed:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

INLET RETRO-FIT LOG BOOK
The following log book shall be utilized to track inlet upgrades or when inlets that should be upgraded are not upgrade. The Stormwater Coordinator shall ensure list that shall be kept by the DPW and Municipal Engineer are kept current every month and then included to the SPPP as part of the annual update. Further, upon development of stormwater assessment management program, the inlets compliance shall be updated.
Date Of Inspection: Inlet Location: Inspected By (Name/Department): Retro Fit Required & Why: Retro-Fit Completed (if known put date or in unknown put N/A): Retro-Fit Not Completed & Why:
Date Of Inspection: Inlet Location: Inspected By (Name/Department): Retro Fit Required & Why: Retro-Fit Completed (if known put date or in unknown put N/A): Retro-Fit Not Completed & Why:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

K. SPPP FORM 10 – MUNICIPAL MAINTENANCE YARDS AND OTHER ANCILLARY OPERATIONS

All records must be available upon request by NJDEP.

DPW OPERATION & YARD LOCATIONS
Address of municipal yard or ancillary operation: **PRIMARY DPW YARD** 441 Heckman Street, Phillipsburg, NJ 08865 **AUXILIARY DPW YARD WASTE/ MATERIAL HOLDING SITE** Walters Park Meyner Road, Phillipsburg, NJ 08865
For each category see attached sheets which cover the Municipalities SOP for maintenance Yard operations and ancillary operations. All inspection logs are to be maintained by the DPW supervisor who will then at least on annual basis provide them to Stormwater Coordinator for inclusion in the SPPP annual plan update.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

EQUIPMENT LIST

On file with DPW and Town clerk

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

DATE OF INSPECTION:

Inspection Completed by:

Required Signs Post:

Spill Kit In Place at area of fuel delivery:

Spill Kit in place at area of fuel dispensing:

Items that need to be addressed:

Signs of stains or spills in area of fueling:

Locations of underground or above ground pipes marked and physically protected:

Are fuel holding tanks have signs of leaks

Every Month Track fuel usage and loses for possible leaks

Amount of fuel delivered in gallons (Year to Date):

Amount of Fuel registered as being pumped in gallons: (Year to Date):

Volume of fuel currently in Tank in gallons:

Estimate fuel loss:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

PRIMARY DPW YARD - MATERIALS STORAGE

This SPPP shall include a list of all materials and machinery located at municipal maintenance yards and ancillary operations which could be a source of pollutants in a stormwater discharge. The materials in question include, but are not limited to: raw materials; intermediate products; final products; waste materials; by-products; machinery and fuels; and lubricants, solvents, and detergents that are related to the municipal maintenance yard operations and ancillary operations. Materials or machinery that are not exposed to stormwater at the municipal maintenance yard or related to Operations do not need to be included.

Raw materials –

Intermediate products –

Final products –

Waste materials – used/spent tires

By-products –

Machinery –

Fuel –

Lubricants –

Solvents –

Detergents related to municipal maintenance yard or ancillary operations –

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

WALTERS PARK AUXILIARY DPW YARD - MATERIALS STORAGE

This SPPP shall include a list of all materials and machinery located at municipal maintenance yards and ancillary operations which could be a source of pollutants in a stormwater discharge. The materials in question include, but are not limited to: raw materials; intermediate products; final products; waste materials; by-products; machinery and fuels; and lubricants, solvents, and detergents that are related to the municipal maintenance yard operations and ancillary operations. Materials or machinery that are not exposed to stormwater at the municipal maintenance yard or related to its Operations do not need to be included.

Raw materials –

Intermediate products –

Final products –

Waste materials – used/spent tires

By-products –

Machinery –

Fuel –

Lubricants –

Solvents –

Detergents related to municipal maintenance yard or ancillary operations –

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

PRIMARY DPW YARD - FUELING OPERATIONS SOP

Establish, maintain and implement standard operating procedures to address vehicle fueling; receipt of bulk fuel deliveries; and inspection and maintenance of storage tanks, including the associated piping and fuel pumps.

A. Place drip pans under all hose and pipe connections and other leak-prone areas during bulk transfer of fuels.

B. Block storm sewer inlets, or contain tank trucks used for bulk transfer, with temporary berms or temporary absorbent booms during the transfer process. If temporary berms or booms are being used instead of blocking the storm sewer inlets, all hose connection points associated with the transfer of fuel shall be within the temporarily bermed or boomed area during the loading/unloading of bulk fuels. A trained employee shall be present to supervise the bulk transfer of fuel.

C. Clearly post, in a prominent area of the facility, instructions for safe operation of fueling equipment. Include all of the following:

   a. "Topping off of vehicles, mobile fuel tanks, and storage tanks is strictly prohibited"

   b. "Stay in view of fueling nozzle during dispensing"

   c. Contact information for the person(s) responsible for spill response.

D. Immediately repair or replace any equipment, tanks, pumps, piping and fuel dispensing equipment found to be leaking or in disrepair.

The Municipality will coordinate with an outside vendor during 2026 to establish a fueling operations Standard Operation Procedures and coordinate in-house inspection process and 3rd party certification of acceptable operations, the SPPP will be updated based on the to be established procedures.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

WEEKLY FUELING OPERATIONS INSPECTION LOG

Date of Inspection:

Inspection Completed by:

Required Signs Post:

Spill Kit In Place at area of fuel delivery:

Spill Kit in place at area of fuel dispensing:

Items that need to be addressed:

Signs of stains or spills in area of fueling:

Locations of underground or above ground pipes marked and physically protected:

Are fuel holding tanks have signs of leaks

Every Month Track fuel usage and loses for possible leaks
Amount of fuel delivered in gallons (Year to Date):

Amount of Fuel registered as being pumped in gallons: (Year to Date):

Volume of fuel currently in Tank in gallons:

Estimate fuel loss:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

PRIMARY DPW YARD - VEHICLE MAINTENANCE & WASHING SOP

The Municipality will coordinate with an outside vendor during 2026 to establish a Vehicle Maintenance Standard Operation Procedures. Currently the DPW maintains vehicles onsite within their public works garage and washes vehicles on concrete pad outside building. However the Department does not have Standard Operating Procedures Manual for this task.

The DPW yard does not have drains to stormwater system, the yard drains to sanitary sewer, DPW has oil/separator that collects runoff and then is cleaned out by the DPW prior to discharge to sanitary sewer, grease is discharge at sewer treatment plant via the vactor truck

Vehicle Maintenance NJDEP Best Practices Requirements

1. Operate and maintain equipment to prevent the exposure of pollutants to stormwater.

2. Whenever possible, conduct vehicle and equipment maintenance activities indoors. For projects that must be conducted outdoors, and that last more than one day, portable tents or covers shall be placed over the equipment being serviced when not being worked on, and drip pans shall be used at all times. Use designated areas away from storm drains or block storm drain inlets when vehicle and equipment maintenance is being conducted outdoors.

On-Site Equipment and Vehicle Washing and Wash Wastewater Containment

Manage any equipment and vehicle washing activities so that there are no unpermitted discharges of wash wastewater to storm sewer inlets or to waters of the State.

1. Tier A Municipalities which cannot discharge wash wastewater to a sanitary sewer or which cannot otherwise comply with 1, above, may temporarily contain wash wastewater prior to proper disposal under the following conditions:

    a. Containment structures shall not leak. Any underground tanks and associated piping shall be tested for integrity every 3 years using appropriate methods determined by "The List of Leak Detection Evaluations for Storage Tank Systems" created by the National Work Group on Leak Detection Evaluations (NWGLDE) or as determined appropriate and certified by a professional engineer for the site specific containment structure(s).

    b. For any cathodically protected containment system, provide a passing cathodic protection survey every three years.

    c. Operate containment structures to prevent overfilling resulting from normal or abnormal operations, overfilling, malfunctions of equipment, and human error. Overfill prevention shall include manual sticking/gauging of the tank before each use unless system design prevents such measurement. Tank shall no longer accept wash wastewater when determined to be at 95% capacity. Record each measurement to the nearest ½ inch.

d. Before each use, perform inspections of all visible portions of containment structures to ensure that they are structurally sound, and to detect deterioration of the wash pad, catch basin, sump, tank, piping, risers, walls, floors, joints, seams, pumps and pipe connections or other containment devices. The wash pad, catch basin, sump and associated drains should be kept free of debris before each use. Log dates of inspection; inspector's name, and conditions. This inspection is not required if system design prevents such inspection.

e. Containment structures shall be emptied and taken out of service immediately upon detection of a leak. Complete all necessary repairs to ensure structural integrity prior to placing the containment structure back into service. Any spills or suspected release of hazardous substances shall be immediately reported to the NJDEP Hotline (1-877-927-6337) followed by a site investigation in accordance with N.J.A.C. 7:26C and N.J.A.C 7:26E if the discharge is confirmed.

f. All equipment and vehicle wash wastewater placed into storage must be disposed of in a legally permitted manner (e.g. pumped out and delivered to a duly permitted and/or approved wastewater treatment facility).

g. Maintain a log of equipment and vehicle wash wastewater containment structure clean-outs including date and method of removal, mode of transportation (including name of hauler if applicable) and the location of disposal. See Underground Vehicle Wash Water Storage Tank Use Log at end of this attachment.

h. Containment structures shall be inspected annually by a NJ licensed professional engineer. The engineer shall certify the condition of all structures including: wash pad, catch basin, sump, tank, piping, risers to detect deterioration in the, walls, floors, joints, seams, pumps and pipe connections or other containment devices using the attached Engineer's Certification of Annual Inspection of Equipment and Vehicle Wash Wastewater Containment Structure. This certification may be waived for self-contained systems on a case-by-case basis. Any such waiver would be issued in writing by the Department.

2. Maintain all logs, inspection records, and certifications on-site. Such records shall be made available to the Department upon request.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

WEEKLY VEHICLE WASHING FACILITIES INSPECTION LOG

Date of Inspection:

Inspection Completed by:

Estimated number of vehicles washed:

Were all vehicles washed in designated area:

Number of Times Oil/Separator was emptied & where and how much material was emptied:

Was oil Separator tank inspected for damages or defects and were any found?

Was there any incidents were vehicles were was not following the SOP

Any time vehicles being washed were discharge to stormwater system and reason

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

ANNUAL VEHICLE WASHING FACILITIES INSPECTION LOG

ENGINEERS CERTIFICATION OF ANNUAL INSPECTION OF EQUIPMENT
AND VEHICLE WASH WASTEWATER CONTAINMENT STRUCTURE

(Complete a separate form for each vehicle wash wastewater containment structure)

Permittee:

NJPDES Permit No:

Containment Structure Location: _____

The annual inspection of the above referenced vehicle wash wastewater containment structure was conducted on _____ (date). The containment structure and appurtenances have been inspected for:

1. The integrity of the structure including walls, floors, joints, seams, pumps and pipe connections
2. Leakage from the structure's piping, vacuum hose connections, etc.
3. Bursting potential of tank.
4. Transfer equipment
5. Venting
6. Overflow, spill control and maintenance.
7. Corrosion, splits, and perforations to tank, piping and vacuum hoses

The tank and appurtenances have been inspected for all of the above and have been determined to be:

- ☐ Acceptable
- ☐ Unacceptable
- ☐ Conditionally Acceptable

List necessary repairs and other conditions:

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment (N.J.A.C. 7:14A-2.4(d)).

Name (print): _____ Seal:

Signature: _____

Date: _____

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

SALT AND DE-ICING MATERIAL STORAGE AND HANDLING & AGGREGATE MATERIAL AND CONSTRUCTION DEBRIS STORAGE

The Municipality stores rock salt and…. at the main DPW yard at Heckman Street in bins within an open faced 3-sided building.

NJDEP Guidance

1. Store material in a permanent structure.
2. Perform regular inspections and maintenance of storage structure and surrounding area.
3. Minimize tracking of material from loading and unloading operations.
4. During loading and unloading:
    a. Conduct during dry weather, if possible;
    b. Prevent and/or minimize spillage; and
    c. Minimize loader travel distance between storage area and spreading vehicle.

5. Sweep (or clean using other dry cleaning methods):
    a. Storage areas on a regular basis;
    b. Material tracked away from storage areas;
    c. Immediately after loading and unloading is complete.

6. Reuse or properly discard materials collected during cleanup.
7. Temporary outdoor storage is permitted only under the following conditions:
    a. A permanent structure is under construction, repair or replacement;
    b. Stormwater run-on and de-icing material run-off is minimized;
    c. Materials in temporary storage are tarped when not in use;
    d. The requirements of 2 through 6, above are met; and
    e. Temporary outdoor storage shall not exceed 30 days unless otherwise approved in writing by the Department;
8. Sand must be stored in accordance with Aggregate Material and Construction Debris Storage SOP.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

AGGREGATE MATERIAL AND CONSTRUCTION DEBRIS STORAGE

Repeat items stored in yard and how they are stored.

The Municipality will be revising their storage of construction debris materials yard at Walters Park to comply with NJDEP best Practices, the DPW will be constructing a berm to control runoff of yard waste and compost pile of leaves, then constructing concrete pads for construction debris storage and material sorting before disposing of the material offsite, the use of pads and dumpsters will utilized A monthly inspection report and log will be developed to track when materials are disposed of, when materials are removed and to where, and visual inspection of debris piles, and runoff control measures.

NJDEP Guidance

1. For the purposes of this permit, this BMP is intended for road cleanup materials as well as other similar materials. Road cleanup materials may include but are not limited to street sweepings, storm sewer clean out materials, stormwater basin clean out materials and other similar materials that may be collected during road cleanup operations. These BMPs do not cover materials such as liquids, wastes which are removed from municipal sanitary sewer systems or material which constitutes hazardous waste in accordance with N.J.A.C. 7:26G-1.1 et seq.

2. Road cleanup materials must be ultimately disposed of in accordance with N.J.A.C. 7:26-1.1 et seq. See the "Guidance Document for the Management of Street Sweepings and Other Road Cleanup Materials" (www.nj.gov/dep/dshw/rrtp/sweeping.htm).

3. Road cleanup materials placed into storage must be, at a minimum:

    a. Stored in leak-proof containers or on an impervious surface that is contained (e.g. bermed) to control leachate and litter; and

    b. Removed for disposal (in accordance with 2, above) within six (6) months of placement into storage.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

YARD TRIMMINGS AND WOOD WASTE MANAGEMENT SITES

The DPW will develop a written SOP based on NJDEP guidance for the operation of their Yard Trimming and wood waste management site. The DPW operates the Walters Park auxiliary yard has yard trimming and wood waste management site. The yard is locked an only open to the public for disposal when they schedule the drop off and material is inspected by DPW. Further, debris collected by the DPW is separated by materials to ensure proper use and control of materials. There are no inlets or stormwater facilities at the yard. In recent DEP audit, it was recommended that berm to control runoff from compost pile is control before leaving site. Further, DPW will only do curb side chipping of yard waste until it obtains a yard waste/wood processing permit from the state that is now required when chipping and storing on site.

NJDEP Guidance

1. These practices are applicable to any yard trimmings or wood waste management site:
    a. Owned and operated by the Tier A Municipality;
        i. For staging, storing, composting or otherwise managing yard trimmings, or
        ii. For staging, storing or otherwise managing wood waste, and
    b. Operated in compliance with the Recycling Rules found at N.J.A.C. 7:26A.
2. Yard trimmings or wood waste management sites must be operated in a manner that:
    a. Diverts stormwater away from yard trimmings and wood waste management operations; and
    b. Minimizes or eliminates the exposure of yard trimmings, wood waste and related materials to stormwater.
3. Yard trimmings and wood waste management site specific practices:
    a. Construct windrows, staging and storage piles:
        i. In such a manner that materials contained in the windrows, staging and storage piles (processed and unprocessed) do not enter waterways of the State;
        ii. On ground which is not susceptible to seasonal flooding;
        iii. In such a manner that prevents stormwater run-on and leachate run-off (e.g. use of covered areas, diversion swales, ditches or other designs to divert stormwater from contacting yard trimmings and wood waste).
    b. Maintain perimeter controls such as curbs, berms, hay bales, silt fences, jersey barriers or setbacks, to eliminate the discharge of stormwater runoff carrying leachate or litter from the site to storm sewer inlets or to surface waters of the State.
    c. Prevent on-site storm drain inlets from siltation using controls such as hay bales, silt fences, or filter fabric inlet protection.
    d. Dry weather run-off that reaches a municipal stormwater sewer system is an illicit discharge. Possible sources of dry weather run-off include wetting of piles by the site operator; uncontrolled pile leachate or uncontrolled leachate from other materials stored at the site.
    e. Remove trash from yard trimmings and wood waste upon receipt.
    f. Monitor site for trash on a routine basis.
    g. Store trash in leak-proof containers or on an impervious surface that is contained (e.g. bermed) to control leachate and litter;
    h. Dispose of collected trash at a permitted solid waste facility.
    i. Employ preventative tracking measures, such as gravel, quarry blend, or rumble strips at exits.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

ROADSIDE VEGETATION MANAGEMENT
The DPW will follow NJDEP guidance for roadside vegetation management.

NJDEP Guidance

1. Tier A Municipalities shall restrict the application of herbicides along roadsides in order to prevent it from being washed by stormwater into the waters of the State and to prevent erosion caused by de-vegetation, as follows: Tier A Municipalities shall not apply herbicides on or adjacent to storm drain inlets, on steeply sloping ground, along curb lines, and along unobstructed shoulders. Tier A Municipalities shall only apply herbicides within a 2 foot radius around structures where overgrowth presents a safety hazard and where it is unsafe to mow.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

L. SPPP FORM 11 – EMPLOYEE TRAINING

All records must be available upon request by NJDEP.

A. **Municipal Employee Training:** Stormwater Program Coordinator (SPC) must ensure appropriate staff receive training on topics in the chart below as required due to job duties assigned within three months of commencement of duties and again on the frequency below. Indicate the location of associated training sign in sheets, dates, and agendas or description for each topic.

Topic	Frequency	Title of trainer or office to conduct training
1. Maintenance Yard Operations (including Ancillary Operations)	Every year	Public Works Supervisor
2. Stormwater Facility Maintenance	Every year	Public Works Supervisor
3. SPPP Training & Recordkeeping	Every year	Municipal Engineer
4. Yard Waste Collection Program	Min. Every 2 years (Every Year Preferred)	Public Works Supervisor
5. Street Sweeping	Min. Every 2 years (Every Year Preferred)	Public Works Supervisor
6. Illicit Connection Elimination and Outfall Pipe Mapping	Min. Every 2 years (Every Year Preferred)	Public Works Supervisor
7. Outfall Pipe Stream Scouring Detection and Control	Min. Every 2 years (Every Year Preferred)	Public Works Supervisor
8. Waste Disposal Education	Min. Every 2 years (Every Year Preferred)	Stormwater Coordinator
9. Municipal Ordinances	Min. Every 2 years (Every Year Preferred)	Stormwater Coordinator
10. Construction Activity/Post-Construction Stormwater Management in New Development and Redevelopment	Min. Every 2 years (Every Year Preferred)	Stormwater Coordinator

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

B. **Municipal Board and Governing Body Members Training:** Required for individuals who review and approve applications for development and redevelopment projects in the municipality. This includes members of the planning and zoning boards, Municipal council, and anyone else who votes on such projects. Training is in the form of online videos, posted at www.nj.gov/dep/stormwater/training.htm.

Within 6 months of commencing duties, watch *Asking the Right Questions in Stormwater Review Training Tool*. Once per term thereafter, watch at least one of the online DEP videos in the series available under Post-Construction Stormwater Management. Indicate the location of records documenting the names, video titles, and dates completed for each board and governing body member.

Implementation Schedule:

- All required persons will be trained in 2025, in effort to ensure all required parties are trained and current.

Training Format:

- The Stormwater Coordinator will notify all governing body members, land use board members and construction/zoning officials and municipal engineer that they are required to review the stormwater training video.
- Each required person will review the video and then report the date they reviewed the video and the Stormwater coordinator will maintain log of persons whom completed the required training.

Required Persons to be trained:

- Governing Body
- Land Use Board
- Construction Official
- Zoning Official
- Municipal Engineer

Item to occur before training and ongoing basis:

- Stormwater Coordinator to verify link to NJDEP site to ensure most current link is provided to people to be trained.

Training shall include the following items:

- Memo directing viewing of NJDEP
- Review of NJDEP Video

Training Closeout:

- Memo & Training Log shall be provided by Stormwater Coordinator to the Municipal Clerk for inclusion into SPPP

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

MUNICIPAL BOARD AND GOVERNING BODY MEMBERS TRAINING LOG	
Date Notification of Required Training Circulated by Stormwater Coordinator:	
Date Training log submitted to Clerk by Stormwater Coordinator:	
Location of Records for NJDEP Review	Within the SPPP located in the Clerks Records once finalized.
List of People that are to be trained.	

Title: Mayor

Name:

Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":*

Date of Post-Construction Stormwater Management Video:

Post-Construction Video that was watched:

Title: Council President

Name:

Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":*

Date of Post-Construction Stormwater Management Video:

Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Council Vice-President Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Council Member Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Council Member

Name:

Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":*

Date of Post-Construction Stormwater Management Video:

Post-Construction Video that was watched:

Title: Council Member

Name:

Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":*

Date of Post-Construction Stormwater Management Video:

Post-Construction Video that was watched:

Title: Construction Official Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Zoning Official Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Municipal Engineer Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Land Use Board Chairman Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Title: Land Use Board Vice Chairman Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Land Use Board Secretary Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Land Use Board Member Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Land Use Board Member Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Title: Land Use Board Member Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Land Use Board Member Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Land Use Board Member Alternate No. 1 Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:
Title: Land Use Board Member Alternate No. 2 Name: Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":* Date of Post-Construction Stormwater Management Video: Post-Construction Video that was watched:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Title: Land Use Technical Assistant

Name:

Date Completed "*Asking the Right Questions in Stormwater Review Training Tool":*

Date of Post-Construction Stormwater Management Video:

Post-Construction Video that was watched:

C. **Stormwater Management Design Reviewer Training:** All design engineers, municipal engineers, and others who review the stormwater management design for development and redevelopment projects on behalf of the municipality must attend the first available class upon assignment as a reviewer and every five years thereafter. The course is a free, two-day training conducted by DEP staff. Training dates and locations are posted at www.nj.gov/dep/stormwater/training.htm. Indicate the location of the DEP certificate of completion for each reviewer.

Title of trainer or office to conduct training	NJDEP

Implementation Schedule:

- All required persons will be trained in 2025, in effort to ensure all required parties are trained and current.

Training Format:

- The Stormwater Coordinator will notify all required persons that they are required to review the stormwater training video.
- Each required person will review the video and then report the date they reviewed the video and the Stormwater coordinator will maintain log of persons whom completed the required training.

Required Persons to be trained:

- Municipal Engineer & review staff
- Land Use Board Engineer & review staff
- Zoning Officer
- Construction Official

Item to occur before training and ongoing basis:

- Stormwater coordinator shall forward email notification from NJDEP of upcoming training and forward to any required persons.
- Verify last time required person attended training
- Identify any new person that must attend training if not already trained by NJDEP in last 5 years.

Training shall include the following items:

- Attendance at NJDEP training class

Training Closeout:

- Person's trained will provide certificate to Stormwater Coordinator who will provide document to clerk for inclusion into SPPP.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

MAINTENANCE YARD OPERATIONS (INCLUDING ANCILLARY OPERATIONS)	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Every Year

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2025.

Training Format:

- Training will be held at a location to be determined by the DPW.
- Training on this topic may be broken down over several periods of time but schedule encourage participation and limit impact is daily job performance. Example – 30 minutes a day over set period of time.

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- Any other department utilizing the maintenance yard

Item to occur before training and ongoing basis:

- Audit compliance with an aspect of maintenance yard operations.
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review Maintenance Yard Standard operating procedures and best practices.
- Review internal compliance/audit findings
- Verify measures and controls are in place
- Review fueling operations sop, stormwater discharge containment, vehicle maintenance, vehicle/equipment washing, salt/de-icing, material storage, street sweepings/catch basin/other material storage/disposal, yard trimming and wood waste management sites and roadside vegetation management.
- Inventory of equipment and materials, inspection, good housekeeping

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

STORMWATER FACILITY MAINTENANCE	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Every Year

Required Persons to be trained (not required to be all at the same time):

- Stormwater Coordinator
- Public Works Department (all staff)
- Construction Inspection Department / Code Enforcement / Zoning (all staff)
- Municipal Engineer
- Municipal Council
- Police Department
- Land Use/Planning Board

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review Municipality's requirements for Stormwater Facilities maintenance Town Owned and privately owned systems
- Review SPPP record keeping requirements related to topic
- Watch NJDEP training video on stormwater maintenance, post construction management
- https://njmel.org/mel-safety-institute/webinars/
- Review inspection requirements, cleaning requirements and improvement requirements for inlets, basins or facilities

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

SPPP TRAINING & RECORDKEEPING	
Title of trainer or office to conduct training	Municipal Engineer
Schedule	Every Year

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2025.

Training Format:

- Training will be held at a location to be determined by the stormwater coordinator.
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- All department heads

Item to occur before training and ongoing basis:

- Audit compliance with an aspect of maintenance yard operations.
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review each department's role and documents that are to be maintained.
- Review internal compliance/audit findings
- Verify measures and controls are in place

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

YARD WASTE COLLECTION PROGRAM	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026.

Training Format:

- Training will be held at a location to be determined by the DPW.
- Training will consist of discussion lead by DPW Supervisor
- May be combined with other training topics should audience be similar to other topics
-

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- Any other Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance with an aspect of Yard Waste Collection
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP
- Review log for Yard waste collection area and disposal records

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review Yard Waste Collection Ordinance and Municipal procedure policy.
- Review enforcing/troubling shooting policy
- Review schedule/frequency of pickups
- Watch NJDEP Training video on stormwater solid and floatable concerns
- https://njmel.org/mel-safety-institute/webinars/

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

STREET SWEEPING	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026.

Training Format:

- Training will be held at a location to be determined by the DPW.
- Training will consist of discussion lead by DPW Supervisor
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- Any other Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance with an aspect of Street Sweeping
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review Street Sweeping Program, Log book/record keeping
- Watch NJDEP Training video on stormwater solid and floatable concerns
- https://njmel.org/mel-safety-institute/webinars/

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

ILLICIT CONNECTION ELIMINATION AND OUTFALL PIPE MAPPING OUTFALL PIPE STREAM SCOURING DETECTION AND CONTROL	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026.

Training Format:

- Training will be held at a location to be determined by the DPW.
- Training will consist of discussion lead by DPW Supervisor
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- Any other Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance with an aspect of illicit connection and outfall pipe mapping
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review illicit connection ordinance and inspection checklist
- Review Municipality's Procedure policy for illicit connection
- Review outfall maps, inspection forms and record keeping
- How to locate, inspect & ID scour or improper flows/illicit connections

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

WASTE DISPOSAL EDUCATION	
Title of trainer or office to conduct training	Public Works Supervisor
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026

Training Format:

- Training will be held at a location to be determined by the DPW.
- Training will consist of discussion lead by DPW Supervisor
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Public Works Department
- Stormwater Coordinator
- Any other Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance waste disposal ordinance
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipal Stormwater Pollution Prevention Plan and associated documents.
- Review waste disposal education
- Watch NJDEP Training video on stormwater solid and floatable concerns
- https://njmel.org/mel-safety-institute/webinars/
- Discuss how to respond to inquiries of improper waste disposal

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

MUNICIPAL ORDINANCES	
Title of trainer or office to conduct training	Stormwater Coordinator
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026.

Training Format:

- Training will be held at a location to be determined by the Stormwater Coordinator
- Training will consist of discussion lead by Stormwater Coordinator
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Any Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance records
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipality's policy and procedure on topic
- Review municipal ordinances listed under MS-4 SPPP

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

CONSTRUCTION ACTIVITY/POST-CONSTRUCTION STORMWATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT	
Title of trainer or office to conduct training	Stormwater Coordinator
Schedule	Min. Every 2 years (Every Year Preferred)

Implementation Schedule:

- Initial training under this new SPPP will be held in 2025 and amended by end of 2026.

Training Format:

- Training will be held at a location to be determined by the Stormwater Coordinator
- Training will consist of discussion lead by Stormwater Coordinator
- May be combined with other training topics should audience be similar to other topics

Required Persons to be trained:

- Any Department Head who's department coordinates or enforces this program

Item to occur before training and ongoing basis:

- Audit compliance records
- Review condition and location of SOPs
- Review records on prior issues, concerns or questions by members of department related to this topic
- Check for new requirements from NJDEP

Training shall include the following items:

- Sign in sheet
- Discussion of the Municipality's policy and procedure on topic
- Review Municipality's MS-4 SPPP
- Review permitting requirements, logs, record keeping
- Review location of information

Training Closeout:

- Minutes and attendance list shall be prepared and submitted to stormwater coordinator for inclusion in SPPP update and annual reporting.
- Provide secondary training via review of meeting minutes by staff that was not able to attend.
- Document any items that need to be addressed such as a new SOP or equipment replacement

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

M.SPPP FORM 12 – OUTFALL PIPES

All records must be available upon request by NJDEP.

1. **Mapping:** Attach an image or provide a link to the most current outfall pipe map. Maps shall be updated at the end of each calendar year.

Note that ALL maps must be electronic by 21 Dec 2020 via the DEP's designated electronic submission service. For details, see http://www.nj.gov/dep/dwq/msrp_map_aid.htm.

Currently the Municipality utilizes a redline of the Municipal Road map to track locations of outfalls and inlets. The Municipality acknowledges the need to document the GPS location of outfalls and inlets and provide digital mapping and number of the structures. To provide digital mapping and GPS coordinates of structures, the Municipality will first work to digitize their tax maps, which is anticipated to be completed in the YR 2025, once the mapping is completed, stormwater facilities will be added to the map based on GPS locations of structures and this will be completed and submitted by YR 2020 In subsequent years the Municipality will update the mapping to include pipe network information.

The Municipality will work to expedite schedule funding permits.

2. **Inspections:** Describe the outfall pipe inspection schedule and indicate the location of records of dates, locations, and findings.

Outfalls are inspected on annual basis, should dry weather flow be observed, the DPW will obtain outside contractor to sample flow as required. They will then track the source of the flow and make required repairs or notify responsible party to address illicit connection.

3. **Stream Scouring:** Describe the program in place to detect, investigate and control localized stream scouring from stormwater outfall pipes. Indicate the location of records related to cases of localized stream scouring. Such records must include the contributing source(s) of stormwater, recommended corrective action, and a prioritized list and schedule to remediate scouring cases.

DPW inspects outfalls on routine basis and as part of the inspection documents condition of outfall area and outfalls. Scour has not been reported at this location over the years.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

4. **Illicit Discharges:** Describe the program in place for conducting visual dry weather inspections of municipally owned or operated outfall pipes. Record cases of illicit discharges using the DEP's Illicit Connection Inspection Report Form (www.nj.gov/dep/dwq/tier_a_forms.htm) and indicate the location of these forms and related illicit discharge records.

   Note that Illicit Connection Inspection Report Forms shall be included in the SPPP and submitted to DEP with the annual report.

DPW is the department responsible for the initial investigation; they have the authority to bring additional resources such Building/Code Department, Engineering or Police for assistance with the investigation. In some cases, the Building/Code department will address illicit connections if it observed during inspections of properties for various permits or occupancy inspections.

The Municipality requires the illicit connection to be documented, notice of violation issued to responsible property and then corrective action taken by responsible party which they can be subject to fines and other penalties for the initial illicit connection and any inaction by the party could be subject to additional fines.

If, after the appropriate amount of investigation, we are unable to locate the source of the illicit connection, we will submit the Closeout Investigation Form with our Annual Inspection and Recertification. If an illicit connection is found to originate from another public entity, Municipality will report the illicit connection to the Department of Environmental Protection.

Complaints and/or reports of illicit connections will be investigated by the DPW, should reports b\e received by a different department, the report will be forwarded to the DPW.


Outside contractor will test flows to confirm content.

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

OUTFALL MAP

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org



Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

OUTFALL INSPECTION FORM

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

OUTFALL INSPECTION
SECTION 1 - GENERAL NOTES
OUTFALL ID:
LOCATION OF OUTFALL:
DATE OF INSPECTION:
INSPECTED BY:
WEATHER AT TIME OF INSPECTION:
PRECIPITATION LAST 24 HOURS (INCHES):
PRECIPITATION LAST 48 HOURS (INCHES):
DESCRIPTION OF AREA AROUND OUTFALL:
SECTION 2 - OUTFALL PIPE DESCRIPTION
PIPE MATERIAL
PIPE SHAPE
PIPE DIMENSIONS (IN.)
SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY
SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY
FLOW PRESENT: YES NO
FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL
SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION
CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:
CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER
DEPTH:
TOP WIDTH:
BOTTOM WIDTH:
FLOW PRESENT: YES NO
FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL
SECTION 4 - OUTFALL OBSERVED CONDITIONS
ODOR DETECTED (DESCRIBE ODOR):
PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:
CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):
ADDITIONAL COMMENTS OR NOTES:

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

OUTFALL INSPECTION LOG PRE 2018

Town of Phillipsburg
120 Filmore Street
Phillipsburg, NJ 08865
Phone: 908-454-5500 x 314
Fax: 908-454-6511
Website: www.phillipsburgnj.org

INSPECTION OF OUTFALL LOG							
Outfall No.	Type	Date of Inspection	Inspected By	Weather	Flow	Scour	Comment
1	Box						
2	Box						
3	36” RCP						
4	24” RCP						
5	24” CMP						
6	18” CMP						
7	18” CMP						
8	36” CMP						
9	Box						
10	Box						
11	18” RCMP						
12	18” RCP						
13	12” VC						
14	24” RCP						

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #1

LOCATION OF OUTFALL: 3rd St

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Brick

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #2

LOCATION OF OUTFALL: China Alley

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Brick

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #3 [redacted]

LOCATION OF OUTFALL: Judd Alley

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Concrete

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 4"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #4

LOCATION OF OUTFALL: JT Baker Way + 2nd

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Water

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Pastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #5

LOCATION OF OUTFALL: Riverside Way toll bridge

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Metal

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #6

LOCATION OF OUTFALL: Riverside Way Pump House

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Plastic

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #7

LOCATION OF OUTFALL: Free Bridge

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Sand + Dead weeds

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 8

LOCATION OF OUTFALL: DRP

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Lacey

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): n/a

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #9

LOCATION OF OUTFALL: Tracks End of center

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: concrete

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 4"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): no

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

no

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

no

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #10 X3

LOCATION OF OUTFALL: near sewer plant Foot Bridge

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

water

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Metal corrigated, plastic, Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30", 24", 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): no

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

no

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

no

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 11

LOCATION OF OUTFALL: Carpentersville Rd

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #12

LOCATION OF OUTFALL: Behind agway

DATE OF INSPECTION: [redacted] 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Brush + weeds

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 18"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #13

LOCATION OF OUTFALL: Lock ST So main

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

weeds + grass

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

FLOW PRESENT: ~~YES~~ NO

FLOW DESCRIPTION: NONE ~~TRICKLE~~ MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: ~~CONCRETE~~ EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: ~~YES~~ NO

FLOW DESCRIPTION: NONE ~~TRICKLE~~ MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 14

LOCATION OF OUTFALL: Lock St

DATE OF INSPECTION: 2-1-24

INSPECTED BY: Eric + Brad

WEATHER AT TIME OF INSPECTION: Cloudy

PRECIPITATION LAST 24 HOURS (INCHES): 1/2

PRECIPITATION LAST 48 HOURS (INCHES): 1/2

DESCRIPTION OF AREA AROUND OUTFALL:

Tree + weeds

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 1

LOCATION OF OUTFALL: 3rd street

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike S. & Snyder

WEATHER AT TIME OF INSPECTION: raining

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Bricks

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #2

LOCATION OF OUTFALL: China alley

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Brick

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #3

LOCATION OF OUTFALL: Judd alley

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/4

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4'

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): ND

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

ND

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

ND

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #4

LOCATION OF OUTFALL: JT Baker way, 2nd

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

water

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #5

LOCATION OF OUTFALL: Riverside way toll Bridge

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL metal

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #6

LOCATION OF OUTFALL: Riverside way Pump House

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/3

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): ND

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

ND

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

ND

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #7

LOCATION OF OUTFALL: Free Bridge

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 8

LOCATION OF OUTFALL: DRP

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): ND

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

ND

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

ND

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 9

LOCATION OF OUTFALL: Tracks end of center

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8"

PRECIPITATION LAST 48 HOURS (INCHES): 1/4"

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: FT ID x3

LOCATION OF OUTFALL: Near sewer plant Foot Bridge

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

water

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Metal Corrigated

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30" 24" 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: ~~#~~ 11

LOCATION OF OUTFALL: Carpentersville Rd

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Cement

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) ~~NO~~

FLOW DESCRIPTION: ~~NONE~~ (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): ND

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

ND

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

ND

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #12

LOCATION OF OUTFALL: Behind Agway

DATE OF INSPECTION: 1-25-24

INSPECTED BY: Mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Brush

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 18"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 13

LOCATION OF OUTFALL: Lock st So. main

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike.s & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Grass

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.)

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 14

LOCATION OF OUTFALL: Lock st

DATE OF INSPECTION: 1-25-24

INSPECTED BY: mike S. & Snyder

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/8

PRECIPITATION LAST 48 HOURS (INCHES): 1/4

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR):

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

NO

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #1

LOCATION OF OUTFALL: End of JT Bakeway

DATE OF INSPECTION: 12/11/23

INSPECTED BY: MS - DM

WEATHER AT TIME OF INSPECTION: Rain

PRECIPITATION LAST 24 HOURS (INCHES): 1/16"

PRECIPITATION LAST 48 HOURS (INCHES): 1/16"

DESCRIPTION OF AREA AROUND OUTFALL:

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic Fiberglass

PIPE SHAPE Round 30"

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #2

LOCATION OF OUTFALL: End of Cypress Alley

DATE OF INSPECTION: 12-11-23

INSPECTED BY: MS - DM

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/16"

PRECIPITATION LAST 48 HOURS (INCHES): 1/16"

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks / TREES

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Cast IRON

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 18"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #3

LOCATION OF OUTFALL: End of Inlet

DATE OF INSPECTION: 12-11-2023

INSPECTED BY: MS - DM

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/16"

PRECIPITATION LAST 48 HOURS (INCHES): 1/16"

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #4

LOCATION OF OUTFALL: End of 3RD St

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): NONE

PRECIPITATION LAST 48 HOURS (INCHES): NONE

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Brick

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER) V

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #5

LOCATION OF OUTFALL: Riverside way under Toll B.

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Corrugated Metal

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 30"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER Ramp

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #6

LOCATION OF OUTFALL: Pump House Riverside way

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

TREES

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Plastic ~~Round~~

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 12"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #7

LOCATION OF OUTFALL: Under Fore BRIDGE

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MB - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Plastic

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 24"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #8

LOCATION OF OUTFALL: End Del. River Park

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): NONE

PRECIPITATION LAST 48 HOURS (INCHES): NONE

DESCRIPTION OF AREA AROUND OUTFALL:

WATER

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Concrete

PIPE SHAPE: Square

PIPE DIMENSIONS (IN.): 2x2

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE (EARTHEN) RIP-RAP OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #9

LOCATION OF OUTFALL: TRACIES End of Center

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MJ - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): NONE

PRECIPITATION LAST 48 HOURS (INCHES): NONE

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4'

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #10 x3

LOCATION OF OUTFALL: NEAR Sewer plant

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

WATER

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Metal Corriggated

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 30" 24" 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NONE

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NONE

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NONE

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #11

LOCATION OF OUTFALL: Carpentersville RD

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

TREES

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Concrete

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 24"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): None

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

None

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

None

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #12 So. Main + Carpentersville RD

LOCATION OF OUTFALL: ~~12-14-23~~

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Water

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Terracotta

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 12"

SUBMERGED IN WATER (CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: ~~NONE~~ TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER) - Wall

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: ~~NONE~~ TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): None

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

None

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

None

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #13

LOCATION OF OUTFALL: Lock + S. Main

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS. MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

BRUSH

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Terracotta

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): NO PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): NO PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): None

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

None

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

None

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #14

LOCATION OF OUTFALL: Lock St.

DATE OF INSPECTION: 12-14-23

INSPECTED BY: MS - MA

WEATHER AT TIME OF INSPECTION: Sunny

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Trees, Bkrsh

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: Terracotta

PIPE SHAPE: Round

PIPE DIMENSIONS (IN.): 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE ~~EARTHEN~~ (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): None

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

None

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

None

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #14

LOCATION OF OUTFALL: Lock St

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Miks S + Mike A

WEATHER AT TIME OF INSPECTION: Sunny, Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE TRICKLE (MODERATE) SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE TRICKLE (MODERATE) SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #13

LOCATION OF OUTFALL: Lock + S. Main

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S + Mike A

WEATHER AT TIME OF INSPECTION: Sunny, Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

GRASS

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.)

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #12

LOCATION OF OUTFALL: Behind Agency

DATE OF INSPECTION: 11-13-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Sunny Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

BRUSH

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 18"

SUBMERGED IN WATER (CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): ~~NO~~ PARTIALLY FULLY

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE ~~TRICKLE~~ MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES NO

FLOW DESCRIPTION: NONE ~~TRICKLE~~ MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #11

LOCATION OF OUTFALL: Carpentersville RD

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Sunny Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #10 x3

LOCATION OF OUTFALL: Near Sewer Plant Foot Bridge

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike 3 Mike A

WEATHER AT TIME OF INSPECTION: Sunny Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

WATER

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Metal Corrigated

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30" 24" 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #7

LOCATION OF OUTFALL: TRACKS End of Canteen

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Sunny Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #8

LOCATION OF OUTFALL: DRP

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Sunny Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #7

LOCATION OF OUTFALL: Free Bridge

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mik. S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Sand

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #6 Riverside way Pump House

LOCATION OF OUTFALL: "

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

TREES

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 10"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #5

LOCATION OF OUTFALL: Riverside way + Toll Bridge

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mik. S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Metal

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: NONE TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #4

LOCATION OF OUTFALL: 3RD ST

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Nick S Mateo A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL: Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL: BRICK

PIPE SHAPE: ROUND

PIPE DIMENSIONS (IN.): 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC (OTHER)

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #3 Dodd Alley

LOCATION OF OUTFALL: "

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Concrete

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 4'

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: (TRAPEZOID) PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #2

LOCATION OF OUTFALL: Chimney Alley

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mike S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

Rocks

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Cast IRON

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 16"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #1

LOCATION OF OUTFALL: JT Baker Way End

DATE OF INSPECTION: 11-15-23

INSPECTED BY: Mik. S Mike A

WEATHER AT TIME OF INSPECTION: Clear

PRECIPITATION LAST 24 HOURS (INCHES): 0

PRECIPITATION LAST 48 HOURS (INCHES): 0

DESCRIPTION OF AREA AROUND OUTFALL:

WATER

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Plastic

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 30"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN (RIP-RAP) OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: YES (NO)

FLOW DESCRIPTION: (NONE) TRICKLE MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #14

LOCATION OF OUTFALL: Lock St

DATE OF INSPECTION: 3-13-23

INSPECTED BY: Mike S + Snyder

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/8th Inch

PRECIPITATION LAST 48 HOURS (INCHES): 1/4"

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 24"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE TRICKLE (MODERATE) SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE TRICKLE (MODERATE) SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #13

LOCATION OF OUTFALL: back + So Main

DATE OF INSPECTION: 3-13-23

INSPECTED BY: Mike S + Smythe

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/8 "

PRECIPITATION LAST 48 HOURS (INCHES): 1/4 "

DESCRIPTION OF AREA AROUND OUTFALL:

GRASS

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.)

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): NO

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

NO

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

NO

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: #12

LOCATION OF OUTFALL: Behind Agway

DATE OF INSPECTION: 3-23-23

INSPECTED BY: Mike S + Snyder

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/8"

PRECIPITATION LAST 48 HOURS (INCHES): 1/4"

DESCRIPTION OF AREA AROUND OUTFALL:

Brush

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Concrete

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 18"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: (CONCRETE) EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES:

OUTFALL INSPECTION

SECTION 1 - GENERAL NOTES

OUTFALL ID: # 11

LOCATION OF OUTFALL: Carpentersville RD

DATE OF INSPECTION: 3-13-23

INSPECTED BY: Mike S + Snyder

WEATHER AT TIME OF INSPECTION: Rainy

PRECIPITATION LAST 24 HOURS (INCHES): 1/8"

PRECIPITATION LAST 48 HOURS (INCHES): 1/4"

DESCRIPTION OF AREA AROUND OUTFALL:

Trees

SECTION 2 - OUTFALL PIPE DESCRIPTION

PIPE MATERIAL Cement

PIPE SHAPE Round

PIPE DIMENSIONS (IN.) 12"

SUBMERGED IN WATER (CIRCLE ONE): (NO) PARTIALLY FULLY

SUBMERGED IN SEDIMENT(CIRCLE ONE): (NO) PARTIALLY FULLY

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 3 - OUTFALL OPEN DRAINAGE DESCRIPTION

CHANNEL TYPE: CONCRETE EARTHEN RIP-RAP OTHER:

CHANNEL SHAPE: TRAPEZOID PARABOLIC OTHER

DEPTH:

TOP WIDTH:

BOTTOM WIDTH:

FLOW PRESENT: (YES) NO

FLOW DESCRIPTION: NONE (TRICKLE) MODERATE SUBSTANTIAL

SECTION 4 - OUTFALL OBSERVED CONDITIONS

ODOR DETECTED (DESCRIBE ODOR): No

PONDING/POOLING WATER EVIDENCE OF COLORS, OIL SHEEN, SUDS, ALGAE, OTHER:

No

CONDITION OF OUTFALL (NEED REPAIR OR DAMAGES OBSERVED):

No

ADDITIONAL COMMENTS OR NOTES: